

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
E 000	Initial Comments Federal Recertification Survey Survey Date: 07.30.2024 Pinnacle Health & Rehab Canton, a long-term care facility, was surveyed pursuant to the National Fire Protection Association 101 Life Safety Code, 2012 Edition as referenced in 42 CFR 483.90 (a - d) - Physical Environment and is not in substantial compliance.	E 000	This is the plan of correction developed for the statement of deficiencies developed for the Life Safety survey at Pinnacle Health & Rehab on July 30,2024	Sept. 7, 2024	
E 006 SS=F	Plan Based on All Hazards Risk Assessment CFR(s): 483.73(a)(1)-(2) §403.748(a)(1)-(2), §416.54(a)(1)-(2), §418.113(a)(1)-(2), §441.184(a)(1)-(2), §460.84(a)(1)-(2), §482.15(a)(1)-(2), §483.73(a) (1)-(2), §483.475(a)(1)-(2), §484.102(a)(1)-(2), §485.68(a)(1)-(2), §485.542(a)(1)-(2), §485.625(a)(1)-(2), §485.727(a)(1)-(2), §485.920(a)(1)-(2), §486.360(a)(1)-(2), §491.12(a)(1)-(2), §494.62(a)(1)-(2) [(a) Emergency Plan. The [facility] must develop and maintain an emergency preparedness plan that must be reviewed, and updated at least every 2 years. The plan must do the following:] (1) Be based on and include a documented, facility-based and community-based risk assessment, utilizing an all-hazards approach.* (2) Include strategies for addressing emergency events identified by the risk assessment. * [For Hospices at §418.113(a):] Emergency Plan. The Hospice must develop and maintain an emergency preparedness plan that must be reviewed, and updated at least every 2 years. The	E 006	All residents have the potential of being affected by this deficiency. Emergency Plan Based on All Hazards Risk Assessment. The facility had developed an All Hazards Emergency Preparedness Plan. Through a lack of communication it had not been printed & placed in the emergency preparedness book. That has been accomplished. This policy will be reviewed & reported to QAPI annually	Aug. 5,2024	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X8) DATE
	ADMINISTRATOR	8/5/2024

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

RECEIVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 AUG 15 2024 B. WING BY:		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
E 006	Continued From page 1 plan must do the following: (1) Be based on and include a documented, facility-based and community-based risk assessment, utilizing an all-hazards approach. (2) Include strategies for addressing emergency events identified by the risk assessment, including the management of the consequences of power failures, natural disasters, and other emergencies that would affect the hospice's ability to provide care. *[For LTC facilities at §483.73(a):] Emergency Plan. The LTC facility must develop and maintain an emergency preparedness plan that must be reviewed, and updated at least annually. The plan must do the following: (1) Be based on and include a documented, facility-based and community-based risk assessment, utilizing an all-hazards approach, including missing residents. (2) Include strategies for addressing emergency events identified by the risk assessment. *[For ICF/IIDs at §483.475(a):] Emergency Plan. The ICF/IID must develop and maintain an emergency preparedness plan that must be reviewed, and updated at least every 2 years. The plan must do the following: (1) Be based on and include a documented, facility-based and community-based risk assessment, utilizing an all-hazards approach, including missing clients. (2) Include strategies for addressing emergency events identified by the risk assessment. This REQUIREMENT is not met as evidenced by: Based on observation, interview and record review, the long term care facility failed to	E 006			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
E 006	Continued From page 2 maintain a risk assessment for Emergency Preparedness Plan in accordance with 42 CFR 483.73 Finding: On 07.30.2023, between 09:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. There was no evidence in the emergency preparedness plan of a risk assessment documented, facility-based and community-based risk assessment, utilizing an all-hazards approach. Assessment states last updated 01.03.2022 The surveyor confirmed this finding with the Maintenance assistant at the time of the observation.	E 006			
E 024 SS=F	Policies/Procedures-Volunteers and Staffing CFR(s): 483.73(b)(6) §403.748(b)(6), §416.54(b)(5), §418.113(b)(4), §441.184(b)(6), §460.84(b)(7), §482.15(b)(6), §483.73(b)(6), §483.475(b)(6), §484.102(b)(5), §485.68(b)(4), §485.542(b)(6), §485.625(b)(6), §485.727(b)(4), §485.920(b)(5), §491.12(b)(4), §494.62(b)(5). [(b) Policies and procedures. The [facilities] must develop and implement emergency preparedness policies and procedures, based on the emergency plan set forth in paragraph (a) of this section, risk assessment at paragraph (a)(1) of this section, and the communication plan at paragraph (c) of this section. The policies and procedures must be reviewed and updated at least every 2 years	E 024	All residents have the potential to be affected by this deficiency The use of Volunteers in an emergency or emergency staffing strategies. The only volunteers utilized at Pinnacle are volunteers who assist in the activities department They have no emergency staffing function, and that is stated in the Emergency Preparedness Plan. This policy will be reviewed & reported annually to QAPI.		Aug.5, 2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

AUG 15 2024

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
E 024	Continued From page 3 [annually for LTC facilities]. At a minimum, the policies and procedures must address the following:] (6) [or (4), (5), or (7) as noted above] The use of volunteers in an emergency or other emergency staffing strategies, including the process and role for integration of State and Federally designated health care professionals to address surge needs during an emergency. *[For RNHCIs at §403.748(b):] Policies and procedures. (6) The use of volunteers in an emergency and other emergency staffing strategies to address surge needs during an emergency. *[For Hospice at §418.113(b):] Policies and procedures. (4) The use of hospice employees in an emergency and other emergency staffing strategies, including the process and role for integration of State and Federally designated health care professionals to address surge needs during an emergency. This REQUIREMENT is not met as evidenced by: Based on observation, interview and record review, the long term care facility failed to have a plan to utilize volunteers for Emergency Preparedness Plan in accordance with 42 CFR 483.73 Finding: On 07.30.2024, between 09:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. The was no evidence in the emergency	E 024			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
E 024	Continued From page 4 preparedness plan for the use of volunteers in an emergency or other emergency staffing strategies, including the process and role for integration of State and Federally designated health care professionals to address surge needs during an emergency. The administrator states the facility does use volunteers in activities. No documentation was provided.	E 024			
E 029 SS=F	The surveyor confirmed this finding with the Maintenance assistant at the time of the observation. Development of Communication Plan CFR(s): 483.73(c) §403.748(c), §416.54(c), §418.113(c), §441.184(c), §460.84(c), §482.15(c), §483.73(c), §483.475(c), §484.102(c), §485.68(c), §485.542(c), §485.625(c), §485.727(c), §485.920(c), §486.360(c), §491.12(c), §494.62(c). (c) The [facility] must develop and maintain an emergency preparedness communication plan that complies with Federal, State and local laws and must be reviewed and updated at least every 2 years [annually for LTC facilities]. This REQUIREMENT is not met as evidenced by: Based on observation, interview and record review, the long term care facility failed to maintain a communication plan for Emergency Preparedness Plan in accordance with 42 CFR 483.73 Finding:	E 029	Development of an Emergency Preparedness Communication Plan. All residents have the potential to be affected by this deficiency. As with the above referenced Emergency Preparedness Plan, the Communication Plan had not been printed & placed in the Emergency Preparedness book. This plan will be reviewed annually & reported to QAPI.	Aug. 5, 2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
E 029	Continued From page 5 On 07.30.2024, between 09:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. The was no evidence in the emergency preparedness plan of a communications plan. The facility must develop and maintain an emergency preparedness communication plan that complies with Federal, State and local laws and must be reviewed and updated at least every year. Communication plan was last reviewed on 08.01.2021 documented at bottom of page. The surveyor confirmed this finding with the Maintenance assistant at the time of the observation.	E 029			
K 000	INITIAL COMMENTS Federal Recertification Survey: Date: 07.30.2024 Pinnacle Health & Rehab Canton, a Long Term Care Facility, was surveyed to the National Fire Protection Association 101 Life Safety Code 2012 Edition as reference on 42 CFR 483.90 (a-d) physical environment and is not in substantial compliance.	K 000	K000 The following Plan of correction is specifically for the K-tags involved in the Federal recertification survey of July 30, 2024		
K 163 SS=F	Interior Nonbearing Wall Construction CFR(s): NFPA 101 Interior Nonbearing Wall Construction Interior nonbearing walls in Type I or II construction are constructed of noncombustible or limited-combustible materials. Interior nonbearing walls required to have a minimum 2 hour fire resistance rating are permitted to be fire-retardant-treated wood enclosed within noncombustible or	K 163	Interior Nonbearing Wall Construction All residents have the potential of being affected by this deficiency. Adjustments were made to the door & assurance of proper functioning noted. All doors will be inspected monthly & a report made to QAPI.		Aug.5. 2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

RECEIVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 163	Continued From page 6 limited-combustible materials, provided they are not used as shaft enclosures. 19.1.6.4, 19.1.6.5 This REQUIREMENT is not met as evidenced by: Based on observation and interview, the long-term care facility failed to maintain the integrity of the 2-hour wall between the LTC, and the Living Center side of the building per NFPA 101, Life Safety Code, 2012 edition, section 19.1.6.5. Finding: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following finding with the Maintenance Assistant present: 1. The 3-hour door in the 90 minute frame in the only 2-hour separation wall did not self-close and latch due to air flow. Fire rated doors shall self-close and positively latch upon release. This surveyor confirmed this finding with the Maintenance Assistant, at the time of the observation.	K 163			
K 211 SS=D	Means of Egress - General CFR(s): NFPA 101 Means of Egress - General Aisles, passageways, corridors, exit discharges, exit locations, and accesses are in accordance with Chapter 7, and the means of egress is continuously maintained free of all obstructions to full use in case of emergency, unless modified by 18/19.2.2 through 18/19.2.11. 18.2.1, 19.2.1, 7.1.10.1 This REQUIREMENT is not met as evidenced	K 211	All residents have the potential to be affected by this deficiency. 1. The north wing med cart has always been intended to be stored in the Nurses Station when not in use. This policy will be reinforced. 2. The barrel bolt on the staff bathroom has been removed.		Aug.5, 2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		RECEIVED AUG 15 2024	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X6) COMPLETION DATE	
K 211	Continued From page 7 by: Based on observation and interview during the facility tour, the long-term care facility failed in 2 of 4 smoke compartments to maintain the exit discharges to continuously maintained free of all obstacles or impediments. No furnishings, decorations, or other objects shall obstruct exits or their access thereto, egress therefrom, or visibility thereof. Ref: NFPA 101, Life Safety Code, 2012 Edition, Sections 7.1.10.1-2, 7.1.6.4, 19.2.2.2.5 and 19.2.1. Findings: On 07.30.2024, between 9:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. North Wing has a med cart with laptop plugged in and stored in hallway across from room 119. The nurse states this is where they store the med cart normally. 2. Living Center barrel bolt on outside of staff bathroom door could be used to lock someone in the bathroom. 3. Living Center near room 221 barrel bolt on outside of client bathroom door could be used to lock someone in the bathroom. The surveyor confirmed these findings with the Maintenance assistant at the time of the observation.	K 211	3. The barrel bolt on the resident's bathroom has been removed.			
K 293 SS=D	Exit Signage CFR(s): NFPA 101 Exit Signage 2012 EXISTING Exit and directional signs are displayed in	K 293	All residents have the potential to be affected by this deficiency.		Sept. 7, 2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/15/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 293	Continued From page 8 accordance with 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1 (Indicate N/A in one-story existing occupancies with less than 30 occupants where the line of exit travel is obvious.) This REQUIREMENT is not met as evidenced by: Based on observation and interview, the long-term care facility in 2 of 4 smoke compartments failed to maintain exit signs in accordance with 7.10 per NFPA 101, Life Safety Code, 2012 Edition, Sections 19.2.10.1 & 7.10 Findings: On 07.30.2024, between 9:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. Above cross corridor doors by the laundry room has Exit sign that does not illuminate. 2. Business office Exit sign above the exterior door does not illuminate. 3. Above cross corridor door by room 206 has an Exit sign that does not illuminate. 4. Business office Exit sign by conference area does not illuminate. The surveyor confirmed these findings with the Maintenance assistant at the time of the observation.	K 293	1. Illuminated exit signs have been obtained for the laundry room, the business office exit, the business office conference area, and, the cross corridor door by room 206. 2. The aforementioned exit signs will be installed by the completion date. 3. A report of completion will be provided by the installing electrician. 4. All exit signs will be inspected monthly to assure compliance & a report will be made monthly to QAPI.		
K 321 SS=F	Hazardous Areas - Enclosure CFR(s): NFPA 101 Hazardous Areas - Enclosure Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour	K 321	Hazardous Areas Fire Barrier having 1 hour Fire Resistance Rating.	Aug.16, 2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 321	Continued From page 9 fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9. When the approved automatic fire extinguishing system option is used, the areas shall be separated from other spaces by smoke resisting partitions and doors in accordance with 8.4. Doors shall be self-closing or automatic-closing and permitted to have nonrated or field-applied protective plates that do not exceed 48 inches from the bottom of the door. Describe the floor and zone locations of hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9 Area Automatic Sprinkler Separation N/A a. Boiler and Fuel-Fired Heater Rooms b. Laundries (larger than 100 square feet) c. Repair, Maintenance, and Paint Shops d. Soiled Linen Rooms (exceeding 64 gallons) e. Trash Collection Rooms (exceeding 64 gallons) f. Combustible Storage Rooms/Spaces (over 50 square feet) g. Laboratories (if classified as Severe Hazard - see K322) This REQUIREMENT is not met as evidenced by: Based on observation, and interview, the long-term care facility failed to maintain the hazard area enclosures in accordance with NFPA 101, Life Safety Code, 2012 edition, sections 19.3.2.1. Findings: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant present:	K 321	All residents have the potential to be affected by this deficiency. 1.The gap in the living center soiled linen center door has been eliminated. 2. The salon door is being fitted with a self closure & latch. 3. The laundry room door has been adjusted & works appropriately. Self closing doors will be inspected monthly& reported to QAPI.		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 07/30/2024
---	---	--	---

NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON	STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------------	--	---------------------	--	----------------------------

K 321

Continued From page 10

1. The Living Center soiled linen door has a 1/2 inch gap at the top of the door.
2. The salon is being used as a storage area. The door doesn't self-close and latch.
3. The laundry room door doesn't self-close and latch upon release.

This surveyor confirmed these findings with the Maintenance Assistant at the time of the observation.

K 331
SS=D

Interior Wall and Ceiling Finish
CFR(s): NFPA 101

Interior Wall and Ceiling Finish
2012 EXISTING

Interior wall and ceiling finishes, including exposed interior surfaces of buildings such as fixed or movable walls, partitions, columns, and have a flame spread rating of Class A or Class B. The reduction in class of interior finish for a sprinkler system as prescribed in 10.2.8.1 is permitted.

10.2, 19.3.3.1, 19.3.3.2

Indicate flame spread rating(s).

This REQUIREMENT is not met as evidenced by:

Based on observation and interview, the long-term care facility in 1 of 4 smoke compartments failed to maintain exposed interior finish in accordance with 10.2 per NFPA 101, Life Safety Code, 2012 Edition, Sections 19.3.3.1 & 19.3.3.2

Findings:

K 321

All residents have the potential to be affected by this deficiency.
1. The gap in the living center soiled linen center door has been eliminated.
2. The salon door is being fitted with a self closure & latch.
3. The laundry room door has been adjusted & works appropriately. Self closing doors will be inspected monthly & reported to QAPI.

K331

Interior Wall & Ceiling
Finish

All residents have the potential to be affected by this

The untreated carpeting on the living center doors in rooms 203, 204, 206, & the soiled linen room will be removed by the completion date.

Aug. 16, 2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

RECEIVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 AUG 15 2024 B. WING _____ BY: _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 331	Continued From page 11 On 07.30.2024, between 9:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. Living Center Patient room 203 door has carpet not treated affixed to the bottom of the door measuring 26" Maintenance assistant states he installed carpet but to scratches on the door. He did not treat carpet with flame retardant spray and provided no documentation. 2. Living Center Patient room 204 door has carpet not treated affixed to the bottom of the door measuring 26" Maintenance assistant states he installed carpet but to scratches on the door. He did not treat carpet with flame retardant spray and provided no documentation. 3. Living Center Patient room 205 door has carpet not treated affixed to the bottom of the door measuring 26" Maintenance assistant states he installed carpet but to scratches on the door. He did not treat carpet with flame retardant spray and provided no documentation. 4. Living Center soiled linen room door has carpet not treated affixed to the bottom of the door measuring 26" Maintenance assistant states he installed carpet but to scratches on the door. He did not treat carpet with flame retardant spray and provided no documentation. The surveyor confirmed these findings with the Maintenance assistant at the time of the observation.	K 331			
K 345 SS=F	Fire Alarm System - Testing and Maintenance CFR(s): NFPA 101 Fire Alarm System - Testing and Maintenance A fire alarm system is tested and maintained in	K 345	All residents have the potential to be affected by this deficiency.	Sept. 7, 2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		RECEIVED AUG 15 2024	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 345	Continued From page 12 accordance with an approved program complying with the requirements of NFPA 70, National Electric Code, and NFPA 72, National Fire Alarm and Signaling Code. Records of system acceptance, maintenance and testing are readily available. 9.6.1.3, 9.6.1.5, NFPA 70, NFPA 72 This REQUIREMENT is not met as evidenced by: Based on observation, Interview and documentation review, the long-term care facility failed to maintain Fire alarm inspection records for review per NFPA 101, Life Safety Code, 2012 edition, sections 9.6.1.3, and 9.6.1.5, and NFPA 72, National Fire Alarm and Signal Code, 2010 edition, Section 14.6.2 Findings: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant and the Administrator. 1. Upon documentation review in the white Fire Alarm Inspection binder, no current fire alarm annual inspection report could be produced. The most recent fire alarm report was dated 08/11/2022. Neither the maintenance Assistant, nor the Maintenance Lead, (by phone) could locate any other documentation regarding the fire alarm inspection. The Administrative assistant could not produce one from the computer database upon request. Please provide the most recent fire alarm inspection report for both buildings. 2. Upon documentation review in the white Fire Alarm Inspection binder, no current fire alarm smoke detector sensitivity report could be	K 345	1. All required inspections will be finalized by the completion date, to include; the fire alarm system inspection, the fire alarm smoke detector sensitivity test, connecting the Maplewood fire alarm system to monitoring by the emergency forces notification. 2. The smoke detector in Maplewood resident room 301 will be replaced by the completion date. All fire alarm inspections will be reported to QAPI.			

CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

AUG 15 2024

FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 345	Continued From page 13 produced. There are no sensitivity reports in the binder. Neither the maintenance Assistant, nor the Maintenance Lead, (by phone) could locate any other documentation regarding the fire alarm inspection sensitivity test. The Administrative assistant could not produce one from the computer database upon request. Please provide the sensitivity report for both buildings. 3. According to the fire alarm report from 2022, the Maple Wood building fire alarm is not monitored for automatic emergency forces notification. 4. The smoke detector in Maple Wood resident room 301 was removed from the room. This surveyor confirmed these findings with Administrator, Maintenance Assistant, and Maintenance Lead, (by phone), at the time of the observation and review.	K 345			
K 353 SS=F	Sprinkler System - Maintenance and Testing CFR(s): NFPA 101 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked _____ b) Who provided system test _____ c) Water system supply source _____	K 353	Sprinkler system Maintenance & Testing All Residents have the potential to be affected by this deficiency. 1. The sprinkler test from June 2024 was performed, the test result is attached.		9/07/2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 353	Continued From page 14 Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 This REQUIREMENT is not met as evidenced by: Based on observation, interview and documentation review, the long-term care facility failed to maintain and provide documentation of maintenance of the sprinkler system per NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems, 2011 edition, sections 4.3.1, 4.3.3, 4.3.5, and 5.2.1.1.4, and in accordance with NFPA 101, Life Safety Code, 2012 edition, sections 9.7.5, and 9.7.8. Findings: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant and the Administrator present. 1. The most recent quarterly sprinkler inspection report on file was dated in June of 2023. No other reports were in the binder labeled Sprinkler Inspections. Neither the maintenance Assistant, nor the Maintenance Lead, (by phone) could locate any other documentation regarding the sprinkler inspection. The office could not locate any records to review. Please provide the last 4 quarterly sprinkler inspection reports, and maintain them on file for review. 2. An escutcheon is missing from the sprinkler head in the kitchen above the pot rack.	K 353	2. The escutcheon from the sprinkler head in the kitchen, above the pot rack, will be replaced by the completion date.	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

RECEIVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 28 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 353	Continued From page 15 This surveyor confirmed these findings with Administrator, Maintenance Assistant, and Maintenance Lead, (on the phone) at the time of the observation and review.	K 353			
K 363 SS=F	Corridor - Doors CFR(s): NFPA 101 Corridor - Doors Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke and are made of 1 3/4 inch solid-bonded core wood or other material capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Corridor doors and doors to rooms containing flammable or combustible materials have positive latching hardware. Roller latches are prohibited by CMS regulation. These requirements do not apply to auxiliary spaces that do not contain flammable or combustible material. Clearance between bottom of door and floor covering is not exceeding 1 inch. Powered doors complying with 7.2.1.9 are permissible if provided with a device capable of keeping the door closed when a force of 5 lbf is applied. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Nonrated protective plates of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies.	K 363	Corridor-Doors All residents have the potential to be affected by this deficiency. 1. Everything interfering with the door closure in room 107 has been corrected. 2. The door in resident room 207 has been adjusted & now closes . 3. has been adjusted & now closes . 4. The door in resident room 304 has been adjusted & now latches. 5. The clean linen storage closet door has been adjusted & the gap eliminated. Door inspections are performed monthly & reported to QAPI.	8/5/2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/15/2024
FORM APPROVED
OMB NO. 0938-0391

AUG 15 2024

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 363	Continued From page 16 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Based on observation, interview and documentation review, the long-term care facility failed to maintain the corridor doors to resist the passage of smoke in accordance with NFPA 101, Life Safety Code, 2012 edition, sections 19.3.6.3 Findings: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant present in all 3 residential care areas. 1. Resident room 107 has clothing hanging on the doorknob with hangers which prevent the door from fully closing. 2. Resident Room 207 door doesn't fully close as it hits on the top of the door frame. 3. Resident room 304 door doesn't latch upon closure. 4. The clean linen storage closet door has a 5/16 gap at the top of the door making it not resist the passage of smoke. This surveyor confirmed these findings with Maintenance Assistant at the time of the observation and review.	K 363			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 712 K 712 SS=F	Continued From page 17 Fire Drills CFR(s): NFPA 101 Fire Drills Fire drills include the transmission of a fire alarm signal and simulation of emergency fire conditions. Fire drills are held at expected and unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Where drills are conducted between 9:00 PM and 6:00 AM, a coded announcement may be used instead of audible alarms. 19.7.1.4 through 19.7.1.7 This REQUIREMENT is not met as evidenced by: Based on observation, interview and documentation review, the long-term care facility failed to conduct fire drills in accordance with NFPA 101, Life Safety Code, 2012 edition, sections 19.7.1. Finding: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant present. 1. The fire drills are not being conducted quarterly per shift. The master sheet shows the June 19th drill happening on 3rd shift, but it actually occurred on 1st shift per the drill log. There was no drill done by third shift in the second quarter of 2024. 2. The drill for February 26th, occurred at 8:30 PM. It is labeled as a silent drill. The times for coded announcement are from 2100-0600. This is outside these times. A coded announcement over an intercom or similar device is still required.	K 712 K 712	FireDrills All residents have the potential of being affected by this deficiency. 1. Fire Drills have not been done consistently quarterly & at the proper times. 2. Fire drills have been performed. Please see the attached information about past drills. There was a misunderstandi ng within the maintenance dept. about rotation of shifts. This has been corrected.	8/2/2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/15/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	AUG 15 2024 BY: _____	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 712	Continued From page 18 3. The drill from July 29th was at 06:30 AM and labeled a silent drill. The times for coded announcement are from 2100-0600. There is no mention of any coded announcement over an intercom or similar device on the sheet. This is outside these times. A coded announcement over an dintercorn or similar device is still required. 4. Upon interview, this surveyor asked the maintenance assistant what RACE and PASS stood for to verify instruction on life safety procedures and equipment, as he writes it on the fire drill documentation page. The employee had to go find a clipboard and read it off the back. Note: This surveyor showed the maintenance assistant the code reference regarding the quarterly drills and night drills in their LSC from their shelf during the documentation review. This surveyor asked the maintenance assistant what RACE stood for as it is on each fire drill documentation page. The employee had to go find a clipboard and read it off the back. This surveyor confirmed this finding with Administrator, Maintenance Assistant, and Maintenance Lead the time of the observation and review.	K 712	All future drills will be in accordance with regulations & reported to QAPI monthly.		
K 753 SS=D	Combustible Decorations CFR(s): NFPA 101 Combustible Decorations Combustible decorations shall be prohibited unless one of the following is met: o Flame retardant or treated with approved fire-retardant coating that is listed and labeled for product. o Decorations meet NFPA 701. o Decorations exhibit heat release less than	K 753	Combustible Decorations All residents have the potential of being affected by this deficiency.		8/8/2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 753	Continued From page 19 100 kilowatts in accordance with NFPA 289. o Decorations, such as photographs, paintings and other art are attached to the walls, ceilings and non-fire-rated doors in accordance with 18.7.5.6(4) or 19.7.5.6(4). o The decorations in existing occupancies are in such limited quantities that a hazard of fire development or spread is not present. 19.7.5.6 This REQUIREMENT is not met as evidenced by: Based on observation and interview, the long-term care facility failed to treat with approved fire-retardant coating per NFPA 101, Life Safety Code, 2012 Edition, Sections 19.7.5.6 (4) Finding: On 07.30.2024, between 9:30 AM and 1:30 PM, a surveyor, with the Maintenance assistant present, observed the following: 1. Physical Therapy room has large plastic plant decoration hanging on the wall. The Maintenance assistant was unable to provide documentation and was unsure if quilt was treated. The surveyor confirmed this finding with the Maintenance assistant at the time of the observation.	K 753	1. There was a lack of documentation attached to the wall hanging in question. 2. Please see the attached laboratory report.		
K 761 SS=F	Maintenance, Inspection & Testing - Doors CFR(s): NFPA 101 Maintenance, Inspection & Testing - Doors Fire doors assemblies are inspected and tested annually in accordance with NFPA 80, Standard for Fire Doors and Other Opening Protectives. Non-rated doors, including corridor doors to	K 761	Fire Doors & Corridor Doors are inspected & tested Annually by trained personnel.	8/2/2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		AUG 15 2024 BY: _____	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X6) COMPLETION DATE	
K 761	Continued From page 20 patient rooms and smoke barrier doors, are routinely inspected as part of the facility maintenance program. Individuals performing the door inspections and testing possess knowledge, training or experience that demonstrates ability. Written records of inspection and testing are maintained and are available for review. 19.7.6, 8.3.3.1 (LSC) 5.2, 5.2.3 (2010 NFPA 80) This REQUIREMENT is not met as evidenced by: Based on observation, Interview and documentation review, the long-term care facility failed to conduct an annual fire door per NFPA 80, Standard for Fire Door and Other Opening Protectives, 2010 edition, section 5.2 and in accordance with NFPA 101, Life Safety Code, 2012 edition, sections 19.7.6, and 8.3.3.1. Finding: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant and the Administrator. 1. The facility failed to complete the assessment of all fire doors in the facility. The facility had no documentation that the doors had been inspected by a trained employee or an outside qualified vendor since 06/13/2022. No other reports were in the binder labeled Fire Door Inspections. All other sheets were blank. Neither the maintenance Assistant, nor the Maintenance Lead, (by phone) could locate any other documentation regarding the fire door inspection. This surveyor confirmed this finding with Administrator, Maintenance Assistant, and Maintenance Lead the time of the observation	K 761	All Residents have the potential of being affected by this deficiency. Documentation has been located. The documentation is available. Annual door inspections will be reported to QAPI			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 761	Continued From page 21 and review.	K 761			
K 918 SS=F	Electrical Systems - Essential Electric System CFR(s): NFPA 101 Electrical Systems - Essential Electric System Maintenance and Testing The generator or other alternate power source and associated equipment is capable of supplying service within 10 seconds. If the 10-second criterion is not met during the monthly test, a process shall be provided to annually confirm this capability for the life safety and critical branches. Maintenance and testing of the generator and transfer switches are performed in accordance with NFPA 110. Generator sets are inspected weekly, exercised under load 30 minutes 12 times a year in 20-40 day intervals, and exercised once every 36 months for 4 continuous hours. Scheduled test under load conditions include a complete simulated cold start and automatic or manual transfer of all EES loads, and are conducted by competent personnel. Maintenance and testing of stored energy power sources (Type 3 EES) are in accordance with NFPA 111. Main and feeder circuit breakers are inspected annually, and a program for periodically exercising the components is established according to manufacturer requirements. Written records of maintenance and testing are maintained and readily available. EES electrical panels and circuits are marked, readily identifiable, and separate from normal power circuits. Minimizing the possibility of damage of the emergency power source is a design consideration for new installations. 6.4.4, 6.5.4, 6.6.4 (NFPA 99), NFPA 110, NFPA 111, 700.10 (NFPA 70)	K 918	Electrical Systems All residents have the potential to be affected by this deficiency 1. No weekly inspection reports on voltage conductance for sealed batteries. The information has been located and is available. 2. No monthly reports for March through July of 2024. The information has been located. All monthly reports will be reported to QAPI	8/10/2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____ AUG 15 2024	(X3) DATE SURVEY COMPLETED 07/30/2024
---	---	---	---

NAME OF PROVIDER OR SUPPLIER

PINNACLE HEALTH & REHAB CANTON

STREET ADDRESS, CITY, STATE, ZIP CODE

28 PLEASANT ST
CANTON, ME 04221

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 918	Continued From page 22 This REQUIREMENT is not met as evidenced by: Based on observation, interview, and generator inspection documentation review during the facility tour, the long-term care facility failed to maintain the Essential Electric System Generator per NFPA 110, Standard for Emergency and Standby Power Systems, 2010 edition, sections 8.3.7. and 8.4.1, and NFPA 99, Healthcare Facilities Code, 2012 edition, section 6.4.4.1.1.3. Findings: On July 16th, 2024, between 9:00 AM and 12:00 PM, a surveyor, with the Maintenance Director and Administrator present, observed the following: 1. Emergency Power Supply Systems, including all appurtenant components, shall be inspected weekly. The weekly generator inspection reports do not show a voltage conductance test for sealed batteries or an electrolyte specific gravity reading for unsealed automotive batteries. The only item listed on the weekly inspection paper is the hour meter. 2. No monthly generator inspections were conducted in the months of March, April, May, June, or July of 2024. Upon interview of the maintenance assistant, the maintenance lead has been out and it hasn't been done since he left. The only generator inspection has been the weekly recording of the hour meter. The surveyor confirmed these findings with the Maintenance Assistant, Maintenance Lead, (by Phone) and Administrator at the time of the	K 918		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/07/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____ BY: _____	AUG 15 2024 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 918	Continued From page 23 observation.	K 918		
K 919 SS=D	Electrical Equipment - Other CFR(s): NFPA 101 Electrical Equipment - Other List in the REMARKS section any NFPA 99 Chapter 10, Electrical Equipment, requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 10 (NFPA 99) This REQUIREMENT is not met as evidenced by: Based on observation and interview, the long-term care facility in 1 of 4 smoke compartments failed to test and maintain multiple outlet connections in patient rooms NFPA 99, Healthcare Facilities Code, 2012 Edition, Sections 10.2.3.6 Finding: On 07.30.2024, between 9:30 AM and 1:30 PM, a surveyor, with the acting Maintenance assistant present, observed the following: 1. Living Center nurse's station multiple outlet connections that are not hospital grade and have no record of testing connection. The surveyor confirmed this finding with the acting Maintenance assistant at the time of the observation.	K 919	Electrical Equipment All residents have the potential of being affected by this deficiency. 1. The multiple electrical outlets at the Living Center Nurses station has been corrected. Monthly electrical outlet inspections will be conducted & reported to QAPI	8/7/2024
K 923 SS=D	Gas Equipment - Cylinder and Container Storage CFR(s): NFPA 101 Gas Equipment - Cylinder and Container Storage	K 923		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED
OMB NO. 0938-0391

RECEIVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		AUG 15 2024 BY: _____	(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 923	Continued From page 24 Greater than or equal to 3,000 cubic feet Storage locations are designed, constructed, and ventilated in accordance with 5.1.3.3.2 and 5.1.3.3.3. >300 but <3,000 cubic feet Storage locations are outdoors in an enclosure or within an enclosed interior space of non- or limited- combustible construction, with door (or gates outdoors) that can be secured. Oxidizing gases are not stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) This REQUIREMENT is not met as evidenced by: Based on observation, and interview, the long-term care facility failed to store oxygen	K 923	Gas equipment combustibles in oxygen room All residents have the potential of being affected by this deficiency. The oxygen stored in the oxygen storage room has been adjusted to below 300 cubic feet. This meets the NFPA regulation for that volume. Routine monitoring will be performed by the maintenance Dept. and reported to QAPI monthly		8/2/2024	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

RECEIVED

PRINTED: 08/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 205101	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 BY: _____ B. WING _____		(X3) DATE SURVEY COMPLETED 07/30/2024
NAME OF PROVIDER OR SUPPLIER PINNACLE HEALTH & REHAB CANTON			STREET ADDRESS, CITY, STATE, ZIP CODE 26 PLEASANT ST CANTON, ME 04221		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 923	Continued From page 25 cylinders in accordance with NFPA 99, Healthcare Facilities Code, 2012 edition, section 11.3.2.3(2) Finding: On 07/30/2024, between 09:30 AM and 1:30 PM, this surveyor, observed the following findings with the Maintenance Assistant present. 1. The oxygen storage room contained 13 E cylinders that are marked to contain 24 cubic feet each. (312 cubic feet) In storage rooms of Oxygen between 300 and 3000 cubic feet there shall be no combustibles within 5 feet of the cylinders. There are combustibles to include wood shelving within five feet of the oxygen cylinders. This surveyor confirmed this finding with the Maintenance Assistant, at the time of the observation.	K 923			

K293 Electrician Documentation of Exit Signs

RECEIVED

AUG 15 2024

BY: _____

Appointment Confirmation - 9/3 and 9/4

Nick Tifft <NTifft@debloiselectric.com>

Thu 8/15/2024 8:45 AM

To: Jim Cossar <JCossar@pinnaclecantan.com>

Hi Jim,

RECEIVED

AUG 15 2024

BY: _____

Per our discussion, we have you scheduled for September 3rd and 4th to install the necessary Emergency Lights and to convert the single gang outlet boxes to quad receptacles.

Please let me know if you need anything else.

Thanks!

**DeBlois Electric, Inc.**

ELECTRICAL CONTRACTOR • DESIGN BUILD

Building Lasting Relationships Since 1967**100% Employee Owned****Nick Tifft**
Service Manager

Office: 207.783.6512 x122

Mobile: 207.740.4984

1033 Sabattus St., Lewiston, ME 04240

**From:** Jim Cossar <JCossar@pinnaclecantan.com>**Sent:** Wednesday, August 14, 2024 2:27 PM**To:** Nick Tifft <NTifft@debloiselectric.com>**Subject:**

Good afternoon, If you could please, I need to know in writing that you will be here, The Pinnacle Health and Rehab, before September 7th, 2024 to install the luminated EXIT signs. If you could send me an email back with that it would be much appreciated.

Thank you!

Jim Cossar.

JCossar@pinnaclecantan.com



Book time to meet with me

K331 Non treated Carpet on Door

RECEIVED

AUG 15 2024

BY: _____

This has been removed per the POC

**K345 Fire Alarm Report& Documentation of Smoke
alarm replacement**

RECEIVED

AUG 15 2024

BY: _____



MAINE FIRE PROTECTION SYSTEMS

PD Industries, Inc.
MAINE FIRE PROTECTION SYSTEMS
P.O. Box 1050
Bangor, ME 04402
(207) 942-8809 TEL
(207) 941-1910 FAX
service@mefirepro.com

DW _____

DATE 2-27-2021

RECEIVED

AUG 15 2024

WORK ORDER

BY: _____

CUSTOMER NAME Pinnacle Healthcare Centers

TELEPHONE _____

JOB LOCATION Canton Me.

CONTACT _____

BILL TO ADDRESS _____

WORK REQUESTED Replace 2 Siemens Smoke Detectors THAT
Failed Sensitivity Tests

WORK PERFORMED Replaced smoke #1073 & #1089 By NURSON STATION.
Tested The 2 Smokes and are good.

COMMENTS _____

LABOR: Straight Time _____ Over Time _____

TIME: From 7:00 am pm To 9:00 am pm

MATERIALS

DESCRIPTION	QTY.	PRICE	EXT. PRICE
SIEMENS HFI-11	2		

☒ Electrical Day Work

☐ Suppression Day Work

OFFICE USE ONLY

Materials \$ _____

Labor \$ _____

Invoice No. _____ TOTAL \$ _____

[Signature]
Customer Signature

Date

[Signature]
Technician Signature



PD Industries, Inc.
MAINE FIRE PROTECTION SYSTEMS
P.O. Box 1050
Bangor, ME 04402
(207) 942-8809 TEL
(207) 941-1910 FAX
service@mefirepro.com

DW _____

DATE 2-23-24

RECEIVED

AUG 15 2024

BY: _____

WORK ORDER

CUSTOMER NAME Pinnacle Rehab

TELEPHONE _____

JOB LOCATION 26 pleasant St, Canton

CONTACT _____

BILL TO ADDRESS _____

WORK REQUESTED Investigate devices that failed to alarm in fire event

WORK PERFORMED Sensitivity tested devices 1073, 1074, 1077, 1078, 1089
devices 1073 & 1089 failed, both adjacent to where fire
occurred. Heat detector outside bathroom also tested normally.

COMMENTS Panel history does not ever show smokes going into
alarm during fire. Smoke model: Siemens HFP-11

ABOR: Straight Time _____ Over Time _____

TIME: From 1:00 am pm To 3:00 am pm

ALL EMERGENCY SERVICE CALLS ARE A MINIMUM OF \$1300.00

MATERIALS

DESCRIPTION	QTY.	PRICE	EXT. PRICE

☒ Electrical Day Work

☐ Suppression Day Work

OFFICE USE ONLY Materials \$ _____

Labor \$ _____

Invoice No. _____ TOTAL \$ _____

Jim Corvax
Customer Signature

Date

Michael Page
Technician Signature





DATE 4/1/80

RECEIVED

AUG 15 2024

BY: _____

CUSTOMER NAME Pinnacle Health/Kehab **TELEPHONE** _____

JOB LOCATION Canton **CONTACT** Jim

BILL TO ADDRESS _____

WORK REQUESTED Replace bad Secure Call receiver

WORK PERFORMED Replaced & reprogrammed / tested new rear

with customer to ensure it was in

good working order. Also fixed broken

COMMENTS wires in another secure core controller.

LABOR: Straight Time _____ **Over Time** _____

TIME: From 7:00 am pm To 11:30 am pm

[illegible]

☒ **Electrical Day Work**

☐ Suppression Day Work

OFFICE USE ONLY **Materials \$** _____

Labor \$ _____

Invoice No. _____ **TOTAL \$** _____

TOTAL \$ _____

Customer Signature

Date _____

Technician Signature



MAINE FIRE PROTECTION SYSTEMS

PD Industries, Inc.
MAINE FIRE PROTECTION SYSTEMS
P.O. Box 1050
Bangor, ME 04402
(207) 942-8809 TEL
(207) 941-1910 FAX
service@mefirepro.com

DW _____
DATE 2-14-24

RECEIVED

AUG 15 2024

WORK ORDER BY: _____

CUSTOMER NAME Pinnacle Rehab in Bangor TELEPHONE _____

JOB LOCATION 26 Pleasant St Bangor ME CONTACT _____

BILL TO ADDRESS _____

WORK REQUESTED Replace and install a smoke detector for the flooded

WORK PERFORMED replaced smoke detector and tested it. It registered correctly.

COMMENTS _____

LABOR: Straight Time _____ Over Time _____

TIME: From 1:45 am (pm) To _____ am pm

MATERIALS

DESCRIPTION	QTY.	PRICE	EXT. PRICE
<u>System Bangor ME 04402 - 2W TA - 6 Smoke</u>	<u>2</u>		

☒ Electrical Day Work

☐ Suppression Day Work

OFFICE USE ONLY Materials \$ _____

Labor \$ _____

Invoice No. _____ TOTAL \$ _____

Customer Signature

Date

Technician Signature

RECEIVED

AUG 15 2024

BY: _____ 08-14-2024

On July 30th, I walked into room 301 in Maplewood and noticed the smoke detector was missing, with one neutral wire hanging. The person in charge at Maplewood said the resident pulled it down from the ceiling and she put it in the Med room.

I replaced it in the ceiling by hard wiring it. I then tested it and it worked fine.

Howard McLean

Maintenance Tech

Home Office
170 Kitehawk Ave.
P.O. Box 1390
Auburn, ME 04210-1390
207-784-1507

EASTERN FIRE

FIRE PROTECTION CONTRACTORS AND ENGINEERS

www.easternfiregroup.com

Satellite Office
408 Harlow St.
Bangor, ME 04401
207-942-8014

AUG 15 2024

BY: _____

Fire Sprinkler | Fire Alarm | Fire Suppression | Gas Detection | Burglar Alarms | CCTV | Access Control | Monitoring | Inspection, Testing, & Maintenance

Office Use -	Contract Start Date:		Customer #:		Contract #:	
--------------	----------------------	--	-------------	--	-------------	--

REMOTE STATION MONITORING CONTRACT

Maplewood Assisted Living
26 Pleasant Street, Canton, ME 04221

~ Proposal to ~

~ Bill to ~

Prepared for: Jim Cossar
Title: Maintenance Director
Company Name: Maplewood Assisted Living
Address: 26 Pleasant Street, Canton, ME 04221
Office: _____ Mobile: 207-890-7127
Personal: _____ Fax: _____
Email Address: jcossar@pinnaclecantan.com

Attention to: Melodie Abbott
Title: _____
Company Name: Pinnacle Health & Rehab
Address: 26 Pleasant Street, Canton, ME 04221
Office: _____ Mobile: 207-597-2501
Personal: _____ Fax: _____
Email Address: mabbott@pinnaclecantan.com

Scope of Work: Provide remote station monitoring of fire alarm system via a UL-listed Central Station.
Installation of cellular subscriber unit as communication pathway.
Programming and testing.

Panel Type: Simplex 4001

Format: Contact ID

Communication Pathway: 4G LTE/Cellular Transmission

Hardware, Installation, and Monitoring Setup Fee:

\$1,000.00

Annual Monitoring Fee:

\$500.00

If accepted, please sign and fax back to 207-782-0566 or e-mail eddie.chervenak@easternfiregroup.us
Please provide a Work Order or PO, if applicable.

Eastern Fire, Inc. Sales Representative

System/Building Owner or Representative

Signed: Edward J Chervenak
Printed: Edward J Chervenak
Title: Fire Alarm Service Manager
Date: 8/8/24 Quote#: _____

Signed: [Signature]
Printed: Ken Huchan
Title: ADMINISTRATOR
Date: 8/14/24 Work Order/PO#: _____

See Notes, Terms, and Conditions on next page...

Home Office
170 Kinyhawk Ave.
P.O. Box 1390
Auburn, ME 04210-1390
207-784-1507

EASTERN FIRE

FIRE PROTECTION CONTRACTORS AND ENGINEERS

www.easternfiregroup.com

Satellite Office
408 Harlow St.
Bangor, ME 04401
207-942-8014

Fire Sprinkler | Fire Alarm | Fire Suppression | Gas Detection | Burglar Alarms | CCTV | Access Control | Monitoring | Inspection, Testing, & Maintenance

Notes:

AUG 15 2024

BY:

- When installing cellular or radio communicators, sufficient signal strength is required. This means that additional hardware and labor may be required for a successful installation. Example: using an external antenna.
- It is the customer's responsibility to inform their current monitoring services provider, if applicable, of the change in service and/or cancellation.
- Eastern Fire, Inc. must be informed by the customer of any changes to the emergency telephone call list, the communication pathway (network, cellular, radio, phone line) service to the fire alarm panel or to the configuration of the fire alarm system
- If a programming code is needed, the customer or its' system installer/current service provider, must provide the needed code to make necessary programming changes for monitoring of the system at our remote station.
- If specialty/proprietary software, not available to Eastern Fire, Inc. is needed, coordination between Eastern Fire, Inc., the customer and programming company must occur in order to make programming changes for monitoring of the system at our remote station.
- Said company will need to program our remote station information (receiver numbers, account number, report format) into the system and/or communicator and assist with providing accurate reporting information (zoning, signal types, report codes).

REMOTE STATION MONITORING CONTRACT TERMS & CONDITIONS:

Contract Duration: This contract is in effect for (60) months from the date it is signed by the System Owner and can be terminated by either party with at least (30) days' notice. The Monitoring Company and System Owner agree to all **Terms and Conditions** contained herein, and both agree to work together to the greatest extent possible so that both receive maximum benefit from this contract.

Contract Renewal: This contract will be automatically renewed every (12) months unless either party, as outlined under Contract Duration above, terminates the contract. If a change in the contract cost is necessary, the System Owner will receive a new contract, for approval, at least (30) days prior to the next scheduled renewal.

Monitoring Company Obligations: The Monitoring Company agrees to provide prompt and courteous service to the System Owner at a time agreeable to both parties. The Monitoring Company agrees to contact the System Owner immediately upon notification of monitoring irregularities with the System Owner's monitoring account. The Monitoring Company agrees not to provide any other person, company or otherwise divulge the account information provided to it by the System Owner to include call list names, telephone numbers and passcodes.

System Owner Obligations: The System Owner agrees to cooperate by providing all necessary access, applicable information and personnel to the Monitoring Company so that monitoring documentation may be filled out to the greatest extent possible and monitoring set up and service can be accomplished. The System Owner agrees to promptly pay the Monitoring Company in accordance with the **Terms and Conditions** set forth below.

Terms and Conditions: The System Owner understands that this is a monitoring contract not a service, nor a testing/inspection contract. The Monitoring Company will make the System Owner aware of all monitoring system component deficiencies observed during the monitoring of the included systems and, if requested, provide the System Owner with pricing to repair those deficiencies. In return for the monitoring services provided by the Monitoring Company, the System Owner agrees to pay the Monitoring Company the stipulated contract amount, in full, within (10) calendar days of the date on the invoice. Semi-annual or quarterly invoicing is available upon request by the System Owner. Only the cost of producing one invoice is included in this contract, therefore a service charge of \$10.00 will be added to each additional requested invoice after the first (\$10 annual additional cost for semi-annual invoicing or \$30 annual additional cost for quarterly invoicing).

K353 2024 Sprinkler report

RECEIVED

AUG 15 2024

BY: _____

Country: United States of America

Email:

<https://www.buildingreports.com/servlet/reports.ReportsServlet?command=load-report&RetrieveAs=html&appId=P1&rpType=36&Inspld=3372850>

Inspection Performed By								
Company: Maine Fire Protection Systems Address: 6 Dowd Road Address: City/State/ZIP Code: Bangor, Maine 04401 Country: United States of America				Inspector: Gary Leblanc Phone: 207-942-8809 Fax: Mobile: Email: gary@mefirepro.com		RECEIVED AUG 15 2024 BY: _____		
System Control Unit								
System Type	System Location			Protected Area		Devices		
Dry Pipe	Building 1					6		
Dry Pipe	Building 2					3		
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	3	33.33%	3	100.00%	3	100.00%	0	0.00%
Device	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Hose	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Pump	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Sprinkler	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Valve	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Totals	9	100%	9	100.00%	9	100.00%	0	0.00%
Certification								
Company: Maine Fire Protection Systems Inspector: Gary Leblanc 6 L Signed: Jun 18, 2024				Building: Pinnacle Health & Rehab Contact: Ken Huhn NDCS Signed: Jun 18, 2024				
Gary Leblanc Certifications								
Certification Type						Number		
Maine Fire Sprinkler Inspector License						JFS581		
NEWWA Certification						0010596		

Navigation Console

Main Report Console

[Executive Summary](#)
[Inspection and Testing](#)
[Service Summary](#)
[Dry Pipe Systems](#)
[Inventory and Warranty Report](#)

Inspection & Testing

Generated by: [BuildingReports.com](https://www.buildingreports.com)



24-Hour Service
207-942-8809

RECEIVED
AUG 15 2024
BY: _____

Request Estimate

Sprinkler Inspection Report

Pinnacle Health & Rehab



Inspector: Gary Leblanc

Synchronized: 6/19/24 4:27:06 AM

Started: 6/18/24 12:27:05 PM

Finished: 6/18/24 12:29:46 PM



[Download this report.](#)



[Email this report to:
khuhn@pinnaclecantan.com](mailto:khuhn@pinnaclecantan.com)

Device Count:	% Tested:	% Passed:	% Failed:
9	100.00%	100.00%	0.00%

Report Navigation

Executive Summary

General information along with overall stats on this inspection.

Inspection and Testing

Each device and item inspected in your building.

Service Summary

A summary of the service performed.

Dry Pipe Systems

Inventory and Warranty Report

Installation Dates and Inventory of items in your building.

Please don't show me this again ☒

Executive Summary

Generated by: *BuildingReports.com*

Building Information

Building: Pinnacle Health & Rehab
Address: 26 Pleasant Street
Address:
City/State/ZIP Code: Canton, ME 04221
Country: United States of America

Contact: Ken Huhn
Phone: 207-597-2510
Fax:
Mobile:
Email:

Inspection Performed By

Company: Maine Fire Protection Systems
 Address: 6 Dowd Road
 Address:
 City/State/ZIP Code: Bangor, Maine 04401
 Country: United States of America

Inspector: Gary Leblanc
 Phone: 207-942-8809
 Fax:
 Mobile:
 Email: gary@mefirepro.com

RECEIVED

AUG 15 2024

BY:

System Control Unit

System Type	System Location	Protected Area	Devices
Dry Pipe	Building 1		6
Dry Pipe	Building 2		3

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	3	33.33%	3	100.00%	3	100.00%	0	0.00%
Device	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Hose	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Pump	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Sprinkler	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Valve	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Totals	9	100%	9	100.00%	9	100.00%	0	0.00%

Certification

Company: Maine Fire Protection Systems

Building: Pinnacle Health & Rehab

Inspector: Gary Leblanc

Contact: Ken Huhn

6 L

NOC

Signed: Jun 18, 2024

Signed: Jun 18, 2024

Gary Leblanc Certifications

Certification Type	Number
Maine Fire Sprinkler Inspector License	IFS581
NEWWA Certification	0010596

Navigation Console**Main Report Console****Executive Summary****Inspection and Testing****Service Summary****Dry Pipe Systems****Inventory and Warranty
Report*****Inspection & Testing***

Generated by: BuildingReports.com

Building: Pinnacle Health & Rehab					
The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred. For more information about an item, click on the link provided.					
Device Type	Location		Service	Time	Date
Passed					
Building 1 Dry Pipe					
<u>Supervisory Signal</u>	Basement	RECEIVED	Tested	12:29:06 PM	06/18/2024
<u>Tamper Switch</u>	Basement	AUG 15 2024	Tested	12:29:28 PM	06/18/2024
<u>Waterflow Switch</u>	Basement	BY: _____	Tested	12:29:14 PM	06/18/2024
<u>Drain</u>	Basement		Tested	12:28:51 PM	06/18/2024
<u>Piping</u>	Basement		Tested	12:27:05 PM	06/18/2024
<u>Dry Pipe Valve</u>	Basement		Tested	12:27:36 PM	06/18/2024
Building 2 Dry Pipe					
<u>Fire Dep't Connection</u>	Basement		Visually Checked	12:28:44 PM	06/18/2024
<u>Air Compressor</u>	Basement		Tested	12:28:31 PM	06/18/2024
<u>Control Valve</u>	Basement		Tested	12:29:46 PM	06/18/2024

Service Summary

Generated by: [BuildingReports.com](https://www.buildingreports.com)

Building: Pinnacle Health & Rehab		
The Service Summary section provides an overview of the services performed in this report.		
Device Type	Service	Quantity
Passed		
Air Compressor	Tested	1
Control Valve	Tested	1
Drain	Tested	1
Dry Pipe Valve	Tested	1
Fire Dep't Connection	Visually Checked	1
Piping	Tested	1
Supervisory Signal	Tested	1
Tamper Switch	Tested	1
Waterflow Switch	Tested	1
Total		9
Grand Total		9

Navigation Console

Main Report Console

Executive SummaryInspection and TestingService SummaryDry Pipe SystemsInventory and Warranty
Report

RECEIVED

AUG 15 2024

Dry Pipe Fire Sprinkler Systems

Generated by: BuildingReports.com

Building: Pinnacle Health & Rehab						Building 1		
This section lists out all the devices and components that have been associated with a Dry Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.								
Alarms								
Supervisory Signal								
Type	Location		Zone/Address		OK	ScanID		
Loe air	Basement		1		☒	79873999		
Tamper Switch								
Type	Description	Location	Number of Turns	Zone/Address	OK	ScanID		
Lever	Supervisory	Basement	2	1	☒	79874004		
Waterflow Switch								
Type	Manufacturer	Model #	Sec	Size	Zone/Address	OK	ScanID	
Pressure Switch	Potter	PS10	03	1/2	1	☒	79874000	
Components								
Dry Pipe Valve								
Manufacturer	Model #	Location	3 Year Leak Test		Internal Date	OK	ScanID	
Viking	C2	Basement	01/03/2024		06/20/2023	☒	79873997	
Type	Status	Position	Size		Serial #			
Flanged	Supervised	Trim Open	4"		unknown			
Water psi	Air Pressure	Trip Air	Trip Time	Total Timing (sec)	Partial Trip Date	Full Trip Date		
					06/20/2023	07/10/2028		
Devices								
Drain								
Current Inspection								
Type	Location	Size	Supply psi	Restored psi	Residual psi	Sec	OK	ScanID
Main	Basement	2"	86	85	80	0	☒	79873998
Previous Inspections								
April 2, 2024								
Type	Location	Size	Supply psi	Static psi	Residual psi	Sec	OK	ScanID
Main	Basement	2"	85	85	80	0	☒	79873998
January 3, 2024								
Type	Location	Size	Supply psi	Static psi	Residual psi	Sec	OK	ScanID
Main	Basement	2"	85	85	80	0	☒	79873998

Piping									
Location	Type	Size	Internal Date						
Basement	Steel	4"	07/10/2028						
Hangers	Braces	Fittings	Identified	Antifreeze	ScanID				
Normal	Normal	Cast Iron	Tagged	N/A	79873996				
Building: Pinnacle Health & Rehab								Building 2	
This section lists out all the devices and components that have been associated with a Dry Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.									
Air Compressor									
Location	Mfr.	Model #	Phase	On psi	Off psi	Serial No.			
Basement	Jenny								
Type	Description	Rated Speed	Horsepower	Volts	Amps	OK	ScanID		
Automatic	Tankless	1740	2	115	60	☒	79874006		
Components									
Control Valve									
Type	Manufacturer	Model	Location	Size	Position	Status	OK	ScanID	
OS&Y	Kennedy		Basement	4"	Open	Supervised	☒	79874005	
Description									
Main Control									
Devices									
Fire Dep't Connection									
Type	Size	BallDrip	Rotating Swivels	5-Year Hydro	Qty	ScanID			
Siamese	2.5"	Yes	Yes	07/10/2028	1	79874002			

RECEIVED

AUG 15 2024

Navigation Console

Main Report Console

BY: _____

Executive SummaryInspection and TestingService SummaryDry Pipe SystemsInventory and Warranty Report

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Pinnacle Health & Rehab			
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.			
Device or Type	Category	% of Inventory	Quantity
Air Compressor	Pump	11.11%	1
Control Valve	Valve	11.11%	1
Drain	Device	11.11%	1

Device or Type		Category		% of Inventory		Quantity	
Dry Pipe Valve		Valve		11.11%		1	
Fire Dep't Connection		Hose		11.11%		1	
Piping		Sprinkler		11.11%		1	
Supervisory Signal		Alarm		11.11%		1	
Tamper Switch		Alarm		11.11%		1	
Waterflow Switch		Alarm		11.11%		1	
Device Type		Qty	Model #	Type	Description		Install Date
<i>In Service - 25 Years or Older</i>							
Building 1 Dry Pipe							
Piping	1	4"	Steel				06/20/1978
Supervisory Signal	1	PS40	Loe air				06/20/1978
Tamper Switch	1		Lever	Supervisory			06/20/1978
Waterflow Switch	1	PS10	Pressure Switch	Alarm			06/20/1978
Drain	1		Main				06/20/1978
Dry Pipe Valve	1	C2	Flanged				06/20/1978
Building 2 Dry Pipe							
Air Compressor	1		Automatic	Tankless			06/20/1978
Control Valve	1		OS&Y	Main Control			06/20/1978
Fire Dep't Connection	1		Siamese				06/20/1978

RECEIVED

Navigation Console

AUG 15 2024

Main Report Console

BY: _____

Executive Summary.Inspection and TestingService Summary.Dry Pipe SystemsInventory and Warranty
Report



24-Hour Service
207-942-8809

Request Estimate

RECEIVED

AUG 15 2024

BY: _____

SprinklerScan		Service Tickets		SprinklerScan - Pinnacle Health &...	
Supervisory Signal		Alarm		11.11%	
Tamper Switch		Alarm		11.11%	
Waterflow Switch		Alarm		11.11%	
Device Type	Qty	Model #	Type	Description	
<i>In Service - 25 Years or Older</i>					
Building 1 Dry Pipe					
Piping	1	4"	Steel		
Supervisory Signal	1	PS40	Loe air		
Tamper Switch	1		Lever	Supervisory	
Waterflow Switch	1	PS10	Pressure Switch	Alarm	
Drain	1		Main		
Dry Pipe Valve	1	C2	Flanged		
Building 2 Dry Pipe					
Air Compressor	1		Automatic	Tankless	
Control Valve	1		OS&Y	Main Control	
Fire Dep't Connection	1		Siamese		
Navigation Console					
Main Report Console					
Executive Summary		Inspection and Testing		Service Summary	
Dry Pipe Systems		Inventory and Warranty Report			



24-Hour Service
207-942-8809

Request Estimate

RECEIVED

AUG 15 2024

BY: _____

SprinklerScan		Service Tickets		SprinklerScan - Pinnacle Health & Rehab	
program is included.					
Device Type	Manufacturer	Model Number	Date		
Items listed for Recall or Replacement/Upgrade					
No items found during this inspection.					
ScanID	Location	Problem	Reference		
Building 1 Dry Pipe					
Piping					
29873996	Basement	Rusted/Corroded	NFPA25 5.2.2.1		
Navigation Console Main Report Console					
Executive Summary Inspection and Testing Inventory and Warranty Report		Discrepancy Report Service Summary		Proposed Solutions Dry Pipe Systems	
Proposed Solutions Report Generated by: BuildingReports.com					
Building: Pinnacle Health & Rehab					
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within 1					

K753 Combustible Decorations

RECEIVED

AUG 15 2024

BY: _____



RECEIVED

AUG 15 2024

BY: _____

PREPARATION: Sufficient sample material was submitted to conform to tunnel test dimensions, 22" wide by 24' feet long. The sample was supported during testing by 2" hexagonal mesh poultry netting running the length of the test chamber and 1/4" round metal rods placed at two foot intervals across the width of the test chamber.

CONDITIONING: The test specimen was conditioned to a constant weight at a temperature of $73.4 \pm 5^\circ \text{F}$ ($23 \pm 2.8^\circ \text{C}$) and a relative humidity of $50 \pm 5\%$.

CEMENT BOARD PLACEMENT: The 1/4" cement boards were placed between the test specimen and the chamber lid

E 84 TEST DATA SHEET:



SAMPLE: Thermaleaf ® Inherently Fire Retardant Foliage

IGNITION: 6 seconds.

FLAME FRONT: 1 foot maximum.

TIME TO MAXIMUM SPREAD: 13 seconds.

TEST DURATION: 10 minutes.

CALCULATION: $9.84 \times 5.15 = 5.06$

SUMMARY: FLAME SPREAD: 5 SMOKE DEVELOPED: 50

SUMMARY OF ASTM E84 RESULTS: Because of the possible variations in reproducibility, the results are adjusted to the nearest figure divisible by 5. Smoke Density values over 200 are rounded to the nearest figure divisible by 50.

In order to obtain the Flame Spread Classification, the above results should be compared to the following table:

<u>NFPA CLASS</u>	<u>IBC CLASS</u>	<u>FLAME SPREAD</u>	<u>SMOKE DEVELOPED</u>
A	A	0 through 25	Less than or equal to 450
B	B	26 through 75	Less than or equal to 450
C	C	76 through 200	Less than or equal to 450

BUILDING CODES CITED:

1. National Fire Protection Association, ANSI/NFPA No. 101, "Life Safety Code".

2. International Building Code, Chapter 8, Interior Finishes, Section 803.

THIS REPORT IS THE CONFIDENTIAL PROPERTY OF THE CLIENT ADDRESSED. THE REPORT MAY ONLY BE REPRODUCED IN FULL. PUBLICATION OF EXTRACTS FROM THIS REPORT IS NOT PERMITTED WITHOUT WRITTEN APPROVAL FROM QAI. ANY LIABILITY ATTACHED THERETO IS LIMITED TO THE FEE CHARGED FOR THE INDIVIDUAL PROJECT FILE REFERENCED. THE RESULTS OF THIS REPORT PERTAIN ONLY TO THE SPECIFIC SAMPLE(S) EVALUATED.

RECEIVED

AUG 15 2024

BY: _____

Test Report No: RJ3378-1

Date: July 18, 2014

SAMPLE ID: The test samples are identified as: Thermaleaf ® Inherently Fire Retardant Foliage.

SAMPLING DETAIL: Test samples were submitted to the laboratory directly by the client. No special sampling conditions or sample preparation were observed by QAI.

DATE OF RECEIPT: Samples were received at QAI on July 11, 2014.

TESTING PERIOD: July 18, 2014.

AUTHORIZATION: Testing authorized by Bryce Peterson. Proposal # MB-2014-070801 dated and signed on 7-8-2014.

TEST REQUESTED: Perform standard flame spread and smoke density developed classification tests on the sample supplied by the Client in accordance with ASTM Designation E84-14, "Standard Method of Test for Surface Burning Characteristics of Building Materials". The foregoing test procedure is comparable to UL 723, ANSI/NFPA No. 255, and UBC No. 8-1.

TEST RESULTS:

Flame Spread

Smoke Developed

5

50

Detailed test results are presented in the subsequent pages of this report.

Prepared By



Brian Ortega

Brian Ortega
Test Technician

**Signed for and on behalf of
QAI Laboratories, Inc.**

Greg Banasky

Greg Banasky
Senior Technician



End of Report

RECEIVED

AUG 15 2024

BY: _____

Test Report No: RJ3378-1	Date: July 18, 2014
--------------------------	---------------------

SAMPLE ID: The test samples are identified as: Thermaleaf ® Inherently Fire Retardant Foliage.

SAMPLING DETAIL: Test samples were submitted to the laboratory directly by the client. No special sampling conditions or sample preparation were observed by QAI.

DATE OF RECEIPT: Samples were received at QAI on July 11, 2014.

TESTING PERIOD: July 18, 2014.

AUTHORIZATION: Testing authorized by Bryce Peterson. Proposal # MB-2014-070801 dated and signed on 7-8-2014.

TEST REQUESTED: Perform standard flame spread and smoke density developed classification tests on the sample supplied by the Client in accordance with ASTM Designation E84-14, "Standard Method of Test for Surface Burning Characteristics of Building Materials". The foregoing test procedure is comparable to UL 723, ANSI/NFPA No. 255, and UBC No. 8-1.

TEST RESULTS:	<u>Flame Spread</u>	<u>Smoke Developed</u>
	5	50


Detailed test results are presented in the subsequent pages of this report.

Prepared By



Brian Ortega
Test Technician

Signed for and on behalf of
QAI Laboratories, Inc.



Greg Banasky
Senior Technician

Page 1 of 3

THIS REPORT IS THE CONFIDENTIAL PROPERTY OF THE CLIENT ADDRESSED. THE REPORT MAY ONLY BE REPRODUCED IN FULL. PUBLICATION OF EXTRACTS FROM THIS REPORT IS NOT PERMITTED WITHOUT WRITTEN APPROVAL FROM QAI. ANY LIABILITY ATTACHED THERETO IS LIMITED TO THE FEE CHARGED FOR THE INDIVIDUAL PROJECT FILE REFERENCED. THE RESULTS OF THIS REPORT PERTAIN ONLY TO THE SPECIFIC SAMPLE(S) EVALUATED.

PREPARATION: Sufficient sample material was submitted to conform to tunnel test dimensions, 22" wide by 24' feet long. The sample was supported during testing by 2" hexagonal mesh poultry netting running the length of the test chamber and 1/4" round metal rods placed at two foot intervals across the width of the test chamber.

CONDITIONING: The test specimen was conditioned to a constant weight at a temperature of $73.4 \pm 5^\circ \text{F}$ ($23 \pm 2.8^\circ \text{C}$) and a relative humidity of $50 \pm 5\%$.

CEMENT BOARD PLACEMENT: The 1/4" cement boards were placed between the test specimen and the chamber lid

E 84 TEST DATA SHEET:



SAMPLE: Thermaleaf @ Inherently Fire Retardant Foliage

IGNITION: 6 seconds.

FLAME FRONT: 1 foot maximum.

TIME TO MAXIMUM SPREAD: 13 seconds.

TEST DURATION: 10 minutes.

CALCULATION: $9.84 \times 5.15 = 5.06$

SUMMARY: FLAME SPREAD: 5 SMOKE DEVELOPED: 50

SUMMARY OF ASTM E84 RESULTS: Because of the possible variations in reproducibility, the results are adjusted to the nearest figure divisible by 5. Smoke Density values over 200 are rounded to the nearest figure divisible by 50.

In order to obtain the Flame Spread Classification, the above results should be compared to the following table:

<u>NFPA CLASS</u>	<u>IBC CLASS</u>	<u>FLAME SPREAD</u>	<u>SMOKE DEVELOPED</u>
A	A	0 through 25	Less than or equal to 450
B	B	26 through 75	Less than or equal to 450
C	C	76 through 200	Less than or equal to 450

BUILDING CODES CITED:

1. National Fire Protection Association, ANSI/NFPA No. 101, "Life Safety Code".
2. International Building Code, Chapter 8, Interior Finishes, Section 803.

THIS REPORT IS THE CONFIDENTIAL PROPERTY OF THE CLIENT ADDRESSED. THE REPORT MAY ONLY BE REPRODUCED IN FULL. PUBLICATION OF EXTRACTS FROM THIS REPORT IS NOT PERMITTED WITHOUT WRITTEN APPROVAL FROM QAI. ANY LIABILITY ATTACHED THERETO IS LIMITED TO THE FEE CHARGED FOR THE INDIVIDUAL PROJECT FILE REFERENCED. THE RESULTS OF THIS REPORT PERTAIN ONLY TO THE SPECIFIC SAMPLE(S) EVALUATED.



Paid in Full

Artificial Plants Unlimited
 6056 Corte Del Cedro
 Carlsbad, CA, 92011
 Phone: 888-320-0626
 Web: www.artificialplantsunlimited.com

INVOICE

Reference No.: IN1019884
 Date: 04-Oct-2017
 Due Date: 04-Oct-2017
 Customer ID: 1034640

RECEIVED

BILL TO:		SHIP TO:	
26 Pleasant St. Canton NY 04221 UNITED STATES Attn: Israel Nachfolger		Israel Nachfolger 26 Pleasant St. Canton ME 04221 UNITED STATES Attn: Israel Nachfolger	
CUSTOMER REF. NBR	TERMS	WEB ORD NBR	CONTACT
	Prepaid	58978	
SO TYPE	SO NUMBER	SHIPMENT NUMBER	CUSTOMER P.O. NO.
SO-Web	SO1014826	SH019282-10/2/2017	
ITEM	QTY.	UOM	UNIT PRICE
AH-I-REPP4872: Replica Indoor Artificial Living Wall 48in.L x 72in.H	2.00	EA	1,561.85
NOTE: panels should not be exactly similar			3,123.70
Freight ShipVia FREIGHT	0.00		.00
Tracking Numbers: 46325718			411.40

Sales Total: 3,535.10
 Tax Total: 0.00
 Total (USD): 3,535.10
 Amount Due: \$ 0.00

Please review the information contained in this invoice for accuracy. If no discrepancies are communicated within 14 days, payment will be considered complete or payment for the exact amount of this invoice will be expected, governed by established terms.

K712 Fire Drill Documentation

RECEIVED

AUG 15 2024

BY: _____

RECEIVED

AUG 15 2024

36 FIRE DRILL REPORTBuilding: MW LC NF X

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location Family Room N.F. Date and Time 1/23/24 10:00 ^{AM} Shift 1ST

Notification:	Name	Before Drill	After Drill	Signal Received
Central Alarm				
600-000-1119	<u>800-639-4068</u>	<u>9:22</u> am / pm	<u> </u> am / pm	Yes ☐ No ☐
Police	<u>207-743-6554 9554</u>	<u>9:37</u> am / pm	<u> </u> am / pm	Yes ☐ No ☐
Fire	<u>N/A</u>	<u> </u> am / pm	<u> </u> am / pm	Yes ☐ No ☐
911 call by	<u>Kathy Kimball</u>	Alarm reset by	<u>Howard McLean</u>	
Duration of Drill	<u> </u> minutes	Duration of Critique	<u>15</u> minutes	
Drill Conducted by	<u>Jim Cossar</u>	Responsible Party	<u>Ken Huber</u>	
Evacuation time (LC & MW)	<u> </u>	(RCF Requirement is 13 minutes)		

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name L & C fax report (287-9307) Date / Time / Employee name Fire Marshal call (626-3870) Date / Time / Employee name Fire Marshal fax (287-6251) Date / Time / Employee name

Summary of what the staff did in responding to the alarm including employee names.

On this day (1/23/24) Pinnacle Health Rehab exercised A Fire Drill with the scenario being smoke coming from the "Family Room" at the end of the North wing because of an electrical outlet. At 10:00 AM Kathy Kimball announced over the PA, CODE RED. There was some confusion due to a few new employees. Kathy Kimball called 911. After the alarm was silenced by J. Cossar we talked about Race Pass and Safety.

PINNACLE/Fire Drill Report 220413

Jim Cossar
1/23/24

RECEIVED

AUG 15 2024

INSERVICE SIGN IN

BY: _____

Dept: Nursing-North Presenter: Jim CossarDate: 01/23/2024 Time started: 10:00 AM Time ended: 10:35Topic/s (attach handout/agenda/program): Race, Pass, Safety
Bed Entrapment zones

NAME	POSITION	NAME	POSITION
Jim Cossar	Maint. Dir.	Jocelynn Ridley	HK
Kathy Kimball	RN	Georgianne Goodwill	RD
Chris Biron CMA, CRR	FJD	Mary Perry	PTA
Katilyn Campbell	FSC	Cynthia (D) Driscoll	CNA
Naomi Marston	OTR/L	Sharon Mercer	Housekeep
Lindsey Hopkins		Jessie V.	Di S
Wendy Guinard	UH	Marcia Chaisson	MC UC
Lisa Barden	RA	Stephanie Curtis	PSS/CPMA
Chadwick Brown	CPM	Christal Pitts	CPMA
Charles Long	ES	Tina Walsh	UC
John	ES	Phil Vito	Maint
John	ES	Donna McLean	Maint
Melodie Abbott	BOM		
Maria Hutchinson	CNA		
Mary Volkmann	CNA		
Makinay Whitney	CNA		

PINNACLE/Inservice Sign in 160101

PINNACLE/Fire Drill Report 220413

RECEIVED

AUG 15 2024

BY: _____

36

FIRE DRILL REPORT

Building: MW

LC

NF

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location Room 305 Maplewood Date and Time 1/26/24 6:30 AM Shift 3rd

Notification: Name

Central Alarm

603-668-1449

800-639-4068

Police

207-743-9854

Fire

207-597-2404

911 call by

N/ADuration of Drill 20 minutesDrill Conducted by Jim CossarEvacuation time (LC & MW) N/A

Before Drill

After Drill

Signal Received

: am / pm

: am / pm

Yes ☐ No ☒

: am / pm

: am / pm

Yes ☐ No ☒

: am / pm

: am / pm

Yes ☐ No ☒

Alarm reset by

Silent drillDuration of Critique 10 minutesResponsible Party Ken Huhn

(RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____

L & C fax report (287-9307) Date / Time / Employee name _____

Fire Marshal call (626-3870) Date / Time / Employee name _____

Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

The scenario for this drill (which was a silent drill) was smoke coming from an outlet on the wall in room #3082. I met with Jannice, Jendolyn and Tina in the med-room. We discussed the drill. We talked about someone would call 911. The fact that we would be evacuating to the rose garden cafe. We also discussed Pass and Race.

Jim Cossar
1/26/24

BY: _____

Topic/s (attach handout/agenda/program): Race Pass

PRINTED NAME

POSITION

Jimmie Winship

CRM A

Jedalynd Murchison

CBMA

Theresa Delaney

Tina Libb

PS

Jim Cossar

Mount. Div.

PRINTED NAME

POSITION

RECEIVED

AUG 15 2024

36

FIRE DRILL REPORT

BY: Building: MW LC X NF

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location Room 219 Date and Time 8/21/25 1255 Shift 1ST

Notification:	Name	Before Drill	After Drill	Signal Received
Central Alarm	<u>800-639-4068</u>	<u>12:48</u> am / <u>pm</u>	<u>1:30</u> am / <u>pm</u>	Yes ☒ No ☐
Police	<u>202-743-9554</u>	<u>12:50</u> am / <u>pm</u>	<u>1:40</u> am / <u>pm</u>	Yes ☒ No ☐
Fire	<u>N/A</u>	am / pm	am / pm	Yes ☐ No ☐

911 call by Tina Walsh Alarm reset by Jim Cossar

Duration of Drill 30 minutes. Duration of Critique 15 minutes.

Drill Conducted by Jim Cossar Responsible Party Ken Huhn

Evacuation time (LC & MW) 10 min (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification

L & C call (1-800-383-2441)	Date / Time / Employee name
L & C fax report (287-9307)	Date / Time / Employee name
Fire Marshal call (626-3870)	Date / Time / Employee name
Fire Marshal fax (287-6251)	Date / Time / Employee name

Summary of what the staff did in responding to the alarm including employee names.

The Sceneria for this drill was smoke coming from a faulty wall fan. ^{STARR} ~~Hartley~~ saw smoke in room 219 of the LC. And yelled "Code Red"

RECEIVED

IN-SERVICE SIGN-IN SHEET

BY: _____

Presenter: Jim CassarDate: 2/21/2024 Time started: 12:55 Time ended: 1:25Topic/s (attach handout/agenda/program): RACE, PASS, SAFETY

PRINTED NAME	POSITION	PRINTED NAME	POSITION
<u>Jim Cassar</u>	<u>m. Director</u>	<u>Chris Bisson</u>	<u>FSJ</u>
<u>Wendy Guinard</u>	<u>UC</u>	<u>Tanya stickney</u>	<u>ESC</u>
<u>Melodie Abbott</u>	<u>BOM</u>	<u>Katilyn Campbell</u>	<u>FSC</u>
<u>Tina Walsh</u>	<u>UC</u>	<u>Shelly Harlow</u>	<u>UC</u>
<u>Baileigh Rocker</u>	<u>EVS</u>	<u>Carol Mitchell</u>	<u>UC</u>
<u>Jocelyn Ridley</u>	<u>HK</u>	<u>Sarah D y</u>	<u>PSS</u>
<u>Tanya Mitchell</u>	<u>FS Aide</u>	<u>Deborah Dolloff</u>	<u>CRMA</u>
<u>Chris Walsh</u>	<u>FS Aide</u>	<u>BRICE HARTINE</u>	<u>FLOOR</u>
<u>Angeline Reed</u>	<u>CRMA</u>	<u>Charles Song</u>	<u>FLOOR</u>
<u>Breanna Demina</u>	<u>EVS</u>	<u>CRMA</u>	<u>CRMA</u>
<u>Starlee McKenna</u>	<u>CRMA</u>	<u>Beez Knox</u>	<u>ADC</u>
<u>Ken MHN</u>	<u>MLNHA</u>		
<u>Kristen Cate</u>	<u>UC/CRMA</u>		
<u>Chris Smikle Gant</u>	<u>AN</u>		
<u>Maureen</u>	<u>CNA</u>		
<u>Cynthia Mauder</u>	<u>CNA</u>		
<u>Mart</u>	<u>MART</u>		

RECEIVED

AUG 15 2024

36

FIRE DRILL REPORT

BY: _____
Building: MW _____ LC _____ NF X

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location Whirlpool/Bath North Date and Time 2/26/24 8:30 PM Shift 2nd

Notification:	Name	Before Drill	After Drill	Signal Received
Eastern 803-6	<u>N/A</u>	<u>Silent</u>	am / pm	Yes ☐ No ☒
Police	<u>N/A</u>	<u>Silent</u>	am / pm	Yes ☐ No ☒
Fire	<u>N/A</u>	<u>Silent</u>	am / pm	Yes ☐ No ☒
911 call by	<u>N/A</u>	Alarm reset by _____		
Duration of Drill	<u>15</u> minutes.	Duration of Critique <u>15</u> minutes.		
Drill Conducted by	_____	Responsible Party <u>Ken Huhn</u>		
Evacuation time (LC & MW)	<u>N/A</u>	(RCF Requirement is 13 minutes)		

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification

L & C call (1-800-383-2441)	Date / Time / Employee name _____
L & C fax report (287-9307)	Date / Time / Employee name _____
Fire Marshal call (626-3870)	Date / Time / Employee name _____
Fire Marshal fax (287-6251)	Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

The scenario for this drill was smoke coming from the Whirlpool/Bath room from a faulty outlet. We talked about PASS, Race and recent Fire Event. We also talked in detail of the staff and what their duties are in the event of a real fire, such as getting a call into 911 and moving equipment out of the halls, checking rooms for residents and doing a headcount. We talked about Fire Extinguisher and their correct use.

2/26/24

Jim Connor

AUG 15 2021

BY:

WINE COSSAR

2 / 26 / 2024

9:30 PM

Base Pass: Recent

FIRE EVENT

POSITION

Jim Cossar

MAINT DIR.

Stephan Hildings

CNA

Jodie Wright

CHAMBERS

Martha Jordan Downie

CNA

Tonya Morrow

LPN

Märzbr. Fenzl nitz

CNA-M

Elizabeth Curtis

CNA

RECEIVED

AUG 15 2024

36

FIRE DRILL REPORT

Building: MW LC X NF

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location Dining RM. MW

Date and Time 3/15/24

Shift 1

Notification: Central Arm
Name Eastern 603-6

Before Drill After Drill Signal Received
: am / pm : am / pm Yes ☒ No ☐

Police

: am / pm : am / pm Yes ☒ No ☐

Fire

: am / pm : am / pm Yes ☐ No ☒

911 call by JIM COSSAR

Alarm reset by JIM COSSAR

Duration of Drill 25 minutes.

Duration of Critique 15 minutes.

Drill Conducted by Phil Cote

Responsible Party Ken Huhn

Evacuation time (LC & MW) 5 min

(RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification

L & C call (1-800-383-2441)	Date / Time / Employee name
L & C fax report (287-9307)	Date / Time / Employee name
Fire Marshal call (626-3870)	Date / Time / Employee name
Fire Marshal fax (287-6251)	Date / Time / Employee name

Summary of what the staff did in responding to the alarm including employee names.

The Scenerip for this drill WAS smoke coming from
A RECEPTICAL in the dining rm. Joni yelled "CODE-
RED" Jim reset the fire pull. Howard Reset the
FIRE Panel. The Resident EVACUATED to the L.C.
Living Room. Talked About SAFETY FIRE Extinguisher
OPERATION AND PASS. and RACE. All Residents were
Accounted for.

JIM COSSAR

RECEIVED

Presenter:

BY _____

Date:

Time started:

Time ended:

Topic/s (attach handout/agenda/program):

INNACLE In-Service Sign-In Sheet 160101

RECEIVED

AUG 15 2024

BY: _____

36 FIRE DRILL REPORTBuilding: MW _____ LC _____ NF X

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location N.F. STAFF Bathroom Date and Time 3/2/24 4:45 Shift 3rd

Notification: Name Before Drill After Drill Signal Received

Eastern
603-668-1119 N/A _____ am/pm _____ am/pm Yes ☐ No ☒Police N/A _____ am/pm _____ am/pm Yes ☐ No ☒Fire N/A _____ am/pm _____ am/pm Yes ☐ No ☒

911 call by _____

Alarm reset by Silent drillDuration of Drill 15 minutesDuration of Critique 15 minutesDrill Conducted by Jim CossarResponsible Party Ken HuhnEvacuation time (LC & MW) N/A

(RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____

L & C fax report (287-9307) Date / Time / Employee name _____

Fire Marshal call (626-3870) Date / Time / Employee name _____

Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

This was a silent drill, the Scenerio was Smoke coming from a receptical in the staff bathroom in the North, I spoke to all staff on duty in the North one of the staff was at the south nurses station, (Melissa Bean) we talked about Race, Pass and safety (ie) clearing the hallway of all equipment. All 36 residents were accounted for.

Jim Cossar
3/2/24

IN-SERVICE SIGN-IN SHEET

RECEIVED

AUG 15 2024

BY: _____

Presenter:

JIM COSSAR

Date:

3 / 21 / 2024

Time started:

4:45

Time ended: _____

Topic/s (attach handout/agenda/program):

RACE, PASS, SAFETY

PRINTED NAME

POSITION

PRINTED NAME

POSITION

JIM COSSAR

MAINT.

Samantha Greenlaw

CNA

Barbara J. Sinter

LPN

Debra Meade

CNA

Melissa Bean

CNA

RECEIVED

AUG 15 2024

BY: _____

36

FIRE DRILL REPORT

Building: MW _____ LC X NF _____

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location Room # 201Date and Time 4/26/2024: 4:15 Shift 2nd

Notification: Name

Before Drill

After Drill

Signal Received

Central Alarm

603-668-1419

800-639-40684:05 am / pm : am / pm Yes ☒ No ☐

Police

1-202-743-95544:08 am / pm : am / pm Yes ☒ No ☐

Fire

202-592-2404 Chief 357-24044:10 am / pm : am / pm Yes ☒ No ☐

911 call by

JAMES JEFFREYAlarm reset by HOWARD McLAINDuration of Drill 05 minutesDuration of Critique 15 minutesDrill Conducted by JIM COSSARResponsible Party Ken AllenEvacuation time (LC & MW) 5 min

(RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____


L & C fax report (287-9307) Date / Time / Employee name _____

Fire Marshal call (626-3870) Date / Time / Employee name _____

Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

The scenario for this drill was a fire in Room 201 at Living Center, caused by a TV. ~~Plug~~ Ashley Glover shouted "CODE RED". James called 911. Ashley then pulled fire pull. Residents through the ramp door to the garden cafe. All residents were accounted for by a head count. We talk about Run, Pass and Evacuation Procedures.



IN-SERVICE SIGN-IN SHEET

RECEIVED

AUG 15 2024

Presenter:

Jim COSSAR - Phil COTE

BY:

Date:

04/26/2024

Time started:

4:15 PM

Time ended:

Topic/s (attach handout/agenda/program):

RACE, PASS

PRINTED NAME

POSITION

PRINTED NAME

POSITION

Jim COSSAR

D. MAINT.

Phil COTE

MAINT

HOWARD McLEAN

MAINT

Veronica Brown

CPW

Jeff Jacques

CRMA

Brianna Soudy

PSS

Rosa Carson

CRMA

Kalynn Glover

PSS

Shelly Glover

PSS

Carlito Gonzalez

Knit Hayer

RECEIVED

AUG 15 2024

CODE RED DRILL REPORTBuilding: MW X LG NF

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location Room 305 Date and Time 5 29 24 Shift 1ST

Notification: Name Before Drill After Drill Signal Received

CENTRAL AM Fire Protection Eastern am / pm 3:35 am / pm Yes ☒ No ☐Police 911 am / pm 3:35 am / pm Yes ☒ No ☐Fire CANTON am / pm 3:35 am / pm Yes ☒ No ☐911 call by Pam Belanger Alarm reset by HOWARD McLENNDuration of Drill 25 minutes. Duration of Critique 20 minutes.Drill Conducted by HOWARD McLENN Responsible Party KEN HANNAEvacuation time (LC & MW) (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name L & C fax report (287-9307) Date / Time / Employee name Fire Marshal call (626-3870) Date / Time / Employee name Fire Marshal fax (287-6251) Date / Time / Employee name

Summary of what the staff did in responding to the alarm including employee names.

THE SCENARIO FOR THIS DRILL WAS SMOKE IN ROOM BY LIGHT SWITCH
IN MAPLE WOOD RN 305 PAM BELANGER CALL 911 BAYLOR PULLED
FIRE ALARM

IN-SERVICE SIGN-IN SHEET

RECEIVED

AUG 15 2024

Presenter: HOWARD McLEAN

BY: _____

Date: 5 / 29 / 24 Time started: 335 Time ended: _____

Topic/s (attach handout/agenda/program): RACE X PASS

PRINTED NAME

POSITION

PRINTED NAME

POSITION

Summary of what the staff did in responding to the alarm including employee names.

<u>Veronica Brown</u>	<u>Lpn</u>	<u>Chris Walsh</u>	<u>Rich Aidu</u>
<u>Stephanie Curtis</u>	<u>CRMA/PSS</u>	<u>Marcia Chaisson</u>	<u>UC/CRMA</u>
<u>Karilyn Campbell</u>	<u>FSC</u>		
<u>Negan Hines</u>	<u>FSS</u>		
<u>[Signature]</u>	<u>CRMA/PSS</u>		
<u>Donnie E. Smith</u>	<u>CRMA/PSS</u>		
<u>Pamela Bell</u>	<u>CRMA</u>		
<u>Michelle J. Stevens</u>	<u>Laundry</u>		
<u>Ken Hahn</u>	<u>ADMINISTRATIVE</u>		
<u>Harold Dawson</u>	<u>CNA</u>		
<u>Harold McLean</u>	<u>MANIT</u>		

RECEIVED

AUG 15 2024

BY: _____

36

FIRE DRILL REPORT

Building: MW _____ LC _____ NF X

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location 229/18 Date and Time 5/24/24 3:15 Shift 3-11

Notification:	Name	Before Drill	After Drill	Signal Received
Eastern 603-668-1119	<u>FIRE PROTECTION</u>	<u>3:38</u> am / pm	<u>3:38</u> am / pm	Yes ☒ No ☐
Police	<u>911</u>	<u>3:38</u> am / pm	<u>3:38</u> am / pm	Yes ☒ No ☐
Fire	<u>CANTON</u>	<u>3:38</u> am / pm	<u>3:38</u> am / pm	Yes ☒ No ☐
911 call by	<u>CINDY</u>	Alarm reset by <u>A. DAWSON</u>		
Duration of Drill	<u>25</u> minutes	Duration of Critique <u>15</u> minutes		
Drill Conducted by	<u>HOWARD McLENN</u>	Responsible Party _____		
Evacuation time (LC & MW)	_____	(RCF Requirement is 13 minutes)		

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____
 L & C fax report (287-9307) Date / Time / Employee name _____
 Fire Marshal call (626-3870) Date / Time / Employee name _____
 Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

THE SCENARIO FOR THIS DRILL WAS SMOKE FROM
ROOM 118 OF THE NORTH WING CRYSTLE PULLED THE
FIRE ALARM CINDY WAS CALLED 911 AND ARON DAWSON
RESET THE FIRE PANEL

RECEIVED

AUG 15 2024

BY:

Time started: 3 15

Time ended:

RACE & PASS

POSITION

Activities

Activities

RN

Abstraining

C. N. A.

CNA

CL4

CNA

CRAM

CNAM

UC

- Maint

10

20

10

•

PRINTED NAME

POSITION

RECEIVED

AUG 15 2024

36

FIRE DRILL REPORT

Building: MW BY: LC NE X

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location ROOM 119 NORTH wing Date and Time 6/19/2024 Shift 1st

Notification: Name

Before Drill

After Drill

Signal Received

CENTRAL ALARM
Eastern603-668-1119 800 639-4068 1:06 am / pm 1:56 am / pm Yes ☒ No ☐Police 207 7518-9554 1:06 am / pm 1:56 am / pm Yes ☒ No ☐Fire 207 387 0162 1:00 am / pm 1:57 am / pm Yes ☒ No ☐911 call by ~~SYNTHIA BAKER~~ ALISON ADAMS Alarm reset by PHIL STDuration of Drill 25 minutes Duration of Critique 10 minutesDrill Conducted by HOWARD MCLEAN Responsible Party KEN HYUNEvacuation time (LC & MW) NA (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name L & C fax report (287-9307) Date / Time / Employee name Fire Marshal call (626-3870) Date / Time / Employee name Fire Marshal fax (287-6251) Date / Time / Employee name

Summary of what the staff did in responding to the alarm including employee names.

MICHAEL MATCHINS TALK ABOUT IF THERE FIRE AND WHAT
TO DO ALISON ADAMS CALL 911 AND WE TALK ABOUT WHAT
BASIC + PASS WAS AND MAKE SURE THE HALL ARE CLEAR

IN-SERVICE SIGN-IN SHEET

RECEIVED

JUL 15 2024

BY: _____

Presenter: HOWARD McLEAN

Date: 6 / 19 / 24

Time started: 105

Time ended: 125

Topic/s (attach handout/agenda/program): RAGE PASS SAFETY

PRINTED NAME	POSITION
Bonnie Cayer	LPT
TINA McLEAN	LED.
Wendy Guiraud	WF
Katilyn Campbell	FSC
Jane Null	KK
Breanna Domina	EVS
Remi Freeman	EVS
Baileigh Backliff	LED
Lynlah Manning	EVS
Maria Rosa Cruz	RN
Mikinzey Whitley	CNA
Megan Heath	FSS
Tanya Mitchell	FSCook/Lead
Chris Velez	Chic Aida
Melodie Abbott	BOD
Alison Adams	CNA
Harley Bn	CNA

PRINTED NAME	POSITION
Ashley Martel	EVS
Jennifer Adams	CNA
Cynthia Lambert	CNA
Denise Mule-Lian	RN
Rosemary BOD	CNA
Cynthia Brooks	CNA-M
Margay Crane	PTA
Raiden Scanlon	K
Michael Stelchick	CU
Stephanie CA	CNA
Howard McLean	MAINT

CODE RED DRILL REPORT

Building: MW ___ LC X NF ___

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location LIVING CENTER Date and Time 6/20/24 Shift 1ST

Notification:	Name	Before Drill	After Drill	Signal Received
CENTRAL AREA				
Eastern	<u>810 684 4969</u>	___ am / pm	<u>1:30</u> am / pm	Yes ☒ No ☐
Police	<u>207 748 8554</u>	___ am / pm	<u>1:30</u> am / pm	Yes ☒ No ☐
Fire	<u>207 357 0112</u>	___ am / pm	<u>1:30</u> am / pm	Yes ☒ No ☐

RECEIVED

AUG 15 2024

911 call by Marie LeCours Alarm reset by Shelly Harlow

Duration of Drill 15 minutes. Duration of Critique 4 minutes.

Drill Conducted by Howard McLean Responsible Party K-N HYHN

Evacuation time (LC & MW) 5 min (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____

L & C fax report (287-9307) Date / Time / Employee name _____

Fire Marshal call (626-3870) Date / Time / Employee name _____

Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

Smoke coming from Room 210, Staff shut door
yelled code Red and pulled "Pull Station"
Outside Room 208, Staff responded to
Alarm and was directed to assist
Resident away from Room 210 to
the "Meeting Room" Nursing Home
Staff responded to drill, Residents
did not participate in Drill and
Staff was aware they were in their
rooms. All resident were educated
On the routine of a Fire drill and
asked questions.

Mancos
Hare
can

IN-SERVICE SIGN-IN SHEET

RECEIVED
AUG 15 2024

Presenter: HOWARD McLEAN

BY: _____

Date: 6 / 20 / 24

Time started: 130

Time ended: 200

Topic/s (attach handout/agenda/program): _____

PRINTED NAME	POSITION
Bonnie Clev	LPR
Ryan J	ED
Ashley Martel	EVS
Melanie Abbott	BOD
Marie Hutchinson	CNA
Melanie Whitney	CUT
Donna Kite	RW
Jennifer Adams	CNA
Melanie Gonzales	CNA
Anne White	PSS
Kim Polvin	LPN
Cynthia Lambert	CNA
Maria A. Lopez	RW
Wendy Guirard	NE
Leigha Mammey	EVS
Ken Huhn	ADMINISTRATOR
Megan Heath	FSS

PRINTED NAME	POSITION
Katilyn Campbell	FSC
Marcia Chaisson	UC
Starlee McKenna	CRMA
Macda Billings	CMA
Sarah D	PSS
Reggie Mancoske	RW
Shirley	
Groundkeepers	MAINT

RECEIVED

AUG 15 2024

BY: _____

36

FIRE DRILL REPORT

Building: MW ~~SV~~ LC ____ NF ____

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location KITCHEN Date and Time 7/29/24 6:30AM Shift 3RD

Notification:	Name	Before Drill	After Drill	Signal Received
CENTRAL <u>ARM</u>				
603-668-1119	<u>800 439-4068</u>	: am / pm	: am / pm	Yes ☐ No ☒
Police	<u>207-743 9554</u>	: am / pm	: am / pm	Yes ☐ No ☒
Fire	<u>207-597 2404</u>	: am / pm	: am / pm	Yes ☐ No ☒
911 call by	<u>NA</u>	Alarm reset by <u>Silent Drill</u>		

Duration of Drill 20 minutes Duration of Critique 10 minutes

Drill Conducted by HOWARD McLEAN Responsible Party KEN HUNN

Evacuation time (LC & MW) NA (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441)	Date / Time / Employee name	
L & C fax report (287-9307)	Date / Time / Employee name	
Fire Marshal call (626-3870)	Date / Time / Employee name	
Fire Marshal fax (287-6251)	Date / Time / Employee name	

Summary of what the staff did in responding to the alarm including employee names.

THE SCENARIO FOR THIS DRILL WHICH WAS SILENT DRILL
SMOKE coming out OUTLET TALK ABOUT PASS PASS

RECEIVED

AUG 15 2024

BY: _____

SIGN IN SHEET

Presenter: HOWARD McLEAN

Date: 7-129-124

Time started: 630

Time ended: 650

Topic/s (attach handout/agenda/program): RACE, PASS

PRINTED NAME

POSITION

Joni Richard

CRMA

Heather Saunders

CRMA

HOWARD McLEAN

MAINT

PRINTED NAME

POSITION

CODE RED DRILL REPORT

Building: MW ___ LC ___ NF A

Please complete form, attach attendance sign in sheet (or sign on back), and deliver to Administrator for review.

Location Rm 117 Date and Time 7/24/24 Shift 6:30-3

Notification: Name Before Drill After Drill Signal Received **RECEIVED**

Eastern Certified Alarm 1:50- 1:28 am / pm 1:57 am / pm Yes ☐ No ☐ AUG 15 2024

Police 207 743 9554 08 1:30 am / pm ___:___ am / pm Yes ☐ No ☐ BY: ___

Fire ___:___ am / pm ___:___ am / pm Yes ☐ No ☐

911 call by Kathy Clari Alarm reset by Monica McLean

Duration of Drill 5 minutes. Duration of Critique 5 minutes.

Drill Conducted by Monica McLean Responsible Party ___

Evacuation time (LC & MW) ___ (RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name ___

L & C fax report (287-9307) Date / Time / Employee name ___

Fire Marshal call (626-3870) Date / Time / Employee name ___

Fire Marshal fax (287-6251) Date / Time / Employee name ___

Summary of what the staff did in responding to the alarm including employee names.

Code Red Rm 117. C 139 pm. "Smoke" Alarm by CHA who
called out Code Red & pulled alarm across the room
Hall was cleared of residents, wheelchairs, 150 Patient
Carts & medication carts. Review was done at North
Wing with staff to include RACE & PASS.

Review of staff's responsibilities was
reviewed again AS staff are not reporting
to designated areas for Assignment.

RECEIVED

IN-SERVICE SIGN-IN SHEET

AUG 15 2024

BY: _____

Presenter: _____

Date: _____

7/24/24

Time started: _____

138p

Time ended: _____

150p

Topic/s (attach handout/agenda/program): _____

See Report

PRINTED NAME

POSITION

Cindy Bedard

CNA M

Wendy Kennison

CNA M

Breanna Domina

EVS

Wendy Guinan

UM

Dorise Smikle RN

RN

Trista Blais

EVS

Tina McLean

LED

Makinzy Whitney

CNA

Kenny Brubaker

RN

Jennifer Adams

CNA

Ashley Hunter

EVS

Cynthia Lambert

CNA

all Cari Mitchell

UC

all Sfr 7 Jean-Louis

FS

Katilyn Campbell

FSC

Stilio Gonzales

FSC

Chris Warren

Aide

PRINTED NAME

POSITION

Baileigh Backliff

LED

Marny Crane

PTA

Chris Byson CNA, CAPP

FSD

all Kathy Kimbrough

Nursing Sup

Rosemary Bell

CNA

Lisa Borden

RN

Haley B

CNA

Allison Adams

CNA

Christy Emery

LED

Howard McLean

MAINT

RECEIVED

AUG 15 2024

BY: _____

36

FIRE DRILL REPORT

Building: MW

LC ~~_____~~NF ~~_____~~ X

Please complete form, attach attendance sign in sheet (or sign back), and deliver to Administrator for review.

Location

North Nursing Station

Date and Time

4/21/23 2:01

Shift

1ST

Notification:

Name

Before Drill

After Drill

Signal Received

Eastern
603-668-11191-800-839-2066

: am / pm

: am / pm

Yes ☐ No ☐

Police

1-207-743-9554

: am / pm

: am / pm

Yes ☐ No ☐

Fire

N/A

: am / pm

: am / pm

Yes ☐ No ☐

911 call by

CARI and Tina

Alarm reset by

Howard McLean

Duration of Drill

15

minutes

Duration of Critique

2

minutes

Drill Conducted by

Jim Cossar

Responsible Party

Mark Jacobs

Evacuation time (LC & MW)

N/A

(RCF Requirement is 13 minutes)

If a smoke or fire event occurs, a verbal and written report must be made to the Department of Licensing and Certification (L&C) and the State Fire Marshal's office as soon as possible.

L & C call (1-800-383-2441) Date / Time / Employee name _____

L & C fax report (287-9307) Date / Time / Employee name _____

Fire Marshal call (626-3870) Date / Time / Employee name _____

Fire Marshal fax (287-6251) Date / Time / Employee name _____

Summary of what the staff did in responding to the alarm including employee names.

The Scenario for this Drill was smoke in the Bath/Scale room coming from an outlet. The pull station by the Nurses station was activated at the Nurses station in the North. CARI and Tina called 911. Residents were all accounted for and trash can were put outside of the doors. The alarm was Reset by Howard. We also did a Brief Discussion on Safety, Race, and Bias.

Jim Cossar

IN-SERVICE SIGN-IN SHEET

RECEIVED

AUG 15 2024

Presenter:

Jim Cassar

BY:

Date: 04/08/2024

Time started: 2:00 PM

Time ended: 2:35

Topic/s (attach handout/agenda/program):

Fire, Safety, Pass

NAME	POSITION
<u>Jim Cassar</u>	<u>MAINT.</u>
<u>Stacey McNamee</u>	<u>CRMA</u>
<u>Maria A. Loria</u>	<u>R</u>
<u>Wendy Greenab</u>	<u>UH</u>
<u>Denise Smikle</u>	<u>UH</u>
<u>Cari Mitchell</u>	<u>UC</u> ^{Detached}
<u>Maria Hutchinson</u>	<u>CNA-</u>
<u>Tina McLean</u>	<u>LED.</u>
<u>Akua Ofoegwu</u>	<u>CRMA</u>
<u>Terressa Phillips</u>	<u>CNA</u>
<u>JESHA PATRICK</u>	<u>CNA</u>
<u>GEORGE GILE</u>	<u>E.S.L.T.</u>
<u>Autumn Trepavier</u>	<u>ESLT</u>
<u>Marsha Fongemir</u>	<u>CNA-M</u>
<u>R. Freeman</u>	<u>ES</u>
<u>Bailey Boothby</u>	<u>ES</u>

NAME	POSITION
<u>Shelly Harlow</u>	
<u>Gina Moro</u>	<u>FS</u>
<u>Lanette Mitchell</u>	<u>FS</u>
<u>Breanna Domingo</u>	<u>ES</u>
<u>Wasa Turner</u>	<u>CNA</u>
<u>Jenny</u>	<u>CNA-MA</u>
<u>Anthony Burgess</u>	<u>ONG</u>
<u>Nancy Crane</u>	<u>PTA</u>
<u>Hellie Sonnywe</u>	<u>RN</u>
<u>Melodie Abbott</u>	<u>BO</u>
<u>Mark Jacobs</u>	<u>Admin</u>
<u>Kathy Curall</u>	<u>UN.C.</u>
<u>Tim Walsh</u>	<u>UN.C.</u>

K761 Door testing & inspector Certification

RECEIVED

AUG 15 2024

BY: _____



NATIONAL FIRE PROTECTION ASSOCIATION

RECEIVED

AUG 15 2024

CERTIFICATE OF COMPLETION

2016 NFPA 80: Inspection, Testing, and Maintenance
of Swinging Fire Door Assemblies Online Training

JAMES COSSAR

Completion Date: January 28, 2024
CEUs: .1 or 1 hour




President, National Fire Protection Association

IT'S A BIG WORLD. LET'S PROTECT IT TOGETHER.

Fire/Smoke Door Inspection

Facility:

Date: 3/15/21

Tester Name:

Door Type: ☒ Fire ☐ Smoke

Rating: 3hr

Location: Kitchen

Door # 9.

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

AUG 15 2024

BY: _____

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Date: 3/14/24

Tester Name:

Door Type: ☐ Fire ☐ Smoke Rating:

Location:

Kitchen door Door #10

BY: _____

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Doors and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other:	Hinges ☒ Correct ☒ Securely installed ☒ Other: Flush Bolts ☒ Correct ☒ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

Date: 3/14/23

Door Type: ☐ Fire ☐ Smoke Rating: 3 hr.

BY: _____

Location: L.C. entrance to hallway Door #11

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
---	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

BY: _____

Date: 3/13/24 Door Type: ☒ Fire ☐ Smoke Rating: 1 hr

Location: L.C. Shelly's Office Door 12

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Doors and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

BY: _____

Facility: _____ Tester Name: _____
 Date: 3/12/24 Door Type: ☐ Fire ☒ Smoke Rating: _____

Location: L.C. hallway dbi doors Door # 13

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Doors and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: _____ Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: _____ Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☐ No visible signs of damage ☐ Other: _____ Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other: _____	Hinges ☒ Correct ☒ Securely Installed ☐ Other: _____ Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: _____ Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other _____ Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other _____
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

BY: _____

Facility:

Tester Name:

Date: 2/15/24 Door Type: ☒ Fire ☐ Smoke Rating: 90 min
Location: maplewood entrance Door #17

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for Items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☐ Any signage is properly affixed ☐ Other
--	---

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

BY: _____

Facility:

Tester Name:

Date:

2/15/24

Door Type:

☐ Fire☒ Smoke

Rating:

Location:

maple wood steps door front

Door #18

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	---

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

Date:

2/13/24

Door Type:

☐ Fire☒ Smoke

Rating:

Location:

maplewood back side door Door #19

BY: _____

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☐ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

BY: _____

Date: 2/13/24 Door Type: ☒ Fire ☒ Smoke Rating:

Location: maple wood stairway off Dining Room Door #20

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.1/19.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Doors and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

Date: 2/13/24

Door Type: ☐ Fire ☒ Smoke Rating:

Location: maplewood Pantry way

Door #21

BY: _____

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

BY: _____

Facility:

Tester Name:

Date: 8/17/24 Door Type: ☐ Fire ☒ Smoke Rating:Location: Garden Cafe double doors #8

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
---	--

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

BY: _____

Facility:

Tester Name:

Date: 2/9/24

Door Type: ☐ Fire ☒ Smoke Rating:

Location: RIS care 2nd Double doors - North #3

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☒ Gaskets intact ☐ Other: Door ☐ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☐ Any signage is properly affixed ☐ Other
--	---

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

RECEIVED

AUG 15 2024

Fire/Smoke Door Inspection

Facility:

Tester Name:

Date: 2/8/24 Door Type: ☐ Fire ☒ Smoke Rating:

Location: res. care double doors headed north #4

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Doors and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

It is recommended that a facility identify all doors to be inspected on a drawing/layout of the facility to track inspections.

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct Clearance ☒ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely Installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely Installed ☐ Other: Lockset/Hardware ☒ All hardware Installed ☒ Strike in good shape ☒ Securely Installed ☐ Other Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other
--	---

Comments/Corrections:

Tester Signature:

Use one for each door inspected. Maintain record for 3 years.

Revised 011717

9

X

Fire/Smoke Door Inspection – Pinnacle Health & Rehab

Location: ☐ NF S. Hall ☐ NF N. Hall ☒ LD ☐ Linen ☐ LC Hall

Date: 2/8/24

Door Type: ☒ Fire ☐ Smoke Rating: 1 1/2

AB #5

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

AUG 15 2024

BY:

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct clearance ☐ No open holes/breaks ☒ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☐ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely installed ☐ Other: Flush Bolts ☐ Correct ☐ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other: Other ☒ No items that interfere installed ☒ No non-compliant field modification ☐ Door has appropriate signage ☐ Any signage is properly affixed ☐ Other:
---	--

Comments/Corrections: MISSING 3 SCREWS IN HINGES

Tester Name Printed/Signature: _____

Fire/Smoke Door Inspection – Pinnacle Health & Rehab

Location: ☐ NF S. Hall ☐ NF N. Hall ☐ LD ☐ Linen ☐ LC Hall

Soiled utility #1

Date: 2/8/2024 Door Type: ☒ Fire ☐ Smoke Rating:

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passage ways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

AUG 15 2024

BY:

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☒ Is secure ☒ No open holes/breaks ☐ Frame not rusted through wood ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct clearance ☒ No open holes/breaks ☐ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☐ Door not rusted-through wood ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☐ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other: Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other:
---	---

Comments/Corrections:

Tester Name Printed/Signature:

Jim Corcoran

Fire/Smoke Door Inspection – Pinnacle Health & Rehab

Location: ☐ NF S. Hall ☐ NF N. Hall ☐ LD ☐ Linen ☐ LC Hall

Date: 3/15/24

Door Type: ☒ Fire ☐ Smoke Rating: 1 Hour

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

AUG 15 2024

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact N/A ☐ Other: Door ☒ Label present and legible ☒ Correct clearance ☒ No open holes/breaks ☐ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☐ Door not rusted-through wooden ☐ No non-compliant field modification ☐ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☐ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☐ Correct BY: _____ ☐ Securely installed ☐ Other: Flush Bolts ☐ Correct ☐ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other Other ☐ No items that interfere installed ☐ No non-compliant field modification ☐ Door has appropriate signage ☐ Any signage is properly affixed ☐ Other:
--	--

Comments/Corrections:

Tester Name Printed/Signature:

JIM COSSAR

Jim Cossar

Fire/Smoke Door Inspection – Pinnacle Health & Rehab

#7

Location: ☐ NF S. Hall ☐ NF N. Hall ☐ LD ☐ Linen ☐ LC Hall *Break room by Time clock*
 Date: *3/12/24* Door Type: ☒ Fire ☐ Smoke Rating: *20 min*

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section, 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☐ Label present and legible ☐ Is secure ☐ No open holes/breaks ☐ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☐ Label present and legible ☐ Correct clearance ☐ No open holes/breaks ☐ Glazing/Vision light frames intact ☐ Not damaged/delaminated door ☐ Door not rusted-through ☐ No non-compliant field modification ☐ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☐ Other: Other ☒ No items that interfere installed ☒ No non-compliant field modification ☒ Door has appropriate signage ☒ Any signage is properly affixed ☐ Other:
---	--

AUG 15 2024

BY: _____

Comments/Corrections:

Tester Name Printed/Signature:

JIM COSSAR / Jim Cossar

Fire/Smoke Door Inspection – Pinnacle Health & Rehab #15

Location: ☒ NF S. Hall ☐ NF N. Hall ☐ LD ☐ Linen ☐ LC Hall

Date: 2/12/24

Door Type: ☒ Fire ☐ Smoke

Rating: LC

TOP OF STAIRS OFFICE
1 hr. Rating

The 2012 edition of the Life Safety Code (NFPA 101) requires facilities to complete an annual fire and smoke door inspection. Section 18.2.2.2.1/19.2.2.2.1 requires compliance with section 7.2.1 and Section 7.2.15.2 requires compliance with NFPA 80 Standard for Fire Door's and Other Opening Protectives (2010 edition, Section 5.2.1) and NFPA 105 Standard for Smoke Door Assemblies and Other Opening Protectives (2010 edition, section 5.2). Below please evaluate all required doors for items listed below and identify issues. All issues should be corrected immediately. Life Safety Code section 7.2.1.15.2 requires all fire and smoke doors to be inspected and tested annually including doors such as:

- Doors with fire protection rating labels
- Door assemblies in exit enclosures-typically stairwells and exit passageways
- Door assemblies in smoke compartment walls
- Hazardous rooms with rated doors

RECEIVED

AUG 15 2024

Operation ☒ Swings Freely ☒ Closes Properly ☒ Latches Properly ☐ Other: Frame ☒ Label present and legible ☒ Is secure ☒ No open holes/breaks ☒ Frame not rusted through ☐ Gaskets intact ☐ Other: Door ☒ Label present and legible ☒ Correct clearance ☒ No open holes/breaks ☐ Glazing/Vision light frames intact ☒ Not damaged/delaminated door ☒ Door not rusted-through ☒ No non-compliant field modification ☒ No visible signs of damage ☐ Other: Door Closer ☒ All hardware installed ☒ Strike in good shape ☒ Securely Installed ☐ Other:	Hinges ☒ Correct ☒ Securely installed ☐ Other: Flush Bolts ☒ Correct ☒ Securely installed ☐ Other: Lockset/Hardware ☒ All hardware installed ☒ Strike in good shape ☒ Securely installed ☒ Other: missing screws Other ☒ No items that interfere installed ☒ No non-compliant field modification ☐ Door has appropriate signage ☐ Any signage is properly affixed ☐ Other:
--	---

Comments/Corrections:

Tester Name Printed/Signature:

Jim COSSAR JIM COSSAR