

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 255315		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/22/2025	
NAME OF PROVIDER OR SUPPLIER POPLAR SPRINGS NURSING CTR, LLC				STREET ADDRESS, CITY, STATE, ZIP CODE 6615 POPLAR SPRINGS DR , MERIDIAN, Mississippi, 39305			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
E0000	Initial Comments		E0000				
	EMERGENCY PREPAREDNESS Survey conducted on 7/22/25 reveals the above facility meets all applicable Federal, State and local emergency preparedness requirements. No deficiencies were cited.						
K0000	INITIAL COMMENTS		K0000				
	42 CFR 483.70(b)						
	The facility must meet the applicable provisions of the 2012 (existing) Edition of the Life Safety Code (LSC) of the National Fire Protection Association (NFPA).						
K0372	Subdivision of Building Spaces - Smoke Barrie		K0372				
SS = D	CFR(s): NFPA 101						
	Subdivision of Building Spaces - Smoke Barrier Construction						
	2012 EXISTING						
	Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier.						
	19.3.7.3, 8.6.7.1(1)						
	Describe any mechanical smoke control system in REMARKS.						
	This STANDARD is NOT MET as evidenced by:						
	Based on the observation, the facility failed to provide half hour rating in the smoke barrier wall in accordance with NFPA 101 sections 19.3.7.3 and 8.5.6.2. This standard deficiency affected two (2) of six (6) smoke compartments in the facility on the day of Survey. Findings Include: On 7/22/25 at 11:45 AM, observation revealed unsealed holes around data cables						

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 255315		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/22/2025	
NAME OF PROVIDER OR SUPPLIER POPLAR SPRINGS NURSING CTR, LLC				STREET ADDRESS, CITY, STATE, ZIP CODE 6615 POPLAR SPRINGS DR , MERIDIAN, Mississippi, 39305			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0372 SS = D	Continued from page 1 and electrical piping at C Hall smoke barrier wall near A/B Nurses Station of the facility. This smoke barrier wall was incapable of resisting the passage of smoke throughout the facility. The finding was acknowledged by the Administrator and Maintenance Supervisor verified this observation during the exit interview on 7/22/25. s/s=D		K0372				