

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments This report is of a Biennial Construction Survey done by Bob Getchell on March 19, 2015. Records indicates this facility was first licensed or submitted on 09/22/1999 as a HA. The facility is currently licensed for 30 Beds. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 and the applicable portions of the 1996 Rules for the Licensing of Adult Care Homes, and, the 1999 revision of the North Carolina State Building Code(s), Institutional Occupancy. Deficiencies were noted which will require a new plan of correction.	C 000		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, egress from all areas was not maintained in a safe manner by having a delayed egress door that would not unlock in the direction of egress. This would effect all residents by not allowing free egress in an emergency. Findings on 03/19/2015:	C 189		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1 a. The delayed Egress door at D201 Mechanical Room did not release upon alarm. The Delayed Egress locking system at this door was also equipped with a key operated emergency release switch located within 3 feet of the door. The facility implemented a Plan of Protection to inservice all staff of the situation and ensure that staff have the key to the emergency release switch. 2. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components. This would effect all residents by not containing smoke and fire in the room or smoke compartment of origin. Findings on 03/19/2015: There are unprotected penetrations in the walls and ceilings in the following locations: a) sprinkler pipe penetration above ceiling at entrance to D208 Mechanical Room, b) The kitchen mop room walls and ceilings have pipe penetrations that have been sealed with an unrated orange foam product. c. There is an unprotected pipe penetration in the Laundry wall at the sink. These unprotected openings are not in conformance with the requirement to use a through penetration fire stop system that has been tested in accordance with ASTM E-814. 3. Based on observation, the building plumbing equipment was not maintained in a safe manner by not maintaining the clearance of a discharge	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 pipe from the top of the drain. This would effect all residents by potentially contaminating the ice. Findings on 03/19/2015: The drain line on the ice machine is inserted into the drain. Provide a 2" air gap between the discharge pipe and the surface of the drain. 4. Based on observation, the building exit signage was not maintained in a safe manner. This would effect all residents by not keeping the exits visible in an emergency. Findings on 03/19/2015: Exit sign at Dining Room exit door is not illuminated. 5. Based on observation, the building electrical system was not maintained in a safe manner by allowing residents to use expansion blocks in the outlets. This would effect all residents by potentially overloading electrical circuits in the bedrooms. Findings on 03/19/2015: Outlet expansion devices were observed in Room D109. 6. Based on observation, the facility was not maintained in a safe manner by having doors that did not close completely in order to contain smoke and fire. This could affect all residents and staff by not containing smoke and fire in the fire compartment or room of origin. Findings on 03/19/2015: The following doors have issues: a) Dining Room door from corridor has hold open device however closer has been removed so door	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3 won't close when released. b) The coordinated doors from the corridor to the Country Kitchen are wedged open and must be adjusted so they will close and latch when released in an emergency. 7. Based on observation, the building was not maintained in a safe manner because toilets are coming loose from the floor. This would effect all residents using the toilets by exposing them to leaks from a broken wax seal. Findings on 03/19/2015: There are toilets coming loose from the floor in the following locations: a) Room D109 bathroom, b) Room D104 bathroom. 8. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components. This would effect all residents by not containing smoke and fire in the room or smoke compartment of origin. Findings on 03/19/2015: a. The 1-hour fire resistance rated ceiling above the tile in the kitchen has been penetrated by a flexible HVAC duct and multiple flexible conduit. b. The 1-hour fire resistance rated walls above the tile in the corridor outside the Laundry have been penetrated by a flexible HVAC duct. c. The 1-hour fire resistance rated walls in D205 Mechanical Room have been penetrated by a flexible HVAC duct.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 9. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components in the attic. This would effect all residents by not containing smoke and fire in the room or smoke compartment of origin. Findings on 03/19/2015: a. The 1-hour fire resistance rated smoke wall near D117 has unprotected penetrations by wire and conduit b. The 1-hour fire resistance rated smoke wall near D201 Mechanical has unprotected penetrations by wire and conduit	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building exhaust ventilation was not maintained in accordance with	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/19/2015
NAME OF PROVIDER OR SUPPLIER CROASDAILE VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 2600 CROASDAILE FARM PARKWAY DURHAM, NC 27705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 5 this Rule. Findings on 03/19/2015: The exhaust fan in the Kitchen Mop Room is not working.	C 199		