

Mar 24 2015 02:41pm

P002/009

PRINTED: 03/12/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023045	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 02/19/2015
NAME OF PROVIDER OR SUPPLIER CLEVELAND HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 950 HARDIN DRIVE SHELBY, NC 28150			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 000	Initial Comments This report is of a Biennial Construction Survey done by Bob Getchell and Dennis Harrell on February 19, 2015. This Facility was first licensed or submitted for licensure as a Home for the Aged on or about May 10, 1991 for Seventy-Two (72) Beds. Therefore the facility is required to meet the 1991 and the applicable portions of the 2005 Rules for the Licensing of Adult Care Homes of Seven or More Beds, and, the 1991 North Carolina State Building Code, Section 409.1 Group I- Unrestrained Occupancy. Deficiencies were noted which will require a new plan of correction.	C 000			
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation, 701 Barbour Drive, Raleigh, North Carolina, 27603 at no cost;	C 101			

CONSTRUCTION SECTION
MAR 25 2015
RECEIVED

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Executive Director

3/25/2015

STATE FORM

X2G921

If continuation sheet 1 of 8

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023045	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 02/19/2015
NAME OF PROVIDER OR SUPPLIER CLEVELAND HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 950 HARDIN DRIVE SHELBY, NC 28150		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 This Rule is not met as evidenced by: 1. Based on observation, the building fire sprinkler equipment was not maintained in a safe manner. This would effect all residents by not replacing damaged fire protection equipment immediately. Findings on 2-19-15: a. Room 33 has a hole in the ceiling where a sprinkler head has been removed b. Room 17 has a hole in the ceiling where a sprinkler head has been removed. c. The most recent sprinkler report indicates the following: i. The Backflow Preventer at the street could not be tested by the sprinkler company. ii. Sprinkler company recommended replacing flex hose with pipe on air compressor, get enough spare heads, and get rebuild kits to rebuild 2 valves. Provide service invoice indicating this work is completed.	C 101	Sprinkler head replaced. Sprinkler head replaced. We have contracted Hoyle Plumbing Co. to repair Back flow Preventer. Estimated completion date: 4/24/2015 We have contracted Century Fire Protection to replace flex hose and do repair work. Estimated completion date: 4/24/2015	03-12-2015 03-12-2015
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023046	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 02/19/2015
NAME OF PROVIDER OR SUPPLIER CLEVELAND HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 950 HARDIN DRIVE SHELBY, NC 28150		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 This Rule is not met as evidenced by: 1. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components. This would effect all residents by not containing smoke and fire in the room or smoke compartment of origin. Findings on 2-19-15: a. The attic smoke barrier wall over the cross corridor doors at Hickory Court has unprotected openings cut for cable and pipe. b. The attic smoke barrier wall over the cross corridor doors at Maple Court has unprotected penetrations by cable and pipe, and a 4" vent pipe in the wall is disconnected. c. The attic smoke barrier wall over the cross corridor doors at Sycamore Court has unprotected penetrations by cable and pipe. d. There are no radiation dampers in the high/low make up air for each of the following ducts: i. 1-hour fire resistance rated Attic HVAC Mechanical Rooms, ii. Central Hot Water Heater Room iii. Tankless Hot Water Heater Room iii. Laundry. Each high/low duct connects to plastic flexible duct once it enters the attic and must be protected. e. The attic access door in the smoke barrier wall above room 10 is damaged. f. There is an opening in the closet ceiling in room 15 where a sprinkler head has dropped	C 189	Smoke barrier wall will be repaired estimated completion date 04-24-2015. Smoke barrier wall will be repaired estimated completion date 04-24-2015. Smoke barrier wall will be repaired estimated completion date 04-24-2015. Radiation dampers will be installed estimated completion date 04-24-2015. Attic access door will be repaired estimated completion date 04-24-2015. Sprinkler head will be repaired estimated completion 04-24-2015.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023045	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 02/19/2015
NAME OF PROVIDER OR SUPPLIER CLEVELAND HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 950 HARDIN DRIVE SHELBY, NC 28150		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 The door to the Activity Room Storage has two holes by the door handle. 9. Based on observation, the building plumbing equipment was not maintained in a safe manner by allowing cross connects. This would effect all residents by potentially siphoning waste water into the potable water system. Findings on 2-19-15: The spray hose on the tub in room 12 bathroom has no vacuum breaker.	C 189	Holes have been repaired in door. Vacuum break has been placed on spray hose.	03-20-2015 03-20-2015
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Based on observation, the building exhaust ventilation was not maintained in accordance with this Rule.	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023045	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 02/19/2015
NAME OF PROVIDER OR SUPPLIER CLEVELAND HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 950 HARDIN DRIVE SHELBY, NC 28150			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 199	Continued From page 7 Findings on 2-19-15: The following exhaust fan issues were noted: a. The Exhaust is not moving any air in room 6, b. The Exhaust is not moving any air in room 25, c. The Exhaust is not moving any air in room 27, d. The Exhaust is not moving any air in the Beauty Shop, e. The Kitchen Mop Closet has no exhaust fan,	C 199	Room 6 exhaust fan will be repaired estimated completion date 04-24-2015. Room 25 exhaust fan will be repaired estimated completion date 04-24-2015. Room 27 exhaust fan will be repaired estimated completion date 04-24-2015. Beauty shop exhaust fan will be repaired, estimated completion date 04-24-2015. Exhaust fan will be installed in kitchen mop closet estimated completion date 04-24-2015.		