

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:	(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801		
(X4) ID PREFIX TAG C 000	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG C 000	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
	Initial Comments Report by Suzanna Fay DHSR Construction Section conducted a Biennial Survey on June 4, 2015 from 1:33 PM to 3:04 PM at the above referenced facility. DHSR records indicate the home was first licensed on June 22, 1991 as a Family Care Home for six ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency.) Based on this information we are requiring the home to maintain compliance with the following: the 1991 Family Care Homes Minimum Standards and Regulations, applicable portions of the 2005 Rules 10A NCAC 13G for Family Care Homes and the 1991 North Carolina State Building Code - Section 513.1, Exception 1 - Residential Care Facilities. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows: Note: DHSR database records the Initial licensure date as June 22, 1991. An initial date of February 26, 1982 was also recorded under previous surveys and affirmed per interview with the prior Owner. There were changes in the licensure rules between 1982 and 1991 that would have a significant impact on the requirements for the facility. If available, provide documentation of when the facility was first licensed or the facility may be required to be brought up to the 1991 licensure rules.		CONSTRUCTION SECTION JUL 06 2015 RECEIVED	
C 117	Have Current San. And Fire Safety Approvals SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION	C 117		
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE <i>Brenda Boyd, Administrator</i>		TITLE <i>Brenda Boyd, Administrator</i>		
DATE FORM 7/1/15		GEF421 continuation sheet 1 of 9		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:	(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 117	Continued From page 1 (n) The home shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on interview with Staff, the facility does not have the annual Fire and Sanitation Inspections available. Provide copies of the Fire and Sanitation Inspections for the last two years to verify compliance. Copies of these records are to be maintained at the facility at all times.	C 117	Sanitation and Fire Inspections will be made 8-23-15 in facility and a copy will be fax to DHSR	
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. Observations revealed that the fire extinguishers were last serviced in April of 2014 and are past due for annual service. Have the fire extinguishers inspected and serviced by a qualified person. Provide receipts or copies of the tags for verification of the correction. 2. Observations revealed that the towel bars in the half bath were broken on the walls behind the toilet and across from the toilet. Have a qualified person repair the broken towel bars. Provide documentation of the repairs.	C 174	Fire extinguishers will be serviced by qualified person and receipts and tags will be fax to DHSR Qualified person will re-mount towel bars on wall receipt and repairs will be sent to DHSR 8-23-15	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:	(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801		
(X4) ID PREFIX TAG C 174	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG C 174	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
	Continued From page 2			
	3. Observations revealed the the exhaust fan in the half bath had an accumulation of dust that could prevent the fan from exhausting properly. Clean the exhaust fan and provide photo verification of the correction.		The fan will be Clean and photo Copy sent to DHRS	8-23-15
	4. Observations revealed that the wall behind the sink in the half bath was damaged and the wall behind the door in Bedroom #3 had been removed. Interview with Staff revealed that they were in the process of installing an electric water cooler. Provide documentation of the repairs to both the bathroom and bedroom walls when the work is complete.		After water Cooler is installed the wall will be repaired and a photo Copy sent to DHRS	8-23-15
	5. Observations revealed that call bells were located in each of the Resident bedrooms. The only bell that sounded when pressed was the left side call in Bedroom #2. Only one call bell was located in Bedroom #3. Have a qualified technician repair or replace the call system. All calls should be within reach of the Residents' beds. Provide documentation of the repairs.		All Six Call bells will be repaired by qualified Technician and documentation sent to DHRS.	8-23-15
	6. Observations revealed a large hole in the closet of Bedroom #4. The hole was adjacent to the attic access panel. Interview with Staff revealed that the hole had been cut by a prior vendor and had not been patched. Have a qualified person repair the hole or repair the opening and provide an access panel in the new opening as the existing hatch is very small and may be difficult to access the attic.		Access panel to Attic will be repaired and access hatch will replace hole in closet	8-23-15
	7. Observations revealed that the paint had bubbled and was beginning to peel away in the upper corner of the hallway outside of Bedroom #2. Have a qualified person repair the damaged wall finish. Provide documentation of the repairs.		Damaged bubbled paint will be repaired and copies sent to DHRS	8-23-15

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:		(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 174	Continued From page 3 8. Observations revealed the kitchen cabinets to be in poor condition. The cabinets were missing handles in front of the sink and the trim along the backsplash over the sink was loose and broken in places. A section of the countertop had been cut away to allow for the oven door to open. The cut was poorly done and has left rough, unsightly edges. One of the drawers to the right of the stove is broken and hanging. The handle on that drawer is also broken. The finish on the cabinets has worn through in several places. Have a qualified technician repair or replace the kitchen cabinets. Provide documentation of the repairs. 9. Observations revealed that the vinyl floor under the kitchen cabinets has come loose from the quarter trim and is curling and bunching along the front of the counters. Have a qualified person repair the flooring in the kitchen. Provide documentation of the repairs. 10. Observations revealed that the floor in front of the shower is soft and giving underfoot. Have a qualified technician identify the cause of the damage and make all necessary repairs to correct the problem. Provide documentation of the repairs. 11. Observations revealed that the vinyl floor between the sink and the shower in the bathroom is no longer adhering to the substrate and has curled inward. Have a qualified person repair or replace the floor. Provide documentation of the repairs. 12. Observations revealed that the tile in the shower was broken around the drain. There were wide sections of grout and there were gaps where the tile had either broken or did not fit properly that were filled in with grout. A black, moldlike	C 174	Kitchen cabinets and all missing handle repaired and Countertop will be repaired by a qualified technician Vinyl floor under Kitchen Cabinets will be repaired and photos sent to DHRS A qualified Technician will repair floor in front of shower to correct the problem and photos sent to DHRS Vinyl floor between the Sink and Shower in bathroom will be repaired by qualified Technician and photos sent to DHRS	8-23-15 8-23-15 8-23-15	

Division of Health Service Regulation
STATE FORM

0010

GEF421

If continuation sheet 4 of 8

STATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

FCL033009

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: 01

B. WING:

(X3) DATE SURVEY
COMPLETED

06/04/2015

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

MY GUARDIAN ANGEL FAMILY CARE HOME

514 COKEY ROAD
ROCKY MOUNT, NC 27801(X4) ID
PREFIX
TAGSUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)ID
PREFIX
TAGPROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)(X5)
COMPLETE
DATE

C 174

Continued From page 4

C 174

substance was observed in the corners of the shower. Have a qualified person replace the damaged tile and properly grout the shower. Clean to remove the black substance. Provide documentation of the repairs.

13. Observations revealed that the entrance to the full bath is off of an enclosed porch. The entry poses a tripping hazard as the porch slopes away from elevation of the bathroom floor. Have a qualified technician repair the floor so the fire entry to the bathroom has a smooth and safe transition. Provide documentation of the repairs.

14. Observations revealed a section of the vinyl siding had popped loose to the left of the front door. Have a qualified person repair the siding. Provide documentation of the repairs.

15. Observations revealed that the handrail at the front ramp was loose. Have a qualified person secure the rail. Provide documentation of the repairs.

16. Observations revealed that a section of the corner trim at the right front corner of the facility had been cut leaving a hole in the trim and the substrate exposed. Have a qualified person replace the damaged trim. Provide documentation of the repairs.

17. Observations revealed that there was not an exhaust cap for the exterior dryer vent. Have a qualified person install a dryer cap. Provide documentation of the repairs.

18. Observations revealed that the crawl space vent adjacent to the dryer opening had been covered with a sheet of insulation. The insulation board is broken and deteriorating. Remove the

Damage tile will be repaired by qualified technician and photo and documentation sent to DHSC 8-23-15

The entrance to full bath will be repaired by qualified technician and documentation will be sent to DHSC

Vinyl siding loose on the top front door will be repaired by qualified person and copies sent to DHSC 8-23-15

Hole at corner trim at right front corner will be repaired and photo copy sent to DHSC 8-23-15

Exhaust Cap will be replaced for the exterior dryer vent. Copy sent photo to DHSC 8-23-15

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

FCL033009

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: 01

B. WING

(X3) DATE SURVEY
COMPLETED

06/04/2015

NAME OF PROVIDER OR SUPPLIER

MY GUARDIAN ANGEL FAMILY CARE HOME

STREET ADDRESS, CITY, STATE, ZIP CODE

514 COKEY ROAD
ROCKY MOUNT, NC 27801

(X4) ID
PREFIX
TAG

SUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID
PREFIX
TAG

PROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)

(X5)
COMPLETE
DATE

C 174

Continued From page 5

Insulation board. Provide verification of the
repairs.

C 174

Insulation board will be
removed and a photo (copy)
sent to DHSR

C 125

Bathroom-for Each Five

C 125

8/23/15

IV. The Building

C. Physical Environment (10 NCAC 42C .2201)

5. Bathroom (10 NCAC 42C .2206)

a. Facilities licensed as of April 1, 1984 must
have one full bathroom for each five or fewer
persons including live-in staff and family.

b. If there is a question whether a home
licensed before April 1, 1984 has a sufficient
number of bathrooms, the Division of Facility
Services is responsible for determining the size
and number of bathrooms required based on the
number of persons living in the home.

This Rule is not met as evidenced by:

1. Observations revealed that the facility has one
full bath and one half bath for six Residents.

As there is a discrepancy in the dates of
licensure, we are allowing the bathroom count to
remain per the current configuration. The 1984
allowance for existing facilities to increase their
capacity to up to Six (6) residents recognized the
fact that not all existing facilities had the
bathroom facilities to meet the requirements of
one bathroom per five residents as defined in the
1984 Licensure Rules. The discretion for
determining the number and size of bathrooms
for the number of residents living in the home
was delegated to the Division of Health Service
Regulation (formerly DFS). At this time DHSR
recognizes that the full bath and the half bath
have been sufficient to meet the needs of the
residents. DHSR reserves the right to revisit this
issue, in the event that a complaint should arise

Thank you.

Division of Health Service Regulation
DATE FORM

GEF421

If continuation sheet 6 of 9

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

FCL033009

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: 01

B. WING:

(X3) DATE SURVEY
COMPLETED

06/04/2015

NAME OF PROVIDER OR SUPPLIER

MY GUARDIAN ANGEL FAMILY CARE HOME

STREET ADDRESS, CITY, STATE, ZIP CODE

514 COKEY ROAD
ROCKY MOUNT, NC 27801

(X4) ID
PREFIX
TAG

SUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID
PREFIX
TAG

PROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)

(X5)
COMPLETE
DATE

C 125 Continued From page 6
due to the limited bath features, to seek remedy.

C 125

C 143 Outside Exits-Locks Single Hand Motion

C 143

IV. The Building
C. Physical Environment (10 NCAC 42C .2201)
8. Outside Entrances/Exits (10 NCAC 42C
.2209)
d. All exit doors locks must be easily operable,
by a single hand motion, from the inside at all
times without keys. (This limits each door to one
locking device which meets the criteria set forth in
this standard.)

This Rule is not met as evidenced by:

1. Observations revealed that the door hardware
at the back exit was not single action. Have a
qualified person replace the door hardware with
single action hardware. Provide documentation
of the repairs.

C 149 Outside Premises-Maintained Safe

C 149

IV. The Building
C. Physical Environment (10 NCAC 42C .2201)
11. Outside Premises (10 NCAC 42C .2215)
a. The outside grounds must be maintained in a
clean and safe condition, in accordance with the
rules governing the sanitation of residential care
facilities of the North Carolina Department of
Environment, Health and Natural Resources;
Division of Environmental Health Services.

*A Single Action Hardware
will be replaced by
back door by a qualified
person. Copy with photo
will be sent to DHSRC*

R-2015

Division of Health Service Regulation
STATE FORM

GEF421

If continuation sheet 7 of 9

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:		(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801			
(X4) IO PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 149	Continued From page 7 This Rule is not met as evidenced by: 1. Observations revealed a large pile of trash, chairs, boards and other items piled up along the fence in the back yard. Several large bags of aluminum cans were stacked up in the back corner of the yard. Remove all trash and broken furniture to maintain a clean and safe environment. Provide photo verification of the correction. 2. Observations revealed that the fence surrounding the back yard was falling apart. The fence was leaning and several of the bracing boards had rotted. Have a qualified person remove or replace the fence. Provide documentation of the repairs.	C 149	<i>All trash piles will be removed and broken fence. I will send a photo copy will be sent to DHSS</i> <i>The facility administrator is asking more time to replace this costly fence which may cost \$200.00 to replace. And taking fence down now will compromise the facility privacy and security of grounds. Asking that more time be granted up to six months to get financing for fence.</i>	8/23/15	
C 155	Building Service Equipment-Hot Water IV. The Building D. Building Service Equipment (10 NCAC 42C .2214) 4. The hot water tank must be of such size to provide an adequate supply of hot water to the kitchen, bathrooms, and laundry. The hot water temperature at all fixtures used by residents must be maintained at a minimum of 100 degrees F (38 degrees C) and must not exceed 116 degrees F (46.7 degrees C). This Rule is not met as evidenced by: 1. At the time of this survey, the water temperature at the kitchen sink was 96 degrees Fahrenheit. Staff adjusted the temperature on the water heater. A later reading at the half bath was 100 degrees. Maintain water temperatures between 100 and 116 degrees. Monitor the water temperature three times a day for three days.	C 155		10-20-15	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL033009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:		(X3) DATE SURVEY COMPLETED 06/04/2015
NAME OF PROVIDER OR SUPPLIER MY GUARDIAN ANGEL FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 514 COKEY ROAD ROCKY MOUNT, NC 27801			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 155	Continued From page 8 Record your findings on the attached Hot Water Temp Log to verify that the temperatures are being maintained. Return the log with the signed Plan of Corrections	C 155	Temp Hot water log will be maintained for three times a day and log signed and sent to DHSR.	8-23-15	
C 100	10A NCAC 13G .0316 (e) Fire Safety And Disaster Plan 10A NCAC 13G .0316 Fire Safety And Disaster Plan (e) There shall be at least four rehearsals of the fire evacuation plan each year. Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, staff members present, and a short description of what the rehearsal involved. This Rule is not met as evidenced by: 1. Based on Interview with Staff, the facility did not have copies of the fire drill logs available. Provide copies of the fire and disaster drill logs for the last 12 months for verification. Maintain copies on site for review.	C 100	The facility will perform four rehearsals of fire evacuation. The records shall be sent to Social Services annually and maintained in the facility. Officers fire and disaster drill logs for DHSR Review.	8-23-15	

Division of Health Service Regulation
STATE FORM

6055

GEF421

If continuation sheet 9 of 9