

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041039	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 07/10/2015
--	---	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

BROOKDALE HIGH POINT NORTH AL (NC)

1508 SKEET CLUB ROAD
HIGH POINT, NC 27266

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 000)	Initial Comments Report of a Follow-Up Construction Survey by Ed Miller and July 10, 2015. The following deficiencies cited during the March 28, 2015, Biennial Construction Survey, have not been satisfactorily corrected and will require a new Plan of Correction.	(C 000)		
(C 189)	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Building was not maintained in a safe and operating condition, because by not having properly working delayed egress system. This could affect all residents, staff and visitors by potentially delaying exiting in an emergency for more than an acceptable time. Findings on July 10, 2015; a. The delayed egress exit door from the Kitchen did not initiate an irreversible process to unlock the door. Deficiency corrected before Construction Surveyors departed the site b. The delayed egress doors from the kitchen did not have the required signage saying "PUSH UNTIL ALARM SOUND, DOOR CAN BE OPENED IN 15 SECONDS."	(C 189)		

CONSTRUCTION SECTION
AUG 10 2015
RECEIVED

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

DATE FORM

562122

562122

If continuation sheet 1 of 2

See attachment!

Division of Health Service Regulation

PRINTED: 07/22/2015
FORM APPROVEDSTATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

HAL041039

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: 01

B. WING:

(X3) DATE SURVEY
COMPLETEDR
07/10/2015

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

BROOKDALE HIGH POINT NORTH AL (NC)

1568 SKEET CLUB ROAD
HIGH POINT, NC 27267(X4) ID
PREFIX
TAGSUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)ID
PREFIX
TAGPROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)(X5)
COMPLETE
DATE

(C 189) Continued From page 1

(C 189)

6. Based on observation, the Building was not maintained in a safe and operating condition, by not maintaining the fire and smoke resistance of doors the 1998 NC State Building Code defines as "Hazardous Area". This could affect all residents, staff and visitors if smoke/fire is not contained in Room or fire compartment of origin. Findings on July 10, 2015:

- a. The Kitchen Pantry Room ¾ hour fire rated door was wedged open.
- b. Kitchen door was held open with mechanical "kick-down."

7. Based on observations and interview with Maintenance Technician, the Building was not maintained in a safe and operating condition, because breaches through the fire-resistance-rated construction invalidated its integrity. This could affect all residents, staff and visitors if smoke/fire is not contained in Room or compartment of origin. Findings on July 10, 2015:

- a. An unidentified sealant (gray in color) was used to seal penetrations of the fire-resistance-rated construction; provide documentation that this application is a listed through penetration system or replace defective installations in accordance with manufacturer's recommendations, listed systems details and applicable code requirements at the following locations to include but not limited to:
- 1. Mech Room near Bedroom 8

High Point Place HA Biennial Survey

The following is a summary of the Plan of Correction for Skeet Club Manor. This Plan of Correction is in regards to the Construction Section Biennial Survey conducted on July 10th, 2015 and received on July 27th, 2015. This Plan of Correction is not to be construed as an admission of or agreement with the findings and conclusions in the Statement of Deficiencies, or any related sanction or fine. Rather, it is submitted as confirmation of our ongoing efforts to comply with statutory and regulatory requirements. In this document, we have outlined specific actions in response to identified issues. We have not provided a detailed response to each allegation or finding, nor have we identified mitigating factors.

1568 Skeet Club Rd., Highpoint NC, 27265

FID #980795 Hal041039

C189 Building Maintained Safe Operating

1.
 - B. Will equip door with proper signage by August 27th, 2015
5. A. Will remove obstructions by August 4th, 2015
 - B. Will remove obstructions by August 4th, 2015
7. A. Will properly seal penetration by August 27th, 2015

To assist with compliance, the Executive Director or designee will review monthly preventative maintenance reports completed by the Maintenance Technician and will do a monthly walk through of the building with the Maintenance Technician for two months.