

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 04/24/2015
--	--	--	---

NAME OF PROVIDER OR SUPPLIER KINGS MOUNTAIN CARE CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 115 FERGUSON DRIVE KINGS MOUNTAIN, NC 28086
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Biennial Construction Survey by Frank Strickland on 04/24/2015: Information gathered from the DHSR database indicates that this facility was either first licensed or submitted for licensure on 07/01/1978 for 20 residents. Based on this information, we are requiring that this facility meet the 1977 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, the applicable portions of the current 2005 Rules for Adult Care Homes and the 1967 edition of the NC State Building Code. Deficiencies were cited and a Plan of Correction is required.	C 000	CONSTRUCTION SECTION JUL 28 2015 09 RECEIVED	
C 133	Bathrooms-Hand Grips SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (6) Hand grips shall be installed at all commodes, tubs and showers used by or accessible to residents; This Rule is not met as evidenced by: 1-Based on observations, the building has not maintained the hand grips at all commodes. This can make use of commodes by residents difficult and unsafe. Findings on 04/24/2015: The hand grip is loose located in the shared bathroom for Rooms 5 & 6. 2-Based on observations, the building has not	C 133	Installed Hand Rails 3 bathrooms Hand grip has been Repaired	12-jun-15 12-jun-15

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE <i>Debbie Conner</i>	TITLE <i>Duren</i>	(X6) DATE <i>30-jun-15</i>
--	---------------------------	-----------------------------------

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 04/24/2015
NAME OF PROVIDER OR SUPPLIER KINGS MOUNTAIN CARE CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 115 FERGUSON DRIVE KINGS MOUNTAIN, NC 28086		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 133	Continued From page 1 maintained the HVAC return-air grilles cleaning and particulate build-up is present. This condition can effect the air quality of the habitable spaces and the efficiency of the HVAC system. Findings on 04/24/2015: The Maintenance Shop Room has a very dirty and clogged with particulates return-air grille.	C 133	<i>Grilles have been cleaned</i>	<i>20-june-15</i>
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observations, the building has not maintained finish surfaces on the ceilings of resident's rooms. This could effect the air quality due to airborne particles for the residents and staff. Findings on 04/24/2015: The ceiling finish for Room 5 is falling off the sheet rock and finish gypsum particles are on the floor. 2-Based on observations, the building has not maintained the attachment of corridor handrails to adjacent supporting walls. This can effect residents that use the handrails to move throughout the facility in a safe manner.	C 166	<i>Ceiling has been repaired</i>	<i>20-june-15</i>

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 04/24/2015
NAME OF PROVIDER OR SUPPLIER KINGS MOUNTAIN CARE CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 115 FERGUSON DRIVE KINGS MOUNTAIN, NC 28086			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 166	Continued From page 2 Findings on 04/24/2015: The corridor handrail was not attached to the wall in a secure manner located outside Rooms 3 & 4.	C 166	Handrail has been re-secured JLH		