

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL076003	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 11/08/2015
NAME OF PROVIDER OR SUPPLIER CROSS ROAD RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1302 OLD COX ROAD ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Biennial Survey by Billy S. Bryant and Frank Strickland conducted on 11/08/2015. * Records indicate this facility was first licensed on 08/01/1986. The facility is currently licensed for 112 beds Beds with a 40 Bed Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1978 (Revision 5) Edition of the North Carolina Building Code(s), Institutional Occupancy and the 1984 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure.	C 000	* Facility was first licensed on 10/16/1983 and received first resident on 10/17/1983.	
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the facility free from hazards. Emergency means of egress/pathways must be kept clear of obstructions and encroachments and not used for storage. In the event of an emergency requiring evacuation from the facility, obstructing or encroaching on the means of egress/pathways could effect occupants of the facility by delaying evacuation.	C 166		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(TITLE)

(X6) DATE

STATE FORM

6899

680221

Stephen L. Runkley Executive Director

12/14/15

If continuation sheet 1 of 5

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL076003	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 11/06/2015
NAME OF PROVIDER OR SUPPLIER CROSS ROAD RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1302 OLD COX ROAD ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 188	Continued From page 1 Finding on 11/06/2015: a. North Hall Nurses' Station - The width of the path of emergency egress was reduced to approximately 5'-0" by stored med carts. - Note: Corrected while surveyor was on site. 2. Based on observation the storage of oxygen bottles was not maintained in a manner that kept the facility free from hazards. Oxygen bottles that are not stored in an oxygen bottle rack or otherwise restrained from falling or being knocked over may present a danger to the occupants of the facility. Finding on 11/06/2015: a. Intersection of South and East Hall - There was an oxygen bottle sitting upright and unrestrained on the nurses' station work counter.	C 188	* Med Carts are now stored out of emergency pathways in designated areas. All staff & Care directors have been notified to monitor and also make sure this is part of new employee training. * We have an oxygen bottle storage trailer with racks & restraints located between the main & special care units. The oxygen bottle left during inspection at the nurse station was immediately taken to the storage trailer. All personal care staff & directors were notified of issue and this is now an emphasis of new employee training.	11/06/15 11/06/15
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (a) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the facility's fire safety systems in a safe manner as evidenced by gaps and open penetrations in the fire resistant rated ceilings. Fire resistant rated ceilings must be free of gaps	C 189		

Anthony L. Runkley, Executive Director 12/14/15

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL076003	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 11/06/2015
NAME OF PROVIDER OR SUPPLIER CROSS ROAD RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1302 OLD COX ROAD ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 188	Continued From page 2 and openings in order to resist the spread of fire and smoke in the event of a fire. Penetrations or holes in fire resistant rated ceilings could effect the occupants of the facility by allowing fire and smoke to spread beyond the area of origin. Findings on 11/06/2015: a. East Hall, Women's Bath Adjacent to Nurse's Station - There is a gap in the fire resistant rated ceiling at the fire sprinkler escutcheon. b. East Hall, Room #7, Bathroom - There is a gap the fire resistant rated ceiling around the perimeter of the exhaust fan in where the exhaust fan grille has detached from the ceiling. 2. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition as evidenced by doors that do not completely close and latch. Doors are required to completely close and latch in the event of a fire in order to resist the passage of smoke or the spread of fire. All the occupants in the facility could be effected if doors do not latch and remain closed so as to limit the spread of smoke or fire to the area of origin. Findings one 11/06/2015: a. North Hall - The door from the laundry to the corridor did not completely close and latch. b. Special Care Unit - The doors to the entrance to the SCU had coordinator type hardware installed that did not work correctly and prevented the doors from completely latching and closing. 3. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition as evidenced by doors with automatic self closing hardware devices and	C 188	a. * East Hall women's bath fire sprinkler escutcheon has been attached back flush to ceiling with no gaps. This will be monitored on a monthly basis along with water temperature inspections. 12/1/15 b. * Room #7 bathroom exhaust fan has been attached flush to ceiling to correct any gaps. Will monitor on regular basis. 12/07/15 a. * North Hall door from laundry to corridor needed adjustment to strike plate to allow door to close & latch. Has been fixed. 12/1/15 b. * The doors to entrance to SCU now close correctly. The coordinator type hardware was adjusted to allow doors to completely latch & close. 12/7/15	

Steph L. Rousley, Executive Director 12/14/15

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL076003	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 11/06/2015
NAME OF PROVIDER OR SUPPLIER CROSS ROAD RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1302 OLD COX ROAD ASHEBORO, NC 27203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 4 (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation there is a widespread absence of exhaust ventilation in spaces required to have exhaust ventilation. Failure to exhaust air from the designated areas could effect the occupants of the facility by not removing odors, fumes or other air borne contaminants from the area of the room requiring exhaust ventilation. Finding on 11/06/2015. a. Special Care Unit - The resident bathrooms do not have mechanical exhaust fans or windows.	C 199	* It is believed that the original mechanical engineer received a letter from DFS in 1995 that allowed a variance based on the air flow and space. * I have engaged the firm of Applied Engineering, P.A. of Winston-Salem, N.C. to address this issue and design/specify the proper exhaust ventilation solution for the areas of concern in our Special Care Unit. Should have solution in January, 2016 and will address ASAP.	

Atty L. Rumbly, Executive Director 12/14/15