

PRINTED: 12/18/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092181	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 11/30/2015
NAME OF PROVIDER OR SUPPLIER THE COVINGTON		STREET ADDRESS, CITY, STATE, ZIP CODE 4810 DURALIGHT ROAD RALEIGH, NC 27618			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE PRECEDED BY FULL REFERENCE TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
(C 000)	Initial Comments Report of a Follow Up Survey by Billy B. Bryant conducted on 11/20/2015. Deficiencies noted during the Biennial Survey on 09/09/2015 remain to be corrected.	(C 000)			
(C 110)	Construction-Meet Sanitary Requirements SECTION 0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION (e) The sanitation, water supply, sewage disposal and dietary facilities shall comply with the rules of the North Carolina Division of Environmental Health, which are incorporated by reference, including all subsequent amendments. The "Rules Governing the Sanitation of Hospitals, Nursing and Rest Homes, Sanitariums, Sanatoriums, and Educational and Other Institutions", 15A NCAC 15A .1300 are available for inspection at the Department of Environment and Natural Resources, Division of Environmental Health, 2728 Capital Boulevard, Raleigh, North Carolina. Copies may be obtained from Environmental Health Services Section, 1632 Mail Service Center, Raleigh, North Carolina 27699-1632 at no cost.	(C 110)	(e) Facility has maintain the proper water supply in the facility per Regulations	12/1/2015	
	This Rule is not met as evidenced by: 1. Based on record review, and interview with Executive Director, the facility failed to maintain in the facility, current (completed within the last twelve months) annual inspection report(s) required. This deficiency affects all residents, staff and visitors by not preventing any systems deficiency that may be discovered with annual inspections.				

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE:

STATE FORM

6000

2010022

TITLE:

DATE:

If continuation sheet 1 of 8

PRINTED: 12/16/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092181	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:		(X3) DATE SURVEY COMPLETED R 11/20/2015
NAME OF PROVIDER OR SUPPLIER THE COVINGTON		STREET ADDRESS, CITY, STATE, ZIP CODE 4610 DORALEIGH ROAD RALEIGH, NC 27616			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE PRECEDED BY THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
(C 110)	Continued From page 1 Findings on 11/20/2015: a. Records indicate that the last annual Building Sanitation Inspection Report was performed on February 4, 2013.	(C 110)	a. completed by building Sanitation inspection.	12/2/2015	
(C 184)	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 18F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to have walls, ceilings, and floors or floor coverings kept clean and in good repair. Findings on 11/20/2015: a. The gypsum wall repairs in the Serenity Spa needed to be completed and painted. b. There was a pattern exhibited where most of the Corridor Closets on the 1st and 2nd floors had large areas of their back walls missing, where it appears plumbing pipes had been accessed. c. There was a pattern exhibited where most of Bedroom Closets doors were missing, creating an untidy appearance. d. The seamless flooring was coming apart in the 2nd floor Staff Station.	(C 184)	a. completed-Patched holes and painted gypsum wall b. replaced & repaired gypsum c. all metal door will be removed and curtains will be d. seamless flooring be replaced	11/28/2015 11/29/2015 1/30/2016	

PRINTED: 12/16/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092181	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:		(X3) DATE SURVEY COMPLETED R 11/20/2015
NAME OF PROVIDER OR SUPPLIER THE COVINGTON		STREET ADDRESS, CITY, STATE, ZIP CODE 4810 DURA LENOIR ROAD RALEIGH, NC 27615			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		(X5) COMPLETE DATE
(C 164)	Continued From page 2 e. The wall base was missing in Room 104 bathroom. f. There was a pattern exhibited where most of the Room signage had been removed for renovations or repairs and not reinstalled.	(C 164)	e. completed- wall base was replaced f. signage was ordered for the entire building		11/26/2015 1/30/2016
(C 188)	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (a) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, this facility, which was equipped with Special Locking (magnetic locks) on the exit doors, failed to maintain the system as required by the NC State Building Code in effect when the locking system was installed. This could affect all residents, staff and visitors if the facility cannot egress quickly during an emergency. Findings on 11/20/2015: a. The central manual overrides for the magnetic locks on the 2nd and 3rd floors did not release the magnetic locks when operated. 2. Based on observation, the Building was not maintained in a safe and operating condition, by	(C 188)			
			a. First Fire was called on that day and the magnetic locks were repaired. Doors will release on override on 2nd and 3rd floor		11/20/2015

Division of Health Service Regulation
STATE FORM

000

Z0Q022

If continuation sheet 3 of 5

