

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084051	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

LENDOR ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments This is a Report of a Biennial Construction Survey conducted by Greg Cates and Ed Miller on September 16, 2015. Based on information gathered from our files, the Facility was first licensed on October 10, 1990 for Sixty (60) residents. A fully sprinkled addition was completed and licensed on February 1, 1996, making a total of Ninety-Four (94) Residents including Thirty-Two (32) Special Care Beds. Based on this information, we are requiring the original facility to meet the 1987 Minimum Standards and Regulations for Homes for the Aged and Disabled and the 1978 North Carolina State Building Code, Section 409- Institutional Occupancy; the addition to meet the 1986 Rules for the Licensing of Adult Care Homes and the 1996 North Carolina State Building Code, Section 409- Institutional Occupancy; and the entire facility to meet the applicable portions of the 2005 Rules for Adult care Home of Seven or More Beds.	C 000		
C 101	Existing Licensed Fac- No less than 71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAO 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971	C 101		

Division of Health Service Regulation

ADDRESS: DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE:

(X6) DATE

STATE FORM

FXTM21

If continuation sheet 1 of 10

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

(17) STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HA1054051	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/16/2015
---	---	---	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

LENOIR ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28372

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 2 1- SCU Nurse 's Station 2- SCU Laundry 3- SCU Laundry closets	C 101	<i>Alarm Company Had to order w/ll have installed by 2-29-16</i>	
C 110	Plans Submittals and Approvals SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0304 PLANS AND SPECIFICATIONS (a) When construction or remodeling of an adult care home is planned, two copies of Construction Documents and specifications shall be submitted by the applicant or appointed representative to the Division for review and approval. As a preliminary step to avoid last minute difficulty with final plan approval, Schematic Design Drawings and Design Development Drawings may be submitted for approval prior to the required submission of Construction Documents. (b) Approval of Construction Documents and specifications shall be obtained from the Division prior to licensure. Approval of Construction Documents shall expire after one year unless a building permit for the construction has been obtained. (c) If an approval expires, renewed approval shall be issued by the Division, provided revised Construction Documents meeting all current regulations, codes and standards are submitted by the applicant or appointed representative and reviewed by the Division. (d) Any changes made during construction shall require the approval of the Division to assure that licensing requirements are maintained. (e) Completed construction or remodeling shall conform to the requirements of this Section including the operation of all building systems and shall be approved in writing by the Division prior to licensure or occupancy. Within 90 days	C 110		

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

HAL054051

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: 01

B. WING:

(X3) DATE SURVEY
COMPLETED

09/16/2015

NAME OF PROVIDER OR SUPPLIER

LENOIR ASSISTED LIVING

STREET ADDRESS, CITY, STATE, ZIP CODE

2773 PINWOOD HOME ROAD
PINK HILL, NC 28672

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 154	Continued From page 5 locations include but are not limited to: 1- Resident Room 311 (missing) 2- Resident rooms on 400 Hall (bent, broken) b- In the Dining/ Conference Room in the rear addition, the plastic laminate is releasing from the counter. c- In the Dining/ Conference Room in the rear addition, there is a drawer front missing on the cabinetry. d- In Resident Room 403, there is no hardware on the bathroom door. e- There is a carpet strip missing at the Men/ Guest bathroom, allowing the carpet to unravel. f- Most of the resident rooms on the 100 Hall are not equipped with chairs for resident use or guests. g- There are several bathrooms where there is missing ceramic tile. Locations include but are not limited to: 1- Shower in the Bathroom beside Room 109. 2- Shower in Bath 3A 3- Bath beside the Janitor's Closet on 300 Hall h- The hardware on the corridor door to the SCU Utility Room is loose and not secure. i- The corridor door hardware at Resident Room 215 is loose and not secure. 2- Based on observations, the facility has failed to maintain the buildings walls, ceilings, and floors in good repair and clean. a- In the several of the bathrooms, there is significant mildew growth on the shower tile. Locations include but are not limited to: 1- Bathroom beside Room 111 2- Bathroom 2B b- There is significant build-up of lint and other items behind the dryer and on the wall in the following locations to include but not limited to:	C 164	b repaired on 10/28/15. c- to be repaired by 12/18/15. d repaired 10/28/15. e repaired 10/28/15. f to be repaired by 12/18/15 g to be repaired by 12/18/15. Have ordered and waiting on supplier. Contractor has ordered tile will set date when tile is delivered h repaired 10/23/15. i repaired 10/23/15 a Cleaned 10/25/15 and ongoing b Cleaned 10/25/15 and ongoing	

Division of Health Service Regulation
STATE FORM

6009

FXT421

(If continuation sheet 6 of 15)

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054051	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

LENOIR ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 6 1- Main Laundry Room (Lint) 2- SCU Laundry Room (Lint, socks, cardboard box) c- In areas with hard floor coverings, the areas around the door frames and in corners, there is a build-up of wax/ dirt. Specific examples include but are not limited to the following: 1- SCU Utility/ Janitors 2- SCU Laundry	C 164	cleaned 10/25/15 and ongoing	
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1- Based on observations, the facility has failed to maintain the building free of hazards by not securing oxygen bottles from falling over or rolling around. Findings include: a- There is an oxygen bottle being stored in the TV Room of the rear addition that is unsupported and could fall over, damaging the cylinder or nozzle. b- The grab bar beside the tub in the bathroom beside the Janitor's closet on the 300 Hall is loose. c- There is a kick-down in use at the RCC office that may prevent the door from closing easily in	C 166	a moved to different location on 10/23/15. b to be repaired by 12/16/15. c removed kick-down on 10/23/15.	

PRINTED: 10/06/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054061	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

LENCOR ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 7 the event of an emergency. d- The handrail located at the ramp in the rear addition is missing screws and is very loose. e- The safety release lock on the refrigerator/ freezer is broken/ disabled and a pad lock is being used to lock the unit, allowing a person to be locked in the refrigerator/ freezer. f- The two closets in the SCU Laundry have deadbolt locks that are installed backwards with the keyed portion on the inside and the thumb-turn to the outside, allowing the possibility of someone being locked in the closets. 2- Based on observation, the facility has failed to keep the building and its environment clean and maintained. Findings include: a- There are several locations throughout the facility where the carpet is torn, unraveling, or stained. Locations include but are not limited to: 1- Resident Room 311- Tear 2- Resident Rooms on the 400 Hall- Tears 3- Corridor outside Room 100- Stains 4- Resident Room 115- Tear 5- Resident Room 200- Stains b- There are several locations throughout the facility where the resident private bathroom floors are not clean or are stained. Locations include but are not limited to: 1- Resident Room 115- Dirty/ stained (Mildew at the toilet caulking) 2- Resident Room 108- Dirty/ Stained (odor of urine) 3- Resident Room 200- Sticky and wet (odor of urine) 4- SCU Laundry bathroom- Stained c- The corridor doors and door frames throughout the facility have been scratched and scarred and	C 166 d e f a b	repaired 10/26/15 removed lock on 10/23/15. deadbolts were reversed on 10/26/15. to be repaired by 12/16/15. 1- Replaced Carpet 2- waiting on contractor to replace floor covering 3- cleaned 4- Replaced carpet 5- cleaned cleaned on 10/23/15 and ongoing.	

Division of Health Service Regulation
STATE FORM

600

FXTM21

If continuation sheet 5 of 10

PRINTED: 10/08/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (N.C. PLAN OF CORRECTION)	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054061	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/18/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

GENOIR ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 9 b- the rear wings, many of the EXIT signs are now not visible and need to be off-set. Locations include but are not limited to: 1- 400 Hall. 2- 300 Hall. 3- Special Care (200 Hall) Wing. 4- 100 Hall c- The EXIT signs in the following locations are broken and hanging by the wires. Locations to include but not limited to: 1- 400 Hall EXIT door. 2- Fire wall leading into the rear addition. d- The EXIT signs in the following locations have the directional arrows punched and are directing people in incorrect directions for exiting. 1- On the Central Hall side of the 100 Hall fire wall. 2- On the inside of the SCU entrance/ EXIT door. e- The EXIT sign on the Living Room side of the fire doors in the SCU has been removed. f- The emergency lights located in the following areas are not equipped with battery back-up. Locations to include but not limited to: 1- 300 Hall 2- 400 Hall 3- Assisted Living Dining Room 4- Central Hall beside the Nursing Aide Office 5- 100 Hall 6- SCU (200 Hall) g- The emergency lights located in the following areas have broken heads, allowing only one head to light. Locations include but are not limited to: 1- Dining/ Conference Room in the rear addition 2- Sitting Room in the rear addition 3- Entrance to the SCU 2- Based on observations, the facility failed to ensure that the building is safe by not maintaining	C 189 b 1-4 C d e f g 1 2 3	to be repaired/replaced by waiting waiting on Electrical Contractor to be repaired by 12/18/15. to be repaired by 12/18/15. to be repaired by 12/18/15 to be repaired by 12/18/15 to be repaired by 12/18/15. repaired by 12/18/15 repaired 10/28/15 repaired 10/28/15	

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL064061	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING:	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

NATURE OF ASSISTED LIVING

2773 PINWOOD HOME ROAD
PINK HILL, NC 28672

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 10 the fire resistance of building components. This deficiency directly affect all residents, personnel, and visitors by allowing the possible spread of smoke beyond the compartment of origin. Findings on include: a- The one-hour rated ceilings are not sealed due to penetrations or damage to the construction system. Locations include but are not limited to: 1- Exterior porch ceiling at the 300 Hall EXIT- gaps around the edges. 2- The ceiling mounted light fixture in Room 311 is missing the cover. 3- Electrical Panel Room- gaps around the conduits and cables. 4- Sprinkler Riser room- ceiling damage and gaps at the sprinkler pipes. 5- Rear addition alcove- ceiling damage. 6- Janitor's Closet beside Men/ Guest bathroom- gaps around conduit. 7- Men/ Guest- ceiling damage/ large hole. 8- Outdoor Mechanical- gaps around conduits and cables. 9- Utility (SCU) - Gap around the heat detector. 10- Room 200- approximately 3/4 " hole in ceiling. 3- Based on observations, the facility has failed to maintain the building electrical system safe and operating. Findings include: a- In the ceiling in the Sitting Room of the rear addition (right side), there is a junction box cover missing. b- The ceiling mounted fluorescent light fixture in the Maintenance Office is loose and hanging down on one end.	C 189	1 repaired 11/4/15. 2 repaired 11/4/15 3 repaired 11/4/15. 4 repaired 11/4/15. 5 repaired 11/4/15. 6 repaired 11/4/15. 7 repairs to be completed by 12/16/15 8 repaired 11/4/15 9 repaired 11/4/15. 10 repaired 11/4/15. a repaired 10/26/15. b repaired 10/26/15	

Division of Health Service Regulation
STATE FORM

6000

FXTN21

If continuation sheet 11 of 15

PRINTED: 10/08/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054051	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

LENOIR ASSISTED LIVING

2773 PINWOOD HOME ROAD

PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 109	Continued From page 11 c- The duplex wall socket on the exterior wall beside the bed is broken. d- One of the ceiling mounted fluorescent light fixtures is missing the cover. e- The GFCI receptacle located in Bathroom 2A in the SCU does not have power and will not trip. f- The light at the rear addition EXIT is not working. J- Based on observations, the facility has not maintained the plumbing system safe and operating. Findings include: a- The tank cover for the toilet in the bathroom in the Sitting Room of the rear addition is oversized, not secure, and in danger of falling off. b- In the large bathroom beside Room 111, there is no vacuum breaker on the walk-in tub hand-held sprayer. c- In the large bathroom beside Room 111, the shower head pipe has pulled out of the wall and is not secured. d- The tank cover for the toilet in the bathroom beside Room 109 is oversized, not secure, and in danger of falling off. e- In Bathroom 2B in the SCU, there is no vacuum breaker on the walk-in tub hand-held sprayer. f- In Bathroom 2A in the SCU, the shower pipe is loose and the escutcheon does not cover the hole around the pipe. 5- Based on observations, the facility has failed to ensure that the doors operate correctly to prevent the passage of fire or smoke. Findings include:	C 109 C d e f a b c d e f	repaired 10/28/15. repairs to be completed by 12/18/15. repairs to be completed by 12/18/15. repaired 10/28/15. to be repaired by 12/18/15 to be repaired by 12/18/15. to be repaired by 12/18/15 to be repaired by 12/18/15 to be repaired by 12/18/15. to be repaired by 12/18/15.	

PRINTED: 10/08/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054051	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/16/2015
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

LENOIR ASSISTED LIVING

STREET ADDRESS, CITY, STATE, ZIP CODE

2773 PINWOOD HOME ROAD
PINK HILL, NC 28572

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 12 a- The corridor doors in the following areas do not close completely and latch. Locations include but are not limited to: 1- The Janitor's Room beside the Men/ Guest Bathroom 2- Resident Room 115 3- Resident Room 116 4- Janitor's Room near Room 109 5- Resident Room 108 6- Resident Room 217 6- Based on observations, the facility has failed to maintain the fire and smoke doors to prevent the passage of fire or smoke. This affects all occupants of the building in the event of a fire emergency. Findings include: a- The fire door located between the original building and the addition has been disabled and does not latch. b- The smoke door on the 300 Hall has a gap of approximately 1/4 inch with no astragal to close the gap. c- The fire door located on the 100 Hall does not completely close and latch as it is rubbing against the frame. d- The fire door located in the SCU releases upon alarm, but drags on the carpet, preventing it from closing. e- There is an approximately 1/4" hole in the fire door separating the original building from the addition. 7- Based on observations, the facility has failed to maintain the EXIT doors in a safe condition. Findings include:	C 189 1-6	repaired on 11/4/2015 a repairs to be made by 12/18/15 b repairs to be made by 12/18/15 c repairs to be made by 12/18/15 d repairs to be made by 12/18/15 e repairs to be made by 12/18/15	

If continuation sheet 14 of 15

CERTIFICATE OF OCCUPANCY

Lenoir County

This Certificate issued pursuant to the requirements of the International Codes certifying that at the time of issuance, this structure was in compliance with the various ordinances of Lenoir County regulating building construction or use.

Project #: 06- HO

Permit #: 12-01036

Master Permit #: 12-01036

Proposed Use: ASSISTED LIVING

Occupancy Type: I Construction Type: VU Fire Zone:

Property Owner: THERAPUETIC ALTERNATIVES

Address: 4270 HEATH DAIRY RD

City: RANDLEMAN

State: NC Zip: 27317

Project Address: PINEWOOD HOME RD 2773

Contractor: HARPER RANDALL C

Dary D. Zent / fm
(Building Official)

11/03/15
Date.

* * * POST IN A CONSPICUOUS PLACE * * *