

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL078086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 03/10/2017
NAME OF PROVIDER OR SUPPLIER WEST WINDS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1241 GOINS ROAD PEMBROKE, NC 28372		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on March 10, 2017 from 9:40 AM to 11:00 AM at the above referenced facility. DHSR records indicate the home was first licensed on May 23, 2011 as a Family Care Home for six (6) ambulatory Residents. On November 24, 2011 the facility was re-classified under the code to serve six (6) residents with up to three (3) of whom may be non-Ambulatory (un-able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, the 2009 North Carolina State Building Code - Section 421.3 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 117	Have Current San. And Fire Safety Approvals SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION (n) The home shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: During record review at the time of the survey, a copy of the Fire Inspection were not available. Provide a copy of the most recent Fire Inspection Report to DHSR along with your signed Plan of	C 117		<i>Rule C117-10 NCAC 13G .0302 enclosed is copy of Fire and Building Safety Inspection which was done on 9/14/16 however it was misfiled when you did your visit 9/14/16</i>

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

2QP521

If continuation sheet 1 of 5

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL078086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 03/10/2017
NAME OF PROVIDER OR SUPPLIER WEST WINDS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1241 GOINS ROAD PEMBROKE, NC 28372		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 117	Continued From page 1 Correction.	C 117		
C 136	Bathroom-Nonskid In Tub/Showers SECTION .0300 - THE BUILDING 10A NCAC 13G .0309 BATHROOM (f) Nonskid surfacing or strips must be installed in showers and bath areas. This Rule is not met as evidenced by: Observations during the survey showed that the walk-in shower in the 2nd hallway bathroom is missing the non-skid material. Install non-skid material in the shower. NOTE: This deficiency was noted during the January 29, 2014 Biennial Survey and has still not been corrected. Provide copies of all receipts, photographs and any other supporting documentation concerning this repair.	C 136	<i>C 316 Rule 10A-NCAC-13G.1309 non skid strips has been installed in shower and in tub photo will be enclosed # 4/14/17</i>	
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. Observations during the survey showed that the toilet in the bathroom next to the office is loose. Have a qualified individual repair the toilet so that it does not move. Provide copies of all invoices, work orders, and any other supporting documentation concerning this repair.	C 174	<i>C 174 Rule 10A NCAC 13G.317 all toilets have been tightened to the floor and toilet seats have been tightened so they do not slip. Copy of repair Bill enclosed 3/29/17</i>	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL078086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 03/10/2017
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

WEST WINDS ASSISTED LIVING

**1241 GOINS ROAD
PEMBROKE, NC 28372**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 2 2. Observations during the survey showed that the toilet seat in the 2nd hall bathroom is loose. Have the seat tightened so that it is secure. Provide the DHSR Construction section with copies of all work orders, and any other supporting documentation concerning this repair. * 3. Observations during the survey showed that in the Staff Bedroom, the ceiling HVAC register is loose. Have the register re-secured. Provide copies of all photographs and any other supporting documentation concerning this repair. 4. Observations during the survey showed that in the first hall bathroom, the tub caulking is black with mold and mildew. Have the caulking cleaned or replaced. Provide copies of all photographs and any other supporting documentation concerning this repair. 5. Observations during the survey showed that in the walk in shower in the 2nd hall bathroom, the tub caulking is black with mold and mildew. Have the caulking cleaned or replaced. Provide copies of all photographs and any other supporting documentation concerning this repair. 6. Observations during the survey showed that in the 2nd hallway bathroom, there are numerous holes in the wall where fixtures have been relocated. Have the holes patched and the repairs painted to match surroundings. Provide copies of all photographs and any other supporting documentation concerning this repair. 7. Observations during the survey showed that approximately half way down the main hallway, several floor tiles are damaged. Have the floor tile replaced. Provide copies of all photographs and any other supporting documentation	C 174	<i>Repaired Photo enclosed</i> <i>C174 Caulking was Removed and Replaced with mold free Caulking.</i> <i>C174 Walk in shower was Cleaned All Caulking Removed and Replaced Pictures will be enclosed</i> <i>C 174 All Holes in Bathrooms has been Repaired and Bathroom Painted</i>	<i>5/1/17</i> <i>4/10/17</i> <i>4/13/17</i>

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL078086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 03/10/2017
NAME OF PROVIDER OR SUPPLIER WEST WINDS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1241 GOINS ROAD PEMBROKE, NC 28372		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 3 concerning this repair.	C 174	<i>Floor tile was removed from hallway and replaced photos enclosed 4/18/17</i>	
X C 177	Building Service Equipment-Hot Water SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (d) The hot water tank shall be of such size to provide an adequate supply of hot water to the kitchen, bathrooms, and laundry. The hot water temperature at all fixtures used by residents shall be maintained at a minimum of 100 degrees F (38 degrees C) and shall not exceed 116 degrees F (46.7 degrees C). (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: Observations during the survey showed that the hot water temperature measured at the kitchen and bathroom sinks was 120 degrees F. Adjust the hot water heater controls so that the temperature falls between 100 and 116 degrees F. On the attached log, record the hot water temperature 3 times a day for 3 consecutive days and return the log to DHSR along with your signed Plan of Correction.	C 177		
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean and safe condition. This Rule is not met as evidenced by: 1. Observations during the survey showed that in the back yard, there is a large hole in the ground	C 183	<i>Rule 10 NCAC 13 G 0318 hole has been filled in and graded to the surrounding yard photos enclosed 4/13/17</i>	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL078086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 03/10/2017
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

WEST WINDS ASSISTED LIVING

**1241 GOINS ROAD
PEMBROKE, NC 28372**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 183	Continued From page 4 approximately 3 feet by 3 feet and 1 foot deep. This is causing a tripping/falling hazard to residents. Have the hole filled and graded to the surrounding lawn. Provide copies of all photographs and any other supporting documentation concerning this repair. 2. Observations during the survey showed that on the left side of the home, a large section of stucco finish is missing. Have the stucco replaced or paint the area to match the stucco. Provide all copies of photographs and any other supporting documentation concerning this repair.	C 183	<i>C 183 Plan is to paint entire Building but will need more time to fix Stucco + paint Will send photos when complete</i>	<i>8/15/17</i>

Division of Health Service Regulation

STATE FORM

6899

2QP521

If continuation sheet 5 of 5

Hot Water Temp Record
 Name of Facility **WEST WINDS ASSISTED LIVING**
FID #060290
 Surveyor **PAUL DIXON**

Date	Reading Location	Temperature	Signature	Print Names	Comments
4-25-17	8 tub Bath	110	<i>[Signature]</i>	Maddyn Sampson	
4-25-17	Shower RM	112	<i>[Signature]</i>	Maddyn Sampson	
4-25-17	office Front Bathroom	112	<i>[Signature]</i>	Maddyn Sampson	
4-26-17	tub Bath	115	<i>[Signature]</i>	Maddyn Sampson	Changed the water
4-26-17	Shower Bath RM	115	<i>[Signature]</i>	Maddyn Sampson	
4-26-17	tub Bath	115	<i>[Signature]</i>	Maddyn Sampson	
4-27-17	tub Bath	115	<i>[Signature]</i>	Maddyn Sampson	
4-27-17	Shower RM	115	<i>[Signature]</i>	Maddyn Sampson	
4-27-17	Tub Bath	115	<i>[Signature]</i>	Maddyn Sampson	

Hot Water Temp – 100 – 116 Deg Recommend Record Temp once/week

Maintain this log of hot water temperatures showing measurements made three times a day for three consecutive days

Return completed log to:
 Division of Health Service Regulation
 Construction Section
 2705 Mail Service Center

Raleigh NC 27699

Fax Number 919-733-6592

Attention:

Paul Hixon

*All Areas of Concern will
be monitored to ensure that the
Rules are met and maintained*

*Wynne Damp
Administrator
West Winds Assisted
Living
910 521-0853
Home 521-4966*

Handwritten: C 117

FIRE AND BUILDING SAFETY INSPECTION REPORT
NORTH CAROLINA STATE DEPARTMENT OF RESOURCES
 Residential Care Facilities for as Many as Six and Less than Ten Individuals
 Chapter V, Section 520 of the North Carolina Building Code

NAME OF FACILITY West Wind Assisted Living NAME OF PERSON IN CHARGE Jimmy Hammonds
 STREET ADDRESS 1241 Goins Rd. CITY Pembroke ZIP 28372 TELEPHONE 910-521-0853
 TYPE OF CONSTRUCTION V NUMBER OF STORIES 1 FIRE RATING OF WALLS/PARTITIONS 1
 FIRE RATING OF CEILINGS 1 SQUARE FEET PER FLOOR _____ HOW MANY FLOORS ARE USED 1
 TYPE OF HEATING SYSTEM Central LOCATION Outside NUMBER OF U/L APPROVED FIRE EXTINGUISHERS 3
 LOCATION OF FIRE EXTINGUISHERS _____ PROPERLY CHARGED Yes
 APPROVED SMOKE DETECTION DEVICES yes EVACUATION PLAN: YES ☒ NO ☐ MANUAL FIRE ALARM: YES ☒ NO ☐
 DEAD-END CORRIDORS GREATER THAN 20 FEET: YES ☐ NO ☒ ARE STAIRS PROPERLY ENCLOSED N/A ARE DOORS
 LOCKED FROM THE INSIDE YES HOW: MANUALLY CAN WINDOWS BE OPENED WITHOUT TOOLS: YES ☒ NO ☐
 DOES THE FACILITY HAVE TWO APPROVED EXITS FROM EACH FLOOR YES
 CONDITION OF BASEMENT N/A USE _____ CONDITION OF ATTIC OK USE NONE
 APPROVED FOR LICENSING: FULLY ☒ CONDITIONALLY ☐ NOT ACCEPTABLE ☐

TYPES OF HAZARDS (Please circle those which apply)

HEATING

1. DEFECTIVE FURNACE
2. DEFECTIVE FLUE
3. DEFECTIVE SMOKE PIPE
4. UNSATISFACTORY STORAGE OF ASHES

5. PORTABLE HEATERS USED

ELECTRICAL

6. DEFECTIVE FIXTURES
7. DEFECTIVE WIRING
8. DEFECTIVE FUSES
9. DEFECTIVE LIGHTING

EXITS

10. HALLS BLOCKED
11. EXITS BLOCKED
12. UNSATISFACTORY FIRE EXITS
13. STORAGE ON ESCAPES
14. INADEQUATE EXIT LIGHTING

MISCELLANEOUS

15. RUBBISH AND TRASH
16. UNSATISFACTORY FIRE EXTINGUISHERS
17. IMPROPER STORAGE AND USE OF FLAMMABLE MATERIALS

18. DEFECTIVE WATER HEATER
19. STORAGE OF MOWER AND GARDEN TRACTOR
20. UNSUPERVISED SMOKING OF RESIDENTS

OTHER HAZARDS FOUND: _____

RECOMMENDATIONS TO CORRECT AND/OR PROVIDE GREATER SAFETY: _____

FACILITY DOES NOT MEET ALL REQUIREMENTS OUTLINED IN CHAPTER V, SECTION 520 OF THE NORTH CAROLINA BUILDING CODE,
 WHAT CHANGES ARE REQUIRED TO BRING THE FACILITY IN FULL COMPLIANCE? _____

NAME: _____ TITLE Fire Inspector
 ADDRESS 38 Legend Dr. Lumberton, NC 28358 DATE OF INSPECTION 09/14/2016

TRIPPLICATE. ONE COPY SHOULD BE GIVEN TO THE PERSON IN CHARGE OF THE FACILITY OR HOME. ONE COPY SHOULD BE
 RETAINED BY DEPARTMENT OF SOCIAL SERVICES. FOR CHILDREN'S FACILITIES, SEND THE THIRD COPY TO THE N.C. STATE
 DIVISION OF SOCIAL SERVICES ADULT FACILITIES, SEND TO THE N.C. STATE DIVISION OF FACILITY SERVICES.

ANTHONY LOCKLEAR'S PLUMBING REPAIRS2008 Buie Philadelphus Road
Red Springs, NC 28377-6052

Over 25 years Experience

(910) 843-2555



PLEASE MAKE CHECKS PAYABLE TO: Anthony Locklear

0 174

Order Number	Department	Date		
		3-29-17		
Name				
Address				
City/State/Zip				
Sold By	Cash	Ck	Visa/MC	Chg
Quantity	Description	Price	Amount	
1				
2				
3	Parts + Labor -		\$ 18.50	
4				
5				
6	Repaired all Comod			
7				
8	Seats and Tighten			
9				
10	Comod on Floor also			
11				
12	Repaired Leak on Comod's			
13				
14				
15	A. Locklear			
16				
17	Lic # 17181			
18				
19				
20				
Received By				

Save for your records