

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Suzanna Fay conducted on June 13, 2017.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost;	C 101	<i>C101 1. - Directional EXIT signage will be installed on the Grand Level and 2nd Level on 8/11/17 - The facility will be surveyed to determine if other directional EXIT signage should be added. - Every month the facility survey staff member will survey the facility to ensure that directional EXIT signage is in place</i>	

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Virginia Starnes

TITLE

Administrative

(X6) DATE

08/01/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 This Rule is not met as evidenced by: 1. Based on observations, the facility did not meet the code requirements in effect at the time of licensure. The 1978 NC State Building Code requires exits to be marked and, where the exits themselves are not visible from the exit approach, directional exits signs indicating the way of egress shall be provided. Findings on June 13, 2017: a. On the third level, directional exit signs are not visible from the corridors indicating the locations of the exits. b. At the lower level, the directional exit sign in the hall outside of dining is not clearly visible when the cross corridor doors are closed. 2. Based on observation, the facility did not have full coverage of the sprinkler system at the time of installation. Findings on June 13, 2017: a. The hall closet beside Room 7 did not have a sprinkler head.	C 101	- On a quarterly basis, the administrator will survey facility to ensure directional exit signs meet code requirements 2- The sprinkler head in the closet beside Room 7 has been installed. - The facility will be surveyed to determine if other sprinkler heads need to be added. - Every month the facility supervisor will survey the facility to ensure that sprinkler system meets code requirements.	
C 153	Exit Door Locks-Single Hand Motion SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (3) All exit door locks shall be easily operable, by a single hand motion, from the inside at all times without keys; and	C 153	- On a quarterly basis the administrator will survey facility to ensure that the sprinkler system meets code requirements. C153 1. A single action lock will be installed on the front door on 6/17. - The facility will be surveyed to determine if other single action locks need to be added.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 153	Continued From page 2 This Rule is not met as evidenced by: 1. Observations revealed that the front entrance door hardware was not operable by a single hand motion.	C 153	- Every month the facility should staff person will have the facility to determine if the superintendent, there is a good looking order of it similar that should be added.	
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the kitchen ceiling was not maintained in good repair. Findings on June 13, 2017: a. The paint finish on the kitchen ceiling was flaking off near the kitchen exit.	C 164	- On a quarterly basis the administrator will ensure facility to ensure that the kitchen meet code requirement. C164 1. the kitchen ceiling has been painted. - The facility will be encouraged to determine if there are other areas that need to be cleaned, painted etc.	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and	C 189	- The facility will be encouraged to determine if there are other areas that need to be cleaned, painted etc. - On a quarterly basis the administrator will ensure the facility to ensure that ceilings, walls, etc. are clean & painted.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3 operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the rated walls were not maintained safe to prevent the transmission of fire or smoke. This affects the safety of the residents, staff and visitors. Findings on June 13, 2017: a. The rated access door to the attic compartment in the third floor closet containing the roof hatch was open and could not be secured by this surveyor. b. There are several holes in the plaster finish behind the ladder leading to the 3rd floor roof access. c. Third floor roof access - the red wires to the right of the ladder penetrate the rated ceiling and are not fire caulked. d. Room 4 - the sprinkler pipe is not fire caulked where it penetrates the corridor wall and the ceiling in the closet. e. Closet by Room 7 - the sprinkler pipe is not fire caulked where it penetrates the corridor wall. 2. Observations revealed that the operation of the fire safety equipment was not consistent throughout the building. Findings on June 13, 2017: a. All strobes flashed upon the initial alarm activation. When the alarm was silenced the strobes on the upper and lower levels ceased to flash. The main level continued to flash. 3. Observations revealed that the handrails were	C 189	<i>C189/1 - The rated access door to the attic has been repaired.</i> <i>b. all holes in the plaster finish behind the ladder leading to the 3rd floor roof have been filled according to code regulations.</i> <i>c. the red wires that penetrate the rated ceiling in the roof access have been fire caulked.</i> <i>d. the sprinkler pipe in the closet in Room 4 has been fire caulked.</i> <i>e. the sprinkler pipe in the closet by Room 7 has been fire caulked where it penetrates the corridor wall.</i> <i>- A survey of the facility was done to see if there were any other areas (via rated walls)</i>	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 not maintained in a safe condition. Findings on June 13, 2107: a. The handrail between Rooms 27 and 28 was loose. b. The handrail outside of Room 7 was loose. 4. Observations revealed that the heat detectors were not maintained in good condition. Findings on June 13, 2017: a. The plate was broken on the heat detector outside of the TV Room on the main level. 5. Based on observation there is a failure to install and maintain plumbing piping in a safe configuration. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if the domestic water supply became contaminated. Findings on June 13, 2017: a. The drain line for the icemaker was sitting directly in the drain cup. A 2" gap is required between the icemaker drain line and the drain to prevent contamination. Also, there was a plastic lid in the drain cup partially obstructing the drain.	C 189	that were not maintained safe to protect the transmission of the air supply. - On a monthly basis the facility workers staff should check the facility to make sure water walls are maintained in such a way that they meet code requirements. - On a quarterly basis, the administrator will survey the facility to ensure that water walls are maintained safe to protect the transmission of fire flame. 2. - All workers have been reported by Jimpex... all are in proper working order. - The facility was workers to determine it all fire safety	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 not maintained in a safe condition. Findings on June 13, 2107: a. The handrail between Rooms 27 and 28 was loose. b. The handrail outside of Room 7 was loose. 4. Observations revealed that the heat detectors were not maintained in good condition. Findings on June 13, 2017: a. The plate was broken on the heat detector outside of the TV Room on the main level. 5. Based on observation there is a failure to install and maintain plumbing piping in a safe configuration. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if the domestic water supply became contaminated. Findings on June 13, 2017: a. The drain line for the icemaker was sitting directly in the drain cup. A 2" gap is required between the icemaker drain line and the drain to prevent contamination. Also, there was a plastic lid in the drain cup partially obstructing the drain.	C 189	equipment was not properly - On a monthly basis, the facility manager staff person will survey the facility to ensure that all fire safety equipment is working properly. - On a quarterly basis, the administrator will survey the facility to ensure that all fire safety equipment is working properly. 3- handrails between Rooms 27 and 28 and outside of Room 7 have been tightened. - the facility was surveyed to determine if any of the handrails were loose. - on a monthly basis, the facility manager staff person will survey facility to make sure that no sections of handrail are loose.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 not maintained in a safe condition. Findings on June 13, 2107: a. The handrail between Rooms 27 and 28 was loose. b. The handrail outside of Room 7 was loose. 4. Observations revealed that the heat detectors were not maintained in good condition. Findings on June 13, 2017: a. The plate was broken on the heat detector outside of the TV Room on the main level. 5. Based on observation there is a failure to install and maintain plumbing piping in a safe configuration. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if the domestic water supply became contaminated. Findings on June 13, 2017: a. The drain line for the icemaker was sitting directly in the drain cup. A 2" gap is required between the icemaker drain line and the drain to prevent contamination. Also, there was a plastic lid in the drain cup partially obstructing the drain.	C 189	On a quarterly basis, the administrator will survey the facility to ensure that no sections of handrail are loose. 4. The heat detectors outside of the TV room on the main level will be replaced by simply on..... - a survey of the facility will be done to determine if other heat detectors need to be replaced. - On a monthly basis, the facility manager will survey the facility to determine if all heat detectors are maintained in good condition. - On a quarterly basis, the administrator will survey the facility to ensure that all heat detectors are maintained.	8/4/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/13/2017
NAME OF PROVIDER OR SUPPLIER THE TAYLOR HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 319 PALMER STREET ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 not maintained in a safe condition. Findings on June 13, 2107: a. The handrail between Rooms 27 and 28 was loose. b. The handrail outside of Room 7 was loose. 4. Observations revealed that the heat detectors were not maintained in good condition. Findings on June 13, 2017: a. The plate was broken on the heat detector outside of the TV Room on the main level. 5. Based on observation there is a failure to install and maintain plumbing piping in a safe configuration. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if the domestic water supply became contaminated. Findings on June 13, 2017: a. The drain line for the icemaker was sitting directly in the drain cup. A 2" gap is required between the icemaker drain line and the drain to prevent contamination. Also, there was a plastic lid in the drain cup partially obstructing the drain.	C 189	<i>in good condition.</i> <i>5 - the drain line for the icemaker has been repaired according to code requirements</i> <i>- A survey of the facility was able to determine if there were other drain situations that did not meet code requirements.</i> <i>- On a monthly basis the facility services staff upon w/ll survey the facility to determine if plumbing piping is being maintained in a safe configuration.</i> <i>- On a quarterly basis the administrator will require the facility to ensure that plumbing piping is maintained in a safe configuration.</i>	