

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL063016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/11/2017
--	--	--	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

THE COVENTRY

**105 GOSSMAN DRIVE
SOUTHERN PINES, NC 28387**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Ed Miller on July 11, 2017. Records indicate this facility was first licensed on June 14, 1996 for fifty Beds. On August 28, 2013 the facility, add ten beds for sixty beds. Based on this information, we are requiring the facility to meet the 1996 Rules for the Licensing of Adult Care Homes, the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds; and the 1996 North Carolina State Building Code Section 409.1- Group I. Deficiencies were cited that require a Plan of Correction.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by:	C 101		

Division of Health Service Regulation
LABORATORY DIRECTORS OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

VP of HCS

(X6) DATE

8/9/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL063016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/11/2017
NAME OF PROVIDER OR SUPPLIER THE COVENTRY		STREET ADDRESS, CITY, STATE, ZIP CODE 105 GOSSMAN DRIVE SOUTHERN PINES, NC 28387		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 1. Based on observation, the Building did not meet the NC State Building and Fire Codes while an addition was being added. This could affect all residents, staff, and visitors by not having the ability to effectively exit the building during an emergency. Findings on July 11, 2017: a. Exit near Bedroom 132 - this door was identified as an exit by an exit sign and was locked on the Assisted Living side, not allowing egress through the exit, creating a dead end corridor of approximately 45 feet which is greater than the 20 feet permitted by Code for I-2 Occupancies. b. The path through the construction area is not an acceptable egress path.	C 101	1. a. New exit created at the end of Corridor 7/31/17. Exit signs in place as well as emergency lights, pull station, and fire extinguisher. Completed 08/03/17 Temporary exit during construction will be removed with new exit in place on 08/30/17. No other areas of building impacted by exit and all other exits meet code Construction will be complete by 8/30/17 with all approved emergency exits in operation Routine building inspections will occur on a quarterly basis for all code compliance by environmental service technician. Record on file in Directors office of inspection.	8/3/17 8/30/17
C 144	Med Prep Area-Sink with Lever Handles SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (f) The requirements for storage rooms and closets are: (5) Handwashing facilities with wrist type lever handles shall be provided immediately adjacent to the drug storage area; This Rule is not met as evidenced by: 1. Based on observation, the building was not maintained in a safe manner by not having properly working wrist type lever handles on the handwashing facilities adjacent to the drug storage area. Findings on July 11, 2017: a. 2nd Floor Med Room - the faucet for the medication preparation sink was equipped with knob handles.	C 144	Replaced faucet with correct hardware. Completed on 07/12/17 7/12/17 building inspection by plant operations designee resulted in no other sink faucet replacements needed. Routine building inspections will occur on a quarterly basis for all code compliance by plant operations designee. Record on file in Directors office of inspection.	7/12/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL063016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/11/2017
NAME OF PROVIDER OR SUPPLIER THE COVENTRY		STREET ADDRESS, CITY, STATE, ZIP CODE 105 GOSSMAN DRIVE SOUTHERN PINES, NC 28387		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to maintain the building in an uncluttered, clean and orderly manner. Findings on July 11, 2017: a. Kitchen - the HVAC return grille and a ventilation grille with their radiation dampers have an excessive accumulation of dust/lint/grease. b. Spa near Bedroom 116 - the ventilation grille with its radiation damper has an excessive accumulation of dust/lint. 2. Based on observation, the Building plumbing equipment was not maintained in a safe manner by not have properly working or installed parts. This could affect all residents, staff, and visitors by not protecting them from falls or injury due to broken or missing parts. Findings on July 11, 2017: a. Staff Restroom near Kitchen - the connection of the commode to the floor is loose.	C 166	1. a. Grills and ducts cleaned on 07/12/17 by Comfort Services. Cleaning will be put on a monthly Kitchen schedule. Annual duct cleaning will be scheduled with contract company in July of each year. 1. b. Grills and ducts cleaned on 07/12/17 by Comfort Services. Cleaning will be put on a monthly Housekeeping schedule. Annual duct cleaning will be scheduled by contract agency in July. Routine building inspections will occur on a quarterly basis for all code compliance by environmental services technician. Record on file in Directors office of inspection. 2. a. Flange was repaired/replaced on 07/11/17. Will be inspected quarterly by plant operations designee. Record on file in Directors office of inspection. If broken or missing pieces are found a work order will be created to fix the issue	7/12/17 7/11/17
C 183	Fire Extinguishers SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0308 FIRE EXTINGUISHERS (a) At least one five pound or larger (net charge) A-B-C type fire extinguisher is required for each	C 183		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL063016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/11/2017
NAME OF PROVIDER OR SUPPLIER THE COVENTRY		STREET ADDRESS, CITY, STATE, ZIP CODE 105 GOSSMAN DRIVE SOUTHERN PINES, NC 28387		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 183	Continued From page 3 2,500 square feet of floor area or fraction thereof. (b) One five pound or larger (net charge) A-B-C or CO/2 type is required in the kitchen and, where applicable, in the maintenance shop. This Rule is not met as evidenced by: 1. Based on observation, the facility failed to properly maintain the fire extinguishers and associated equipment. This could hamper staffs ability to extinguish a small fire and permit it to grow larger. This would affect all residents, staff, and visitors by not identifying emergency equipment not in proper working order. Findings on July 11, 2017: a. 1st Floor Mech Room near Elevator - the documentation of the portable fire extinguisher's monthly inspections stopped in April 2017.	C 183	1. a. inspected fire extinguisher 7/12/17 and found it to be in proper condition. Will be monitored quarterly during fire Drill and noted on fire report copies will be maintained in Directors office. Extinguishers will be replaced as needed if determined on inspection.	7/12/17
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Fire Alarm system was not maintained in a safe and operating condition. This would affect residents, staff, and visitors by not providing early detection and activating the fire alarm system. Findings on July 11, 2017:	C 189		

Division of Health Service Regulation
STATE FORM

STATE FORM

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL063016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/11/2017
NAME OF PROVIDER OR SUPPLIER THE COVENTRY		STREET ADDRESS, CITY, STATE, ZIP CODE 105 GOSSMAN DRIVE SOUTHERN PINES, NC 28387		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 8	C 199		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on July 11, 2017: a. Staff Restroom near Kitchen - the exhaust ventilation system did not work, and the room has a musty odor.	C 199	1. a. Removed exhaust ventilation fan and replaced motor part ordered 7/12/17 installed and operational on 8/3/17. Routine building inspections will occur on a quarterly basis for all code compliance by environmental services technician. Record on file in Directors office of inspection. The facility alleges compliance effective 8- 13-17	8/3/17



DEPARTMENT OF HEALTH AND HUMAN SERVICES
DIVISION OF HEALTH SERVICE REGULATION

ROY COOPER
GOVERNOR

MANDY COHEN, MD, MPH
SECRETARY

MARK PAYNE
DIRECTOR

July 27, 2017

Kim Morton
105 Grossman Drive
Southern Pines, NC 28387

RE: The Coventry - HA Biennial Survey
105 Gossman Drive
Southern Pines Moore County
FID #960429 Hal063016

Dear Ms. Morton :

Thank you for the cooperation and courtesies extended during the recent Division of Health Service Regulation (DHSR) – Construction Section Biennial survey of your facility on July 11, 2017. As a result of the survey, deficiencies were cited which will require an acceptable Plan of Correction. The deficiencies cited are listed on the enclosed Statement of Deficiency. Your Plan of Correction should indicate the following:

- What corrective action(s) will be accomplished in those areas of the facility found to have been affected by the deficient practice;
- How you will identify other areas of the facility having the potential to be affected by the same deficient practice and what corrective action will be taken;
- What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur; and,
- How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place.

CONSTRUCTION SECTION
WWW.NCDHHS.GOV • WWW.NCDHHS.GOV/DHSR
TEL 919-855-3893 • FAX 919-733-6592
LOCATION: WILLIAMS BUILDING, 1800 UMSTEAD DRIVE • RALEIGH, NC 27603
MAILING ADDRESS: 2705 MAIL SERVICE CENTER • RALEIGH, NC 27699-2705
AN EQUAL OPPORTUNITY / AFFIRMATIVE ACTION EMPLOYER

Please do not hesitate to call us if you have questions concerning the deficiencies or if we can be of other assistance.

Sincerely,

Ed Miller

Ed Miller
Architect
DHSR - Construction Section

cc: Adult Care Licensure Section-with attachment
City Building Inspection Department - with attachment-(via e-mail only)
Moore County DSS - with attachment-(via e-mail only)