

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054062	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/20/2017
NAME OF PROVIDER OR SUPPLIER KINSTON ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 2130 ROSE VISTA ROAD KINSTON, NC 28504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Billy S. Bryant conducted on 07/20/2017. Records indicate this facility was first licensed on 04/01/1985. The facility is currently licensed for 60 Beds. Therefore the facility was surveyed for conformance with the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1978 (Revision 5) Edition of the North Carolina Building Code(s), Institutional Occupancy, and the 1984 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure.	C 000		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the walls and floor coverings have not been kept clean and in good repair. Findings on 07/2017: a. Room 111 - The wall at the corner of the closet is damaged and the gypsum board corner bead is exposed and loose. b. Corridors - The walls are scuffed and marred.	C 164	WILL BE COMPLETED	9-3-17

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Sammy Torres

TITLE

RCC

(X6) DATE

8-9-17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054062	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 07/20/2017
NAME OF PROVIDER OR SUPPLIER KINSTON ASSISTED LIVING			STREET ADDRESS, CITY, STATE, ZIP CODE 2130 ROSE VISTA ROAD KINSTON, NC 28504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 164	Continued From page 1 c. Throughout the building the doors and frames to resident rooms, resident closets, corridor doors to storage rooms, closets and bathrooms etc., are damaged and scarred. d. Kitchen - The wall board above the walk refrigerator and freezer is disintegrating due to moisture damage.	C 164	WILL BE COMPLETED	9-3-17	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the building's fire safety equipment systems in a safe condition. Holes or gaps at penetrations in the fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on 07/20/2017: a. 100 Hall Bath/Shower, Across from Room 105 - There is a gap in the fire resistant rated ceiling where the HVAC grille is detached from the ceiling. b. 100 and 200 Hall Water Heater Closets, Adjacent to Bath/Shower Rooms - There are	C 189		COMPLETED	7-17-17
			COMPLETED	7-17-17	

Division of Health Service Regulation
ATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL054062	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 07/20/2017
NAME OF PROVIDER OR SUPPLIER KINSTON ASSISTED LIVING			STREET ADDRESS, CITY, STATE, ZIP CODE 2130 ROSE VISTA ROAD KINSTON, NC 28504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 189	Continued From page 3 Finding on 07/20/2017: a. Administrator's Office - The wall mounted emergency light did not illuminate when tested on battery power. 4. Based on observation the electrical equipment has not been maintained. Finding on 07/20/2017: a. Room 213 - There is a gap between the wall and the GFCI electric outlet cover plate next to the sink. 4. Based on observation the HVAC mechanical equipment is not maintained in an operating condition: Finding on 07/20/2017: a. Room 202 - The thru wall unit cover is dislodged and the knobs to control the unit are missing.	C 189	COMPLETED	7-25-17	
			COMPLETED	7-25-17	
			COMPLETED	7-25-17	