

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

VINTAGE INN RETIREMENT COMMUNITY

826 EAST BOULEVARD HWY 17 N BYPASS
WILLIAMSTON, NC 27892

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Mitchell Moran

Director of Maintenance

6/30/17

STATE FORM

0066

D8IN21

If continuation sheet 1 of 10

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 Findings on 06/08/2017: a. Administrator's Office - The ceiling paint is peeling from the ceiling surface. b. There is a pattern of HVAC return air and exhaust fan grilles and the radiation dampers that need cleaning. Approximately 1/2 of the HVAC return air and exhaust fan grilles and the radiation dampers above the grilles in the facility's ceiling were clogged with dust. 2. Based on observation the floors are not maintained clean and in good repair. Finding on 06/08/2017: a. Kitchen - There is trash and a build up of dirt on the floor under the prep table immediately adjacent to the ice machine.	C 164 A B A	Ceiling was repaired and painted HVAC return air and exhaust fan was cleaned and put on Schedule to be cleaned Trash and build up has been cleaned and will be kept cleaned daily	6/21/17 6/29/17 6/16/17
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility is not maintained free from hazards. Findings on 06/08/2017: a. S.C.U., Janitor's Closet - Access to the electrical panels is obstructed by disposable diapers stored in front of the panels.	C 166 A	 janitor's closet cleaned out and nothing will be stored in front panels	 6/17/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 3 b. Kitchen, Main Electrical Room - The electrical room is being used for kitchen supplies storage and access to the electrical panels is obstructed by items stored in front of the panels. 2. Based on observation the facility was not maintained free from hazards due to oxygen bottles that are stored without any means of restraint to prevent them from falling or being knocked over. Oxygen bottles that are improperly stored may present a danger to the occupants of the facility. Finding on 06/08/2017: a. Oxygen Storage Room - Oxygen cylinders were stored standing upright and without any means of restraint to prevent them from falling over. 3. Based on observation the facility was not maintained free from hazards. Finding on 06/08/2017: a. S.C.U. Spa Adjacent to Room #44 - The fluorescent light fixture lens is almost cracked in two and is in danger of completely detaching from the fixture.	C 166 B A A	Electrical room has had all obstructions move out from front of panels Oxygen cylinders has been put in racks Light Fixture replaced	6/17/17 6/16/17 6/17/16
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing	C 189		

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 escutcheon in the living area has dropped down creating a gap in the fire resistant rated ceiling where it is penetrated by the sprinkler pipe. g. S.C.U. Living Room - The fire sprinkler head escutcheon in the living area has dropped down creating a gap in the fire resistant rated ceiling where it is penetrated by the sprinkler pipe. 2. Based on observation there is a failure to maintain the facility's fire safety systems in a safe manner due to holes in the fire resistant rated walls. Failure to maintain fire safety systems in a safe condition could effect occupants of the facility if the system did not provide the required fire resistant rated protection. Finding on 06/08/2017: a. Main Hall Utility Room - An approximately 4 square foot section of drywall has been removed from the section of the fire resistant rated wall that is shared with the corridor. 3. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Doors that open to corridors are required to close completely and latch. The occupants in the smoke compartment could be effected if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on 06/08/2017: a. S.C.U., Room #41 - The door hardware is loose so that it will not operate and latch to keep the door shut when the door is closed. b. S.C.U., Cross Corridor Doors - The doors adjacent to the dining room did not completely close and latch when released from their	C 189 E, F, G A A B	all escutcheons was pushed back up to the ceiling Drywall was replaced door hardware tight up door latches now Door adjusted closes and latches	6/26/17 6/29/17 6/27/17 6/27/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 magnetic hold open devices. c. S.C.U. Dining room - When the door to the corridor is shut there is an approximately 1/4" gap between the door and the door frame stop that would prevent the door from resisting the passage of smoke. d. Cross Corridor Doors, Adjacent to Room #10 - The doors did not completely close and latch when released from their magnetic hold open devices. Note: Repaired while the surveyor was on site. e. Room # 32 - The door hits the door frame preventing it from completely closing and latching when shut. 4. Based on observation and testing there is failure to maintain the facility's emergency fire alarm system devices and equipment in a safe operating condition. Failure to maintain fire alarm system devices and equipment in a safe and operable condition could effect all occupants of the facility if the equipment did not function when and as required. Finding on 06/08/2017: a. Room # 37 - The ceiling smoke heat detector was detached from its mounting base and was hanging by its wiring. Note: Repaired while the surveyor was on site. 5. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage or if illuminated directional exit signs could not be seen.	C 189 C D E A	door was repaired to close up 1/4 gap Repaired day of survey Door adjusted closes and latches Repaired day of survey	6/20/17 6/8/17 6/26/17 6/8/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 7 Findings on 06/08/2017: a. Corridor at Room #26 - When tested on battery power the directional exit sign did not illuminate. b. Fire Alarm Panel - When tested on battery power the wall mounted emergency light above the F.A. panel did not illuminate. 6. Based on observation there is a failure to install and maintain required plumbing safety devices or equipment. Failure to maintain or install plumbing safety devices or equipment could cause the domestic water supply to become contaminated. Finding on 06/08/2017: a. S.C.U., Room #62 - The hand held shower head reaches the bottom of the tub but a vacuum breaker is not installed for the shower head. b. Kitchen - There is no gap between the ice machine drain pipe and the floor drain. The drain pipe for the ice machine is plumbed down into the floor drain.	C 189 A, B A	Battery will be replaced or device will be replaced replaced hand held shower so it will not reach the bottom of tub	7/14/17 6/23/17
C 191	Unvented & Portable Elec. Heaters Prohibited SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (b) There shall be a heating system sufficient to maintain 75 degrees F (24 degrees C) under winter design conditions. In addition, the following shall apply to heaters and cooking appliances. (2) Unvented fuel burning room heaters and portable electric heaters are prohibited. (k) This Rule shall apply to new and existing	C 191		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 191	Continued From page 8 facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. The facility did not comply with portable electrical heaters being prohibited. Finding on 06/08/2017: a. Room #27 - There was a portable electrical heater in use by the resident in the room.	C 191 A	portable heater was removed	6/19/17
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility failed to provide the required exhaust ventilation equipment in spaces required to be mechanically exhausted by rule. Finding on 06/08/2017 a. In 7 out of the first 12 resident bathrooms and	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL058010	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 06/08/2017
NAME OF PROVIDER OR SUPPLIER VINTAGE INN RETIREMENT COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 826 EAST BOULEVARD HWY 17 N BYPASS WILLIAMSTON, NC 27892			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 199	Continued From page 9 3 out of 4 of the Spas surveyed the exhaust fans are not working indicating a pattern of exhaust fans that do not operate.	C 199 A	Fan have been checked and have started repairing or replace them	7/31/17	


Williamston Fire/Rescue
Fire Prevention Bureau
901 Washington St.
Williamston, N.C. 27892
Inspection Report

Date 06/20/2017 Type Institutional
Occupancy Name VINTAGE INN Phone # 792-8311
Address 826 EAST BLVD
Business Owner VICTORIAN SENIOR CARE Phone # 877-698-2463
Address PO BOX 814 City RANDLEMAN State NC Zipcode 27317
Building Owner BECKY DYMECK (ADMINISTRATOR) Phone # _____
Address _____ City WILLIAMSTON State NC Zipcode 27892
Keyholder KAREN Phone # 799-1076
Keyholder STACEY MARTIN Phone # _____ **Knox Box** ☐

This occupancy has been inspected pursuant to the North Carolina State Fire Code. As a result of this inspection, the following conditions or violations have been found:

VIOLATION	<u>KITCHEN HOOD SUPPRESSION SYSTEM INSPECTION PAST DUE</u>
CORRECTION	<u>DUE A SIX MONTH INSPECTION INSTALL NEW TANK AND INSPECT</u>
VIOLATION	<u>SPRINKLER HEADS IN KITCHEN CORRODED OR GREASE LADEN</u>
CORRECTION	<u>REPLACE SPRINKLER HEADS AS RECOMMENDED IN SPRINKLER REPORT</u>
VIOLATION	<u>SPARE SPRINKLER HEAD BOX ON FLOOR</u>
CORRECTION	<u>REMOUNT CABINET BACK ON WALL IN SPRINKLE ROOM</u>
VIOLATION	<u>STORAGE HEIGHT IN LAUNDRY CLOSET</u>
CORRECTION	<u>18 INCH STORAGE FROM SPRINKLER HEADS</u>
VIOLATION	<u>CLOTHES DRYERS NEED TO BE CLEANED FROM LINT ACCUMULATION</u>
CORRECTION	<u>CLEAN THEM ON A ANNUAL OR MORE FREQUENT BASIS IF NEEDED</u>
VIOLATION	<u>STORAGE BUILDING NEEDS ORGANIZATION AND OR CLEANED OUT</u>
CORRECTION	<u>CLEAN OR ORGANIZE TO MAINTAIN A CLEAR WALKING AREA</u>

You are required to have these conditions or violations corrected within _____ days. Please notify the Fire Prevention Bureau in writing upon completion so the files on this matter may be closed.

STACEY PIPPIN 
Inspector

Occupant

WILLIAMSTON FIRE/RESCUE DEPARTMENT
FIRE PREVENTION BUREAU
P.O. Box 602, Williamston, NC 27892

Type Institutional

PERMIT TO OPERATE

Date 06/20/2017

Permit is hereby granted to VINTAGE INN
(Business Name)

located at 826 EAST BLVD for the following
(Business Location)

activities (list each functional):

ASSISTED LIVING CENTER FOR MORE THAN 16

Pursuant to the provision of the North Carolina State Fire Prevention Code and Williamston Town Ordinance, any violation of these regulations may be grounds for revocation of this permit.

This permit does not take the place of any license required by law and is not transferable. Any change in the use or occupancy of premises shall require a new permit.

Approved By:  STACEY PIPPIN Title: Fire Inspector II

THIS PERMIT MUST AT ALL TIMES BE POSTED ON THE PREMISES MENTIONED ABOVE