

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____

TITLE

(X6) DATE

Mitchell Moran

Maintenance Director

10/27/17

6552-6

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL079053	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/21/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE OF MAYODAN		STREET ADDRESS, CITY, STATE, ZIP CODE 6970 NC HWY 135 MAYODAN, NC 27027		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 4-Based on observation, the facility has not maintained the HVAC supply and return air grilles in a clean condition. Findings on 09/21/2017: The exhaust & return-air grilles throughout the entire facility have excessive particulate build-up.	C 164 4	all exhaust & return-air grilles will be cleaned and put on schedule to be cleaned monthly	10/27/17
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to store gas cylinders in a orderly manner to be free of hazards. Findings on 09/21/2017: There are oxygen gas cylinder located in the Assisted Living Storage Room that are free-standing and not in a storage racks.	C 166 1	Oxygen was put in storage rack and staff has been made aware of the importance of putting in the racks	9/21/17
C 188	Electrical Outlets in Wet Locations SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters.	C 188		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL079053	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/21/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE OF MAYODAN		STREET ADDRESS, CITY, STATE, ZIP CODE 6970 NC HWY 135 MAYODAN, NC 27027		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 188	Continued From page 3 This Rule is not met as evidenced by: 1-Based on observation, the facility has not maintained electrical ground-fault protection in wet areas. Findings on 09/21/2017: There is not GFCI protection for the receptacle that is within 6 feet from the hand wash sink in the Salon.	C 188 1	 GFCI receptacle was add	 9/28/17
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to maintain all fire safety equipment in a safe condition as relates to the sprinkler system components Findings on 09/21/2017: The accelerator has been shut-off due to repair/service. 2-Based on observations, this facility has failed to maintain clear and unobstructed paths for egress. Findings on 09/21/2017: There are buckets and mops blocking exit door	C 189 1 2	 Sprinkler company is going to repair system buckets and mops was removed	 11/23/17 9/21/17

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL079053	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/21/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE OF MAYODAN		STREET ADDRESS, CITY, STATE, ZIP CODE 6970 NC HWY 135 MAYODAN, NC 27027		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 because the noted interior doors do not latch preventing the containment of fire and/or smoke from the room of origin. Findings on 09/21/2017: The doors at the following locations do not latch: (a) Room 28 (b) Room 30 (c) Room 42 (d) Room 43	C 189 6-A-D	All doors was adjusted so they will latch	10/25/17
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility failed to provide an environment in accordance with this Rule by not providing ventilation where odors are generated. This could affect residents and staff by subjecting them to unwanted odors. Findings on 09/21/2017:	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL079053	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/21/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE OF MAYODAN		STREET ADDRESS, CITY, STATE, ZIP CODE 6970 NC HWY 135 MAYODAN, NC 27027		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 6 The roof-top mechanical exhaust fans are not exhausting interior air at the following locations: (a) All of the Bathrooms in the Assisted Living Wing (b) All of the Bathrooms in the Memory Care Unit (c) Soiled Utility Closet in Memory Care Unit (d) Janitorial Closet in Memory Care Unit	C 199 1-A-D	motor had to be ordered for roof-top mechanical exhaust fan. repair will be done as soon as it comes in	11-23-17