

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098029	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/04/2017
NAME OF PROVIDER OR SUPPLIER PARKWOOD VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 1730 PARKWOOD BLVD WILSON, NC 27895		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Ed Miller and Billy Bryant conducted on October 4, 2017. Records indicate this facility was first licensed on 8-19-1997, as a Home for the Aged. The facility is currently licensed for 70 Beds including a 20 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, the 1996 (1997 Revision) Edition, of the North Carolina Building Code(s), Institutional Occupancy, and the 1996 Minimum Standards and Regulations for Homes for the Aged in effect at time of initial licensure. Deficiencies were cited that require a Plan of Correction.	C 000		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on record review and interview with Executive Director and Maintenance Director the facility failed to maintain in the facility, current (completed within the last twelve months) annual inspection report(s) required by this Rule. Findings on October 4, 2017: a. A current Building Sanitation Inspection Report was not available for review by the	C 111	In reference to Tag C 111 – 1a A current building sanitation inspection report was not available for review. An Inspection was done by the NC Dept. of Environment and Natural Resources Division of Environmental Health receiving a score of 98 inspection date was 10/26/2017 (See Attachment)	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

8635

PWRG21

If continuation sheet 1 of 8

David K Hill

Director of Maintenance

11-3-2017

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

1730 PARKWOOD BLVD
WILSON, NC 27895

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098029	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/04/2017
NAME OF PROVIDER OR SUPPLIER PARKWOOD VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 1730 PARKWOOD BLVD WILSON, NC 27895		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 185	Continued From page 2 (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Record review and interview with Executive Director/Administrator/Maintenance Technician/Manager the Facility failed to document all aspects of the fire plan rehearsals. Findings on October 4, 2017: a. The fire plan rehearsal records included date, time, shift, and staff members present, but little to no description of what the rehearsal involved.	C 185	In reference to Tag C 185 - 1a Little or no description of what the fire drill rehearsal involved. Future fire drills will include a fire plan rehearsal record with detailed description of the location and type of fire rehearsal involved. This documentation will be completed by the maintenance director. (See attached copy of 10/27/2017 fire drill rehearsal with the expanded description at {Location} section of report)	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building's emergency equipment was not maintained in a safe and operating condition. This would affect all if they could not promptly find their way to an exit during an emergency. Findings on October 4, 2017: a. Exit near Bedroom 108 - the exit sign did not illuminate on backup power when tested. b. Exit near Bedroom 216 - the exit sign did not illuminate on backup power when tested. c. Exit From Dining - the exit sign did not	C 189	In reference to tag C189 - 1a, b, c Exit signs did not illuminate on backup power when tested, near bedroom 108, bedroom 216, dining room. New batteries were installed the exit signs now illuminate on backup power completed on 10/6/2017	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098029	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/04/2017
NAME OF PROVIDER OR SUPPLIER PARKWOOD VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 1730 PARKWOOD BLVD WILSON, NC 27895		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3 illuminate on backup power when tested. d. Dining left front side - the wall-mounted self-contained emergency light did not illuminate on backup power when the test button is pushed. 2. Based on observation, the facility was not maintained in a safe manner because the smoke barrier doors are not fitting well enough when closed to contain smoke and fire. This could affect all residents and staff by not containing smoke and fire in the fire compartment of origin. Findings on October 4, 2017: a. Smoke Barrier on 100 Hall - there was a gap of about 3/8 inch to 1/8 inch between leafs. 3. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in Room of origin. Findings on October 4, 2017: a. Corridor near Bedroom 108 - the fire sprinkler escutcheon plate missing exposing an opening in the ceiling. b. SCU Dining - a fire sprinkler head is debris-loaded with lint. 4. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Extension cords cannot substitute for permanent wiring. Findings on October 4, 2017: a. Kitchen Office - an extension cord is being used to power equipment. b. Bedroom 405 - an extension cord is being used to power equipment. 5. Based on Observation, the facility failed to keep plumbing in a safe and operating condition.	C 189	In reference to tag C189 – 1d Wall mount emergency light did not illuminate on backup power when tested, at dining left front side. A new battery was installed on 10/10/2017 and now emergency light illuminates on backup power In reference to Tag C189 – 2a A gap 3/8 inch was noted at the 100 hall smoke barrier door. An astragal was installed to close and assure a tight fit to the smoke barrier door at 100 hall on 11/1/17/2017 In reference to Tag C189 – 3a Corridor near bedroom 108 fire sprinkler escutcheon plate missing. A new escutcheon plate was installed to the sprinkler head closing the opening in the ceiling on 10/5/2017 In reference to Tag C189 – 3b SCU dining sprinkler head loaded with lint. Sprinkler heads were cleaned in SCU dining room unit on 11/1/2017. In reference to Tag C189 – 4a, b Non-approved extension cords were being use in kitchen office and bedroom 405 for power. Extension cord were replaced with approved surge protected power strip on 10/6/2017	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098029	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/04/2017
NAME OF PROVIDER OR SUPPLIER PARKWOOD VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 1730 PARKWOOD BLVD WILSON, NC 27895		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 Findings on October 4, 2017: a. Kitchen - the ice machine drain is almost on to the floor drain, resulting in the potential for the drain line to clog because of the lack of required air gap and contaminate the ice.	C 189	In reference to Tag C189 – 5a Kitchen ice machine drain too close to floor drain with potential for drain line to clog. <u>Drain line gap was increased to assure space to prevent ice machine drain line from clogging on 10/31/2017</u>	
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to provide ventilation in areas where odors are generated or required. This could affect all residents, staff and visitors by subjecting them to odors. Findings on October 4, 2017: a. 100 Hall Residents Laundry - there was no exhaust ventilation system and odor is present. b. 100 Hall - the central exhaust ventilation system did not work, and there was a slight odor in the Resident Bathroom. c. 200 Hall including Public Unisex Restrooms-	C 199	In reference to Tag C199 – a 100 hall resident laundry was found to have no exhaust ventilation. Work has been contracted to install an exhaust vent in the resident laundry by tying duct it into 100 hall central exhaust ventilation. Contractor is scheduled to complete work by 11/15/2017 or sooner In reference to Tag C199 – b 100 hall central exhaust ventilation system did not work. A new belt was installed on the exhaust fan motor and is now operating as design. The central exhaust ventilation system is now working in all resident bathrooms. In reference to Tag C199 – c 200 hall public unisex restrooms central exhaust ventilation did not work. Work has been contracted to install a new exhaust ventilation motor for the 200 hall to provide central exhaust ventilation to the public restrooms. Contractor is scheduled to complete work by 11/15/2017 or sooner	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL098029	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/04/2017
NAME OF PROVIDER OR SUPPLIER PARKWOOD VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 1730 PARKWOOD BLVD WILSON, NC 27895		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 5 the central exhaust ventilation system did not work, and there was a slight odor in the Resident Bathroom. d. Bulk Laundry and 300 Hall Housekeeping - the central exhaust ventilation system did not work, and there was a slight odor in the Resident Bathroom.	C 199	In reference to Tag C199 – d 1. Bulk laundry central exhaust ventilation did not work. Work has been contracted to install a new exhaust ventilation motor for the bulk laundry, to provide central exhaust ventilation to the bulk laundry. Contractor is scheduled to complete work by 11/15/2017 or sooner In reference to Tag C199 – d 2. 300 hall housekeeping closet central exhaust ventilation did not work. The duck work damper for the 300 housekeeping room was found closed when examined. The damper was opened and the central exhaust ventilation system is now working as designed in the housekeeping closet repairs were made on 10/31/2017	