

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL026056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/25/2017
--	---	---	--

NAME OF PROVIDER OR SUPPLIER
CARILLON ASSISTED LIVING OF FAYETTEVILLE

STREET ADDRESS, CITY, STATE, ZIP CODE
**1164 71ST SCHOOL ROAD
CUMBERLAND, NC 28331**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Biennial Survey by Suzanna Fay and Ed Miller conducted on October 25, 2017. Records indicate this facility was first licensed on June 10, 2008. The facility is currently licensed for 96 Beds including a 36 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure and applicable portions of the 2006 Edition of the North Carolina Building Code(s), Institutional Occupancy; Group I-2.	C 000		
C 150	Corridors-Free of equipment and Obstructions SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the facility free from hazards. Means of egress or exit paths must not be obstructed, blocked or have their required width encroached upon. This could delay or hinder evacuation of the occupants from the facility in the event of an emergency. Findings on October 25, 2017: a. SCU - there was a chair in the corridor outside of the nurses' station that was partially obstructing the corridor. The chair was removed at the time of survey. b. SCU - there were two med carts stored outside the suite adjacent to the nurses' station which	C 150	C150 1a) Remove white surveyor ONSITE b) Med Carts were removed from obstructing room	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

MGVB21

If continuation sheet 1 of 6

If continuation sheet 2 of 6

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL026056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/25/2017
NAME OF PROVIDER OR SUPPLIER CARILLON ASSISTED LIVING OF FAYETTEVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 1164 71ST SCHOOL ROAD CUMBERLAND, NC 28331		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 188	Continued From page 2	C 188		
C 188	Electrical Outlets in Wet Locations SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters. This Rule is not met as evidenced by: 1. Observations revealed that the adult care home did not have ground fault interrupters at all wet locations and outside locations. Findings on October 25, 2017: a. Room D11 - the GFCI in the bath did not reset when tripped. b. D Hall screened porch - the GFCI at the right of the door did not reset when tested.	C 188	<i>C188</i> <i>1a) GFCI has been replaced in Room D11</i> <i>b) GFCI at right of hall porch has been replaced</i>	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. The occupants in the smoke compartment could be effected if the fire	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL026056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/25/2017
NAME OF PROVIDER OR SUPPLIER CARILLON ASSISTED LIVING OF FAYETTEVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 1164 71ST SCHOOL ROAD CUMBERLAND, NC 28331		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3 resistant rated doors do not completely close and latch to help limit the spread of smoke and/or fire to the area of origin. Findings on October 25, 2017: a. The right leaf on the B Hall cross corridor doors did not latch. This item was corrected at the time of survey. b. The left leaf on the D Hall cross corridor doors did not latch. This item was corrected at the time of survey. 2. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. Occupants of the facility could be effected if signs indicating exit paths could not be seen in the event of an emergency evacuation. Findings on October 25, 2017: a. The battery back up did not function on the exit sign outside of Room C16. 3. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on October 25, 2017: a. D Hall Resident laundry - a folding table was too long for the room and extended into the doorway preventing the door from closing. b. Kitchen janitor's closet - the door hardware was broken preventing the door from closing and latching. 4. Based on observation there is a failure to	C 189	C189 1a) Item was corrected while surveyor onsite b) Same as above 2a) Exit sign outside Rm C16 has been repaired 3a) Table in Resident Laundry has been Relocated in order for Room Door to close properly b) Door closure to Janitors Closet has been repaired and closing properly	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL026056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/25/2017
NAME OF PROVIDER OR SUPPLIER CARILLON ASSISTED LIVING OF FAYETTEVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 1164 71ST SCHOOL ROAD CUMBERLAND, NC 28331		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. 5. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on October 25, 2017: a. Corridor outside of the guest bathrooms - a sprinkler escutcheon plate had dropped leaving a small gap in the ceiling. This item was corrected on site. 6. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device that is used to keep a door open is an impediment to quickly closing a door to aid in containing smoke and/or fire. The occupants in the facility could be effected if doors cannot be closed as required. Findings on October 25, 2017: a. B Hall, Soiled Linen room - the door was held open with trash cans and other furnishings. 7. Observations revealed that the mechanical equipment was not maintained in a safe and operating condition. Findings on October 25, 2017: a. SCU Living Room - the R/A grille and filter are clogged with dust. b. Bathroom by Room C4 - the exhaust fan has a	C 189	C189 5a) Sprinkler Escutcheon has been sealed to ceiling outside guest bathroom 6a) All obstructions have been removed to close door easily in B Hall Linen 7a) SCU Living Room vent has been cleaned of all dust b) Bathroom vent in Rm C4 has been cleaned	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL026056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/25/2017
NAME OF PROVIDER OR SUPPLIER CARILLON ASSISTED LIVING OF FAYETTEVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 1164 71ST SCHOOL ROAD CUMBERLAND, NC 28331		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 heavy accumulation of dust which can restrict the air flow.	C 189	ALL work has been verified by CDM as complete. 	