

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____

TITLE

(X5) DATE

Mitchell Moran

~~Maintenance Director~~

10/13/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL075032	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 07/20/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE ASSISTED LIVING OF ARCHD.		STREET ADDRESS, CITY, STATE, ZIP CODE 303 ALDRIDGE ROAD ARCHDALE, NC 27263		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1	C 189		
C 189	Building Equipment Maintained Safe, Operating	C 189		
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation the required one-hour fire rated walls and/or ceilings were compromised in several locations. Holes and penetrations that are not sealed with materials approved for use in one-hour fire rated construction present the possibility that a fire that begins in one space can quickly spread to other areas of the facility. Findings include: a. Unsealed penetrations in the ceiling of the riser room, b. Unrated foam used to seal a hole in the ceiling of the riser room, c. Unsealed penetration in the ceiling of the kitchen at the hood fire suppression system, d. Unsealed penetrations (2) in the ceiling of the Resident Care Coordinator office, e. Unsealed penetration in the ceiling of the mechanical room behind the kitchen, f. Unsealed penetration behind each speaker in the corridor, g. Unsealed penetration in the ceiling of the mechanical room off the utility room in Special Care, h. The sprinkler escutcheon in the Administrator's office did not fit tightly to the			
		A-G	unrated foam was removed and All penetration was filled with fire barrier sealant	7/25/17 to 8/4/17
		H	escutcheon was pushed back in to place so that it fits tightly to ceiling	8/31/17

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL076032	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/20/2017
NAME OF PROVIDER OR SUPPLIER NORTH POINTE ASSISTED LIVING OF ARCHD.		STREET ADDRESS, CITY, STATE, ZIP CODE 303 ALDRIDGE ROAD ARCHDALE, NC 27263		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 ceiling to maintain the fire resistance rating. 2. Based on observation, many corridor doors are prevented from closing quickly and latching to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility. Findings include: a. The smoke barrier door near the Beauty Parlor did not latch when closed. b. The double doors to the resident laundry closet off the corridor in Special Care are damaged and do not latch when closed. c. The door to the employee lounge was hard to close and latch. d. The 20 minute fire rated door between the kitchen and dining room was propped open. e. The door to bedroom 5 would not latch when closed. f. The door to bedroom 3 was propped open. g. The door to bedroom 5 was propped open. h. The door to bedroom 7 was propped open. i. The door to bedroom 10 was propped open. j. The door to Suite F was propped open. k. The door to Suite G was hard to close. l. The door to bedroom 1 does not fit the opening properly to be resistant to the passage of smoke. m. The door to bedroom 4 does not fit the opening properly to be resistant to the passage of smoke. n. The door to bedroom 9 does not fit the opening properly to be resistant to the passage of smoke. o. The door to bedroom 14 does not fit the opening properly to be resistant to the passage of smoke.	C 189		
		A	Adjusted so it will latch	7/31/17
		B	ordered latch hardware	11/10/17
		C	Adjusted so it will latch	8/2/17
		D	removed door props	7/20/17
		E	Adjusted so it will latch	8/2/17
		F-J	removed door props	7/20/17
		K	Adjusted to close easier	11/10/17
		I-O	Add wood shims to doors	8/2/17

If continuation sheet 4 of 4