

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092140	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/09/2018
NAME OF PROVIDER OR SUPPLIER WRENETTES PLACE		STREET ADDRESS, CITY, STATE, ZIP CODE 7029 SAN JAN HILL COURT RALEIGH, NC 27610		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on February 9, 2018 from 10:30 AM to 11:45 AM at the above referenced facility. DHSR records indicate the home was first licensed on June 24, 2008 as a Family Care Home for six (6) ambulatory Residents (Who are able to respond and evacuate without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, the 2006 North Carolina State Building Code - Section 421.2 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 117	Have Current San. And Fire Safety Approvals SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION (n) The home shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. At the time of the survey it was observed during record review that the most current Sanitation Inspection was not available. This rule requires that the Sanitation Inspection be maintained and available for review in the home.	C 117		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092140	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/09/2018
NAME OF PROVIDER OR SUPPLIER WRENETTES PLACE		STREET ADDRESS, CITY, STATE, ZIP CODE 7029 SAN JAN HILL COURT RALEIGH, NC 27610		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 149	Continued From page 1	C 149		
C 149	Outside Entrances/Exits-Handrails At Porches SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (f) All steps, porches, stoops and ramps shall be provided with handrails and guardrails. This Rule is not met as evidenced by: At the time of the survey it was observed that the stairs to the rear porch only had a hand rail on one side. This rule requires hand rails on both sides of the stairs.	C 149		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the grill covers for the exhaust fans in the 2 bathrooms were heavily clogged with dust and lint. This rule requires the mechanical equipment to be maintained in an operating condition.	C 174		
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean	C 183		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092140	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/09/2018
NAME OF PROVIDER OR SUPPLIER WRENETTES PLACE		STREET ADDRESS, CITY, STATE, ZIP CODE 7029 SAN JAN HILL COURT RALEIGH, NC 27610		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 183	Continued From page 2 and safe condition. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that there was a build-up of pine straw on the front roof, and the rear gutters were also clogged with pine-straw and debris. The rule requires that the facility be maintained in a clean condition.	C 183		
W 190	AC-90 Hot Water Relief Discharge 10 NCAC 27G .0301. COMPLIANCE WITH BUILDING CODES (b) Each facility operating under a current license issued by DHSR upon the effective date of this Rule shall be in Compliance with all applicable portions of the North Carolina State Building Code in effect at the time the facility was constructed or last renovated. The discharge from the relief valve shall be piped full-size separately to the crawlspace, 6 inches above the floor, outside of the building, or to another approved terminal as provided for safety pan drain terminals but in no case shall the discharge from the relief valve be trapped When a safety pan is required, the discharge from the relief valves is to be discharged in to a safety pan. It shall be piped full-size of the valve outlet pipe size to a point not more than 2 inches and not less than 1 inch above the pan flood level rim. The pan shall be drained by an indirect waste pipe. Relief valve discharging piping shall be of those materials that are approved for such use.	W 190		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092140	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/09/2018
NAME OF PROVIDER OR SUPPLIER WRENETTES PLACE		STREET ADDRESS, CITY, STATE, ZIP CODE 7029 SAN JAN HILL COURT RALEIGH, NC 27610		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
W 190	Continued From page 3 This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the new hot water heater did have the pressure/temperature relief valve piped to the floor. This does not meet the State Plumbing Code. For all deficiencies listed above provide documentation of completed work in the form of photographs, receipts, invoices, etc. All deficiencies listed above were discussed with on-site staff during the exit interview.	W 190		