

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 11/08/2017
NAME OF PROVIDER OR SUPPLIER AUSTIN ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 511 BUMGARNER INDUSTRIAL DRIVE CONOVER, NC 28613		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 000)	Initial Comments Report of Biennial Follow Up Construction Survey by Dennis Harrell on 11-8-2017. Many deficiencies were not corrected. Further action is required.	(C 000)		
(C 160)	Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition; This Rule is not met as evidenced by: 1. Based on observation, the outside grounds were not maintained in a safe condition. This affects the safety of the residents and staff. Findings on August 23, 2017 and 11-8-2017: a. An open gutter downspout drain pipe was observed at the back corner outside of the med room. The sidewalk at the pipe was broken and pulling away from the building. These two items pose a possible tripping hazard. Interview with Staff revealed that the Owner had begun repairs on the front walks and had not yet started on the back. b. The sidewalk leading to the basketball goal was broken and cracked creating a possible tripping hazard. Interview with Staff revealed that the Owner had begun repairs on the front walks and had not yet started on the back. c. One of the concrete covers for the grease pits had broken leaving a large well approximately 2 cubic feet in size. The grease pits are not near	(C 160)	downspout replaced & sidewalk w/nting to be repaired - weather. sidewalk to basketball goal to be repaired grease pits covers will be replaced	1/12/18 1/12/18 1/12/18

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

VUMJ23

If continuation sheet 1 of 6

If continuation sheet 2 of 6

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 11/08/2017
NAME OF PROVIDER OR SUPPLIER AUSTIN ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 511 BUMGARNER INDUSTRIAL DRIVE CONOVER, NC 28613		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 164}	Continued From page 2 4. Observations revealed that the floors were not kept clean and in good repair. Findings on August 23, 2017 and 11-8-2017: b. The VCT flooring is stained and heavily scuffed throughout the facility. The tile adhesive is seeping through the seams throughout the rooms. The living room tile has scratch marks across the length of the room. Interview with Staff revealed that the Owner had completed some repairs, but had not finished all of the work. New finding on 11-8-2017: There is now a sign on the door to the women's bathroom stating "OUT OF ORDER."	(C 164)	tile adhesive cleaned & tile floor to be stripped waxed toilets fixed	11/31/18 12/23/17
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: New finding on 11-8-2017: Based on observation, the fire alarm system was showing a "Trouble" condition #2. Further investigation revealed that a #2 trouble condition means the secondary telephone line was not working. Fire alarms in "Trouble" may fail to operate properly or notify the local fire department	{C 189}	Fire system repaired Smoke detectors replaced	12/19/17

If continuation sheet 4 of 6

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 11/08/2017
NAME OF PROVIDER OR SUPPLIER AUSTIN ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 511 BUMGARNER INDUSTRIAL DRIVE CONOVER, NC 28613		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 4 b. A section of the exterior siding was loose and separating from the building above and to the left of the entrance at the office. Interview with Staff revealed that the Owner was responsible for completing the repairs. Some of the exterior repairs had been completed and they were working on the remaining citations. c. At the air handling unit outside the office, there are gaps in the soffit panels around the duct penetrations leaving holes for pests to enter. Interview with Staff revealed that the Owner was responsible for completing the repairs. Some of the exterior repairs had been started and they were working on completing the repairs.	{C 189}	ext siding was repaired will repair all voids with appropriate material	12/21/17 1/31/18
{C 195}	Hot Water System SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (d) The hot water system shall be of such size to provide an adequate supply of hot water to the kitchen, bathrooms, laundry, housekeeping closets and soil utility room. The hot water temperature at all fixtures used by residents shall be maintained at a minimum of 100 degrees F (38 degrees C) and shall not exceed 116 degrees F (46.7 degrees C). (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the facility failed to maintain the hot water temperature at a minimum of 100 degrees F at all fixtures used by residents. Findings on August 23, 2017 and 11-8-2017:	{C 195}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 11/08/2017
NAME OF PROVIDER OR SUPPLIER AUSTIN ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 511 BUMGARNER INDUSTRIAL DRIVE CONOVER, NC 28613		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 195}	Continued From page 5 a. The water temperature taken at the Men's bath was 95 degrees F. Interview with Staff revealed that they were getting readings between 100 and 115 degrees. She stated that when the residents showered, the water temperature dropped.	{C 195}	Will do weekly temp checks to verify temp is to maintain 100° & use - If necessary will replace heater	1/31/18