

PRINTED: 01/04/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL070008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 12/13/2017
NAME OF PROVIDER OR SUPPLIER WATERBROOKE OF ELIZABETH CITY		STREET ADDRESS, CITY, STATE, ZIP CODE 143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Billy Bryant and Frank Strickland on December 13, 2017. Records indicate this facility was first licensed on 01/28/1997. The facility is currently licensed for 130 Beds with a 26 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1996 (1997 Revision) Edition of the North Carolina Building Code(s), Institutional Occupancy. Deficiencies were cited that will require a plan of correction.	C 000		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on a review of documentation there is a failure to maintain current (within the calendar year) and required inspection reports on site. Finding on 12/13/2017: a. At the time of the survey a current fire marshal's inspection report was not available for the surveyor's review.	C 111	Fire Marshall was contacted and current reports were requested to be sent on January 10, 2018. Will forward copy upon receipt.	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Dana Rabon Smith

TITLE

Administrator/Director

(X5) DATE

1/19/18

STATE FORM

0199

X4GH21

If continuation sheet 1 of 5

PRINTED: 01/04/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL070008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 12/13/2017
NAME OF PROVIDER OR SUPPLIER WATERBROOKE OF ELIZABETH CITY		STREET ADDRESS, CITY, STATE, ZIP CODE 143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 2 stored oxygen bottles. Improperly stored oxygen could present a danger to the occupants of the facility. Finding on 12/13/2017: a. Oxygen Storage Room - Oxygen bottles were sitting in a flimsy wire rack that was sitting precariously on a shelf mounted approximately 6 1/2 feet above the floor. b. S.C.U. Room 59 - The residents's closet door has a barrel type bolt mounted on the exterior of the door. The closet is large enough that person could be locked inside and would not be able to get out of the closet.	C 166	c166a Oxygen company was notified day after inspection. Rack was secured. C166b Closet lock was removed and family was notified of removal of the lock	12/13/17 12/14/17
C 175	Bedroom Furnishings-Clean Towel, Towel Bar SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (b) Each bedroom shall have the following furnishings in good repair and clean for each resident: (7) individual clean towel, wash cloth and towel bar in the bedroom or an adjoining bathroom; and (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation a towel bar has not been furnished for each resident. Finding on 12/13/2017: a. S.C.U. - Rooms with bathrooms shared by 4 residents did not have a separate towel bar for each resident's use.	C 175	C175a All SCU rooms have been inspected. Hooks and/or towel bars for shared bathrooms will be installed, repaired or replaced.	2/12/18

Division of Health Service Regulation
STATE FORM

6899

X4GH21

If continuation sheet 3 of 5

PRINTED: 01/04/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HA1070008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 12/13/2017
NAME OF PROVIDER OR SUPPLIER WATERBROOKE OF ELIZABETH CITY		STREET ADDRESS, CITY, STATE, ZIP CODE 143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3	C 189		
C 189	Building Equipment Maintained Safe, Operating	C 189		
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on 12/13/2017: a. S.C.U. Room 59 and 56, A.L. Room 17 - The fire sprinkler head escutcheon is missing creating a hole in the fire resistant rated ceiling where it is penetrated by the fire sprinkler pipe. Note: These deficiencies were repaired while the surveyor was on site.		C189a Fire Sprinkler Head Escutcheon in Rooms 17,56,59 repaired while survey was being conducted.	12/13/17
C 199	Exhaust Ventilation	C 199		
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed			

Division of Health Service Regulation
STATE FORM

6899

X4GH21

If continuation sheet 4 of 5

