

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Biennial Survey by Suzanna Fay and Ed Miller conducted on May 22, 2018. Records indicate this facility was first licensed on April 10, 1999. The facility is currently licensed for 90 Beds with a 38 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1996 (1999 Revision) Edition of the North Carolina Building Code(s), Institutional Occupancy and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure.	C 000	Construction Survey 5/22/2108 for Cambridge Hills Assisted Living Biennial Survey Findings and Solutions • Below are the corrective actions that have been corrected.	
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by:	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE


(X6) DATE

STATE FORM

N06H21

If continuation sheet 1 of 14

Cambridge Hills Assisted Living
Interior Main Entrance - Special Locking Wiring Diagram
Prepared March 2016 by Piedmont Door Solutions - Terry Arnold



Attachment 1

PR FILE 201600881

Chatham County Fire Marshal's Inspection Report

Name of Business / Facility <i>Cambridge Assisted Living</i>	Owner or Manager <i>Julie Brown</i>
Address <i>140 Brookshire Frederic Lane</i>	Telephone <i>919 545-9573</i>
<i>Pittsboro, NC 27312</i>	Inspection Date <i>March 24, 2016</i> Time <i>1:50 PM</i>
Building Use Code <i>FAS</i>	Occupancy Type <i>2</i> Square Footage
☒ Original Inspection ☐ First Re-Inspection ☐ Second Re-Inspection ☐ Third Re-Inspection	

BUILDING	COMPLIANCE		
	N/A	Yes	No
Exit Access			
Exit Signs / Lights	/		
Aisle Space	/		
Door Locks		✓	
Ingress / Egress	/		
ELECTRICAL			
Circuit Panel	/		
Fixtures	/		
Permanent Wiring	/		
Extension Cords	/		
FIRE PROTECTION			
Fire Extinguishers	/		
Sprinkler / Standpipe	/		
F.D. Connection	/		
Fire Alarm Systems		✓	
Mod System	/		

FLAMMABLE LIQUIDS	COMPLIANCE		
	N/A	Yes	No
Excessive Amounts	/		
Storage Practices	/		
Hazardous Chemicals	/		
Compatibility	/		
HEATING EQUIPMENT			
Appliances	/		
Vents	/		
Combustible Clearances	/		
Shut Off Valve	/		
Water Heater Relief Valve	/		
Inspection Date			
HOUSEKEEPING			
Rubbish	/		
Inside Combust. Storage	/		
Outside Combust. Storage	/		
Emergency Lighting	/		

Comments / Corrections: *Inspection for special locking device for front main door system accepted as tested*

Thomson Door Solutions
556 Arbor Hills Road, Suite D
Keeneville, NC 27284
(336) 643-3999

Status

☒ In Compliance☐ Not In Compliance

Re-Inspection Date

Amount Due to Chatham County for
Fire Inspections \$ *75.00*

For more information regarding Chatham County's Fire Inspection Program or the statewide fire code, contact the Chatham County Fire Marshal's Office at 545-8342 ; 545-8467 or 542-8259, Monday through Friday, 8 a.m. until 5 p.m.

Owner / Operator

Inspector

Your Comments are welcome and appreciated

Please complete our Customer Service Survey at www.chathamnc.org/fire-marshal

Tear along perforation and send bottom portion with payment.

The amount below is due and payable to the Chatham County Building Inspections Department within 15 days following the date of inspection.

Business

Name *Cambridge Hill Assisted Living*

Amount Due

Amount Remitted

MAIL PAYMENT TO:

Chatham County Building Inspections Office

PO Box 548

Pittsboro, N. C. 27312-0548

FAS
P/FAS
March 24, 2016



FUNDAMENTALS OF FIRE ALARM SYSTEMS

72-31

FIRE ALARM SYSTEM RECORD OF COMPLETION		
Name of protected property: <u>Cambridge Hills Assisted Living</u>		
Address: <u>140 Brookstone Dr. Pittsboro, NC</u>		
Representative of protected property (name/phone): <u>Julie Brown 919-545-9573</u>		
Authority having jurisdiction: <u>Chatham County Fire Marshall</u>		
Address/telephone number: _____		
	Organization name /phone	Representative name /phone
Installer _____	<u>SimplexGrinnell</u>	<u>919-279-6400</u>
Supplier _____	<u>SimplexGrinnell</u>	
Service organization _____	<u>SimplexGrinnell</u>	
Location of record (as-built) drawings: <u>On Site</u>		
Location of operation and maintenance manuals: _____		
Location of test reports: _____		
A contract for test and inspection in accordance with NFPA standard(s) _____		
Contract No(s): <u>N/A</u>	Effective date: <u>N/A</u>	Expiration date: <u>N/A</u>
System Software		
(a) Operating system (executive) software revision level(s): _____		
(b) Site-specific software revision date: _____		
(c) Revision completed by: _____		
	(name)	(firm)
1.Type (s) of System or Service		
<u>_____</u> <u>NFPA 72, Chapter 6 Local</u>		
If alarm is transmitted to location(s) off premises, list where received: _____		
<u>_____</u> <u>NFPA 72, Chapter 8 - Remote Station</u>		
Telephone numbers of the organization receiving alarm: _____		
Alarm: _____		
Supervisory: _____		
Trouble: _____		
If alarms are retransmitted to public fire service communications centers or others, indicate location and telephone numbers of the organization receiving alarm: _____		
Indicate how alarm is retransmitted: _____		
<u>_____</u> <u>NFPA 72, Chapter 8 - Proprietary</u>		
Telephone numbers of the organization receiving alarm: _____		
Alarm: _____		
Supervisory: _____		
Trouble: _____		
If alarms are retransmitted to public fire service communications centers or others, indicate location and telephone numbers of the organization receiving alarm: _____		
Indicate how alarm is retransmitted: _____		
☒ <u>NFPA 72, Chapter 9 - Central Station</u>		
Prime contractor _____		
Central station location _____		

(NFPA 72, 1 of 4)

FIGURE 4.5.2.1 Record of Completion.

72-32

NATIONAL FIRE ALARM CODE

Means of transmission of signals from the protected premises to the central station:

☐ McCulloch ☐ Multiplex ☐ One-way radio
☒ Digital alarm communicator ☐ Two-way radio ☐ Others

Means of transmission of alarms to the public fire service communications center:

(a) _____
 (b) _____

System location: _____

NFPA 72, Chapter 9 Auxiliary

Indicate type of connection: ☐ Local energy ☐ Shunt ☐ Parallel telephone

Location of telephone number for receipt of signals: _____

2. Record of System Installation

(Fill out after installation is complete and wiring is checked for opens, shorts, ground faults, and improper branching, but prior to conducting operational acceptance tests.)

This system has been installed in accordance with the NFPA standards as shown below, was inspected by Jeffrey Wilkinson on 3/24/16 includes the devices shown in 5 and 6, and has been in service since N/A

☒ NFPA 72, Chapters 1 2 3 4 5 6 7 8 9 10 11 (circle all that apply)

☒ NFPA 70, National Electrical Code, Article 760

☒ Manufacturer's instructions

☐ Other (specify) N/A

Signed: [Signature] Date: 3/24/16

Organization: SimplexGrinnell

3. Record of System Operation

Documentation in accordance with Inspection Testing Form, Figure 10.6.2.3, is attached N/A
 All operational features and functions of this system were tested by Jeffrey Wilkinson date 3/24/16
 and found to be operating properly in accordance with the requirements of:

☒ NFPA 72, Chapters 1 2 3 4 5 6 7 8 9 10 11 (circle all that apply)

☒ NFPA 70, National Electrical Code, Article 760

☒ Manufacturer's instructions

☐ Other (specify) N/A

Signed: [Signature] Date: 3/24/16

Organization: SimplexGrinnell

4. Signaling Line Circuits

Quantity and class of signaling line circuits connected to system (see NFPA 72, Table 6.6.1):

Quantity: _____ Style: _____ Class: _____

(NFPA 72, 2 of 4)

FIGURE 4.5-2.1 Continued

FUNDAMENTALS OF FIRE ALARM SYSTEMS

72-33

5. Alarm-Initiating Devices and Circuits

Quantity and class of initiating device circuits (see NFPA 72, Table 6.5):

Quantity: _____ Style: _____ Class: _____

MANUAL

(a) Manual stations Noncoded _____ Transmitters _____ Coded _____ Addressable _____

(b) Combination manual fire alarm and guard's tour coded stations _____

AUTOMATIC

Coverage: Complete _____ Partial _____

Selective _____ Nonrequired _____

(a) Smoke detectors Ion _____ Photo _____ Addressable _____

(b) Duct detectors Ion _____ Photo _____ Addressable _____

(c) Heat detectors FT _____ RT _____ FT/RT _____ RC _____ Addressable _____

(d) Sprinkler waterflow indicators: Transmitters _____ Noncoded _____ Coded _____ Addressable _____

(e) The alarm verification feature is disabled _____ or enabled _____ changed from _____ seconds to _____ seconds

(f) Other (list): _____

6. Supervisory Signal-Initiating Devices and Circuits (use blanks to indicate quantity of devices)**GUARD'S TOUR**

(a) _____ Coded stations

(b) _____ Noncoded stations

(c) _____ Compulsory guard's tour system comprised of _____ transmitter stations and intermediate stations

Note: Combination devices are recorded under 5(b), Manual, and 6(a), Guard's Tour.

SPRINKLER SYSTEM

Check if provided

(a) _____ Valve supervisory switches

(b) _____ Building temperature points

(c) _____ Site water temperature points

(d) _____ Site water supply level points

Electric fire pump:

(e) _____ Fire pump power

(f) _____ Fire pump running

(g) _____ Phase reversal

Engine-driven fire pump:

(h) _____ Selector in auto position

(i) _____ Engine or control panel trouble

(j) _____ Fire pump running

ENGINE-DRIVEN GENERATOR:

(a) _____ Selector in auto position

(b) _____ Control panel trouble

(c) _____ Transfer switches

(d) _____ Engine running

Other supervisory function(s) (specify): _____

(NFPA 72, 3 of 4)

FIGURE 4.5-2.1 Continued

72-34

NATIONAL FIRE ALARM CODE

7. Annunciator(s)

Number: _____ Type: _____ Location: _____

8. Alarm Notification Appliances and Circuits

NFPA 72, Chapter 6 - Emergency Voice/Alarm Service

Quantity of voice/alarm channels: _____ Single: _____ Multiple: _____

Quantity of speakers installed: _____ Quantity of speaker zones: _____

Quantity of telephones or telephone jacks included in system: _____

Quantity and the class of notification appliance circuits connected to system (see NFPA 72, Table 6.7):

Quantity: _____ Style: _____ Class: _____

Types and quantities of notification appliances installed:

(a) Bells _____ With Visible _____

(b) Speakers _____ With Visible _____

(c) Horns _____ With Visible _____

(d) Chimes _____ With Visible _____

(e) Other _____ With Visible _____

(f) Visible appliances without audible: _____

9. System Power Supplies

(a) Fire Alarm Control Panel: Nominal voltage: 120V Current rating: 9A

Overcurrent protection: Type: Trip Breaker Current rating: 20A

Location: _____

(b) Secondary (standby): ☒ Storage battery: _____ Amp-hour rating: 10ah

Calculated capacity to drive system, in hours: 24

Engine-driven generator dedicated to fire alarm system: _____

Location of fuel storage: _____

(c) Emergency system used as backup to primary power supply: _____

Emergency system described in NFPA 70, Article 700: _____

10. Comments

Frequency of routine tests and inspections, if other than in accordance with the referenced NFPA standard(s):

N/A

System deviations from the referenced NFPA standard(s) are: This Certifies one (1) magnetic door holder and alarm release function. All devices were tested and function properly.

(signed) for installation contractor/supplier (date) Technician 3/24/16

(signed) for alarm service company (date) Technician 3/24/16

(signed) for central station (date) (date) (date)

Upon completion of the system(s) satisfactory test(s) witness if required by the authority having jurisdiction:

(signed) representative of the authority having jurisdiction (date) Chatham County 3/24/2016

(date) Fire Inspector (date)

(NFPA 72, 4 of 4)

FIGURE 4.3.2.1 Continued

MEANS OF EGRESS

3.3. A wiring diagram and system components location map shall be provided under glass adjacent to the fire alarm panel.

3.4. An on/off emergency release switch(es) must be capable of interrupting power to all electromagnetically locked doors in the facility. Release switch(es) shall be located and identified at each nurses station serving the locked unit and any other control station responsible for the evacuation of the occupants of the locked units which are manned 24 hours.

3.5. An additional emergency release switch shall be provided for each locked door and located within 3 feet (919 mm) of the door, and shall not depend on relays or other devices to cause the interruption of power.

3.6. Any required emergency release switch shall interrupt power to the locking device(s). If any required emergency release switch is of the locking type, all staff that are responsible for the evacuation of the occupants of the locked unit must carry emergency release switch keys. Additional convenience release devices may be provided.

4. Each special locking installation shall be approved by the appropriate fire and building inspection authority prior to installation, after installation, and prior to initial use and reviewed periodically thereafter.

5. Emergency lighting shall be provided at the door.

1008.1.9.7 Delayed egress locks. *Approved, listed*, delayed egress locks shall be permitted to be installed on doors serving any occupancy except Group A, E and H occupancies in buildings that are equipped throughout with an automatic sprinkler system in accordance with Section 903.3.1.1 or an approved automatic smoke or heat detection system installed in accordance with Section 907, provided that the doors unlock in accordance with Items 1 through 6 below. A building occupant shall not be required to pass through more than one door equipped with a delayed egress lock before entering an exit.

1. The doors unlock upon actuation of the automatic sprinkler system or automatic fire detection system.
2. The doors unlock upon loss of power controlling the lock or lock mechanism.
3. The door locks shall have the capability of being unlocked by a signal from the fire command center.
4. The initiation of an irreversible process which will release the latch in not more than 15 seconds when a force of not more than 15 pounds (67 N) is applied for 1 second to the release device. Initia-

tion of the irreversible process shall activate an audible signal in the vicinity of the door. Once the door lock has been released by the application of force to the releasing device, relocking shall be by manual means only.

Exception: Where approved, a delay of not more than 30 seconds is permitted.

5. A sign shall be provided on the door located above and within 12 inches (305 mm) of the release device reading: PUSH UNTIL ALARM SOUNDS. DOOR CAN BE OPENED IN 15 (30) SECONDS.

6. Emergency lighting shall be provided at the door.

1008.1.9.8 Electromagnetically locked egress doors. Doors in the means of egress that are not otherwise required to have panic hardware in buildings with an occupancy in Group A, B, E, M, R-1 or R-2 and doors to tenant spaces in Group A, B, E, M, R-1 or R-2 shall be permitted to be electromagnetically locked if equipped with listed hardware that incorporates a built-in switch and meet the requirements below:

1. The listed hardware that is affixed to the door leaf has an obvious method of operation that is readily operated under all lighting conditions.
2. The listed hardware is capable of being operated with one hand.
3. Operation of the listed hardware releases the electromagnetic lock and unlocks the door immediately.
4. Loss of power to the listed hardware automatically unlocks the door.

1008.1.9.9 Locking arrangements in correctional facilities. In occupancies in Groups A-2, A-3, A-4, B, E, F, I-2, I-3, M and S within correctional and detention facilities, doors in means of egress serving rooms or spaces occupied by persons whose movements are controlled for security reasons shall be permitted to be locked when equipped with egress control devices which shall unlock manually and by at least one of the following means:

1. Activation of an automatic sprinkler system installed in accordance with Section 903.3.1.1;
2. Activation of an approved manual alarm box; or
3. A signal from a constantly attended location.

1008.1.9.10 Stairway doors. Interior stairway means of egress doors shall be openable from both sides without the use of a key or special knowledge or effort.

Exceptions:

1. Stairway discharge doors shall be openable from the egress side and shall only be locked from the opposite side.
2. This section shall not apply to doors arranged in accordance with Section 403.5.3 of the International Building Code.

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 111	Continued From page 2 This Rule is not met as evidenced by: 1. Review of records revealed that the sprinkler inspection report had comments regarding the test. Findings on May 22, 2018: a. The sprinkler report dated May 2, 2018 stated that the "customer did not want full flow trip of systems due to leaks." Full flow tests should be conducted every three years. Verify that the facility is in compliance with testing.	C 111	C111- Full flow test was conducted on June 12th, 2018, by Fess Fire Protection. See copy of report. Attachment 2. Maintenance Director was retrained 6/15/2018 on the requirements for conducting full flow testing per regulations. Executive Director will review all inspections to ensure compliance has been met.	
C 116	Plans Submittals and Approvals SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0304 PLANS AND SPECIFICATIONS (a) When construction or remodeling of an adult care home is planned, two copies of Construction Documents and specifications shall be submitted by the applicant or appointed representative to the Division for review and approval. As a preliminary step to avoid last minute difficulty with final plan approval, Schematic Design Drawings and Design Development Drawings may be submitted for approval prior to the required submission of Construction Documents. (b) Approval of Construction Documents and specifications shall be obtained from the Division prior to licensure. Approval of Construction Documents shall expire after one year unless a building permit for the construction has been obtained. (c) If an approval expires, renewed approval shall be issued by the Division, provided revised Construction Documents meeting all current regulations, codes and standards are submitted by the applicant or appointed representative and reviewed by the Division.	C 116	C116- A. Washer and Dryer on 100 hall have been removed on 6/6/2018. B. The original door is in place for the space and should meet the requirement for the original approved intended use of the space.	



CHARLESTON
353 North American Street
North Charleston, SC 29412
(843) 321-6000 • (800) 350-6000

CHARLOTTE
3001 Mangrove Avenue
Charlotte, NC 28209
(704) 321-6000 • (800) 350-6000

RALEIGH-DURHAM
331 International Drive
Raleigh, NC 27607
(919) 661-0800 • (800) 350-6000

Bill To: Cambridge Hills
140 Brookstone Ln.
Pittsboro, NC

Phone: 919-545-9573

FESS Fire Protection is responsible for the work and materials described below, subject to the terms and conditions outlined below. Contact the owner of the installation.

Indicate FESS to proceed with the work.

Lucas R James Gerber
Print Name Signature

WORK ORDER # Service Date: 6/12/18

Technician: Laryce Barnes

Service Address: 140 Brookstone Ln.
Pittsboro, NC

Contact Name: John Brown Mike Walters

Contact Number: 919-545-9573

Contract Work ☐

Time & Materials ☐

Emergency Call ☐

Description of Work: Arrived to perform full flow trip on 2 dry systems.
FESS Fire Protection is not responsible for any damages that may
occur from the tripping of dry valves.

Travel Time / Distance: Overnight Stay Required ☐ YES ☒ NO

VEHICLE USED	QTY	MATERIALS USED	QTY

Notes: Full flow tripped dry systems, left
water pressure on for 30 min, appears to
not be any leaks.

Labor

TECH NAME	ST	OT	DT
<u>Laryce Barnes</u>	<u>8</u>		
<u>Ken Cuevas</u>	<u>8</u>		

Job # CI-007-1

Left System In Service ☒ YES ☐ NO	Main Drain Test Performed ☒ YES ☐ NO	1st Static <u>70</u> Residual <u>45</u> 2nd Static <u>65</u>	Return Trip Required ☐ YES ☒ NO	Lift Rental ☐ YES ☒ NO	Equipment Called in for RETURN/PICKUP ☐ YES ☒ NO	Valve Seal # <u> </u>
--	---	--	--	--	---	-----------------------------------

NOTE: FIELD WORK ORDER IS EXPRESSLY SUBJECT TO AND INCLUDES THE TERMS AND CONDITIONS ON THE REVERSE SIDE HEREOF.

Customer Signature: [Signature]
(Customer Signature confirms all products and services listed have been returned to customer)

Print Name: Michael Walters Date: 6/12/2018



Thanks for Your Business!



JOHNSON'S AUTOMATIC SPRINKLER
P.O. Box 1307
Mooresville, North Carolina 27550
Phone (919)469-1872 / Fax (919)275-4157
Contractor's License: NC#25502 / SC FSC 1812
Website - www.jasnet.net

Report To : Cambridge Hills

Street: 140 Brookstone Ln.

City & State: Pittsboro, N.C.

Zip: 27312

Attn: Michael Walters

Building or Location: 140 Brookstone Ln. Pittsboro, N.C.

Inspector: Laverne Rames

Date: 6/12/2018

Systems: 1 and 2

Type of Inspection:

Quarterly: ☐Semi-Annual: ☐Annual: ☒

1. General		YES	N/A**	NO**
a.	Is the building occupied according to information furnished by owner or owner's representative?	X		
b.	Is occupancy same as previous inspection according to information furnished by owner or owner's representative?	X		
c.	Are all systems in service?	X		
d.	Are all fire protection systems same as last inspection according to information furnished by owner or owner's representative?	X		
e.	In areas protected by wet system, does the building appear to be properly heated in all areas, including blind attics, perimeter areas and are all exterior openings protected against entrance of cold air?		X	
f.	Are all required spare heads, wrenches, signage, hydraulic placards, and sprinkler head sticker(s) present?		X	
g.	Has piping had an internal inspection within the last 5 years?		X	
h.	Has drypipe action/deluge system piping been leak tested within the last 3 years? Date?		X	
2. CONTROL VALVES (See section 11)				
a.	Are all sprinkler system main control valves open?	X		
b.	Are all other valves in proper position?	X		
c.	Are all control valves in good condition and sealed or supervised?	X		
d.	All valves appear to be conditioned space above 40° F?	X		
3. WATER SUPPLIES (See section 12)				
a.	If backflow device is present, test and condition satisfactory?		X	
b.	Backflow device forward flow test conducted: Date: GPM:		X	
c.	Was a water flow test made and results satisfactory?		X	
4. TANKS, PUMPS, FIRE DEPT. CONNECTIONS				
a.	Are fire pumps, gravity tanks, reservoirs and pressure tanks in good condition and properly maintained?		X	
b.	Are fire dept. connections in satisfactory condition, coupling free, caps in place and check valves tight?	X		
5. WET SYSTEMS				
a.	Are alarm valves, water-flow indicators and retards in satisfactory condition?	X		
6. DRY SYSTEMS (See Section 14)				
a.	Is dry valve in service and in good condition?	X		
b.	Is air pressure and priming water level normal?	X		
c.	Is air compressor in good condition if equipped?	X		
d.	Were low points drained during fall and winter inspections?	X		
e.	Are quick-opening devices in service?	X		
f.	Have dry valves been trip tested satisfactorily as required? ☐ Partial ☒ Full	X		
g.	Are dry valves adequately protected from freezing?	X		
h.	Are valve house and heater condition satisfactory?	X		
7. PREACTION & DELUGE SYSTEMS				
a.	Were valves tested as required?		X	
b.	Were all heat responsive systems tested and results satisfactory?		X	
c.	Were supervisory features tested and results satisfactory?		X	
8. ALARMS				
a.	Are water motor and bong test satisfactory?		X	
b.	Is electric alarm test satisfactory?	X		
c.	Is supervisory alarm service test satisfactory?	X		

Rev 03/17

** Explain "NO" answers on Page 2

* Not Applicable



dba JOHNSON'S AUTOMATIC SPRINKLER
P.O. Box 1337
Millsboro, North Carolina 27568
Phone (919)484-1672 / Fax (919)275-4157
Contractor's License: NC625532 / SC FSC 1812
Website: www.jessinc.net

Building or Location: 140 Brookstone Ln. Pittsboro, N.C.

Date: 6/12/2018

Systems: 1 and 2

Inspector: Lanya Barnes

9. SPRINKLERS - PIPING		YES	N/A*	NO**
a. Are all sprinklers appear to be in good condition, not obstructed, and free of corrosion or loading?			X	
b. All wet sprinklers less than 50 years old, dry sprinklers less than 10 years old, and quick response sprinklers less than 20 years old?			X	
c. Are extra sprinklers readily available?			X	
d. Is condition of piping, drain valves, check valves, hangers, pressure gauges, open sprinklers, strainers satisfactory?			X	

10. SYSTEMS							
System	Wet	Dry	PAV	Deluge	Size	Make	Model
1		X			8	Viking	F-1
2		X			6	Viking	F-1

11. CONTROL VALVES		#	Type?	OPEN		SECURED		EXERCISED		SIGNS	
				Yes	No	Yes	No	Yes	No	Yes	No
City Connection Control Valve				Yes	No	Yes	No	Yes	No	Yes	No
Tank Control Valve				Yes	No	Yes	No	Yes	No	Yes	No
Pump Control Valve				Yes	No	Yes	No	Yes	No	Yes	No
Backflow Device	2	OS&Y		Yes	No	Yes	No	Yes	No	Yes	No
Sectional Control Valve				Yes	No	Yes	No	Yes	No	Yes	No
System Control Valve	2	Grooved butterfly valves		Yes	No	Yes	No	Yes	No	Yes	No

12. WATER FLOW TEST							
Water Pressure?		City	65	PSI	Tank		PSI
				Fire Pump			
System Located	Size Test Pipe	Pressure Before	Flow Pressure	Pressure After	Air Pressure Trip Point	Waterflow (Seconds)	Trip time (Seconds)
1	2	85	40	80	20	70	6
2	2	70	45	66	33	52	8

13. Explanation of any "NO" answers/Comments:

14. Recommended improvements:

15. Miscellaneous Notes:
 Is heat trace present and appear to be operating normally? Yes ☐ No ☒ N/A ☐
 Date of dry system full trip: 6/12/2021

Rev 03/17 ** Explain "NO" answers on Page 1 in item #14 * Not Applicable

Inspector Signature: Lanya Barnes Date: 6/12/2018 Accepted by: [Signature]



JOHNSON'S AUTOMATIC SPRINKLER

P.O. Box 1307

Morrisville, North Carolina 27560

Phone (919)408-1222 / Fax (919)275-4157

Contractor's License: NC#23332 / SC F60 1012

Website - www.jasinc.net

Building or Location: 140 Brookstone Ln. Pittboro

Date: 6/12/2018

Systems: 1 and 2

Inspector: Lance Barnes

Explanation of any "NO" answers/Comments (Continued)

1) Full trip only, annual inspection done on 6/2/18.

2) After tripping systems left water pressure on for 30 minutes. Didn't see any water leaks coming below ceiling."

Comments (Continued)

REV 03/17

Inspector Signature:

Date:

6/12/2018

Accepted by:

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO			STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 116	Continued From page 3 (d) Any changes made during construction shall require the approval of the Division to assure that licensing requirements are maintained. (e) Completed construction or remodeling shall conform to the requirements of this Section including the operation of all building systems and shall be approved in writing by the Division prior to licensure or occupancy. Within 90 days following licensure, the owner or licensee shall submit documentation to the Division that "as built" drawings have been received from the builder. (f) The applicant or designated agent shall notify the Division when actual construction or remodeling starts and at points when construction is 50 percent, 75 percent and 90 percent complete and upon final completion. This Rule is not met as evidenced by: 1. Observations revealed that the facility conducted remodeling without approval of DHSR Construction nor of the local building official. Findings on May 22, 2018: a. 100 Hall - the resident tub bathroom was remodeled to house laundry equipment. Plans were not submitted to DHSR Construction and only a verbal approval was received from the local building official which was later rescinded. An alternative location was discussed with the Surveyors. Plans must be submitted to DHSR Construction Section and the local Building Inspections Department for review and approval prior to construction. b. 100 Hall laundry - the room exceeds 100 square feet and the door is not a 45 minute rated door.	C 116			

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 150	Continued From page 4	C 150		
C 150	Corridors-Free of equipment and Obstructions SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Observations revealed that the corridors were not free of obstructions. Findings on May 22, 2018: a. SCU - at the time of survey, the magnetic locking system was not working due to fire alarm trouble. The exits were blocked by furniture, a wheelchair and a plant. Items were removed at the time of survey. b. 200 Hall - narrow corridor by private dining - a ladder was stored in the hallway.	C 150	C150- A. A staff training was held on May 24th to review and refresh staff with appropriate protocol when fire alarm goes down, or is set off. See copy of report. Attachment 3 B. The ladder in the hallway belonged to the contractor working to diagnose issue with fire alarm panel. The ladder was removed when finished his work.	
C 153	Exit Door Locks-Single Hand Motion SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (3) All exit door locks shall be easily operable, by a single hand motion, from the inside at all times without keys; and This Rule is not met as evidenced by: 1. Observations revealed that all exit door locks are not easily operable by single hand motion.	C 153	C153- A. Exit door hardware replaced by a single hand motion door knob.	

Attachment 3

5/24/2018

When the fire alarms go down, several things need to go in to place immediately to assure the safety of our residents:

- The 100 hall Exit doors unlock. Staff on 100 hall need to start monitoring all doors and residents. Staff includes, but is not limited to; Nursing staff, Activity staff, Maintenance, Housekeeping, or Dietary. A check of all residents needs to be completed at least every 30 minutes to assure no one has gone out through any of the doors.
- DO NOT PLACE ANYTHING in front of fire doors under ANY circumstances. Fire Door walkways must stay clear AT ALL TIMES. No exceptions!
- A staff member in charge needs to assign someone to do 30 minute walk through of the entire building and start the Fire Watch Log immediately.
- Notify Luis in Maintenance, or any other Department Head that the Fire Alarm system has stopped working.

The Fire Watch will continue until the Fire Alarms are back online and working. It must be done every 30 minutes around the clock.

Cambridge Hills Assisted Living

Education Sign in sheet

Program: Safety - Fire Drills

Instructor: Lisa Ridge Health + Wellness Director

AV Aides: see attached handout

Location: 300 hall activity room

Date: 5/24/18

Program Length: 1 hr Time: _____

Program Objectives: Understanding protocol + procedure

NAME-PRINT	NAME-SIGNATURE	TITLE
Lisa Ridge	Lisa Ridge LPA	HCD
Regina Bartshe	Regina Bartshe	ASST Admin
Luz M. Naranga	Luz M. Naranga	Housekeeper
Luis Restrepo	Luis Restrepo	Maintenance Director
Patricia Suen	Patricia Suen	Housekeeping
Adey Abelaich	Adey Abelaich	laundry
BILIO APILARDO	BILIO APILARDO	MAINT
Crystal Hawkins	Crystal Hawkins	med Tech/CNA
Mamie Cuyler	Mamie Cuyler	CNA
Kalina Walker	Kalina Walker	med Tech/CNA
Kenneth Fawcett	Kenneth Fawcett	med tech
Charidy Thompson	Charidy Thompson	CNA
Raymond Goldston JR	Raymond Goldston JR	medtech
Shirley mecos	Shirley mecos	med-tech
Theresa Mesta	Theresa Mesta	CNA

Cambridge Hills Assisted Living

Education Sign in sheet

NAME-PRINT	NAME-SIGNATURE	TITLE
Cheryl Orshack	Cheryl Orshack	Activity Director
Palmeri Susan	Palmeri Susan	House Keeping
Monna Harris	Monna Harris	CNA
Tony Lassiter	Tony Lassiter	Housekeeping / Maintenance
Angela deNunck	Angela deNunck	Activity Manager
Richard Walters	Richard Walters	Executive Director
Ronnie P. Stubbs	Ronnie P. Stubbs	HQ Dir / Mkt Dir
Raymond Goldston Jr	Raymond Goldston Jr	Med Tech
Dorcel Hall	Dorcel Hall	Dietary aide
Luz Na	Luz Na	
Ladeshia Green	Ladeshia Green	PCA
Sherry Stinson	Sherry Stinson	Med-Tech
Phiscilla Goldston	Phiscilla Goldston	Med-Tech
Sumatra Oulton	Sumatra Oulton	CNA
Susan Worley	Susan Worley	Hairdresser
Monica Spore	Monica Spore	Rt Manager
Kasie May	Kasie May	CNA
Kimberly Hoxley	Kimberly Hoxley	Dietary aide
Annie Brim	Annie Brim	Dietary
Rosa Brillant	Rosa Brillant	Dietary
Madison Tilley	Madison Tilley	Intern
Ashley Martin	Ashley Martin	Activity Director
Terron Bethea	Terron Bethea	PCA

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL015019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 6 (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility was not maintained free from hazards. Oxygen bottles that are improperly stored may present a danger to the occupants of the facility. Findings on May 22, 2018: a. Room 221 - there were seven oxygen bottles stored in a Coke crate. 2. Observations revealed that the facility is not maintained free of hazards. Findings on May 22, 2018: a. 100 Hall Clean Linen - the doors have a barrel bolt latch on the exterior of the closet. The closet is large enough for a person to occupy making it possible to lock an individual in the closet. b. 100 Hall Exit by Room 101 - the cover for the pushbar housing was missing as well as the end cap. The sharp edges could cause injury.	C 166	C166- 1A. Oxygen bottles were removed from resident's room and returned to vendor. Resident no longer on oxygen. Other residents now have appropriate cylinder holders. 2A. The barrel bolt latch has been removed from the closet containing 100 hall clean linen. 2B. The end cap housing cover has been put on the panic release bar by Room 101.	
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of	C 185	C185- A. Fire rehearsals are completed and logged. Each rehearsal is now including a description of the drill and purpose. See attachment 4.	

Attachment 4

Cambridge Hills Assisted Living
Fire Drill ReportDate 5/29/18Time 11:06Shift DayInstructor Jules PostageTitle Maintenance DirectorResponse time 11:08

Employee name (must be legible)

Angela de MuinckPatricia S. SmithPatsy CrossAmber MooreCharity ThompsonABILIO ABELARDESKalina WamblerKim FyanLeake WatsonKernory FousheeAngel McMathKelly GueastaSam BullardDorset HazardKimberly HarkerCheryl OushealAnnie BrimJasmine DominguezRachael AllmanLuz Noran p. S.Rajina BritsheMO WATTony JovitaLisa RidgeShirley MicalDescription of rehearsal 300 Hallway StairroomResponse time - 2 minsFire Drill training, staff responded to locator with extinguishers, Alarm reset when test was over

PRINTED: 06/06/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 186	Continued From page 6 (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility was not maintained free from hazards. Oxygen bottles that are improperly stored may present a danger to the occupants of the facility. Findings on May 22, 2018: a. Room 221 - there were seven oxygen bottles stored in a Coke crate. 2. Observations revealed that the facility is not maintained free of hazards. Findings on May 22, 2018: a. 100 Hall Clean Linen - the doors have a barrel bolt latch on the exterior of the closet. The closet is large enough for a person to occupy making it possible to lock an individual in the closet. b. 100 Hall Exit by Room 101 - the cover for the pushbar housing was missing as well as the end cap. The sharp edges could cause injury.	C 166	C166- 1A. Oxygen bottles were removed from resident's room and returned to vendor. Resident no longer on oxygen. Other residents now have appropriate cylinder holders. 2A. The barrel bolt latch has been removed from the closet containing 100 hall clean linen. 2B. The end cap housing cover has been put on the panic release bar by Room 101.	
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of	C 185	C185- A. Fire rehearsals are completed and logged. Each rehearsal is now including a description of the drill and purpose. See attachment 4.	

Attachment 4

Cambridge Hills Assisted Living
Fire Drill Report

Date 5/29/18 Time 11:06 Shift Day
 Instructor Jess Pestrop Title Maintenance Director
 Response time 11:08

Employee name (must be legible)

<u>Angela de Muinck</u>	<u>Patricia Scumier</u>
<u>Patsy Cross</u>	<u>Amber Moore</u>
<u>Charity Thompson</u>	<u>Abilio Adelores</u>
<u>Kalina Wenter</u>	<u>Kim Fyan</u>
<u>Livale Watson</u>	<u>Kemond Foushee</u>
<u>Angel McMath</u>	<u>Kelly Gueastad</u>
<u>Sam Bullock</u>	<u>Dorset Hazard</u>
<u>Kimberly Harker</u>	<u>Cheryl Overholt</u>
<u>Annie Brem</u>	<u>Jasmine Dominguez</u>
<u>Rachael Allman</u>	<u>Luz Noran p. S.</u>
<u>Regina Britton</u>	<u>MO Wat</u>
<u>Tony Joviter</u>	<u>Lisa Ridge</u>
<u>Shirley Mical</u>	

Description of rehearsal 300 Hallway Sup room
 Response time - 2 mins
 Fire Drill training, staff responded to locator
 with extinguishers, Alarm reset when test was over

Cambridge Hills Assisted Living Fire Drill Report

Date _____ Time _____ Shift _____

Instructor _____ Title _____

Response time _____

Employee name (must be legible)

_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Description of rehearsal _____

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO			STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 185	Continued From page 7 social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Review of records revealed that the fire rehearsal documentation did not meet the requirements of the licensure rules. Findings on May 22, 2018: a. The fire rehearsal logs did not include a brief description of what the rehearsal involved.	C 185			
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and testing there is failure to maintain the facility's emergency fire alarm system devices and equipment in a safe operating condition. All the occupants of the facility could be effected if the equipment failed to alert the occupants in case of a fire. Findings on May 22, 2018:	C 189			

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(C1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(C2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(C3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(C4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(C5) COMPLETE DATE
C 189	Continued From page 8 a. At the time of survey, the fire alarm system was in trouble. The system was partially shut down. Areas down included the main corridor and the SCU. The panel indicated the trouble code "6" which stated that it was a ground fault problem. Interview with Staff revealed that the system failed at approximately 11:00 am. A fire watch had been initiated. The Fire Marshal was notified. Maintenance had contacted the fire alarm vendor and they arrived at 4:15 pm. A call from staff on May 23, 2018 at 7:55 am revealed that the central air was working, but the panel needed additional parts to complete. Confirmation on Friday, May 25, 2018 revealed that the panel had been repaired on Thursday, May 24. 2. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device used to keep a door open is an impediment to quickly closing the door. The occupants in the facility could be effected if doors cannot be closed as required so as to limit the spread of smoke and/or fire to the area of origin. Findings on May 22, 2018: a. The cross corridor doors to the 300 hall were propped open using a rag. 3. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings or walls could allow fire and smoke to spread beyond the area of origin. Findings on May 22, 2018: a. 300 Hall Mechanical - there are two unsealed penetrations over the HVAC panel.	C 189	C189. 1A. All fire alarm systems are up and running properly. 2A. All cross corridor doors that were propped open to 300 hall were removed of props. 3A. All penetrations have been filled with fire caulk. 4A. The 300 hall Dining room doors now latches completely. 5A. All storage closets have been marked with a 18 inch line from the ceiling to ensure items are not stored higher than the line. 6A. All HVAC dampers in the building have been removed, cleaned inside and out of dust and dirt. 7A. Kitchen drain pipes have been cut to maintain a 2 inch air gap. 8A. The exit signs have been checked and adjusted to show the correct arrow to the exit. 9A. The emergency light was replaced and now works correctly. All lights have now been put on a monthly check.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1203 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 9 b. Boiler Room - there were seven unsealed penetrations where the copper pipes entered the ceiling and the fire caulk has deteriorated and separated in one of the cable bundles for the data wiring. c. Boiler Room - there was a small, 1/2" diameter hole in the ceiling of the boiler room. d. Boiler Room - there is a 6"x 12" hole at the base of the wall. e. Boiler Room - there is a 15" x 30" patch on the ceiling. The patch appears to be of suitable material, but does not appear to have been caulked and sealed. f. Boiler Room - there are three 4" PVC pipes that penetrate the ceiling which are sealed with fire caulk, but do not have collars. f. Pantry - there is a 1" copper water pipe penetrating the ceiling. The hole has not been sealed with fire caulk. g. 300 Hall Dining - there is a hole at the light in the high portion of the ceiling. h. 300 Hall Dining - there is a small penetration at the camera wiring. i. 300 Hall corridor - the sheetrock tape has separated at the edge of the coffered ceiling outside of Room 304. j. 300 Hall Clean Linen - there is a small 1" diameter hole at the light fixture. k. 308 - there is a gap around the sprinkler head. l. 300 Hall - there is a hole in the wall at the drinking fountain where the water line penetrates. m. Records room - there are holes in the ceiling where two copper pipes penetrate the ceiling. n. Kitchen - the escutcheon plate for the sprinkler head near the dining door has dropped leaving an opening in the ceiling. o. Dining Room - the sprinkler head near the kitchen door has shifted leaving a hole in the rated ceiling assembly and there is a small hole at the sprinkler head by the exterior exit.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 189	Continued From page 10 p. Housekeeping - there is an open penetration at the plumbing pipe. q. Electrical closet 200 Hall - there is an open penetration at the speaker cable. r. Time Clock room - one of the cables has moved and pulled the ceiling finish and the attached fire caulk away from the penetration. s. Front entry portico - four of four sprinkler heads have dropped or the ceiling panel is damaged leaving holes in the underside of the portico. t. 100 Hall Electrical Room - the escutcheon plate at the sprinkler head has dropped leaving a gap in the ceiling. u. 100 Hall Corridor - there is a gap around the nurse call light at Room 101. v. Exit near Room 101 - there is a hole in the ceiling at the mounting bracket of the exit light/sign. w. Riser Room - there are two copper lines penetrating the ceiling that do not have fire caulk. 4. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch. Findings on May 22, 2018: a. 300 Hall Dining - the corridor door does not latch when closed. 5. Based on observation the facility's fire safety equipment is not maintained in operating condition. Failure to maintain fire safety equipment in operating due to sprinkler heads being obstructed could effect occupants in the fire compartment if the sprinkler head could not suppress a fire.	C 189			

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
C 189	Continued From page 11 Findings on May 22, 2018: a. 300 Hall Clean linen - items are stored within 18" of the ceiling. b. 200 Hall Clean linen - pillows and other items are stored to the ceiling. 6. Based on observation the mechanical equipment is not maintained in operating condition. Findings on May 22, 2018: a. The damper in the HVAC grille outside the 300 hall doors has a heavy accumulation of dust. b. Kitchen - the HVAC grilles have an accumulation of dust and grease. 7. Based on observation there is a failure to install and maintain plumbing piping in a safe configuration. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if the domestic water supply became contaminated. Findings on May 22, 2018: a. Kitchen - the drain pipes for the icemaker and sinks were at the level of the floor drain or below and did not maintain a minimum 2" air gap. 8. Based on observation the facility's fire safety equipment is not maintained in a safe manner. Directional arrows on exit lights/signs should indicate the direction of travel to an exit. Providing incorrect directions can jeopardize the safety of the residents, staff and visitors. Findings on May 22, 2018: a. The exit sign outside of the employee bath had both arrows uncovered, incorrectly indicating exits to the right and left. b. 100 Hall Exit near Room 101 - both of the	C 189			

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 12 directional arrows were punched out incorrectly indicating exits to the right and left. 9. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on May 22, 2018: a. SCU Dining - the emergency light failed to illuminate when tested.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility failed to provide exhaust ventilation in the required areas. Findings on May 22, 2018: a. The central exhaust system for the bathrooms	C 199	C199- 1A. The central exhaust system fans have been fixed and are working throughout the building.	

PRINTED: 06/05/2018
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 05/22/2018
NAME OF PROVIDER OR SUPPLIER CAMBRIDGE HILLS OF PITTSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE P O BOX 1209 PITTSBORO, NC 27312			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 199	Continued From page 13 connected to Room 320 was not working. b. Room 219 Bath - the exhaust fan is not working. c. Women's Guest Bath - the exhaust fan is not working. d. 100 Hall Resident's baths - the exhaust fans are not working.	C 199	ALL DEFICIENCIES HAVE BEEN CORRECTED AS OF TODAY 6/20/2018 The following measures have been put in place to help ensure compliance with the Construction regulations. 1. Maintenance checklist is completed monthly to include exit lights, door closures, etc. Then filed once all items out of compliance have been addressed. 2. Quality Assurance Inspection completed monthly. All Concerns addressed and inspected the following month. 3. Repeat violations will be addressed at quarterly C.Q.I. (Continuous Quality Improvement) meetings with all department heads.		