

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey conducted by Suzanna Fay on August 21, 2018. This facility was first licensed or submitted for licensure as a Home for the Aged serving 64 residents on or about December 31, 1998. On or about April 25, 2011 an addition and renovation was approved, bring the total capacity to Seventy-Six (76) Residents, 48 of which reside in the Special Care Unit. Therefore the facility must meet the 1996 and the applicable portions of the 2005 Rules for the Licensing of Adult Care Homes and the 1996 North Carolina State Building Code Section 409.1 Group I- Institutional Occupancy-Unrestrained; and the new addition must meet the 2009 North Carolina State Building Code, Section 407, Group I-2. Deficiencies were noted which require a Plan of Correction.	C 000		
C 160	Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition; This Rule is not met as evidenced by: 1. Observations revealed that the outside premises were not maintained clean and safe. Findings on August 21, 2018: a. The grass around the facility was in need of mowing, but the grass in the SCU courtyard was	C 160	We have communicated with our Landscapers that we need to be schedule	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

9/26/18

Mandi Purni

TITLE

Executive Director

(X6) DATE

9/26/2018

STATE FORM

8889

45FK21

If continuation sheet 1 of 8

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 160	Continued From page 1 extremely tall, exceeding 2' in some areas.	C 160	once a week. They must also mow the special care area every time the yard is mowed.	8/23/2018
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility was not maintained free of unpleasant odors. Findings on August 21, 2018: a. Janitor/Soiled Linen Closet - there was an extremely unpleasant odor emanating from the room. Two open barrels of soiled linen were in the closet. 2. Observations revealed that the furnishings were not maintained in good repair. Findings on August 21, 2018: a. Room 203 - the door hardware was loose. This item was repaired on site.	C 164		
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the	C 185	We have in-service our laundry crew they must immediately process the linen and keep the barrels covered. We have requested a review by our Corporate office to review our furniture needs and to process a requisition. Estimated completion date 9/20/2018	8/23/2018

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 185	Continued From page 2 requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Review of records revealed that the fire safety rehearsal logs are not maintained per the licensure rules. Findings on August 21, 2018: a. The monthly drills do not include a short description of what the rehearsal involved. The description should include the location of the "fire" and how the residents were directed.	C 185	We will maintain records of our fire drills and will be more descriptive.	8/22/2018	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and testing there is failure to maintain the facility's emergency fire	C 189	The emergency light has been replaced.	8/23/2018	

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 c. Electrical Room on the Activity Hall - there is an unsealed sleeve with a bundle of cables running through. d. There are gaps around the attic access door outside of the dining room. e. Kitchen - an escutcheon plate is missing for the sprinkler head at the dishwasher area. f. Kitchen - there is a leak in the ceiling outside the freezer door. There is a small hole where the ceiling is cracked and falling in. The area around the hole has brown water stains and the ceiling around the hole has moisture droplets. g. Copy Room - there is a 1/2" diameter hole in the back corner of the ceiling where a cable was removed. The ceiling around the hole has a large brown water stain. h. Oxygen Storage - the smoke detector is not secure to the ceiling leaving a gap. i. Room 105 - the escutcheon plate is missing from the sprinkler head in the right closet. j. There is a hole in the ceiling at the cable penetration outside of Room 311. k. SCU - there is a small hole at the sprinkler head outside of housekeeping. l. SCU - the escutcheon plates are missing from the sprinkler heads outside of Rooms 213 and 214. m. Front porch - one of the sprinkler heads is missing an escutcheon plate. 4. Based on observation fire safety equipment has not been inspected to assure it has been maintained in a safe and operable condition. Occupants of the facility could be effected if fire safety equipment did not operate when needed to provide fire protection. Findings on August 21, 2018: a. Laundry Room - the fire extinguisher was last serviced in April of 2017.	C 189	The sleeve has been caulked with UL Fire rated caulk. 9/4/2018 Gaps around attic access door has been caulked. 9/4/2018 The kitchen leak in the ceiling has been repaired. 9/4/2018 The copy room 1/2" diameter hole has been repaired. 9/4/2018 The smoke detector has been secured. 8/30/2018 Odyssey fire has been contracted to repair sprinkler head. Estimated completion 10/4/2018 The hole has been filled. 9/4/2018 Odyssey Fire has been contracted to repair sprinkler head. Estimated completion date 10/4/2018 The fire extinguisher has been serviced. 8/30/2018	

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 blocked could delay or hinder emergency evacuation of the occupants from the facility. Findings on August 21, 2018: a. SCU - 200 Hall - one of the residents had placed a chair in front of the smoke doors and was sitting in the chair. The chair partially obstructed the path of egress. Staff moved the resident at the time of survey. 9. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device used to keep a door open is an impediment to quickly closing the door. The occupants in the facility could be effected if doors cannot be closed as required so as to limit the spread of smoke and/or fire to the area of origin. Findings on August 21, 2018: a. SCU - 200 Hall Activity Room - the corridor door was blocked open by an armchair and a resident was sitting in the chair. 10. Based on observation there is a failure to install and maintain required plumbing safety devices or equipment. Failure to install a backflow preventor could cause the domestic water supply to become contaminated. Findings on August 21, 2018: a. SCU Room 214 - the shower head nozzle extends to the floor of the shower and there is not a backflow preventor on the shower head.	C 189	We have in-serviced our our caregivers to not to allow residents to obstruct the path of egress.	8/22/2018
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER	C 199	The shower head has a backflow preventor.	8/30/2018

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL084009	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2018
NAME OF PROVIDER OR SUPPLIER WOODHAVEN COURT		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 WOODHAVEN DRIVE ALBEMARLE, NC 28001		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 7 REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not maintain exhaust ventilation in required areas. Findings on August 21, 2018: a. Oxygen Storage - the exhaust fan is not working. b. SCU Bath - the exhaust fan is not working.	C 199	The fans have been repaired.	9/18/2018