



NC DEPARTMENT OF
HEALTH AND
HUMAN SERVICES

ROY COOPER • Governor

MANDY COHEN, MD, MPH • Secretary

MARK PAYNE • Director, Division of Health Service Regulation

November 1, 2018

Tokesha Gilchrist
P.O. Box 588
Red Springs, NC 28377

RE: Red Springs Assisted Living - HA Biennial Survey
1301 E. Fourth Avenue
Red Springs Robeson County
FID #960772 Hal078083

Dear Ms. Gilchrist:

Thank you for the cooperation and courtesies extended during the recent Division of Health Service Regulation (DHSR) – Construction Section Biennial survey of your facility on October 18, 2018. As a result of the survey, deficiencies were cited which will require an acceptable Plan of Correction. The deficiencies cited are listed on the enclosed Statement of Deficiency. Your Plan of Correction should indicate the following:

- What corrective action(s) will be accomplished in those areas of the facility found to have been affected by the deficient practice;
- How you will identify other areas of the facility having the potential to be affected by the same deficient practice and what corrective action will be taken;
- What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur; and,
- How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place.
- Include dates when corrective action will be completed. The corrective action dates must be acceptable to the State.

NC DEPARTMENT OF HEALTH AND HUMAN SERVICES • DIVISION OF HEALTH SERVICE REGULATION

CONSTRUCTION SECTION

LOCATION: 1800 Umstead Drive, Williams Building, Raleigh, NC 27603

MAILING ADDRESS: 2705 Mail Service Center, Raleigh, NC 27699-2705

www.ncdhhs.gov/dhsr/ • TEL: 919-855-3893 • FAX: 919-733-6592

AN EQUAL OPPORTUNITY / AFFIRMATIVE ACTION EMPLOYER

1. Corrective action must begin immediately.
2. Any completion date greater than 45 days from date of survey requires a written waiver from DHSR-Construction Section.

Please type or print clearly your correction action on the enclosed Statement of Deficiencies. You will need to **SIGN, DATE AND RETURN** the Plan of Correction to DHSR-Construction by November 16, 2018. Failure to return the signed Plan of Correction within this time period could jeopardize the status of your license. The PROVIDER may copy form(s) to be retained for your files.

Your Plan of Correction can be:

Mail to: DHSR Construction Section
2705 Mail Service Center
Raleigh NC 27699-2705

Fax to: (919)-733-6592

Email to: DHSR.Construction.Admin@dhhs.nc.gov

Prior to making any changes to your facility you will need to verify with the local Building Official whether or not a permit is needed to make the changes on the enclosed Statement of Deficiencies. The North Carolina State Building Code requires that "No person, firm or corporation shall erect, construct, enlarge, install, alter, repair, move, improve, convert or demolish any building, structure, or service system without first obtaining a permit for such from the Inspection Department having jurisdiction".

Informal Dispute Resolution

In accordance with G.S. § 131D-2.11(a2), you have one opportunity to question cited deficiencies through an informal dispute resolution (IDR) process. You may also contest the severity of noncompliance that resulted in a violation determination. To be given such an opportunity, you are required to send your written request identifying the specific deficiencies being disputed postmarked by November 16, 2018. An explanation of why you are disputing those deficiencies (or why you are disputing the severity of noncompliance that resulted in a violation determination) along with any supporting documentation must be sent and postmarked by November 16, 2018. You must submit 2 copies of material and highlight or use some other means to identify written information pertinent to the disputed deficiency(ies). Additional written material that does not meet these requirements will not be reviewed. This information should be sent to: Steven C. Lewis, Construction Section Chief, 2705 Mail Service Center, Raleigh NC 27699-2705. An incomplete informal dispute resolution process will not delay the effective date of any enforcement action. IDR Procedures can be accessed at: <http://www.ncdhhs.gov/dhsr/acls/idr.html>.

Please do not hesitate to call us if you have questions concerning the deficiencies or if we can be of other assistance.

Sincerely,

Suzanna Fay

Suzanna Fay

Biennial Institutional Engineering Surveyor

DHSR - Construction Section

cc: Adult Care Licensure Section-with attachment

City Building Inspection Department - with attachment-(via e-mail only)

Robeson County DSS - with attachment-(via e-mail only)

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Suzanna Fay and Dennis Harrell conducted on October 18, 2018. Records indicate this facility was first licensed on October 8, 1996 with a capacity of 81 beds. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, and applicable portions of the 1996 Edition, of the North Carolina Building Code(s), Institutional Occupancy, and the 1996 Minimum Standards and Regulations for Homes for the Aged in effect at time of initial licensure.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Observations revealed that the facility does	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Mitchell Moran

TITLE

Maintenance Director

(X6) DATE

11/26/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 not meet all of the NC Fire Code requirements. Findings on October 18, 2018: a. The riser room is located in an exterior building behind C and D Halls. The building does not have a sign indicating where the FDC (Fire Department Connection) is located. Also, since the location is not visible from the road (direction of approaching Fire Department apparatus), there was also a label missing from the street front or side of the building.	C 101 A	will add signs to show FDC	12/14/18
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Review of records revealed that the facility did not maintain all fire safety inspection reports available for review. Findings on October 18, 2018: a. A copy of the current fire alarm inspection report was not available for review.	C 111 A	New Fire alarm will be inspected on 11-26-18 (paper work attached)	11/26/18
C 160	Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe	C 160		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 160	Continued From page 2 condition; This Rule is not met as evidenced by: 1. Observations revealed that the outside premises were not maintained in a clean and safe condition. Findings on October 18, 2018: a. One of the gates has fallen off and is lying on the ground in the back yard fenced-in area. The fence is leaning where the gate came off.	C 160 A	called fence company to repaired gate and fences	12/14/18
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the furnishings are not kept in good repair. Findings on October 18, 2018: a. The Activity Office bathroom door has two small holes in the door. The edges are rough and splintered and could cause injury. b. Room B-11 - the door to the bathroom is damaged. c. Activity Office - one of the windows is full of dirty green water and there are black mildew	C 164 A B C	filled holes and repired edge of door Repaired door Window will be replaced	11/24/18 12/14/18 12/14/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING			STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 164	Continued From page 3 stains in the water. 2. Observations revealed that the ceilings are not kept clean and in good repair. Findings on October 18, 2018: a. B-5 Bath - the ceiling around the sprinkler head is spalling. b. C Hall Water heater room - there is a large yellow water stain along the back wall. The ceiling is spalling and the popcorn finish is falling off in large sections. 3. Observations revealed that the walls and floors are not kept clean and in good repair. Findings on October 18, 2018: a. B-15 Toilet - the wall base behind the toilet is falling off of the wall. This was repaired at the time of survey. b. Kitchen - there is a 3" diameter hole in the wall behind the pantry door. c. C Hall Living Room - the carpet is worn, stained and buckling which creates a tripping hazard. d. C Hall Files Storage - there is a 14"x14" hole cut into the wall to conduct repairs. e. Outside Electrical Room - water is dripping down the wall and onto the floor from a condensate line run through the wall. The moisture is causing mildew to grow on the wall and floor and the wall is deteriorating along the bottom.	C 164			
		A	repaired ceiling	12/14/18	
		B	repaired back wall and ceiling	12/14/18	
		A	repaired time of survey	10/18/18	
		B	repaired hole in wall	11/30/18	
		C	will repair carpet so it is not trip hazard until flooring is replaced getting quotes now	12/14/18	
		D	repaired wall	11/30/18	
		E	repaired condensate line so water will run out the building	11/24/18	
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS	C 166			

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 4 (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility was not maintained free of hazards. Findings on October 18, 2018: a. At the time of survey, the medication room was unlocked and there were no staff near the room. Further observations revealed aspirin and other medication in an unlocked cabinet in the med room. After notifying staff, the med room was locked. b. B Hall Shower Room - one of the shower chairs has a broken wheel which could cause a resident to slip and injure themselves. Also the metal at the chair leg is rusting and staining the tub where it is sitting.	C 166 A B	Staff was re-trained on making sure the med room stays locked replaced shower chair and cleaned tub	10/18/18 10/18/18
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short	C 185		

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 equipment in operating condition could effect occupants of the facility if the equipment did not function during a fire or other emergency. Findings on October 18, 2018: a. At the time of survey, staff revealed that the fire alarm panel was in trouble mode as it had been damaged during a lightning strike. They were waiting on a new panel. The fire alarm did sound upon activation of a smoke detector. b. Due to the damage to the fire alarm panel, the interior magnetic hold open devices were not working. c. The fire alarm was tested by spraying canned smoke in one of the smoke detectors. None of the exterior magnetic locks released. All of the manual override switches released the doors as well as the master manual override. The facility filled out a Plan of Protection designating that they would hold an all staff meeting to inform the staff of the problem and make sure they knew how to manually release the exit doors. The Fire Marshal was also contacted. Based on a phone conversation with the administrator at 4:30 pm on Monday, October 22, the fire alarm panel had been replaced and the system was working properly. d. Riser Room - the tamper switches have been removed. 2. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on October 18, 2018: a. Observation at the time of survey revealed the facility was not equipped with the typical battery backed up emergency lighting. Staff indicated	C 189	A-C New Fire panel was installed all magnetic door holder and exterior magnetic locks was repaired and work as they should (Paper work Attached)	10/19/18
		D	Tamper switches was replaced	10/23/18
		A	Generator will be replaced	12/7/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 7 that the emergency lighting is tied into a generator. However, according to staff, the generator has been down for about a year. Note: Review of DHSR Construction Records indicated that there is no evidence the generator meets the requirements for an emergency generator therefore battery units are required. 3. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. Occupants of the facility could be effected if the signs indicating exit paths could not be seen in the event of an emergency evacuation. Findings on October 18, 2018: a. Observation at the time of survey revealed the facility does not have battery backed up emergency exit lighting. Staff indicated the facility's exit signs/lights (with one exception) receive emergency power from the building generator. However, according to staff, the generator has been down for about a year. Note: Review of DHSR Construction Records indicated that there is no evidence the generator meets the requirements for an emergency generator, therefore battery units are required. 4. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on October 18, 2018: a. Administrator's Office - one of the sprinkler head escutcheon plates has dropped leaving a	C 189	Generator was order on 10/24/18 should be installed by 12/7/18 (notice of shipment paper included with POC)	12/7/18
		A	Generator will be replaced	12/7/18
		A	Escutcheon was fixed	10/18/18

Division of Health Service Regulation
STATE FORM

If continuation sheet 10 of 11

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/18/2018
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not maintain exhaust ventilation in required areas. Findings on October 18, 2018: a. Kitchen Housekeeping - the exhaust fan is not working. b. Beauty Shop - the exhaust fan is not working. c. D Hall Community Bath - the exhaust fan is not working. d. D Hall Guest Bath - the exhaust fan is not working. e. Utility Closet off of Laundry - the exhaust fan is not working. f. D-20 - the exhaust fan is not working.	C 199	A Exhaust fans was repaired 10/18/18 B-C Exhaust fans will be replaced or repaired 12/14/18 D Exhaust fans was repaired 11/9/18 E-F Exhaust fans will be replaced or repaired 12/14/18	

FIRE DRILL SCHEDULE

(Drills must be conducted once a quarter on each shift)

Name of Adult Care Home Reel Springs Assisted Living

Address: 1301 east 4th Ave Reel Springs NC 28377

Date of rehearsal: 10/18/18 Time of rehearsal: 4:15pm Shift 1st-2nd-3rd
(Circle any that apply)

Person in charge: TOKESHA GILCHRIST

Other staff members present: Amy Pena, Charmica Westfelceel, Rashama Lone
Brandy Locklear, Lynia McPhaul, Whitney Currier, James McLean

Time for evacuation: Did not evacuate

Areas covered: (check any that apply)

Fire extinguishers instructions ✓ Fire alarm operation ✓

Fire evacuation maps ✓ Discuss fire hazards to look for ✓

Other: Protocol of fire alarm panel & the importance to remain calm
and assist residents to safety

Date of rehearsal: 10/18/18 Time of rehearsal: 11:05 Shift 1st-2nd-3rd
(Circle any that apply)

Person in charge: Brandy Locklear / Carolyn McCallum

Other staff members present: Anthony Sinclair, Michaela Davis

Time for evacuation: Did Not Evacuate

Areas covered: (check any that apply)

Fire extinguishers instructions _____ Fire alarm operation ✓

Fire evacuation maps _____ Discuss fire hazards to look for ✓

Other: Timeliness of responding

FIRE DRILL SCHEDULE

(Drills must be conducted once a quarter on each shift)

Name of Adult Care Home RSAL

Address: 1301 East 4th Ave Red Springs

Date of rehearsal: 10/19/18 Time of rehearsal: 9:30am Shift (1st) 2nd-3rd
(Circle any that apply)

Person in charge: Tokesee Gilchrist

Other staff members present: Debra, Rose, Yohanna, Shakiesha, Billie, Amanda, Jermeca, Tameka, Latasha, Amy, Chantel, Brenda S., Shamaine, Rod.

Time for evacuation: 5 min, 30 sec. Evacuated all residents

Areas covered: (check any that apply) and staff to parking lot

Fire extinguishers instructions ✓ Fire alarm operation ✓

Fire evacuation maps ✓ Discuss fire hazards to look for ✓

Other: Went over all exits, and the importance of remaining calm to make sure everyone is accounted for and safe

Date of rehearsal: _____ Time of rehearsal: _____ Shift 1st-2nd-3rd
(Circle any that apply)

Person in charge: _____

Other staff members present: _____

Time for evacuation: _____

Areas covered: (check any that apply) _____

Fire extinguishers instructions _____ Fire alarm operation _____

Fire evacuation maps _____ Discuss fire hazards to look for _____

Other: _____

INSPECTION AND TESTING FORM			
SERVICE ORGANIZATION Name: <u>Patriot Systems, LLC</u> Address: <u>7339 F.W. Friendly Ave, Greensboro, NC 27410</u> Representative: <u>Alex Williamson</u> License No.: _____ Telephone: <u>336.297.2171</u>		PROPERTY NAME (USER) Name: <u>Red Springs Assisted Living</u> Address: <u>1301 E. Fourth Ave, Red Springs</u> Owner Contact: _____ Telephone: <u>Mitchell Moran</u>	
MONITORING ENTITY Contact: <u>Security Central</u> Telephone: <u>800-286-5699</u> Monitoring Account Ref. No.: _____		APPROVING AGENCY Contact: _____ Telephone: _____	
TYPE TRANSMISSION ☐ McCulloch ☐ Multiplex ☒ Digital ☐ Reverse Priority ☐ RF ☐ Other (Specify) _____		SERVICE ☐ Weekly ☐ Monthly ☐ Quarterly ☐ Semiannually ☒ Annually ☐ Other (Specify) _____	
Control Unit Manufacturer: <u>Silent Knight</u> Circuit Styles: <u>Y</u> Number of Circuits: <u>10</u> Software Rev.: _____ Last Date System Had Any Service Performed: _____ Last Date That Any Software or Configuration Was Revised: _____		Model No.: <u>5208</u>	
ALARM-INITIATING DEVICES AND CIRCUIT INFORMATION			
Quantity of Devices Installed	Circuit Style	Quantity of Devices Tested	
<u>8</u>	<u>Y</u>	<u>8</u>	Manual Fire Alarm Boxes
<u>26</u>	<u>Y</u>	<u>26</u>	Ion Detectors
<u>2</u>	<u>Y</u>	<u>2</u>	Photo Detectors
<u>5</u>	<u>Y</u>	<u>5</u>	Duct Detectors
			Heat Detectors
			Waterflow Switches
			Supervisory Switches
			Other (Specify): _____
Alarm verification feature is disabled ☒ enabled ☐			

FIGURE 10.6.2.3 Example of an Inspection and Testing Form.



ALARM NOTIFICATION APPLIANCES AND CIRCUIT INFORMATION

Quantity of Appliances Installed	Circuit Style	Quantity of Appliances Tested	
5	5	5	Bells
			Horns - Strobes
			Chimes
			Strobes
			Speakers
			Other (Specify):

No. of alarm notification appliance circuits: 2

Are circuits monitored for integrity? ☒ Yes ☐ No

SUPERVISORY SIGNAL-INITIATING DEVICES AND CIRCUIT INFORMATION

Quantity of Devices Installed	Circuit Style	Quantity of Devices Tested	
N/A	N/A	N/A	Building Temp.
			Site Water Temp.
			Site Water Level
			Fire Pump Power
			Fire Pump Running
			Fire Pump Auto Position
			Fire Pump or Pump Controller Trouble
			Fire Pump Running
			Generator in Auto Position
			Generator or Controller Trouble
			Switch Transfer
			Generator Engine Running
			Other:

SIGNALING LINE CIRCUITS

Quantity and style of signaling line circuits connected to system (see NFPA 72, Table 6.6.1):

Quantity 8 Style(s) Y

SYSTEM POWER SUPPLIES

(a) Primary (Main): Nominal Voltage 120VAC Amps 20
 Overcurrent Protection: Type Breaker Amps 20
 Location (of Primary Supply Panelboard):
 Disconnecting Means Location:

(b) Secondary (Standby): 2 12V Storage Battery: Amp-Hr Rating 24
 Calculated capacity in 7 Amp-Hrs to operate system for 24 hours
 Engine-driven generator dedicated to fire alarm system:
 Location of fuel storage:

TYPE BATTERY

- ☐ Dry Cell ☐ Lead-Acid
☒ Nickel-Cadmium ☐ Other (Specify):
☒ Sealed Lead-Acid

(c) Emergency or standby system used as a backup to primary power supply, instead of using a secondary power supply:

- ☒ Emergency system described in NFPA 70, Article 700
☐ Legally required standby described in NFPA 70, Article 701
☐ Optional standby system described in NFPA 70, Article 702, which also meets the performance requirements of Article 700 or 701

FIGURE 10.6.2.3 Continued

PRIOR TO ANY TESTING							
NOTIFICATIONS ARE MADE		Yes	No	Who	Time		
Monitoring Entity	☒	☐	SEC. Control	10:30A			
Building Occupants	☒	☐	AG				
Building Management	☒	☐	AG				
Other (Specify)	☐	☐					
AHJ Notified of Any Impairments	☐	☐					
SYSTEM TESTS AND INSPECTIONS							
TYPE	Visual	Functional	Comments				
Control Unit	☒	☒					
Interface Equipment	☒	☒					
Lamps/LEDs	☒	☒					
Fuses	☒	☒					
Primary Power Supply	☒	☒					
Trouble Signals	☒	☒					
Disconnect Switches	☒	☒					
Ground-Fault Monitoring	☒	☒					
SECONDARY POWER							
TYPE	Visual	Functional	Comments				
Battery Condition	☒	☒					
Load Voltage		☒					
Discharge Test		☒					
Charger Test		☒					
Specific Gravity		☒					
TRANSIENT SUPPRESSORS							
	☐						
REMOTE ANNUNCIATORS							
	☐	☐					
NOTIFICATION APPLIANCES							
Audible	☒	☒					
Visible	☒	☒					
Speakers	☐	☐					
Voice Clarity		☐					
INITIATING AND SUPERVISORY DEVICE TESTS AND INSPECTIONS							
Loc. & S/N	Device Type	Visual Check	Functional Test	Factory Setting	Measured Setting	Pass	Fail
		☐	☐			☐	☐
		☐	☐			☐	☐
		☐	☐			☐	☐
		☐	☐			☐	☐
		☐	☐			☐	☐
		☐	☐			☐	☐
Comments:							

FIGURE 10.6.2.3 Continued



EMERGENCY COMMUNICATIONS EQUIPMENT	Visual	Functional	Comments
Phone Set	☐	☐	
Phone Jacks	☐	☐	
Off-Hook Indicator	☐	☐	
Amplifier(s)	☐	☐	
Tone Generator(s)	☐	☐	
Call-in Signal	☐	☐	
System Performance	☐	☐	

COMBINATION SYSTEMS	Visual	Device Operation	Simulated Operation
Fire Extinguisher Monitoring Device/System	☐	☐	☐
Carbon Monoxide Detector/System	☐	☐	☐
(Specify) _____	☐	☐	☐

INTERFACE EQUIPMENT	Visual	Device Operation	Simulated Operation
(Specify) <u>Door Holders</u>	☒	☒	☒
(Specify) <u>Mag Locks</u>	☒	☒	☒
(Specify) <u>None</u>	☒	☐	☐

SPECIAL HAZARD SYSTEMS	Visual	Device Operation	Simulated Operation
(Specify) _____	☐	☐	☐
(Specify) _____	☐	☐	☐
(Specify) _____	☐	☐	☐

Special Procedures: _____

Comments: _____

SUPERVISING STATION MONITORING	Yes	No	Time	Comments
Alarm Signal	☒	☐	<u>11:40 A</u>	
Alarm Restoration	☒	☐		
Trouble Signal	☒	☐		
Trouble Signal Restoration	☒	☐		
Supervisory Signal	☒	☐		
Supervisory Restoration	☒	☐		

NOTIFICATIONS THAT TESTING IS COMPLETE	Yes	No	Who	Time
Building Management	☒	☐	<u>WJ</u>	<u>11:40 P</u>
Monitoring Agency	☒	☐		
Building Occupants	☒	☐		
Other (Specify) _____	☒	☐		

The following did not operate correctly: one smoke on '13" H&D - 11-3 has no wires - det

System restored to normal operation: Date: 11/26/18 Time: 11:40 A

THIS TESTING WAS PERFORMED IN ACCORDANCE WITH APPLICABLE NFPA STANDARDS.

Name of Inspector: Alex Williamson Date: 11/26/18 Time: 11:45 A

Signature: Alex Williamson

Name of Owner or Representative: Amy Peña Date: 11/26/18 Time: 11:47 am

Signature: Amy Peña

© 2007 National Fire Protection Association NFPA 72 (p. 4 of 4)

FIGURE 10.6.2.3 Continued



Patriot Systems, LLC

7339 West Friendly Avenue, Suite F
Greensboro, North Carolina 27410
Phone (336) 297-2171 Fax (336) 297-2174
www.patriotsystems.biz

Invoice

Date	Invoice #
10/23/2018	38069

Customer
Therapeutic Alternatives P.O. Box 814 Randleman, NC 27317

Reference
Red Springs Assisted Living Emergency FACP Replacement

Project	Terms	Work Order Number
2365 - Red Springs A.L.	Net 30	

Item	Qty	Description	Rate	Amount
Per Quote		Replace Silent Knight Fire Alarm Control Panel	675.50	675.50
Per Quote	23	Smoke Detectors (Replaced as Needed)	85.00	1,955.00
Per Quote	1	Heat Detector	60.00	60.00
Per Quote Parts			2,037.00	2,037.00T
		REVISED 11-8-18 TO REFLECT SALES TAX ON EQUIPMENT		
		Sales Tax	6.75%	137.50

Total \$4,865.00

For questions regarding this invoice or other general accounting issues,
please contact Gina Williamson at (336)297-2171 ext. 602 or
gina.williamson@patriotsystemsllc.com

Balance Due \$4,865.00

A MONTHLY 1.5% LATE FEE WILL BE ADDED TO PAST DUE ACCOUNTS.

FIRE ALARM - AREA OF RESCUE - SECURITY - ACCESS CONTROL - SOUND & PAGING - NURSE CALL - CCTV - VOICE & DATA
LOW VOLTAGE SYSTEMS - SALES - SERVICE - INSTALLATION - INSPECTIONS - SERVICE CONTRACTS - CENTRAL MONITORING

Patriot Systems, LLC is a Minority Business Enterprise under the WBE Classification

Celebrating our 15th Anniversary! 2003 - 2018