

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Ed Miller and Dennis Harrell, conducted on September 26, 2018. Records indicate this facility was licensed on 8-8-2007, for 70 residents including a 40 bed Special Care Unit. Therefore, the facility was surveyed for conformance with the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, and the 2006 North Carolina State Building Code(s), Intentional Occupancy I-2. Deficiencies were cited that require a Plan of Correction.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Based on observation and interview with	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Renee Robinson

TITLE

Administrator

(X6) DATE

11/1/18

If continuation sheet 2 of 12

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 2 no exit sign directing you to exit through the Smoke Barrier doors. The corridor is 32 feet long from the Smoke Barrier doors and the Control doors.	C 101		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on record review, and interview with Executive Director, the facility has unresolved deficiencies cited on their current (completed within the last twelve months) annual inspection report(s) required by this Rule. Findings on September 26, 2018: a. The Annual Fire Sprinkler System Inspection, Testing, and Maintenance Report, in accordance with NFPA 25 performed on 06/13/ 2018 listed several deficiencies that have not been addressed as either corrected or not required.	C 111	(a) Administrator called the Sprinkler Inspection Company 10/26/18 to schedule a crew to correct deficiencies in facility. The Sprinkler inspection company will correct all unresolved deficiencies at the facility. The administrator will ensure all deficiencies are corrected	11/9/18
C 150	Corridors-Free of equipment and Obstructions SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Based on observation, corridors are not free	C 150		

If continuation sheet 4 of 12

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Building plumbing equipment was not maintained in a clean and orderly manner free of hazards. Findings on September 26, 2018: a. Bedroom 411 Bathroom - the sink is loose from the wall and the gap has been filled with 1 inch of caulk. 2. Based on observation, the building ceiling are not kept clean and in good repair. Findings on September 26, 2018: a. Bedroom 15 - the texture ceiling is flaking off near the light. 3. Based on Observation, the facility failed to have furniture kept clean and in good repair. Findings on September 26, 2018: a. Bedroom 206 - the wardrobes are delaminating. b. Bedroom 208 - the wardrobes are delaminating.	C 164		
		C 164	(a) Sink was removed, old caulking was removed, the sink bracket was tightened and sink was re-installed and caulking was replaced. Facility maintenance tested the sink after repairs to ensure sink was in proper working order. All sinks were inspected to ensure the stability and safety of all the sinks in resident bathrooms. All staff have been instructed to report loose sinks immediately to Administrator or unit coordinators. Administrator or coordinators will place a work order in maintenance system immediately. In service was held for staff on 10/5/18 to explain reporting procedure.	10/5/18
C 188	Electrical Outlets in Wet Locations SECTION .0300 - PHYSICAL PLANT	C 188	(a) new wardrobes have been installed. (b) new wardrobes have been installed. maintenance has inspected wardrobes in all rooms to check for quality.	10/31/18 10/31/18 10/31/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 188	Continued From page 5 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to provide electrical outlets in wet locations at sinks, bathrooms and outside of building with ground fault interrupters. This would affect residents, staff, and visitors by not providing ground fault protection to these devices. Findings on September 26, 2018: a. Dining Room Patio- there are two ground-fault circuit-interrupter (GFCI) electrical power receptacles that do not have electrical power and could not be tested for ground faults. b. Med Room- there is a ground-fault circuit-interrupter (GFCI) electrical power that did not have electrical power and cannot be tested for ground fault.	C 188	(a+b) GFCI outlets have been re-tested since inspection, with a Southwire 400105-A Series tester on 3 separate occasions, 10/5/18, 10/12/18, and 10/16/18. All GFCI outlets are in proper working order. Facility maintenance will check GFCI outlets monthly to ensure outlets are in proper working order. A log of these checks will be kept in office of the Administrator	10/16/18
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building's	C 189	(1a) Battery in exit sign near #412 was replaced. Sign is in proper working order. Building maintenance, or admin-	10/5/18

If continuation sheet 7 of 12

If continuation sheet 8 of 12

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 8 assembly. 4. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Findings on September 26, 2018: a. Bedroom 403 - due to renovations, multiple electrical devices with energized components are missing their cover plates and the door to the room is unlocked. 5. Based on observation, the smoke tight corridor doors are not maintained in a safe and operating condition. Findings on September 26, 2018: a. Dining Room - the pair of corridor door leafs have an excessive gap between their meeting edges, ranging between 3/16 to 5/8 inches. This gap is not smoke tight. 6. Based on observation, the Building is not maintained in a safe and operating condition, because the commercial kitchen hood's fire suppression system lacked the inspections, maintenance, and documentation required to ensure a properly working system. This could affect residents, staff, and visitors if the commercial kitchen hood's suppression system fails to operate properly when needed. Findings on September 26, 2018: a. Kitchen - the commercial kitchen hood's suppression system is aimed at the shelf above the stove and cannot extinguish a fire in that area. b. Kitchen - per the attached maintenance tag, the commercial kitchen hood's fire suppression system had its last semi-annual maintenance performed in July of 2017. 7. Based on Observation, the corridor doors are	C 189 C189 C189 C189	(A) The cover plates were replaced on the electrical outlets in room 403. Building maintenance was educated by inspectors regarding not allowing residents to come into contact with open faced outlets. If building maintenance must remove cover plates to do repairs, maintenance tech will ensure space is not accessible to any resident or staff member until cover plates are replaced. (5a) A Flashing was placed on the corridor leaf doors in the dining room to ensure the gap between the doors is smoke tight. Maintenance will ensure all doors in facility have a smoke tight gap. (6a) Maintenance tech pushed the stove back, closer to the wall to ensure the hood suppression system was aimed at stove, instead of shelf. Kitchen staff was in serviced on the reason and importance of making sure the suppression system was aimed at stove. (b) Administrator contacted Odyssey Fire regarding semi annual maintenance. Scheduled tech to perform maintenance. Administrator will ensure the Semi Annual maintenance is completed.	9/26/18 10/30/18 9/28/18 11/10/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE			STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 189	Continued From page 9 not maintained in a safe and operating condition. This affects all by not containing smoke and fire in the room of origin. Findings on September 26, 2018: a. Dryer Room - the corridor door has a 5-gallon bucket holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch. b. Laundry Room - the corridor door has a 5-gallon bucket holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch. c. Clean Linen Room - the corridor door has a sock tied to the shelf holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch. 8. Based on observations, the Building was not maintained in a safe and operating condition. The fire sprinkler heads have become obstructed. This could affect all if the fire sprinkler heads' spray cannot reach an area of a room. Findings on September 26, 2018: a. Clean Linen - items are being stored within the area 18 inches below the fire sprinkler head. b. Storage Room near Bedroom 201 - items are being stored within the area 18 inches below the fire sprinkler head.	C 189	(a) 5 gallon bucket was removed from door in the dryer room, allowing the doors rapid release mechanism to work properly. (b) 5 gallon bucket was removed from door in the laundry room, allowing the doors rapid release mechanism to work properly. (c) sock holding the door open to the clean linen room has been removed, allowing the rapid release of the door to work properly. In service regarding propping doors, and tying doors open was held for all staff to ensure the doors will not held open.	9/26/18	9/26/18
		189	(a) All items stored within the area 18 inches below the fire sprinkler head have been removed. (b) all items stored in the storage room near room 201, that were stored between the area 18 inches below the fire sprinkler have been moved. Maintenance has placed tape lines on walls in storage areas, indicating the height limit of storage. Storage areas will be monitored frequently by staff to ensure all storage areas are within correct height limits. Staff was in service regarding storage height limits	9/28/18	9/28/18
C 191	Unvented & Portable Elec. Heaters Prohibited SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (b) There shall be a heating system sufficient to maintain 75 degrees F (24 degrees C) under winter design conditions. In addition, the following shall apply to heaters and cooking appliances.	C 191		9/28/18	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 191	Continued From page 10 (2) Unvented fuel burning room heaters and portable electric heaters are prohibited. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to prevent the use of portable electric heaters in an Adult Care Home. This could affect residents, staff, and visitors if heater is the ignition source of a fire. The danger increases if used by resident or combustible material is near. Findings on September 26, 2018: a. Nuring Office - a portable electric heater was found in this room.	C 191	a) portable heater in nurses office was removed. nurse and staff were educated about not using portable heaters.	9/26/18
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL100005	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 09/26/2018
NAME OF PROVIDER OR SUPPLIER YANCEY HOUSE			STREET ADDRESS, CITY, STATE, ZIP CODE 4 COOPER LANE BURNSVILLE, NC 28714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 199	Continued From page 11 plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on September 26, 2018: a. Bedroom 409 Bathroom - the required exhaust ventilation system did not work.	C 199	a) new exhaust fan motor will be installed by facility maintenance. Exhaust fans will be checked frequently in bathrooms to ensure all fans are operating.	11/5/18	