

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL093001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/06/2018
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

BOYD'S REST HOME # 2

**295 CARROLLTOWN ROAD
MACON, NC 27551**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay and Frank Strickland conducted on September 6, 2018. There are deficiencies cited in the Biennial Construction Survey that remain to be corrected.	{C 000}		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and testing there is failure to maintain the facility's emergency fire alarm system devices and equipment in a safe operating condition. All the occupants of the facility could be effected if the equipment failed to alert the occupants in case of a fire. Findings on September 6, 2018: a. In addition to the monitored fire alarm system, the facility has smoke detectors with battery back-up in the hallways and in each bedroom. The batteries have been removed from all of the smoke detectors. Interview with Staff revealed that the batteries were purchased and will be installed. 2. Observations revealed that the mechanical	{C 189}	9V6 Batteries placed in smoke detectors	9/15/18

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

6899

9KPD22

If continuation sheet 1 of 4

STATE FORM

RECEIVED

NOV 15 2018

CONSTRUCTION SECTION

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL093001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/06/2018
NAME OF PROVIDER OR SUPPLIER BOYD'S REST HOME # 2		STREET ADDRESS, CITY, STATE, ZIP CODE 295 CARROLLTOWN ROAD MACON, NC 27551		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 1 equipment was not maintained in good repair. Findings on September 6, 2018: a. The dryer cap for the duct extending through the side wall is missing. Interview with Staff indicated that they were not aware of the second dryer duct as it is behind the A/C units and partially obscured. b. Kitchen - the filters on the kitchen range hood have a heavy accumulation of grease. Interview with Staff revealed that the vendor is scheduled to come and clean the range hood this week. 3. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings and walls could allow fire and smoke to spread beyond the area of origin. Findings on September 6, 2018: a. Water heater room - there are four unsealed penetrations along the back wall. Interview with Staff revealed that she was not aware of those penetrations and will get them sealed. b. Basement stair - there is a red pipe penetrating the wall of the stair that has not been sealed. Interview with Staff revealed that she would have the pipe sealed. 4. Observations revealed that the electrical equipment was not maintained in a safe operating condition. Findings on September 6, 2018: a. Water Heater Room - the electrical outlet to the right of the abandoned water heater does not have a cover plate. Interview with Staff revealed that she would purchase a cover plate and get it	{C 189}	Dryer cap installed Filters cleaned at car wash using ZEP degreaser remover product Remaining holes & gaps filled in w/ 3M Fire Barrier Sealant. Purchased fcover plate for water heater and installed it	9/20/18 9/26/18 9/26/18 10/24/18

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL093001	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/06/2018
NAME OF PROVIDER OR SUPPLIER BOYD'S REST HOME # 2		STREET ADDRESS, CITY, STATE, ZIP CODE 295 CARROLLTOWN ROAD MACON, NC 27551		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 3 7. Observations revealed that the plumbing equipment was not maintained in a safe operating manner. Findings on September 6, 2018: a. Resident Restroom - the toilet was loose. Interview with Staff indicated that she would have the toilet secured.	{C 189}	Bathroom toilet secured - see receipt	7/27/18
{C 199}	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that exhaust ventilation was not provided in required areas. Findings on September 6, 2018: a. Visitor Restroom - the exhaust fan was not working at the time of survey. Interview with Staff revealed that she was waiting on the same electrician to repair the exhaust fan.	{C 199}	Exhaust fan installed	10/29/18