

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL061011	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/06/2019
NAME OF PROVIDER OR SUPPLIER MITCHELL HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 13681 HWY 226 SOUTH SPRUCE PINE, NC 28777		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Ed Miller, conducted on February 6, 2019. Deficiencies were cited that will require a new Plan of Correction.	{C 000}		
{C 164}	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 3. Based on observation, the building mechanical systems are not kept clean and in good repair. Findings on February 6, 2019: a. Kitchen - the ventilation system with its radiation damper has an excessive accumulation of dust/lint. b. SCU Spa - the ventilation system with its radiation damper has an excessive accumulation of dust/lint.	{C 164}	3a Maintenance Tech has cleaned the kitchen ventilation system and removed excessive accumulation of dust. See the attached photo labeled kitchen 3b Maintenance Tech has cleaned the SCU spa ventilation system and removed excessive accumulation of dust See the attached photo labeled SCU spa	3/26/2019 3/26/2019
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS	{C 189}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

M. Jennelle Gayle 3/26/19. ED

STATE FORM

6899

PTVP22

If continuation sheet 1 of 4

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL061011	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/06/2019
NAME OF PROVIDER OR SUPPLIER MITCHELL HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 13681 HWY 226 SOUTH SPRUCE PINE, NC 28777		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 2 assembly. Firestopping incomplete and material is not approved for firestopping. g. The Trophy Room - there is a gap around a cable not firestopped as it penetrates the fire-resistance-rated ceiling assembly. Firestopping incomplete and material is not approved for firestopping. 4. Based on Observation, the corridor doors are not maintained in a safe and operating condition. This affects all by not containing smoke and fire in the room of origin. Findings on February 6, 2019: b. Bedroom 404 - the corridor door has a chair holding the door open. This prevents the rapid release of the door with a light push or pull of the door, to close and latch.	{C 189}	3g The Maintenance Tech filled the gap around a cable in the Trophy Room with firestopped. See attached photo labeled Trophy Room 4b Bedroom 404- ED removed the chair holding the door. See attached photo labeled Room 404.	3/26/19 3/26/19
{C 199}	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.	{C 199}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL061011	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/06/2019
NAME OF PROVIDER OR SUPPLIER MITCHELL HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 13681 HWY 226 SOUTH SPRUCE PINE, NC 28777		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 199}	Continued From page 3 This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on February 6, 2019: a. AL Spa - the required exhaust ventilation system did not work. b. AL Soiled Utility Laundry - the required exhaust ventilation system did not work.	{C 199}	1a AL Spa- the required exhaust ventilation system will be repaired and a new fan motor will be ordered 1b AL Soiled Utility Laundry- the required exhaust ventilation system will be repaired and a new fan motor will be ordered.	4/16/19 4/16/19