

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Ed Miller, conducted on April 18, 2019. Records indicate this facility was first licensed in 1966. The facility is currently licensed for fifty-four Beds. Therefore the facility was surveyed for conformance with the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and the applicable portions of the 1958 NC State Building Code.. Deficiencies were cited that require a Plan of Correction.	C 000		
C 128	Bathrooms-Minimum Facilities SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (1) Minimum bathroom and toilet facilities shall include a toilet and a hand lavatory for each 5 residents and a tub or shower for each 10 residents or portion thereof; This Rule is not met as evidenced by: 1. Based on observation and interview with Manager and Administrator, the facility failed to maintain the minimum plumbing fixture to resident ratio required by the Rule. Findings on April 18, 2019: a. Entire Building - there are 3 showers and 1 tub available to the Residents. A tub was remove since the last survey. The facility is require to have 6 tubs and/or showers available for residents.	C 128		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 150	Continued From page 1	C 150		
C 150	Corridors-Free of equipment and Obstructions SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions. This Rule is not met as evidenced by: 1. Based on observation, corridors are not free of obstructions. This would affect all residents, staff, and visitors by slowing or obstructing egress during an emergency. Findings on April 18, 2019: a. Exit near Bedroom 24 - there two wheel chair and a bike chained to the handrail, obstructing the required six feet width of the corridor..	C 150		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building mechanical systems are not kept clean and in good repair. Findings on April 18, 2019: a. Bedroom 6 - the ventilation system with have	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 an excessive accumulation of dust/lint. b. Bedroom 9 - the ventilation system with have an excessive accumulation of dust/lint. 2. Based on observation, the building walls are not kept clean and in good repair. Findings on April 18, 2019: a. File Room on Laundry Porch.- water is infiltrating this space, wetting the gypsum walls and the room's contents. Some of the gypsum is missing and mold is present. 3. Based on observation, the building ceilings are not kept clean and in good repair. Findings on April 18, 2019: a. Bedroom 3 - there is a leak in the closet and the ceiling is stained and mold present. b. Bedroom 24 - there is a leak in the closet and the ceiling is stained	C 164		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the Building was not maintained free of hazards, if oxygen cylinders fall, breaking their valves, propelling the cylinder, and turning it into a dangerous projectile. Findings on April 18, 2019:	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 3 a. Storage Building - 4 portable medical oxygen cylinders are standing up on the floor not physically secured in racks, stands or chained to the structure. b. Storage Building - 7 portable medical oxygen cylinders are standing up on the floor in an unapproved plastic crate not physically secured in racks, stands or chained to the structure. 2. Based on Observation, the Building was not maintained free of hazards, because general maintenance was not being done or had not been completed. This could affect all residents, staff, and visitors if items are broken or partially removed and left where they could injure all. Findings on April 18, 2019: a. Bedroom 24 - the kick plate on the door is not secured. The exposes residents to rough and sharp edges along with the screws..	C 166		
C 175	Bedroom Furnishings-Clean Towel, Towel Bar SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (b) Each bedroom shall have the following furnishings in good repair and clean for each resident: (7) individual clean towel, wash cloth and towel bar in the bedroom or an adjoining bathroom; and (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the facility failed to provide residents areas, with the required individual towels and/or towel bars for each resident. Findings on April 18, 2019:	C 175		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 175	Continued From page 4 a. Entire Building - in the Bedrooms or adjoining Bathrooms, there is insufficient individual towel bars for the number of Residents.	C 175		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Fire Alarm system was not maintained in a safe and operating condition. This would affect all by not providing early detection and activating the fire alarm system. Findings on April 18, 2019: a. File Room on Laundry Porch - this space, which was created some time after the facility was originally constructed, does not have automatic fire detection. 2. Based on observation, the building's emergency equipment was not maintained in a safe and operating condition. This would affect all if they could not promptly find their way to an exit during an emergency. Findings on April 18, 2019: a. Main Corridor Entrance into Living - the exit sign did not illuminate on backup power when tested.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 3. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in room of origin. Findings on April 18, 2019: a. Most Bedroom Closets - there is a cable not firestopped as it penetrates the fire-resistance-rated ceiling assembly. b. Many Bedroom Closets - there is a cable with its firestopped sealant pulled out of the penetration of the fire-resistance-rated ceiling, leaving an unprotected opening. c. Shared Toilet Room between Bedrooms 6 & 8 - - there is a gap around a conduit not firestopped as it penetrates the fire-resistance-rated ceiling assembly. d. Living Room - there are two pipes with their firestopped sealant pulled out of the penetration of the fire-resistance-rated ceiling, leaving an unprotected opening. e. Main Corridor Entrance into Living - there is a gap around the base of the exit sign not firestopped as it penetrates the fire-resistance-rated ceiling assembly. f. Dining Room - there is a pipe with its firestopped sealant pulled out of the penetration of the fire-resistance-rated ceiling, leaving an unprotected opening. g. Dining Room - there is a cable not firestopped as it penetrates the fire-resistance-rated corridor wall assembly. h. Laundry - there are three holes not firestopped as they penetrate the fire-resistance-rated ceiling assembly. i. Laundry Porch - there is a 6 x 12 inch hole not firestopped as they penetrate the fire-resistance-rated ceiling assembly and roof. j. Bedroom 12 - there is a hole not firestopped as it penetrates the fire-resistance-rated ceiling	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 assembly. k. Bedroom 11 Closet - there is a gap around the base of the heat detector not firestopped as it penetrates the fire-resistance-rated ceiling assembly. l. Lower Lobby Closet - there are two pipes not firestopped as they penetrate the fire-resistance-rated ceiling assembly. m. Bedroom 18 - there are two pipes and a cable not firestopped as they penetrate the fire-resistance-rated ceiling assembly. n. Bedroom 20 - there are two pipes and a cable not firestopped as they penetrate the fire-resistance-rated ceiling assembly. o. Attic Firewall - there are three cables not firestopped as they penetrate the firewall. p. Attic Draft Stops - both draft stop doors were left open 4. Based on observation, the Building was not maintained in a safe and operating condition, because the corridor doors do not resist the passage of smoke. Corridor door must positively/automatically latch into their frame under normal closing force. This could affect all residents, staff, and visitors if the doors did not latch to contain smoke/fire in the room of origin. Findings on April 18, 2019: a. Bedroom 5 - the corridor door's latch bolt is install backwards and the door cannot closed and latch unless the latch bolt is retracted with the handles. b. Bedroom 9 - the corridor door is missing its latch bolt, therefore the door cannot latch to its frame. c. Bedroom 20 - the corridor door is missing its latch bolt, therefore the door cannot latch to its frame. d. Bedroom 15 - the corridor door has a hole through the door.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 7 e. Bedroom 19 - the corridor door has a hole through the door. 5. Based on Observation, the corridor doors are not maintained in a safe and operating condition. This affects all by not containing smoke and fire in the room of origin. Findings on April 18, 2019: a. Bistro - the corridor door has a coat hanging off the top of the leaf, preventing the door from closing. This prevents the rapid closing of the door to latch with a light push or pull of the door. 6. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Findings on April 18, 2019: a. Laundry - the left electrical panel has three open slots where breakers had been removed and there were two blanks filling the slots. This allows access to energized components that are not guarded against accidental contact. b. Boiler Room - there is an electrical power receptacle with an unsecured cover plate. c. Boiler Room - there is an electrical device with an unsecured cover plate. d. Pantry - the ceiling mounted electrical power receptacle has a broken cover plate. e. Bedroom 6 - two power taps are daisy chained into another power tap. Power taps must connect directly to permanently installed branch circuit electrical power receptacles. f. Bedroom 6 - the first power tap in the daisy chain is hanging from its electrical power receptacle. g. Bedroom 9 - an extension cord is plugged into a power tap. Extension cords cannot substitute for permanent wiring. h. Bedroom 9 - the power tap is hanging from its electrical power receptacle.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 8 i. Bedroom 21 - a power tap (power strip) is plugged into an extension cord. Power taps must connect directly to permanently installed branch circuit electrical power receptacles. j. Shower Room near Bedroom 21 - there is an old light fixture missing an end cap. This allows access to energized components that are not guarded against accidental contact.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on April 18, 2019: a. Shared Toilet Room between Bedrooms 2 & 4 - the required exhaust ventilation system did not work, and there is odor.	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086002	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/18/2019
NAME OF PROVIDER OR SUPPLIER COLONIAL LONG TERM CARE FACILITY		STREET ADDRESS, CITY, STATE, ZIP CODE 340 SNOWHILL DRIVE MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 9 b. Shared Toilet Room between Bedrooms 5 & 7 - the required exhaust ventilation system did not work, and there is odor. c. Bathroom near Bedrooms 8 - the required exhaust ventilation system did not work, and there is odor. d. Bedrooms 10 Bathroom - the required exhaust ventilation system did not work, and there is odor.	C 199		