

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Suzanna Fay and Ed Miller conducted on June 13, 2019. Records indicate this facility was first licensed on April 14, 2015 for 91 beds including a 34 bed Special Care Unit. The facility is required to meet the 2005 Rules for Adult Care Homes of Seven or More Beds and the 2006 North Carolina State Building Code Section 409.1- Institutional Occupancy Group I-2) Unrestrained. Deficiencies were cited that require a Plan of Correction.	C 000		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility is not maintained free of all hazards. Findings on June 13, 2019: a. D5 - there was one unsecured bottle of oxygen on the floor. b. Room C06 - there is a non UL listed multi-plug adaptor in use.	C 166		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1	C 189		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on June 13, 2019: a. TMSD Office - the escutcheon plate has dropped on the sprinkler head leaving a gap at the ceiling. b. D Hall: Electrical Room off of the Warming Kitchen - there is a 2" diameter cut in the the ceiling that has not been properly patched. c. Room D14 - the sprinkler head in the closet nearest the window did not have an escutcheon plate leaving a hole in the rated ceiling assembly. d. Dining Room - there is a gap around the recessed light in the last bay. e. FACP Room - there are 10 4" diameter pipes sealed with fire caulk instead of fire collars. f. FACP Room - there is a 3/4" water line behind the sprinkler riser in which the fire caulk is falling out of the opening. g. Soiled Utility by Activity Room - the	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 escutcheon on the sprinkler head has dropped leaving a gap in the ceiling. 2. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on June 13, 2019: a. Room A15 - the door does not latch when closed. b. Dining Room - the double doors overlap at the top and do not close and latch. c. Room CO1 - the door is sticking and is difficult to open. d. Room C13 - the door does not latch when closed. e. B Hall Living Room - the double doors overlap at the top and do not close and latch. 3. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated walls could allow fire and smoke to spread beyond the area of origin. Findings on June 13, 2019: a. Laundry Room - there is a 2 1/2" diameter hole in the corridor wall. b. Laundry Room dryer chase - the opening for the electrical outlet is larger than the outlet cover leaving a hole on either side of the cover plate. 4. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe condition. In order to resist the passage of smoke resident room doors must not have gaps	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 3 between the door and the door frame stops or holes through the face of the door. Findings on June 13, 2019: a. Laundry Room - the rated door has large holes through the door where the previous hardware was removed. The front was patched with a FRP panel. b. Room D09 - there is a quarter inch hole through the door at the door hardware. 5. Observations revealed that the mechanical equipment was not maintained in a safe and operating condition. Findings on June 13, 2019: a. D Hall Housekeeping Closet - the grille for the exhaust fan had fallen off and was sitting on shelf in the room. 6. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. Occupants of the facility could be effected if the signs indicating exit paths could not be seen in the event of an emergency evacuation. Findings on June 13, 2019: a. D10 - the exit light/sign did not illuminate on battery test. b. Activity Room - the emergency/exit light by the closets did not illuminate on test. 7. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device used to keep a door open is an impediment to quickly closing the door. The occupants in the facility could be effected if doors cannot be closed as required so as to limit the	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 spread of smoke and/or fire to the area of origin. Findings on June 13, 2019: a. Kitchen Pantry - the rated door was held open using a coat hanger. The coat hanger was removed at the time of survey.	C 189		
C 193	Ovens, Ranges in Activity or Res. Rooms SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (4) Ovens, ranges and cook tops located in resident activity or recreational areas shall not be used except under facility staff supervision. The degree of staff supervision shall be based on the facility's assessment of the capabilities of each resident. The operation of the equipment shall have a locking feature provided, that shall be controlled by staff. (5) Ovens, ranges and cook tops located in resident rooms shall have a locking feature provided, controlled by staff, to limit the use of the equipment by residents who have been assessed by the facility to be incapable of operating the equipment in a safe manner. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility had an oven capable of operation that was not supervised. Findings on June 13, 2019: a. Activity Room - the activity room had an oven that, at the time of survey, had power. No staff were present in the room to supervise the oven.	C 193		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL019021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/13/2019
NAME OF PROVIDER OR SUPPLIER CHATHAM RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 114 POLKS VILLAGE LANE CHAPEL HILL, NC 27517		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 193	Continued From page 5 There was a locking feature on the adjacent wall which appeared to be designated for the oven. Staff were not aware that this was a locking feature and the key could not be located.	C 193		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that exhaust ventilation was not provided in required areas. Findings on June 13, 2019: a. D Hall Residential Laundry - the exhaust fan is not working. b. D Hall Soiled Utility - the exhaust fan is not working. c. D Hall Staff Restroom - the exhaust fan is not working. d. Room B10 - the bathroom exhaust fan is not working.	C 199		