

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Suzanna Fay conducted on July 10, 2019. Records indicate this facility was first licensed as a Home for the Aged serving 64 residents, including a 16 bed Special Care Unit, on October 23, 1997. Therefore, the facility must meet the 1996 Rules for Adult Care Homes, the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and the 1996 North Carolina State Building Code(s), Section 409.1 Institutional Occupancy. Deficiencies were cited that require a Plan of Correction.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by:	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 1. Observations revealed that the facility was is not in compliance with building code requirements in effect at the time of construction, addition or renovation. Delayed egress doors are not properly labeled to notify residents and staff when they can exit. Findings on July 10, 2019: a. The building is equipped throughout with delayed egress doors. The doors are operated with a 15 second delay. Most of the delayed egress signs posted state that the "door can be opened in 30 seconds" instead of 15 seconds. b. Stairwell 2 in the SCU was not labeled as a delayed egress door that can be opened in 15 seconds. 2. Observations revealed that the facility was is not in compliance with building code requirements in effect at the time of construction, addition or renovation. Rooms open to the corridor must have the same fire protection as the corridor. Findings on July 10, 2019: a. Bistro - the doors to the Bistro were removed making the room open to the corridor. There is not a smoke detector in the Bistro.	C 101		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair;	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the ceilings were not kept clean and in good repair. Findings on July 10, 2019: a. Third Floor Residential Laundry - the ceiling around the supply vent is dirty and the finish tape is separating and peeling away from the ceiling. b. Second Floor Laundry - the ceiling finish is bubbled and flaking at the wall/ceiling junction behind the door. 2. Observations revealed that the walls were not kept clean and in good repair. Findings on July 10, 2019: a. Room 318 - the wall beside the closet in the right side room is heavily damaged. 3. Observations revealed that the facility was not kept free of chronic unpleasant odors. Findings on July 10, 2019: a. Room 316 - has a strong pet odor emanating from the room. 4. Observations revealed that the furnishings were not kept in good repair. Findings on July 10, 2019: a. Stairwell 2 - the wall mounted handrail between the third and second floors is not secure to the wall. b. Second Floor Nurse Station - one of the drawer faces is missing.	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 3	C 166		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility was not maintained free of hazards. Findings on July 10, 2019: a. Room 102 - the transition strip at the bathroom door is loose creating a trip hazard.	C 166		
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities.	C 185		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 185	Continued From page 4 This Rule is not met as evidenced by: 1. Review of records revealed that the facility was not conducting fire rehearsals quarterly on each shift. Findings on July 10, 2019: a. There was not a record of a fire rehearsal conducted on the first shift during the third quarter of 2018. b. There was not a record of a fire rehearsal conducted on the third shift during the fourth quarter of 2018. c. There was not a record of a fire rehearsal conducted on the first or third shift during the first quarter of 2019. d. There was not a record of a fire rehearsal conducted on the first shift during the second quarter of 2019.	C 185		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 origin. Findings on July 10, 2019: a. Third Floor - the escutcheon plate on the sprinkler head outside of Stairwell 1 has dropped leaving an opening in the ceiling. b. Third Floor - there is a small hole in the ceiling at the exit sign by Stairwell 1. c. Room 301 - the escutcheon plate on the sprinkler head in front of the closet in the sitting area has dropped leaving an opening in the ceiling. d. Third Floor - the escutcheon plate on the sprinkler head in front of the elevator has dropped leaving a gap in the ceiling. e. The escutcheon plate on the sprinkler head outside of Room 314 has dropped leaving an opening in the ceiling. f. Second Floor Laundry - there is a hole in the ceiling in front of the door where a cover plate does not completely cover the opening. g. Second Floor - there is a small hole in the ceiling at the base of the cross corridor door's exit sign outside of Room 208. h. Second Floor Janitor Closet - there is a hole in the ceiling at the exhaust fan. i. First Floor left Guest Toilet - there is a small hole at the sprinkler head. j. First Floor Screened Porch - one of the vent grilles is not secure and beginning to fall out of the ceiling. 2. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe condition. In order to resist the passage of smoke resident room doors must not have gaps between the door and the door frame stops. Findings on July 10, 2019: a. Room 310 - there is a 1/4" gap between the	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 door and door frame at the top left side of door. b. Room 202 - there is a gap between the door and frame at the top left side of the door. c. Room 106 - the door has dropped leaving a substantial gap at the top of the door and making it difficult to close. 3. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on July 10, 2019: a. Room 219 - the corridor door sticks at the top left of the frame making it difficult to close and latch. b. Second Floor Laundry - the door does not close and latch. c. Room 209 - the door drags heavily on the frame making it difficult to close and latch. The drag is pulling the veneer off of the door. d. Room 205 - the door does not close and latch. e. Second Floor - the double doors at the room containing the scale hit and do not close and latch. f. First Floor Living Room - the doors do not close and latch. g. Room 103 - the door does not close and latch. h. Dining - the doors are not synchronized to close when released on the fire alarm. 4. Observations revealed that the mechanical equipment is not maintained clean. Findings on July 10, 2019: a. Third Floor Nurse Station - the R/A grills have a heavy accumulation of dust.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 7 5. Observations revealed that the electrical equipment is not maintained in a safe and operating condition. Findings on July 10, 2019: a. Third Floor Nurse Station - the data box cover plate is not secure to the wall. b. Room 204 - there is no power to the electrical outlet in the bathroom and could not be tested for ground fault protection. c. Kitchen - Panel K has an open breaker. d. Room 104 - there is no power to the electrical outlet in the bathroom and could not be tested for ground fault protection. 6. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on July 10, 2019: a. First Floor Living Room - the emergency light did not illuminate on battery test. 7. Based on observation there is a failure to maintain the buildings's fire safety components in a safe operating condition. Any unapproved device used to keep a door open is an impediment to quickly closing the door. The occupants in the facility could be effected if doors cannot be closed as required so as to limit the spread of smoke and/or fire to the area of origin. Findings on July 10, 2019: a. First Floor Living Room - the double doors on the corridor wall were blocked by furnishings.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL068008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/10/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE MEADOWMONT		STREET ADDRESS, CITY, STATE, ZIP CODE 100 LANARK ROAD CHAPEL HILL, NC 27514		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 8	C 199		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not provide exhaust ventilation in required areas. Findings on July 10, 2019: a. Second Floor Spa - the exhaust fan is not working.	C 199		