

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE  TITLE Administrator (X6) DATE 08-14-19

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL041067	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/11/2019
NAME OF PROVIDER OR SUPPLIER PEAR MANOR		STREET ADDRESS, CITY, STATE, ZIP CODE 2521 PEAR STREET GREENSBORO, NC 27401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 1 2. At the time of the survey it was observed that the time noted on the fire drills for evacuation was including the time for returning back into the home. This is not compliant with the rule. Take the necessary steps to only record the time for evacuation of the home. 3. At the time of the survey it was observed that the fire extinguishers were not being monitored on a monthly basis by the staff. This is not compliant with the rule. Take the necessary steps to have the staff check the extinguishers monthly and initial the tags. 4. At the time of the survey it was observed that there were several areas of the floors around the air conditioner registers that were deteriorated and the registers covers did not fit properly or were falling in. This is not compliant with the rule. Take the necessary steps to repair all of these areas. 5. At the time of the survey it was observed that the door to the bedroom at the front foyer would not latch properly. This is not compliant with the rule. Take the necessary steps to repair the door so it latches. 6. At the time of the survey it was observed that the floor transition at the threshold to the bedroom at the front foyer was missing causing a trip hazard. This is not compliant with the rule. Take the necessary steps to replace the transition strip. 7. At the time of the survey it was observed that the smoke detector in the bedroom at the front foyer had missing batteries. This is not compliant with the rule. Take the necessary steps to replace	C 174	C 174 2. To correct this action, effective July 25, 2019, the facility will not include the return time for evacuations. Please see the end of this report for further details. 3. To correct this action, effective July 25, 2019, the facility staff will document when the fire extinguishers have been monitored monthly. Please see the end of this report for further details. 4. To correct this action, the several areas around the air conditioner registers were either repaired or replaced where needed. Repairs were made on August 3, 2019. Please see the end of this report for further details. 5. To correct this action, the door to the bedroom was repaired to latch properly on August 3, 2019. Please see the end of this report for further details. 6. To correct this action, the floor transition at the threshold to the bedroom at the front foyer has been installed. The installation was done on August 3, 2019. Please see the end of this report for further details. 7. To correct this action, a new smoke detector was installed in the bedroom at the front foyer. The installation was made on August 14, 2019. Please see the end of this report for further details.	07-25-19 07-25-19 08-03-19 08-03-19 08-03-19 08-14-19

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation
STATE FORM