

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Ed Miller, conducted on August 21, 2019. Records indicate that the was licensed on 02/02/1987 for Twenty-Four (24) residents. An addition constructed in 1996 increased the total resident capacity to Fifty- Six (56) Beds. Based on this information, we are requiring the original facility to meet the 1984 Minimum Standards and Regulations for Homes for the Aged and Disabled, 1978 North Carolina State Building Code (Rev 8), Section 409- Institutional Occupancy- Unrestrained and the 32-bed addition to meet the 1996/Applicable 2005 Rules for the Licensing of Adult Care Homes and the 1991 North Carolina State Building Code (1995 Rev), Section 409.1 Institutional Occupancy, Unrestrained. Deficiencies were cited that require a Plan of Correction.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Based on observation, the facility failed to meet the NC State Building Code in effect at the time of construction Findings on August 21, 2019: a. Living Room - this space is open to the corridor. This space does not meet all the requirements which would permit it to be open to the corridor. Specifically, the space is not equipped with smoke detectors.	C 101		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Based on record review, and interview with Owner the facility failed to maintain in the facility, current (completed within the last twelve months) annual inspection report(s) required by this Rule. Findings on August 21, 2019: a. The current Fire and Building safety Inspection (Fire Marshal) Report is not available for review by the Surveyor.	C 111		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building mechanical systems are not kept clean and in good repair. Findings on August 21, 2019: a. Front Lobby Housekeeping - the ventilation system with their radiation dampers have an excessive accumulation of dust/lint. b. Staff Bathroom - the ventilation system with their radiation dampers have an excessive accumulation of dust/lint.	C 164		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the Building was not maintained free of hazards, if oxygen cylinders	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 3 fall, breaking their valves, propelling the cylinder, and turning it into a dangerous projectile. Findings on August 21, 2019: a. Staff Bathroom - seven portable medical oxygen cylinders are standing up on the floor in an unapproved plastic beverage crate not physically secured in racks, stands or chained to the structure. b. Bedroom 108 - four portable medical oxygen cylinders are standing up on the floor in an unapproved plastic beverage crate not physically secured in racks, stands or chained to the structure. c. Diaper Room near Bedroom 112 - five portable medical oxygen cylinders are standing up on the floor in an unapproved plastic beverage crate not physically secured in racks, stands or chained to the structure.	C 166		
C 184	Fire Safety-Evacuation plan SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (a) A written fire evacuation plan (including a diagrammed drawing) which has the written approval of the local Code Enforcement Official shall be prepared in large print and posted in a central location on each floor of an adult care home. The plan shall be reviewed with each resident on admission and shall be a part of the orientation for all new staff. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the Facility failed to properly post and maintain the evacuation maps. This would affect all by not providing proper	C 184		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 184	Continued From page 4 guidance during an emergency. Findings on August 21, 2019: a. Corridor near Bedroom 107 - the mounted evacuation map does not identified the viewer's location. ("You Are Here").	C 184		
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Record review of the last 12 months of rehearsals, and interview with owner the Facility failed to document a short description of what the rehearsal involved, and the locations of the simulated fire. Findings on August 21, 2019: a. The rehearsal records do not provide a short description of what the rehearsal involved for all the rehearsals.	C 185		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 5 REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building's emergency equipment was not maintained in a safe and operating condition. This would affect all if they could not promptly find their way to an exit during an emergency. Findings on August 21, 2019: a. Front Door - the exit sign does not illuminate on backup power when tested. b. Corridor near Nurse Station - the self-contained emergency light did not illuminate on backup power when the test button is pushed. c. Corridor near Bedroom 214 - the exit sign does not illuminate on backup power when tested. d. Mechanical Room near Kitchen - the self-contained emergency light did not illuminate on backup power when the test button is pushed. 2. Based on observation, the Building was not maintained in a safe and operating condition, because the doors protecting the opening in the Firewall failed to function as designed. This could affect all residents, staff and visitors by not containing smoke/fire in the fire compartment of origin. Findings on August 21, 2019: a. Firewall near Kitchen - the cross-corridor door is missing its strike bolt and cannot latch into its frame.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 6 3. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in room of origin. Findings on August 21, 2019: a. RCC Office (behind drapes and room)- there are several holes with conduit not firestopped as they penetrate the fire-resistance-rated ceiling assembly. b. Front Lobby Housekeeping - there is a PVC conduit not firestopped as it penetrates the fire-resistance-rated ceiling assembly. c. Med Room - there is an EMT conduit not firestopped as it penetrates the fire-resistance-rated ceiling assembly. d. Mechanical Room near Kitchen - there are multiple holes, pipes, and cables not firestopped as they penetrate the fire-resistance-rated ceiling assembly. e. Riser Room - there are two holes not firestopped as they penetrate the fire-resistance-rated ceiling assembly. f. Front Entrance Exterior Mechanical Room - there many holes, gaps around pipes and cables not firestopped as they penetrate the fire-resistance-rated ceiling assembly. g. Front Entrance Exterior Mechanical Room - the attic access panel is missing, permitting a large penetration of the fire-resistance-rated ceiling assembly. h. Front Entrance Exterior - there are multiple penetration sealed with orange foam. This orange foam is not approved for penetrations through fire-resistance-rated construction. i. Refrigerator Room - a new refrigerator was built into this room and fills-up the room. There is no means to inspect the rated ceiling above the acoustical ceiling tile and the corridor door is a siding barn style that is not smoke tight.	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 7 4. Based on observation, the smoke tight corridor doors are not maintained in a safe and operating condition. Findings on August 21, 2019: a. RCC Office - there are two 1/4-inch diameter holes through the corridor door around the door handle. b. Bedroom 210 - the corridor door does not latch into its frame when closed. c. Bedroom 214 - the corridor door does not latch into its frame when closed. d. Diaper Room near Bedroom 112 - there are two 1/4-inch diameter holes through the corridor door around the door handle. e. Dietary Storage - the corridor door latch bolt does not automatically retract when closing the door, the handle must be turned. 5. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Findings on August 21, 2019: a. Bedroom 112 - the ground-fault circuit-interrupter (GFCI) electrical power receptacle does not trip when its test button is pushed or when tested with a ground fault receptacle tester & circuit analyzer. b. Public Restroom near Kitchen - the ground-fault circuit-interrupter (GFCI) electrical power receptacle does not trip when its test button is pushed or when tested with a ground fault receptacle tester & circuit analyzer. c. Mechanical Room near Kitchen - an electrical junction box with energized components, was missing its cover plate. 6. Based on observation, the Building Sprinkler System was not maintained in a safe and operating condition. This could affect all	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 8 residents, staff, and visitors if smoke/fire is not contained in the room or compartment of origin. Findings on August 21, 2019: a. Front Lobby Housekeeping - the escutcheon plate on the fire sprinkler has dropped down from the fire-resistance-rated ceiling, exposing an opening that allows the spread of smoke and heat.	C 189		
C 191	Unvented & Portable Elec. Heaters Prohibited SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (b) There shall be a heating system sufficient to maintain 75 degrees F (24 degrees C) under winter design conditions. In addition, the following shall apply to heaters and cooking appliances. (2) Unvented fuel burning room heaters and portable electric heaters are prohibited. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to prevent the use of portable electric heaters in an Adult Care Home. This could affect residents, staff, and visitors if heater is the ignition source of a fire. The danger increases if used by resident or combustible material is near. Findings on August 21, 2019: a. Bedroom 112 - a portable electric heater was found in this room.	C 191		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/21/2019
NAME OF PROVIDER OR SUPPLIER ST ANDREWS LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 246 CABARRUS WEST CONCORD, NC 28025		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 9 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in rooms required to be mechanically exhausted. Findings on August 21, 2019: a. Bathroom near Bedroom 206 - the required exhaust ventilation system at the commode does not work. b. Public Restroom near Kitchen - the required exhaust ventilation system at the commode does not work.	C 199		