

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Dennis Harrell on 8-28-2019. A Complaint Follow Up Survey was conducted at the same time. Records indicate this Facility was first licensed on 1-8-1979, and an addition to the building was completed in 1982. Another addition was completed in 1986 for a total capacity of 57 residents. Therefore, the original facility and the first addition are required to meet the 1977 Minimum and desired Standards and Regulations for Homes for the Aged and Infirm and the second addition to meet the 1984 Minimum Standards and Regulations to Homes for the Aged and Disabled. The entire facility is required to meet the applicable portions of the 2005 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm and the 1978 North Carolina State Building Code, Section 409.1(c), Institutional (I) Occupancy- Unrestrained, Group I-2. Deficiencies were cited which will require a plan of correction.	C 000		
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: Based on observation, the installation of new HVAC equipment was mostly complete with the	C 111		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 111	Continued From page 1 following exception; On the day of the survey, a technician was onsite installing a duct mounted smoke detector. Based on interview with the owner/maintenance director the project (project HA-3198) is ready and waiting inspection by the local authorizes. Based on a review of documents, there were no approved Building Inspection documents available for the several new gas pack/air conditioning units recently installed. New air conditioning systems must be inspected and approved.	C 111		
C 154	Entrances/Exits-Wanderer Alarms SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (4) In homes with at least one resident who is determined by a physician or is otherwise known to be disoriented or a wanderer, each exit door accessible by residents shall be equipped with a sounding device that is activated when the door is opened. The sound shall be of sufficient volume that it can be heard by staff. If a central system of remote sounding devices is provided, the control panel for the system shall be located in the office of the administrator or in a location accessible only to staff authorized by the administrator to operate the control panel. This Rule is not met as evidenced by: Based on interview with staff, some residents are considered confused and/or disoriented. Based on observation, the Wander Guard alarm	C 154		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 154	Continued From page 2 provided did not work at the exit near the oxygen room.	C 154		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the exit door near the community laundry was at first stuck and then continued to be very hard to open after it was unstuck. Exits that could stick or be difficult to open could delay or prevent an evacuation in an emergency. 2. Based on observation, the building was not maintained in a safe manner by not properly handling portable medical oxygen cylinders. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings on 8-28-2019: Two portable medical oxygen cylinders were stored in no container or rack in the oxygen room. 3. Based on observation, the hose on the shower wands at the tubs in the bathrooms off the Long Hall and the 300 Hall were long enough to reach the tub basin and there were no vacuum breakers provided. Hoses on water fixtures that are long	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 3 enough to reach the flood rim of the fixture present the possibility of siphoning contaminated water into the water system unless a vacuum breaker is installed.	C 166		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, corridor doors are prevented from closing quickly and latching to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility. Findings on 8-28-2019; a. One of the fire doors near room 205 did not close completely and latch when activated by the fire alarm system. b. The door to the resident laundry will not latch when closed. c. The door to bedroom 207 will not latch when closed. d, The door to the living room was blocked open with a table. i. The door to bedroom 203 does not fit the opening properly to be resistant to the passage of	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 smoke. 2. Based on observation, the required one-hour fire rated walls and/or ceilings were compromised in locations. Holes and penetrations that are not sealed with materials approved for use in one-hour fire rated construction present the possibility that a fire that begins in one space can quickly spread to other areas of the facility. Findings on 8-28-2019: a. Unsealed penetration in the ceiling of the maintenance room, b. Hole in the ceiling of the kitchen at the exit sign, c. Unsealed penetrations in the ceiling of the "Mechanical Closet" on 300 Hall. 3. Based on observation, the roof flashing was damaged at a fire wall on the left side of the building. The damaged flashing could cause a leak and compromise the one-hour fire rated ceiling. 4. Based on observation, the corridor smoke detector near room 107 was hanging by the wires. Smoke detectors that are not properly mounted compromise the one-hour fire rated ceiling and may not work properly in a fire. Note; This deficiency was corrected during the survey.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL012040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/28/2019
NAME OF PROVIDER OR SUPPLIER JONAS RIDGE ADULT CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 9051 HWY 181 JONAS RIDGE, NC 28641		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 5 before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Based on observation the facility failed to maintain required exhaust in a working condition. Findings on 8-28-2019; The exhaust provided was not working in "Environmental Services" on 300 Hall.	C 199		