

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 000	Initial Comments Report of a Construction Section Biennial Survey by Suzanna Fay and Tod Hancock conducted on July 19, 2023. Records indicate this facility was first licensed or submitted for licensure on October 8, 1996 as a Home for the Aged. The facility is currently licensed for 78 Beds with a 20 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the current 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and the 1996 Edition of the North Carolina Building Code(s), Institutional Occupancy and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure. Deficiencies were cited that require a Plan of Correction.	C 000	Responses to the cited deficiencies do not constitute an admission or agreement by the facility of the truths of the facts alleged or conclusions set forth in the Corrective Action Report; The Plan of Correction is prepared solely as a matter of compliance with State law.		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of	C 101			

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Amey Carter

Executive Director

9/8/2023

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 101	Continued From page 1 Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Observations revealed that the facility does not meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration. Doors located in smoke barrier walls are required to automatically close. Findings on July 19, 2023: a. Office Hall - the closer on the door in the smoke barrier wall has been removed so that the door does not automatically close. 2. Observations revealed that the facility does not meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation or alteration. Electromagnetic locks shall have an on/off emergency release switch capable of interrupting power to all electromagnetically locked doors in the facility. Release switches shall be located and properly identified at each nurses station serving the locked unit. An additional emergency release switch shall be provided for each locked door and located within 3 feet of the door. Findings on July 19, 2023: a. Exit by Room D134 - the screamer box covering the emergency release switch was screwed shut which would not allow access to the emergency release during an emergency if the door did not release automatically. The screw was removed at the time of survey.	C 101	New Closer installed. Corrected and replaced Battery	8/24/23 8/24/23	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 111	Continued From page 2	C 111			
C 111	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Review of records revealed that the facility did not have current fire and building safety inspection reports maintained in the home and available for review. Findings on July 19, 2023: a. There was not a copy of the current Fire Official's Inspection Report available for review. b. There was not a copy of the current Annual Fire Alarm Inspection Report available for review. c. There was not a copy of the current Annual Sprinkler Inspection Report available for review.	C 111			
C 135	Bathrooms-Not to Be Utilized for Storage SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (10) Resident toilet rooms and bathrooms shall not be utilized for storage or purposes other than those indicated in Item (4) of this Rule; This Rule is not met as evidenced by: 1. Observations revealed that one of the bathrooms was being utilized for storage.	C 135		Scheduled for completion on 9/11/23. Annual Fire Alarm Inspection printed and filed for review. Annual Sprinkler report printed and filed for review. 9/11/23	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK		STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 135	Continued From page 3 Findings on July 19, 2023: a. AL Spa - there are approximately 30 cardboard boxes of toilet paper and other supplies as well as cleaning equipment stored in the bathroom.	C 135	Removed and stored in storage room.	8/28/23	
C 154	Entrances/Exits-Wanderer Alarms SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (4) In homes with at least one resident who is determined by a physician or is otherwise known to be disoriented or a wanderer, each exit door accessible by residents shall be equipped with a sounding device that is activated when the door is opened. The sound shall be of sufficient volume that it can be heard by staff. If a central system of remote sounding devices is provided, the control panel for the system shall be located in the office of the administrator or in a location accessible only to staff authorized by the administrator to operate the control panel. This Rule is not met as evidenced by: 1. Observations revealed that the facility has residents known to be disoriented or a wanderer which requires that each exit door accessible by residents to be equipped with a sounding device that is activated when the door is opened. Findings on July 19, 2023: a. B Hall - the screamer box at the porch did not alarm when opened. b. C Hall - the screamer boxes on either side of the entry doors into the the SCU did not alarm when opened.	C 154	Screamer box ordered from First Fire Boxes repaired and working properly	9/20/23 8/28/23	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 160	Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition; This Rule is not met as evidenced by: 1. Observations revealed that the outside premises were not maintained in a clean and safe condition. Findings on July 19, 2023: a. The porch over the can wash outside of the Kitchen has areas of water damage and is showing signs of decay. b. Exit outside of Room D134 - there is a sharp slope where the concrete stoop connects to the sidewalk creating a possible fall hazard. There is a large crack, approximately 1" in width between the steep sloped portion and the concrete sidewalk creating a possible trip hazard.	C 160	The area has been removed to eliminate decay. Crack area has been replaced/ repaired not to cause possible t rip hazard.	8/31/23	9/6/23
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities.	C 164			

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 164	Continued From page 5 This Rule is not met as evidenced by: 1. Observations revealed that the furnishings were not kept in good repair. Findings on July 19, 2023: a. Room B114 - B Closet has a 1" square hole in the surface of the door where the door stop is hitting the door. 2. Observations revealed that the ceilings were not kept in good repair. Findings on July 19, 2023: a. Room B116 - the ceiling finish around the back sprinkler head is flaking and peeling.	C 164	Hole has been repaired.	8/24/23	
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility was not maintained free from hazards. Oxygen bottles were improperly stored. Oxygen bottles without any means of restraint to prevent them from falling or being knocked over may present a danger to the occupants of the facility. Findings on July 19, 2023:	C 166	Ceiling finish has been patched to ensure no flaking and peeling.	8/24/23	

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 185	Continued From page 7 conducted quarterly on each shift. Findings on July 19, 2023: a. There was not a fire rehearsal recorded on the first shift of the third quarter of 2022. b. There was not a fire rehearsal recorded on the third shift of the fourth quarter of 2022. c. There was not a fire rehearsal recorded on the third shift of the second quarter of 2023.	C 185	Training has been conducted with ED/RCC/BOM to ensure a fire rehearsal/drill is completed quarterly on each shift, along with attendees, time of drills, shift and short description of what rehearsal/drill involved. These records shall be maintained and copies furnished to the county annually.	8/30/23	
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation there is a failure to maintain the building's fire safety systems in a safe condition. Holes or gaps at penetrations through fire resistant rated ceilings could allow fire and smoke to spread beyond the area of origin. Findings on July 19, 2023: a. Mechanical Room in Dining - there is a hole in the ceiling around the mechanical lines. b. There is a small hole in the ceiling at the base of the sprinkler head outside of Room D125. c. The escutcheon ring on the sprinkler head outside of the Guest Bathrooms has dropped	C 189		Hole in Mechanical room in dining has been fire caulked. Small hole in ceiling at sprinkler head outside RM#D125 has been Fire Caulked. Escutcheon ring has been repaired	8/24/23 8/24/23 8/24/23

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/19/2023
---	---	---	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

SOUTHFORK

1345 JONESTOWN ROAD

WINSTON SALEM, NC 27103

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 8 leaving a hole in the fire resistant rated ceiling. d. Mechanical Room - the duct for the hot water heater is missing a collar leaving an unsealed penetration in the fire resistant rated ceiling. e. Room C108 - the escutcheon plate on the sprinkler head nearest the window has dropped leaving a gap in the fire resistant rated ceiling. f. C Hall Dining/Activity Room - there is a 2" diameter hole in the ceiling that has been stuffed with a paper towel. g. C Hall Spa - there is an unsealed data cable penetration in the ceiling near the corridor wall. The cable is hanging loose and not secured. 2. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on July 19, 2023: a. Mechanical Closet in Dining - the door hits the frame and does not close automatically using the attached closer. b. Kitchen - a gallon jug of hand sanitizer was on the shelf below the roll-down door which could prevent the door from closing during a fire. The sanitizer was removed at the time of survey. 3. Based on observation the facility's fire safety components are not being maintained in a safe operable manner. Doors were blocked open or held open by unapproved devices or methods. All the occupants in the facility could be effected if doors cannot be closed or closed rapidly so as to limit the spread of smoke and fire to the area of origin.	C 189	Mechanical Room duct has been repaired RoomC108 escutcheon has been repaired. Awaiting Sprinkler company to replace C Hall spa ceiling issue has been repaired. Door has been repaired/adjusted in Mechanical closet in Dining area. All Sanitizer removed from shelf and placed properly in storage.	8/31/23 8/24/23 8/24/23 8/24/23 7/19/23

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 189	Continued From page 9 Findings on July 19, 2023: a. Kitchen Pantry - the door was held open using a wedged device. b. Clean Linen - the door was held open using a wire hanger. The hanger was removed at the time of survey. c. Laundry - the door between Laundry and Soiled Linen was held open using a wedged device. When the device was removed the door was prevented from closing due to a clothespin hanging on the door closer arm. Both items were removed at the time of survey. d. Room D131 - the door was tied back using a plastic garbage bag. The plastic was removed at the time of survey. e. Room C114 - the door was tied back using a plastic garbage bag. The plastic was removed at the time of survey. 4. Based on observation the facility's fire safety equipment is not maintained in operating condition. Failure to maintain fire safety equipment in operating condition could effect occupants of the facility if the equipment could not operate properly to suppress a fire. Findings on July 19, 2023: a. The deflector on the sprinkler head outside of Room D125 is bent which may deter the ability of the head to suppress a fire. 5. Based on observation the electrical equipment has not been maintained in a safe manner. This is a potential shock hazard if receptacles near water sources do not function to provide shock protection. Findings on July 19, 2023: a. Drop Off Porch - the exterior GFCI outlet to the left of the door does not have power.	C 189	Wedge removed and door closed Hanger removed and door closed Items removed to prevent door from properly closing. All items removed to ensure door closes. All items removed to ensure door closes. Awaiting Sprinkler company to replace Replaced the GFCI outlet.	8/24/23 7/19/23 7/19/23 7/19/23 7/19/23 8/25/23	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK			STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 189	Continued From page 10 b. Room D137 Bath - the bottom screw of the GFCI cover plate at the sink was missing and the plate and box were not secure. 6. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on July 19, 2023: a. The emergency light outside of Room D134 did not illuminate on test. 7. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. Occupants in the smoke compartment could be exposed to smoke or fire if doors do not completely close and latch to help limit the spread of smoke or fire to the area of origin. Findings on July 19, 2023: a. Room C110 - the door rubs hard on the floor and requires excessive force to close.	C 189	Repaired. Battery replaced and working. Repaired Door trimmed and repaired to close with no force	8/24/23 8/28/23 8/28/23 8/28/23	
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room;	C 199			

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/19/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK		STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 11 (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not maintain exhaust ventilation in specified spaces. Lack of ventilation allows for the build up humidity that can cause mildew and slick areas and prevents the dissipation of odors. Findings on July 19, 2023: a. D Hall - the exhaust fans on D Hall are not working.	C 199	New exhaust fan motor ordered. Will install upon arrival.	9/20/23