

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL051056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 03/14/2024
NAME OF PROVIDER OR SUPPLIER THE VILLAS BENSON I		STREET ADDRESS, CITY, STATE, ZIP CODE 606 EAST MORRIS AVENUE BENSON, NC 27504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report by Scott Greenwood DHSR Construction Section conducted a Biennial Follow Up Survey on March 14, 2024 from 9:20 AM to 9:45 AM. At the time of the follow up survey not all of the previously cited deficiencies have been corrected. . Therefore further action is required. The cited deficiencies are as follows;	{C 000}		
{C 174}	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that there was lint buildup and debris behind the clothes dryer. This is not compliant with the rule. Take the necessary steps to correct this deficiency. 2. At the time of the survey it was observed that the toilet paper holder was missing in bathroom #1. This is not compliant with the rule. Take the necessary steps to correct this deficiency. 3. At the time of the survey it was observed that	{C 174}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL051056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 03/14/2024
NAME OF PROVIDER OR SUPPLIER THE VILLAS BENSON I		STREET ADDRESS, CITY, STATE, ZIP CODE 606 EAST MORRIS AVENUE BENSON, NC 27504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 174}	Continued From page 1 there was peeling ceiling paint at the attic access panel in the dining room. This is not compliant with the rule. Take the necessary steps to correct this deficiency. 4. At the time of the survey it was observed that the exterior clothes dryer vent was damaged. This is not compliant with the rule. Take the necessary steps to correct this deficiency.	{C 174}		