

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL095008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/16/2024
NAME OF PROVIDER OR SUPPLIER DEERFIELD RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 287 BAMBOO ROAD BOONE, NC 28607		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Tod Hancock conducted on April 16, 2024. This facility was first licensed on March 25, 1999, and is currently licensed for 96 beds including the 44 beds in the SCU. Therefore, this facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds, and applicable portions of the 1996 with 1999 revisions of the North Carolina State Building Code(s), Intuitionl Occupancy Unrestrained, and the 1996 Minimum Standards and Regulations for Homes for the Aged in effect at time of initial licensure. Deficiencies have been cited and a Plan of Correction is required.	C 000		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and review of the Fire Sprinkler inspection report, the building's sprinkler system was not maintained in a safe and operating condition. This would affect all if the fire was not contained in the room of origin.	C 189		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL095008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/16/2024
NAME OF PROVIDER OR SUPPLIER DEERFIELD RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 287 BAMBOO ROAD BOONE, NC 28607		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1 Findings on April 16, 2024: a. Entrance Portico- The sprinklers are rusted and pitted and should be replaced. 2. Based on observation, and review of damper inspection report, there is a failure to maintain the facility's fire safety equipment in a safe operating condition. The occupants in the smoke compartment could be affected if the fire-dampers do not operate when activated to help limit the spread of smoke and/or fire to the area of origin. Findings on April 16, 2024: a. A Hall- Room 6-Bathroom-The damper is missing parts. b. A Hall-Room 7- Bathroom- The damper is missing parts. c. A Hall- Room 8- Bathroom- The damper is missing parts. d. A Hall- Room 12- Inspection revealed it is damaged. d. Main Lobby- Men's restroom- The damper failed its operational test. c. Main Lobby- Private Dinig Room- The damper failed its operational test. 3. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition. The occupants in the smoke compartment could be affected if the fire-resistant rated doors do not completely close and latch to help limit the spread of smoke and/or fire to the area of origin. Findings on April 16, 2024: a. Memory Care- Laundry- The door is missing	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL095008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/16/2024
NAME OF PROVIDER OR SUPPLIER DEERFIELD RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 287 BAMBOO ROAD BOONE, NC 28607		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 the closer arm and strike plate.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the facility is not maintaining its exhaust fan in an operable condition. This could cause unnecessary odors as well as mildew. Findings on April 16, 2024: a. Assisted Living-Guest Bathroom- The exhaust fan is not working.	C 199		