

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL086008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 08/06/2024
NAME OF PROVIDER OR SUPPLIER TWELVE OAKS			STREET ADDRESS, CITY, STATE, ZIP CODE 1297 GALAX TRAIL MOUNT AIRY, NC 27030		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
{C 000}	Initial Comments Report of a Construction Section Biennial Follow Up Survey by Tod Hancock, conducted on August 6, 2024. Deficiencies remain uncorrected and a Plan of Correction is required.	{C 000}	Responses to the cited deficiencies do not constitute an admission by the facility of the truth of the facts alleged or conclusions set forth in the statement of deficiencies or corrective action report. The plan of correction is prepared solely as a matter of compliance with state law.		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS	{C 189}			
	(a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.		a) The Fire Alarm Panel (FACP) was repaired on 9/6/2024. The system is now fully operational.		
	This Rule is not met as evidenced by: 1. Based on observation and interview with the Maintenance Director, the Fire Sprinkler system was not maintained in a safe and operating condition. This would affect all by not providing suppression of a fire. Findings on August 6, 2024: a. The Fire Alarm Control Panel (FACP) was signaling a supervisory alarm. Staff indicated that there were leaks in the fire sprinkler system on the SCU side and that the system had been taken out of service and repairs had been initiated. A fire watch had been put in place until repairs could be completed.				

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE *Executive Dir* (X6) DATE

STATE FORM

6896

NRWG23

9/27/24

If continuation sheet 1 of 1