

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041082	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 01/09/2025
NAME OF PROVIDER OR SUPPLIER ALPHA CONCORD OF GREENSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE 3301 GAR PLACE GREENSBORO, NC 27406		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay conducted on January 9, 2025. There are deficiencies cited in the Biennial Construction Survey that remain to be corrected.	{C 000}		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observations, the building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in the room of origin. Findings on January 9, 2025: b. 300 Hall, Kitchen Pantry - there was one unsealed black cable penetration remaining at the commercial kitchen hood's fire suppression system. 5. Based on observation, the Building Sprinkler System was not maintained in a safe and operating condition. This would affect all if a fire were not contained in the room or compartment of origin.	{C 189}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041082	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 01/09/2025
NAME OF PROVIDER OR SUPPLIER ALPHA CONCORD OF GREENSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE 3301 GAR PLACE GREENSBORO, NC 27406		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 1 Findings on January 9, 2025: d. 200 Hall, Corridor near Bedroom 212 - a fire sprinkler was missing its escutcheon plate exposing an opening through the fire-resistance-rated ceiling. Interview with staff revealed that they added the escutcheon plate to a different head.	{C 189}		
{C 199}	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and testing with a thin plastic sheet, the facility did not provide working ventilation in spaces needed to have ventilation. Findings on January 9, 2025: a. 100 Hall, Utility Room near Bedroom 101 - the exhaust ventilation system was not removing air. Interview with staff revealed that they had the unit running but it tripped off after a period of time. b. 300 Hall, Dining Room Utility Closet - the	{C 199}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041082	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 01/09/2025
NAME OF PROVIDER OR SUPPLIER ALPHA CONCORD OF GREENSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE 3301 GAR PLACE GREENSBORO, NC 27406		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 199}	Continued From page 2 exhaust ventilation system was not removing air. Interview with staff revealed that they had the unit running but it tripped off after a period of time. d. 400 Hall, Men Restroom - the exhaust ventilation system was not removing air. Interview with staff revealed that they had the unit running but it tripped off after a period of time.	{C 199}		