

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/09/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355053	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - KNIFE RIVER CARE CENT B. WING 2011	(X3) DATE SURVEY COMPLETED 06/06/2011
NAME OF PROVIDER OR SUPPLIER KNIFE RIVER CARE CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 118 22ND ST NE BEULAH, ND 58523	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
			(X5) COMPLETION DATE

K 000 INITIAL COMMENTS

K 000

This survey used the 2000 edition of NFPA 101, Life Safety Code, Chapter 18 New Health Care Occupancies in compliance with 42 CFR 483.70(a). The findings demonstrate noncompliance with these standards.

The facility is located in a one-story building of Type V (111) construction built in 2007. The building is equipped with an automatic wet and dry sprinkler system with quick response sprinklers designed to meet the requirements of NFPA 13, Standard for Installation of Sprinkler Systems.

K 029 NFPA 101 LIFE SAFETY CODE STANDARD
SS=D

K 029

Hazardous areas are protected in accordance with 8.4. The areas are enclosed with a one hour fire-rated barrier, with a 3/4 hour fire-rated door, without windows (in accordance with 8.4). Doors are self-closing or automatic closing in accordance with 7.2.1.8. 18.3.2.1

K029 Plan of Correction

06-22-11

Maintenance will properly reinstall the door self-closing device. Maintenance will add self-closing device to the Door Inspection list.

This STANDARD is not met as evidenced by:
The facility failed to protect door openings to one (1) of six (6) hazardous areas with self-closing doors.

Observation determined the Clean Linen/Laundry Room corridor door was not equipped with a self-closing device.

K 062 NFPA 101 LIFE SAFETY CODE STANDARD
SS=E

K 062

Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested

K 062 Plan of Correction

07-08-11

Maintenance has call Nova Sprinkler Systems to correct the system by lowering the sprinklers in rooms 161, 263,

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

R. [Signature]

ADMINISTRATOR

06-15-11

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/09/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355053	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - KNIFE RIVER CARE CENT B. WING _____		(X3) DATE SURVEY COMPLETED 06/06/2011
NAME OF PROVIDER OR SUPPLIER KNIFE RIVER CARE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 118 22ND ST NE BEULAH, ND 58523		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 062	Continued From page 1 periodically. 18.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: The facility failed to ensure the automatic sprinkler system was continuously maintained in a reliable operating condition as required by NFPA 25, Standard for the Inspection, Testing and Maintenance of Water-based Fire Protection Systems. Observation determined the sprinklers in Resident Rooms 161, 263, and 314 were obstructed by surface mounted lift rails.		K 062	and 314 to clear the ceiling track life rail. Before anymore rails are added sprinkler head clearance will be checked.	
K 130 SS=F	NFPA 101 MISCELLANEOUS OTHER LSC DEFICIENCY NOT ON 2786 This STANDARD is not met as evidenced by: A functional test must be conducted on every required emergency lighting system at 30-day intervals for not less than 30 seconds. An annual test must be conducted on every required battery-powered emergency lighting system for not less than 1 1/2-hours. Equipment must be fully operational for the duration of the test. Written records of visual inspection and tests must be kept by the owner for inspection. 7.9.3 The facility failed to assure maintenance and testing of emergency lighting. Review of records could not verify 30-second monthly tests and the 1 1/2-hour annual test of the battery-powered lighting located throughout the facility.		K 130	K 130 Plan of Correction Maintenance will be checking emergency lights monthly for 30 seconds and yearly for 90 minutes. This will be recorded on the Generator Inspection sheet. This has already been started and is on the inspection sheet for June 7, 2011. Continuous Quality Improvement focus will be added to current CQI meeting with quarterly reviews.	06-07-11