

North Dakota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8104	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - GOOD SAMARITAN SOCIETY-FARGO B. WING _____	(X3) DATE SURVEY COMPLETED 03/03/2021
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - FARGO		STREET ADDRESS, CITY, STATE, ZIP CODE 4502 37TH AVE S FARGO, ND 58104		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 32 New Residential Board and Care Occupancies (Large), and Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located in a one-story building of Type V (111) construction that was protected by an automatic sprinkler system designed to meet the requirements of NFPA 13, Standard for the Installation of Sprinkler Systems. An occupancy separation wall having a two-hour fire resistance rating separated the church building that was attached to the north side of the basic care building. A one-story addition of Type V (111) construction was attached to the south side of the existing building in 2017. This addition was surveyed using Chapter 32. Resident evaluation determined a Slow level of evacuation difficulty. The E-Score was 2.18. Note: Review of records and observations made during the survey determined the facility was in compliance with the 2012 edition of NFPA 101, Life Safety Code.	K 000		

Health Resources Section

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE