

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/02/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355064		RECEIVED BUILDING 01 - MAIN BUILDING 01 MAR 17 2011 DIVISION OF LIFE SAFETY AND CONSTRUCTION GARRISON, ND 58540		(X3) DATE SURVEY COMPLETED 03/01/2011	
NAME OF PROVIDER OR SUPPLIER BENEDICTINE LIVING CENTER OF GARRISON				STREET ADDRESS, CITY, STATE, ZIP CODE 809 4TH AVE NE GARRISON, ND 58540			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS This survey used the 2000 edition of NFPA 101, Life Safety Code, Chapter 19 Existing Health Care Occupancies, in compliance with 42 CFR 483.70(a). This facility is located in a one-story building of Type III (200) construction with no automatic sprinkler system. The Fire Safety Evaluation System (FSES) was used as an alternative safety method for K 012 Construction Type and K 017 Corridor Walls. The Benedictine Living Center does not meet the Life Safety Code requirements for minimum construction type and corridor wall construction but does pass the FSES if all other deficiencies are corrected. Note: CMS requires unsprinklered long term care facilities to install an approved, supervised automatic sprinkler system in accordance with the 1999 edition of NFPA 13, Standard for the Installation of Sprinkler Systems throughout the building by August 13, 2013.		K 000				
K 011 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD If the building has a common wall with a nonconforming building, the common wall is a fire barrier having at least a two-hour fire resistance rating constructed of materials as required for the addition. Communicating openings occur only in corridors and are protected by approved self-closing fire doors. 19.1.1.4.1, 19.1.1.4.2		K 011				

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE 	TITLE Administrator	(X6) DATE 3/14/11
---	------------------------	----------------------

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/02/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355064	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 03/01/2011
NAME OF PROVIDER OR SUPPLIER BENEDICTINE LIVING CENTER OF GARRISON			STREET ADDRESS, CITY, STATE, ZIP CODE 609 4TH AVE NE GARRISON, ND 58540		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 011	Continued From page 1 This STANDARD is not met as evidenced by: The facility failed to ensure complete two-hour fire rated wall assemblies between the nursing home and the assisted living center. Manufacturers typically design 90-minute fire rated metal double doors to latch into the door frame and into the floor. Observation determined the 90-minute fire rated double doors located between the nursing home and the assisted living center were not latching into the floor.	K 011			
K 012 SS=C	NFPA 101 LIFE SAFETY CODE STANDARD Building construction type and height meets one of the following. 19.1.6.2, 19.1.6.3, 19.1.6.4, 19.3.5.1 This STANDARD is not met as evidenced by: The facility has not ensured the appropriate construction type for a one-story health care occupancy. Observation determined the building is of Type III (200) construction and is not protected with an automatic sprinkler system. The Life Safety Code requires existing health care occupancies of this construction type to be protected by an automatic sprinkler system meeting the requirements of NFPA 13, Standard for Installation of Sprinkler Systems.	K 012			
K 017 SS=C	NFPA 101 LIFE SAFETY CODE STANDARD Corridors are separated from use areas by walls	K 017	The 03/01/11 Life Safety Code survey used the Fire Safety Evaluation System (FSES) for K 012 to allow the present type of construction of the facility. The facility passes the FSES upon correction of all other deficiencies.		

PRINTED: 03/02/2011
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 62BM21 Facility ID: ND136 If continuation sheet Page 3 of 5

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/02/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355064	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/01/2011
---	--	---	--

NAME OF PROVIDER OR SUPPLIER BENEDICTINE LIVING CENTER OF GARRISON	STREET ADDRESS, CITY, STATE, ZIP CODE 609 4TH AVE NE GARRISON, ND 58540
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 038	Continued From page 3 The forces required to fully open any door manually in a means of egress shall not exceed 15 lbf to release the latch, 30 lbf to set the door in motion, and 15 lbf to open the door to the minimum required width. 7.2.1.4.5 The facility failed to ensure exit access was readily accessible at all times. Observation determined the exterior exit door from the Boiler Room required excessive force to open because of frost heaving at the exit discharge.	K 038	K- 038 SS= D 1) The heaving cement will be removed and re-cemented. 2) All outside exit accesses will be evaluated in the months of December, January, February, March and April to assure they are accessible. 3) Regular monitoring of exit access. 4) Monthly check-off list for months indicated in #2. 5) Will be completed by April 15, 2011.	4/15/11
K 045 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Illumination of means of egress, including exit discharge, is arranged so that failure of any single lighting fixture (bulb) will not leave the area in darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8 This STANDARD is not met as evidenced by: The facility failed to ensure the illumination of means of egress, including exit discharge, was arranged so that failure of a single lighting fixture or bulb would not leave the area in darkness.	K 045	K-045 SS= D 1) An additional light fixture will be installed. 2) All other exit areas have double lights. 3) Monthly monitoring. 4) Monthly check-off list will be used to monitor lighting at exits. 5) Will be completed by April 15, 2011.	4/15/11
K 069 SS=B	NFPA 101 LIFE SAFETY CODE STANDARD Cooking facilities are protected in accordance with 9.2.3. 19.3.2.6, NFPA 96 This STANDARD is not met as evidenced by:	K 069		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/02/2011
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355064	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 03/01/2011
NAME OF PROVIDER OR SUPPLIER BENEDICTINE LIVING CENTER OF GARRISON			STREET ADDRESS, CITY, STATE, ZIP CODE 609 4TH AVE NE GARRISON, ND 58540		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 069	Continued From page 4 Fire extinguishing systems for commercial cooking operations must meet NFPA 96, Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations. NFPA 96 requires an inspection and servicing of the fire-extinguishing system be made at least every 6 months by properly trained and qualified persons. The facility failed to inspect and service the fire-extinguishing system at least every 6 months. Review of the records determined the cooking equipment fire extinguishing system was inspected on 5/26/10 and 12/02/10. The time period between each inspection exceeds 6 months.	K 069	K- 069 SS= B 1) Hood inspections will be scheduled every 6 months 2) No other portions of the facility are affected with only one protective hood. 3) Regular scheduled protective hood inspections. 4) Protective hood will be inspected for cleanliness monthly. Servicing of protective hood will be scheduled every May and November. 5) Completion date of March 22, 2011.	3/22/11	