



PRINTED: 10/29/2025
FORM APPROVED

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8204	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING _____	(X3) DATE SURVEY COMPLETED 10/28/2025	
NAME OF PROVIDER OR SUPPLIER EDGEWOOD JAMESTOWN, LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1104 25TH ST SW JAMESTOWN, ND 58401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 32 New Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The findings that follow demonstrate noncompliance with these standards. The facility was located in a one-story building of Type V (111) construction. The building was fully sheathed and was protected with a wet and dry automatic sprinkler system designed to meet the requirements of NFPA 13, Standard for the Installation of Sprinkler Systems. An assisted living facility was located in the same building. Resident evaluation determined a Slow level of evacuation difficulty. The E-score was 4.18.	K 000		
K 244	Emergency Egress and Relocation Drills Emergency Egress and Relocation Drills. Emergency egress and relocation drills shall be conducted in accordance with 33.7.3.1 through 33.7.3.6. 33.7.3 This State Licensing Rule is not met as evidenced by: Fire drills must be held monthly with a minimum of twelve drills per year, alternating with all work shifts. Residents and staff, as a group, shall either evacuate the building or relocate to an assembly point identified in the fire evacuation plan. At least once a year, a fire drill must be conducted during which all staff and residents evacuate the building.	K 244		

Health Response and Licensure

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X8) DATE

STATE FORM

6399

VQQ021

If continuation sheet 1 of 5

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8204	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING _____	(X3) DATE SURVEY COMPLETED 10/28/2025
NAME OF PROVIDER OR SUPPLIER EDGEWOOD JAMESTOWN, LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1104 25TH ST SW JAMESTOWN, ND 58401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 244	Continued From page 1 Written records of fire drills must be maintained. These records must include dates, times, duration, names of staff and residents participating and those absent and why, and a brief description of the drill, including the escape path used and evidence of simulation of a call to the fire department. Each resident shall receive an individual fire drill walk-through within five days of admission. Any variation to compliance with the fire safety requirements must be approved in writing by the department. Residents of facilities meeting a greater level of fire safety must meet the fire drill requirements of that occupancy classification. 4.7.4, NDAC 33-03-24.2-08. The facility failed to conduct fire drills as required. Fire drill records review determined no fire drill was conducted on the Night Shift during the fourth quarter in the past year. Failure to conduct fire drills as required increases the risk of injury and death. The deficiency affected one (1) of twelve (12) required fire drills in the past year.	K 244	All fire drills are entered into our TELS system and will be Conducted monthly on all shifts and at different times.	10/30/2025
K 251	MANUAL FIRE ALARM General. A fire alarm system in accordance with Section 9.6 shall be provided, unless all of the following conditions are met: (1) The facility has an evacuation capability of prompt or slow. (2) Each sleeping room has exterior exit access in accordance with 7.5.3. (3) The building does not exceed three stories in height.	K 251		

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8204	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING _____	(X3) DATE SURVEY COMPLETED 10/28/2025
NAME OF PROVIDER OR SUPPLIER EDGEWOOD JAMESTOWN, LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1104 25TH ST SW JAMESTOWN, ND 58401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 251	Continued From page 2 33.3.3.4.1 This State Licensing Rule is not met as evidenced by: A fire alarm system in accordance with section 9.6 shall be provided. 32.3.3.4.1. A fire alarm system required for life safety shall be installed, tested, and maintained in accordance with the applicable requirements of NFPA 70, National Electrical Code and NFPA 72, National Fire Alarm and Signaling Code. 9.6.1.3. 2010 NFPA 72, 14.1.1 The facility failed to test the fire alarm system as required. Fire alarm system batteries shall be subjected to a load voltage test semiannually. NFPA 72, 14.4.2.2, Table 14.4.2.2 item 5(e). Review of fire alarm system test records indicated the semiannual load voltage tests of the sealed lead acid batteries were not performed as required. A load voltage test of the fire alarm system batteries was done during the annual inspection by an outside company on 10/23/2025. Records did not indicate any other load voltage test on the fire alarm system batteries in the past year. Failure to install, test and maintain the fire alarm system in accordance with NFPA 72 increases the risk of death or injury due to fire.	K 251	Fire alarms will be tested monthly and entered into TELS. Contacted Summit fire protection and we are on schedule to have batteries load tested every 6 months.	10/30/2025 11/12/2025

Health Response and Licensure
STATE FORM

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8204	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING: _____	(X3) DATE SURVEY COMPLETED 10/28/2025
NAME OF PROVIDER OR SUPPLIER EDGEWOOD JAMESTOWN, LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1104 25TH ST SW JAMESTOWN, ND 58401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K2130	Continued From page 4 manufacturer requirements. Written records of maintenance and testing are maintained and readily available. EES electrical panels and circuits are marked, readily identifiable, and separate from normal power circuits. Minimizing the possibility of damage of the emergency power source is a design consideration for new installations. NFPA 110 The facility failed to ensure the emergency generator was in compliance with NFPA 110. Record review and interview with staff determined the emergency generator was not exercised under load for a minimum of 30 minutes during all months in the past year. Failure to inspect, test and maintain the emergency generator in accordance with NFPA 110 increases the risk of death or injury due to fire. The deficiency affected one (1) of one (1) emergency generator which provides all emergency power to the facility.	K2130		