

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 19-Existing Health Care Occupancies and the 2012 edition of NFPA 99, Health Care Facilities Code in compliance with 42 CFR 483.70(a)(b). The findings that follow demonstrate noncompliance with these standards. The facility consisted of three separate units: the east unit, west unit and south unit were of Type II (222) construction with a wet automatic sprinkler system designed to meet the requirements of NFPA 13, Standard for the Installation of Sprinkler Systems. The east (1977), west (1958), and central core (1990) buildings were four stories in height. The south building (1967) was a three-story building. The central core/atrium connected the units. A one-story carpenter shop/storage building was attached to the west side of the south building and was not included in this survey. The long term care building was separated from the carpenter shop/storage building with an occupancy separation wall having a two-hour fire resistance rating. A Type II (000) one-story emergency generator building was attached to the north side of the central core building. A two-hour occupancy separation wall separated the emergency generator building from the rest of the facility. The basement storage areas and Day Care Occupancy of the south building were not included in this survey because they were	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Electronically Signed

11/30/2016

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016	
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES				STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	Continued From page 1 separated from the nursing facility with a floor/ceiling assembly having a fire resistance rating of two hours. Note: A Fire Safety Evaluation System (FSES) was conducted as a result of the 11/15/2016 survey. The FSES was specifically used as an alternative safety method for K 161 (two-hour fire-rated structural members), K 311 (two-hour fire rated shafts), and K 371 (travel distance within smoke compartments). Trinity Homes did not meet the Life Safety Code requirements for construction type, two-hour fire rated shafts and travel distance within smoke compartments, but passes the FSES when all other deficiencies have been corrected.			K 000			
K 161 SS=B	NFPA 101 Building Construction Type and Height Building Construction Type and Height 2012 EXISTING Building construction type and stories meets Table 19.1.6.1, unless otherwise permitted by 19.1.6.2 through 19.1.6.7 19.1.6.4, 19.1.6.5 Construction Type 1 I (442), I (332), II (222) Any number of stories non-sprinklered and sprinklered 2 II (111) One story non-sprinklered Maximum 3 stories sprinklered			K 161			11/17/16

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 161	Continued From page 2 3 II (000) Not allowed non-sprinklered 4 III (211) Maximum 2 stories sprinklered 5 IV (2HH) 6 V (111) 7 III (200) Not allowed non-sprinklered 8 V (000) Maximum 1 story sprinklered Sprinklered stories must be sprinklered throughout by an approved, supervised automatic system in accordance with section 9.7. (See 19.3.5) Give a brief description, in REMARKS, of the construction, the number of stories, including basements, floors on which patients are located, location of smoke or fire barriers and dates of approval. Complete sketch or attach small floor plan of the building as appropriate. This STANDARD is not met as evidenced by: The structural framing throughout buildings of Type II (222) construction must be protected with materials that provide a two-hour fire resistance rating. 19.1.6.1. The facility failed to maintain a two-hour fire resistance rating on structural steel members and ceiling/roof assemblies. Observation determined the structural steel of the skywalk was not protected with material having a two-hour fire resistance rating. Failure to meet the requirements of building construction type increases the risk of death or injury due to fire.	K 161	A Fire Safety Evaluation System (FSES) was conducted for deficiency Tag K 161 of the 11/15/2016 survey to allow unprotected structural members. The facility passes the FSES when all other deficiencies have been corrected.		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 161	Continued From page 3	K 161			
K 311 SS=B	This deficiency affected the entire facility. NFPA 101 Vertical Openings - Enclosure Vertical Openings - Enclosure 2012 EXISTING Stairways, elevator shafts, light and ventilation shafts, chutes, and other vertical openings between floors are enclosed with construction having a fire resistance rating of at least 1 hour. An atrium may be used in accordance with 8.6. 19.3.1.1 through 19.3.1.6 If all vertical openings are properly enclosed with construction providing at least a 2-hour fire resistance rating, also check this box. This STANDARD is not met as evidenced by: The facility failed to maintain the two-hour fire resistive rating at three (3) of three (3) shaft enclosures throughout the west building. 19.3.1. Observation determined: 1) The east and west elevator shafts were open to the elevator equipment rooms in the west building. Elevator shafts and the elevator equipment rooms in four story buildings of Type II (222) construction must be enclosed with two-hour fire resistive construction. 2) The walls of the east elevator room were not constructed as two-hour fire rated assemblies. a) The walls were eight inch clay block with sheet rock and plaster on only one side of the wall assembly. b) The pipe and electrical conduit penetrations	K 311	A Fire Safety Evaluation System (FSES) was conducted for deficiency Tag K 311 of the 11/15/2016 survey to allow smoke resisting shaft enclosures. The facility passes the FSES when all other deficiencies have been corrected.		11/17/16

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 311	Continued From page 4 were not sealed with fire rated material. c) The missing and partially missing clay block were not replaced or repaired. 3) The doors to the east and west elevator equipment rooms were not 90-minute labeled fire rated door assemblies. 4) The four (4) doors to the west stair enclosure of the west building were not labeled to indicate a 90-minute fire resistive rating. Failure to protect vertical openings with construction having a fire resistance rating of at least two hours increases the risk of death or injury due to fire.	K 311			
K 351 SS=D	This deficiency affected seven (7) of fifteen (15) smoke compartments in the facility. NFPA 101 Sprinkler System - Installation Spinkler System - Installation 2012 EXISTING Nursing homes, and hospitals where required by construction type, are protected throughout by an approved automatic sprinkler system in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems. In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where state or local regulations prohibit sprinklers. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 square feet and sprinkler coverage covers the closet footprint as	K 351			11/17/16

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016	
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES				STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 351	Continued From page 5 required by NFPA 13, Standard for Installation of Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.4.2, 19.3.5.10, 9.7, 9.7.1.1(1) This STANDARD is not met as evidenced by: Buildings containing nursing homes shall be protected throughout by an approved, supervised automatic sprinkler system in accordance with section 9.7. 19.3.5.1, 9.7.1.1(1), NFPA 13, 8.3.2.1. Unless the requirements of 8.3.2.2, 8.3.2.3, 8.3.2.4, or 8.3.2.5 are met, ordinary- and intermediate-temperature sprinklers shall be used throughout buildings. NFPA 13, 8.3.2.1. The facility failed to install the automatic sprinkler system in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems. Observation determined two (2) of two (2) sprinklers in the first floor west Air Handler Room were green bulb sprinklers indicating high temperature rated sprinklers. No evidence was available to indicate the temperature at the ceiling in the room exceeded 100 degrees. Failure to install the automatic sprinkler system in accordance with NFPA 13 increases the risk of injury and death due to fire. The deficiency affected two (2) of numerous sprinklers in the facility. The automatic sprinkler system serves the entire facility.			K 351	1. The Green High Temp quick response sprinkler heads will be replaced with Red ordinary Temp Quick Response Sprinkler heads. 2. The plant operations Director will check all air handler/mechanical rooms to verify the correct Temp Sprinkler heads are in use. 3. The Plant Operations director will work with our Fire Sprinkler Contractor to maintain compliance. 4. The plant Operations Director will monitor compliance. 5. 11/17/2016		
K 371 SS=B	NFPA 101 Subdivision of Building Spaces - Smoke Compar Subdivision of Building Spaces - Smoke			K 371			11/17/16

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 371	Continued From page 6 Compartments 2012 EXISTING Smoke barriers shall be provided to form at least two smoke compartments on every sleeping floor with a 30 or more patient bed capacity. Size of compartments cannot exceed 22,500 square feet or a 200-foot travel distance from any point in the compartment to a door in the smoke barrier. 19.3.7.1, 19.3.7.2 Detail in REMARKS zone dimensions including length of zones and dead-end corridors. This STANDARD is not met as evidenced by: The facility failed to ensure the travel distance to reach a door in the required smoke barrier does not exceed 200 feet. 19.3.7.1 Observation determined the 2nd, 3rd and 4th floor smoke compartments of the west building exceeded the maximum 200 feet travel distance to reach the door in the nearest smoke barrier. Failure to ensure travel distance to and from any point to reach a door in a required smoke barrier does not exceed 200 feet increases the risk of death or injury due to fire. This deficiency affected three (3) of fifteen (15) smoke compartments in the facility.	K 371	A Fire Safety Evaluation System (FSES) was conducted for deficiency Tag K 371 of the 11/15/2016 survey to allow travel distance exceeding 200 feet. The facility passes the FSES when all other deficiencies have been corrected.		
K 901 SS=F	NFPA 101 Fundamentals - Building System Categories Fundamentals - Building System Categories Building systems are designed to meet Category 1 through 4 requirements as detailed in NFPA 99. Categories are determined by a formal and documented risk assessment procedure performed by qualified personnel. Chapter 4 (NFPA 99)	K 901		12/9/16	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/21/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355074	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2016
NAME OF PROVIDER OR SUPPLIER TRINITY HOMES			STREET ADDRESS, CITY, STATE, ZIP CODE 305 8TH AVE NE MINOT, ND 58702		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 901	Continued From page 7 This STANDARD is not met as evidenced by: The facility failed to provide a documented risk assessment of building systems. NFPA 99, 4.2 Review of documentation and interview of staff determined the facility failed to conduct and document a risk assessment of building systems. Failure to conduct a risk assessment of building systems increases the risk of injury or death due to fire. This deficiency affected building systems throughout the entire facility.	K 901	1.A formal documented Risk assessment of our facility building systems will be completed and kept on file to meet NFPA 99 Requirements . 2.The Plant operations Director will determine and make a list of the building systems and complete a risk assessment for all of them. 3.The plant operations Director will work with the plant operations staff to maintain compliance. 4.The plant operations Director will monitor compliance. 5.12/9/2016		