

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/01/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/28/2012
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS This survey used the 2000 edition of NFPA 101, Life Safety Code, Chapter 19 Existing Health Care Occupancies in compliance with 42 CFR 483.70(a). The facility is located in a one-story building of Type V (000) construction with a wet automatic sprinkler system designed to meet the requirements of NFPA 13, Standard for Installation of Sprinkler Systems.	K 000			
K 051 SS=F	NFPA 101 LIFE SAFETY CODE STANDARD A fire alarm system with approved components, devices or equipment is installed according to NFPA 72, National Fire Alarm Code, to provide effective warning of fire in any part of the building. Activation of the complete fire alarm system is by manual fire alarm initiation, automatic detection or extinguishing system operation. Pull stations in patient sleeping areas may be omitted provided that manual pull stations are within 200 feet of nurse's stations. Pull stations are located in the path of egress. Electronic or written records of tests are available. A reliable second source of power is provided. Fire alarm systems are maintained in accordance with NFPA 72 and records of maintenance are kept readily available. There is remote annunciation of the fire alarm system to an approved central station. 19.3.4, 9.6	K 051	The fire alarm system will be tested, inspected and maintained by Simplex Grinnell. A report of the testing will be made available to the ND Department of Health and Human Services. In succeeding years Simplex Grinnell will be notified of the necessity of an annual test at least 1 month prior to the due date.	3/15/12	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/01/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/28/2012
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 051	Continued From page 1	K 051			
K 054 SS=F	This STANDARD is not met as evidenced by: The fire alarm system must be in compliance with NFPA 72. This standard requires annual functional testing of the fire alarm system. The facility failed to ensure the fire alarm system was maintained, inspected and tested in accordance with the manufacturer's specifications. Review of the fire alarm testing, inspection, and maintenance records indicated the last fire alarm system test was conducted in 2010. NFPA 101 LIFE SAFETY CODE STANDARD All required smoke detectors, including those activating door hold-open devices, are approved, maintained, inspected and tested in accordance with the manufacturer's specifications. 9.6.1.3 This STANDARD is not met as evidenced by: Visual inspection frequencies and specific testing and maintenance frequencies for smoke detection systems are dictated by the prescriptive requirements of NFPA 72, National Fire Alarm Code (Chapter 10-Inspection, Testing and Maintenance Tables 10.3.1, 10.4.2.2 and 10.4.3). This code identifies specific inspection, testing and maintenance frequencies and methods. Sensitivity testing of smoke detectors is to be completed for all smoke detectors during the first year in service, and the alternate year following. After the second required calibration test, if the	K 054	The smoke detection system will be tested, inspected and maintained by Simplex Grinnell. A report of the testing will be made available to the ND Department of Health and Human Services. In 2 years Simplex Grinnell will be notified of the necessity of a test at least 1 month prior to the due date.	3/15/12	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/01/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/28/2012
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 054	Continued From page 2 detector has remained within its listed and marked sensitivity range, the length of time between calibration tests may be extended, not to exceed five years. The facility failed to ensure smoke detectors were maintained, inspected and tested in accordance with NFPA 72. Review of the fire alarm test results indicated the smoke detection system was not sensitivity tested at frequencies in compliance with the minimum requirements of NFPA 72. If the smoke detection system does not meet the allowance for five (5) years between testing, the system must be tested at least every two (2) years. The test records indicated the smoke detectors have not been tested for sensitivity since 2009. The only smoke detector sensitivity tests the facility had on record were done in 2006 and in 2009. The smoke detector sensitivity test results did not allow the five-year interval. The two-year interval required smoke detector sensitivity testing in 2011.	K 054			
K 130 SS=F	NFPA 101 MISCELLANEOUS OTHER LSC DEFICIENCY NOT ON 2786 This STANDARD is not met as evidenced by: Transfer switches must be subjected to a maintenance program including connections, inspection or testing for evidence of overheating and excessive contact erosion, removal of dust and dirt, and replacement of contacts when	K 130	The transfer switch will be inspected and tested by a qualified electrician. If the testing and inspection indicates that additional maintenance must be done that work will be done by a licensed electrician. Notification of the testing and inspection will be placed at the transfer switch. The due date	3/30/12	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/01/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/28/2012
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 130	Continued From page 3 required. NFPA 110, Standard for Emergency and Standby Power Systems. Based on record review, the facility failed to provide evidence of a preventive maintenance program for the emergency generator electrical transfer switch.	K 130	of the annual inspection will be part of a periodic quality assurance check list and notification of the next inspection will be made on a timely basis.	3/15/12	
K 144 SS=F	NFPA 101 LIFE SAFETY CODE STANDARD Generators are inspected weekly and exercised under load for 30 minutes per month in accordance with NFPA 99. 3.4.4.1. This STANDARD is not met as evidenced by: The facility failed to inspect the emergency generator on a weekly basis as required by NFPA 99, Standard for Health Care Facilities. Review of generator test records identified the lack of documentation of weekly inspections during 2011 and 2012.	K 144	The generator will be inspected weekly and run at full load for 30 minutes each month. A record of each of these procedures will be placed at the site of the generator. Verification of the records will be part of a periodic quality assurance check list.		