

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/24/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING		(X3) DATE SURVEY COMPLETED 03/18/2014
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	INITIAL COMMENTS This survey used the 2000 edition of NFPA 101, Life Safety Code, Chapter 19 Existing Health Care Occupancies in compliance with 42 CFR 483.70(a). The findings that follow demonstrate noncompliance with these standards. The facility was located in a one-story building of Type V (000) construction with a wet automatic sprinkler system designed to meet the requirements of NFPA 13, Standard for Installation of Sprinkler Systems.	K 000	K 029 1. The automatic door closer was adjusted so that the correct amount of force was there to allow the door to shut completely. 2. All remaining automatic doors were checked and found to be in working order. 3. Automatic doors will be checked monthly x 3 months, then quarterly indefinitely by the Maintenance Dept. 4. Auditing of the automatic doors will be reviewed at the monthly QA, Safety, and Infection Control meeting. 5. Date of correction was		3/18/14
K 029 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: The facility failed to separate two (2) of five (5) hazardous areas from other spaces with smoke resistive partitions and self-closing and latching doors. Observation determined: 1- The corridor door to the Central Supply Room did not self-close and latch into the door frame.	K 029	K 029 1. Approved fireproof caulking was applied to the open area surrounding the data cable, sealing the point of penetration. 2. Maintenance Dept will inspect various areas where cables penetrate the wall to ensure these areas include the fireproof caulking.		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Robert Shahan

4-1-14

Administrator

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 03/24/2014
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: NTX021 Facility ID: ND163 If continuation sheet Page 2 of 3

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/24/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 355094	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 03/18/2014
NAME OF PROVIDER OR SUPPLIER GOOD SAMARITAN SOCIETY - MOHALL			STREET ADDRESS, CITY, STATE, ZIP CODE 602 E MAIN ST MOHALL, ND 58761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 069	Continued From page 2 Portable fire extinguishers shall be installed in kitchen cooking areas in accordance with NFPA 10, Standard for Portable Fire Extinguishers, and shall be specifically listed for such use. 10.10.1 Fire Extinguisher Size and Placement for Class K Fires. NFPA 10, 3.7 Fire extinguishers shall be provided for hazards where there is a potential for fires involving combustible cooking media (vegetable or animal oils and fats). NFPA 10, 3.7.1 The facility failed to provide a proper type fire extinguisher in the Kitchen cooking area. Observation determined there was not a K-type fire extinguisher located in the Kitchen.	K 069	K 069 1. Dakota Fire Extinguisher was in the facility on 3/11/14 for the annual fire extinguisher inspection. While here, they found an issue with the 'K' extinguisher located in the kitchen. They took this extinguisher for maintenance, but did not leave a replacement. Dakota Fire Extinguisher was called on 3/18/14 and asked for a replacement of the 'K' extinguisher. A 'K' extinguisher was brought to the facility on 3/24/14. 2. All residents and staff within the facility have the potential to be affected. 3. Dakota Fire Extinguisher was educated on the need for an immediate replacement of any extinguisher in need of repair. 4. Maintenance Dept will accompany Dakota Fire Extinguisher personnel upon inspections, ensuring that all required extinguishers are in place or have a replacement upon inspection completion. 5. Date in compliance		3/24/14

Robert J. Sheeber 4-1-14