



Department of Disabilities, Aging and
Independent Living
Division of Licensing and Protection
280 State Drive/HC 2 South
Waterbury, VT 05671-2060
www.dlp.vermont.gov

[phone] 802-241-0344
[fax] 802-241-0343

AGENCY OF HUMAN SERVICES

February 24, 2026

Mr. Travis Bergeron, Administrator
Union House Nursing Home
3086 Glover Street
Glover, VT 05839

Provider ID #: 475036

Dear Mr. Bergeron:

The Division of Licensing and Protection completed a Life Safety Code survey at your facility on **February 17, 2026**. The purpose of the survey was to determine if your facility was in compliance with Federal participation requirements for nursing homes participating in the Medicare and Medicaid programs. This survey found that your facility was in substantial compliance with the participation requirements. However, there were three deficiencies that do not require a plan of correction but do require a commitment to correct. All references to regulatory requirements contained in this letter are found in Title 42, Code of Federal Regulations. Please **sign the enclosed CMS-2567 and return** the original to this office by **March 6, 2026**.

Informal Dispute Resolution (IDR) Opportunity

In accordance with 42 CFR §488.331, you have one opportunity to question cited deficiencies through an informal dispute resolution process. To be given such an opportunity, you are required to send your written request, along with the specific deficiencies being disputed, including an explanation of why you are disputing those deficiencies, to Pamela Cota, RN, at the Division of Licensing and Protection. Contact information is listed below. Please include if you would prefer a virtual meeting or prefer to submit information in writing for review. This request must be sent during the same ten days you have for submitting your plan of correction. You must still submit a plan of correction for all deficiencies, including those you are disputing, by the due date. An incomplete informal dispute resolution process will not delay the effective date of any enforcement action. Please note that the following are not allowable disputes in the IDR process: scope and severity of deficiencies, unless they are immediate jeopardy level or constitute substandard quality of care; remedies imposed by CMS; survey process or inconsistency issues; or concerns about the IDR process.


A facility cannot use the IDR process to claim past noncompliance.

Email (preferred): Pamela.Cota@vermont.gov

Mailing address: Division of Licensing and Protection, attn Pamela Cota
HC 2 South, 280 State Drive
Waterbury, VT 05671-2060

Phone: (802) 241-0480

Sincerely,

A handwritten signature in black ink that reads "tammy wehmeyer". The signature is written in a cursive, lowercase style.

Tammy Wehmeyer
Administrative Services Manager

Enclosure

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 475036		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 01 BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/17/2026	
NAME OF PROVIDER OR SUPPLIER Union House Nursing Home				STREET ADDRESS, CITY, STATE, ZIP CODE 3086 Glover Street , Glover, Vermont, 05839			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0000	INITIAL COMMENTS The Division of Fire Safety completed an unannounced onsite Life Safety Code inspection on February 17, 2026. Entry and exit interviews were conducted with the Maintenance Supervisor, the Administrator and the Administrator in Training. While the facility was found to be in substantial compliance with applicable Life Safety Code Requirements, the following issues were identified that require a commitment to correct by the facility.		K0000				
K0353 SS = A	Sprinkler System - Maintenance and Testing CFR(s): NFPA 101 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked _____ b) Who provided system test _____ c) Water system supply source _____ Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 This STANDARD is NOT MET as evidenced by: Per observation on 02/17/2026, accompanied by the Maintenance Supervisor, the Administrator, and the Administrator in Training, the facility failed to ensure that automatic sprinkler and standpipe systems are inspected, tested, and maintained as required by		K0353				

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE		TITLE	(X6) DATE
---	--	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 475036		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 01 BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/17/2026	
NAME OF PROVIDER OR SUPPLIER Union House Nursing Home				STREET ADDRESS, CITY, STATE, ZIP CODE 3086 Glover Street , Glover, Vermont, 05839			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			(X5) COMPLETION DATE	
K0353 SS = A	Continued from page 1 regulation. Findings include the following: An inspection of the boiler room revealed that there is a sprinkler head that is obstructed by a duct.	K0353					
K0363 SS = A	Corridor - Doors CFR(s): NFPA 101 Corridor - Doors Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke and are made of 1 3/4 inch solid-bonded core wood or other material capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Corridor doors and doors to rooms containing flammable or combustible materials have positive latching hardware. Roller latches are prohibited by CMS regulation. These requirements do not apply to auxiliary spaces that do not contain flammable or combustible material. Clearance between bottom of door and floor covering is not exceeding 1 inch. Powered doors complying with 7.2.1.9 are permissible if provided with a device capable of keeping the door closed when a force of 5 lbf is applied. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Nonrated protective plates of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This STANDARD is NOT MET as evidenced by: Per observation on 02/17/2026, accompanied by the Maintenance Supervisor, the Administrator, and the Administrator in Training, the facility failed to ensure that doors protecting corridor openings other	K0363					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 475036		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 01 BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/17/2026	
NAME OF PROVIDER OR SUPPLIER Union House Nursing Home				STREET ADDRESS, CITY, STATE, ZIP CODE 3086 Glover Street , Glover, Vermont, 05839			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			(X5) COMPLETION DATE	
K0363 SS = A	Continued from page 2 than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke as required by regulation. Findings include the following: Inspection of door 105 that enters the tub room had a gap that would allow smoke to pass into the corridor. Inspection of door 13 on the second floor had a gap that would allow smoke to pass into the corridor.	K0363					
K0500 SS = A Bldg. 01	Building Services - Other CFR(s): NFPA 101 Building Services - Other List in the REMARKS section any LSC Section 18.5 and 19.5 Building Services requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. This STANDARD is NOT MET as evidenced by: Per observation on 02/17/2026, accompanied by the Maintenance Supervisor, the Administrator, and the Administrator in Training, the facility failed to ensure that boiler inspections are completed every two years as required by regulation. Findings include the following: Inspection of the boiler in the boiler room revealed that the boilers were overdue for their inspections and did not have a valid operating certificate.	K0500					