

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 0015331	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/17/2026
NAME OF PROVIDER OR SUPPLIER URBAN LIVING II		STREET ADDRESS, CITY, STATE, ZIP CODE 1919 N 19TH STREET MILWAUKEE, WI 53205		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{M 000}	INITIAL COMMENTS On 02/17/2026, Surveyor conducted a standard survey and verification visit at Urban Living II One deficiency was identified. Under statutory provisions of Wis. Stat. Ch. 50, a \$200 revisit fee will be assessed. Census: 3	{M 000}		
M 334	88.05(4)(b)1 FIRE SAFETY-SMOKE DETECTORS Every adult family home shall be equipped with one or more single station battery operated, electrically interconnected or radio signal emitting smoke detectors on each floor level. Required smoke detectors shall be located in each habitable room except the kitchen and bathroom and specifically in the following locations: at the head of each open stairway, at the door leading to every enclosed stairway, on the ceiling of the living room or family room, on the ceiling of each sleeping room and in the basement. This Rule is not met as evidenced by: Based on observation and interview, Administrator B did not ensure smoke detection was present in all required locations. There was no smoke detector located upstairs in the living room. Findings include:	M 334		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 0015331	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED R 02/17/2026
NAME OF PROVIDER OR SUPPLIER URBAN LIVING II			STREET ADDRESS, CITY, STATE, ZIP CODE 1919 N 19TH STREET MILWAUKEE, WI 53205		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
M 334	Continued From page 1 On 02/17/2026 at 9:00 AM, Surveyor toured the facility. Surveyor observed that the upstairs living room did not have a smoke detector installed. On 02/17/2026 at 10:15 AM, Surveyor interviewed Administrator B regarding the missing smoke detector. Administrator B stated they did not know a smoke detector was required in the living room as there was one located in the hallway at the top of the stairs. Surveyor shared DHS 88 requirements with Administrator B. Administrator B stated that a smoke detector would be installed as soon as possible.	M 334			