

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 410275	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED C 11/05/2025
NAME OF PROVIDER OR SUPPLIER SYLVAN VIEW		STREET ADDRESS, CITY, STATE, ZIP CODE W9405 GIVENS RD BOX 400 HORTONVILLE, WI 54944		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 000	Initial Comments On 11/05/2025, Surveyors conducted a standard survey and 2 complaint investigations at Sylvan View in Hortonville. Two (2) of 2 complaints were unsubstantiated. As a result of the survey, 1 deficiency was issued. Census: 7	N 000		
N 666	83.59(7)(a) Emergency egress lighting provided All exit passageways and stairways shall be provided with emergency egress lighting with a stand-by power source. This Rule is not met as evidenced by: Based on observation, record review and interview, the provider did not ensure all exit passageways and stairways were clearly identified with emergency egress lighting with a stand-by power source. Three (3) of 3 exits identified on the fire evacuation map were not clearly identified at the door with emergency egress lighting with a stand-by power source. Findings Include: On 11/05/2025 at approximately 11:00 AM, Surveyor conducted a tour of the home with Program Manager A. During the tour, Surveyor observed the fire evacuation map on the wall. Surveyor identified 3 exit passageways (exit door in foyer on 1st floor, exit doorway to garage exit on 1st floor, and exit door in foyer in basement) on the map. Throughout the tour, Surveyor observed the 3 exit passageways did not have	N 666		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 410275	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED C 11/05/2025
NAME OF PROVIDER OR SUPPLIER SYLVAN VIEW			STREET ADDRESS, CITY, STATE, ZIP CODE W9405 GIVENS RD BOX 400 HORTONVILLE, WI 54944		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
N 666	Continued From page 1 emergency egress lighting above or near the door indicating they were exit doors. Surveyor did not observe any other exit passageways throughout the home. At approximately 12:15 PM, Surveyor interviewed Program Manager A and House Manager B regarding the exit passageway signage and egress lighting. Program Manager A and House Manager B stated the maintenance person had just ordered lighted exit signs and was in the process of putting them up in the house.	N 666			