

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 53503	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 09/21/2010
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE - EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS Requirements for Long Term Care Facilities Section 42 CFR 483.70 (a) except as otherwise provided in this section, the facility must meet the applicable provisions of the 2000 edition of the Life Safety Code, Existing Health Care of the National Fire Protection Association (NFPA). The facility was a fully sprinkled single story building of Type V (111) construction built in 1985. The building was equipped with supervised automatic wet sprinkler system and with an addressable fire alarm system. The facility had a capacity of 60 certified Medicare and Medicaid beds with a census of 36.	K 000			
K 029 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with one hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure hazardous areas were separated from use areas in 1 of 5 smoke compartments. The findings were: Observation of resident room #311 on 10/21/10 at	K 029	K 029 The storage room will be converted back to a resident room on or before 10/15/2010. The locking door knob will be replaced with standard room door knob and materials stored in that location will be moved to storage garage behind building. The maintenance director will ensure rooms are not being used for unapproved storage and will report any concerns to the Quality Assurance Committee at least quarterly.	10/15/10	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Nancy R. [Signature]

ADMINISTRATOR

10/4/2010

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FOR MODERN & ACCEPTANCE W/ NANCY RENDON, NHA

RECEIVED
Wyoming Dept of Health

FORM CMS-2567(02-99) Previous Versions Obsolete

Ident ID: 88LX21

Facility ID: WY0025

If continuation sheet Page 1 of 2

ON 10/13/10.

CCT 0 4 2010

Office of Healthcare
Licensing and Surveys

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535013	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 09/21/2010
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE - EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 029	Continued From page 1 8:36 AM showed 9 mattresses were being stored in the room. Further review showed the corridor door was not equipped with a self-closing device. At the time of observation the maintenance director reported he was not aware that rooms storing excessive combustible must have fire separation.	K 029			
K 038 SS-E	NFPA 101 LIFE SAFETY CODE STANDARD Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure egress doors had proper headroom in 1 of 5 smoke compartments. The findings were: Observation of the egress system on 9/21/10 at 9:10 AM showed the double egress doors leading to the secure unit were equipped with magnetic locks. Further review showed the bottom of the egress locks were not the required 6 foot 8 inches above the floor. The maintenance director measured the bottom of the locks at 6 foot 5 inches. He was not aware of the 6 foot 8 inch requirement.	K 038	K 038 The magnetic closure on the Secure Unit doorway will be relocated using Z brackets to ensure proper head clearance of 6 feet 8 inches. This will be completed on or before 10/31/2010. <i>FACILITY DOORS WILL BE INSPECTED ANNUALLY TO ENSURE PROPER HEAD ROOM & DOORS WORKING PROPERLY. REMOVE ALL FINDINGS WILL BE ADDRESSED @ THE NEXT Q.A. MEETING.</i>	10/31/10	